



Allambie Heights Village Ltd

**Proposed New Development
181 Allambie Road, Allambie Heights, NSW**

Geotechnical Desktop Study

Our ref: 5002-R1
15 June 2018

DOCUMENT AUTHORISATION

Proposed New Development 181 Allambie Road, Allambie Heights, NSW Geotechnical Desktop Study

Prepared for Allambie Heights Village Ltd

Our ref: 5002-R1
15 June 2018

For and on behalf of

Asset Geotechnical Engineering Pty Ltd



Mark Green

BSc (Hons) MIEAus CPEng NPER CGeol FGS
Principal Geotechnical Engineer

DOCUMENT CONTROL

Distribution Register

| Copy | Media | Recipient | Location |
|------|------------|---------------|--------------------------------|
| 1 | Secure PDF | Richard Pajor | Centurion Group |
| 2 | Secure PDF | Mark Bartel | Asset Geotechnical Engineering |
| | | | |

Document Status

| Rev | Revision Details | Author | Reviewer | | Approved for Issue | | |
|-----|------------------|-----------|----------|-----------|--------------------|------------|--------------|
| | | | Name | Initials | Name | Initials | Date |
| 0 | Initial issue | S. Khanal | M. Green | <i>MG</i> | M. Bartel | <i>MAB</i> | 15 June 2018 |
| | | | | | | | |

Asset Geotechnical Engineering Pty Ltd
Suite 2.05 / 56 Delhi Road
North Ryde NSW 2113
02 9878 6005
assetgeo.com.au

© Copyright Asset Geotechnical Engineering Pty Ltd. All rights reserved.

This document is and shall remain the property of Asset Geotechnical Engineering Pty Ltd. The document may only be used for the purpose for which it was commissioned and in accordance with the Terms of Agreement for the commission. Unauthorised use of this document in any form whatsoever is prohibited.

Contents

| | | |
|-----------|--|-----------|
| 1. | INTRODUCTION | 1 |
| 1.1 | General..... | 1 |
| 1.2 | Scope of Work..... | 1 |
| 2. | SITE DESCRIPTION | 2 |
| 3. | SUBSURFACE CONDITIONS | 2 |
| 3.1 | Geology..... | 2 |
| 3.2 | Subsurface Conditions..... | 2 |
| 3.3 | Groundwater..... | 3 |
| 4. | DISCUSSIONS & RECOMMENDATIONS | 3 |
| 4.1 | Key Geotechnical Site Constraints..... | 3 |
| 4.2 | Earthworks | 4 |
| 4.3 | Site Classification..... | 7 |
| 4.4 | Footings | 7 |
| 4.5 | Groundwater Control..... | 8 |
| 4.6 | Excavation Support | 8 |
| 5. | RECOMMENDATION FOR FURTHER GEOTECHNICAL INVESTIGATION | 10 |
| 6. | LIMITATIONS | 10 |

FIGURES

- 1 Site Locality

APPENDICES

- A Information Sheets

1. INTRODUCTION

1.1 General

This report presents the results of a Geotechnical Desktop Study for the above project. The investigation was commissioned on 29 May 2018 by Mr Ciaran Foley of Allambie Heights Village Ltd. The work was carried out in accordance with the proposal by Asset Geotechnical Engineering Pty Ltd (Asset) dated 25 May 2018, reference 5002-P1.

Drawings supplied to us for this study comprised:

- Architectural plans prepared by Jackson Teece, Project No.: 2017019, Issue A, Drawings 011, 100, 101, 102, 103, 104 and 105, dated 09 March 2018.

Based on the supplied drawings, we understand that the project involves construction of twenty-four independent living units across two buildings north of existing facilities. Building A will include a single level basement car park with two storeys above, on the gently sloping site. The basement will be approximately 3m deep. Building B includes a lower ground floor habitable space as well as an upper ground floor (making up a total of two storeys). The rear of the lower ground floor building will require a retaining structure of approximately 3m height. South of the existing Martin Luther Lane, a new single storey community centre is also proposed. The drawings indicate the need for a buried on-site detention (OSD) tank and an irrigation tank. The depths of these are not given but are assumed to be at least 1m deep.

1.2 Scope of Work

The main objectives of the investigation were to assess the surface and subsurface conditions and to provide comments and recommendations relating to:

- Key geotechnical constraints to the development
- Excavation conditions, methodology and monitoring
- Subgrade preparation and earthworks
- Site Classification as per AS2870 'Residential Slabs and Footings' (2011)
- Suitable foundations and founding stratum
- Allowable bearing pressure and shaft adhesion for piles
- Excavation support methodology and design parameters
- Maximum allowable permanent and temporary batter slopes
- Groundwater conditions
- Potential for contamination
- Further geotechnical investigation to confirm subsurface conditions and provide geotechnical parameters for footing design

The following scope of work was carried out to achieve the project objectives:

- A review of existing regional maps and reports relevant to the site held within our files, including geotechnical investigation carried out by Asset Geotechnical in 2017 for an earlier expansion to the village.
- Walkover observations of site conditions.
- Engineering assessment and reporting.

This report must be read in conjunction with the attached "Important Information about your Geotechnical Report" in Appendix A. Attention is drawn to the limitations inherent in site investigations and the importance of verifying the subsurface conditions inferred herein.

2. SITE DESCRIPTION

The site is located north of Martin Luther Place and the existing Allambie Heights Village as shown in Figure 1. There is an existing road on the south of the site through Martin Luther Place. It has a street frontage of about 5m. The site is bounded to the east by William Charlton Village, to the south by existing facility and to the other directions by vacant land.

Topographically, the site is slightly raised with a slight southerly downward fall to give a low point at the south-western end. The overall ground surface slopes in the region are about 3° to 8°.

At the time of investigation, the site was a vacant grassy land and to the west of the site there were existing shed buildings to be demolished. The site has also two pavements to enter building on the west of site. There were numerous sandstone rock outcrops towards the northern and southern part of the site. The site is accessible with bitumen sealed. Vegetation is mainly shortly grass with some scattered trees and bushes. Site drainage is assessed to good due to the favourable slopes and slightly elevated position of the site within the surrounding topography.

The historical aerial photograph from 1943 (from SIX Maps website) shows the site to be undeveloped. The site is devoid of significant vegetation and shows little soil cover over the many rock exposures. Google Earth aerial photos show no obvious changes back to 2005. The existing site clearance probably dates back to the time of construction of the adjacent William Charlton Village.

3. SUBSURFACE CONDITIONS

3.1 Geology

The 1:100,000 Sydney Geological Map indicates the site is underlain by Hawkesbury Sandstone.

The eSPADE web site indicates the site to be within the "Lambert" Soil Type. This consists of undulating to rolling rises and low hills on Hawkesbury Sandstone covered in shallow soils. The geotechnical issues associated with this soil type include very high soil erosion hazard, rock outcrop, seasonally perched water table, shallow, highly permeable soil, very low soil fertility.

3.2 Subsurface Conditions

Table 1 provides the subsurface conditions for a borehole drilled at a nearby Asset project location (approx. 50m to the south) and may provide an indication of what the subsurface conditions may be like on site; namely with respect to the natural layers of *residual* soil and *bedrock*.

Table 1 - Generalised Site Geotechnical Model (Asset Borehole Data- Nearby Site)

| Layer | Origin | Description | Soil Density / Consistency | Assessed Rock Classification ¹ |
|---------------|---------------|---|----------------------------|---|
| Unit 1 | Bitumen | Asphalt | -- | -- |
| Unit 2 | Topsoil | Silty/Clayey SAND; fine to medium grained, low plasticity fines, dark brown, roots & root fibres (Plant debris) | Loose | -- |
| Unit 3 | Fill | Silty/Clayey SAND/Sandy GRAVEL/Sandy Silty GRAVEL; fine to coarse grained gravel, rounded, subrounded, sand is fine to medium grained, low plasticity fines, dark brown, orange, yellow, with some assorted cobbles | Loose and medium dense | -- |
| Unit 4 | Residual Soil | Silty SAND; fine to medium grained, low plasticity fines, orange brown | Loose and medium dense | -- |
| Unit 5 | Bedrock | SANDSTONE, fine to medium grained, grey, brown, extremely weathered, extremely-very low strength, defects | -- | Class 5 Sandstone |
| Unit 6 | Bedrock | SANDSTONE, fine to medium grained, pale grey, highly-moderately weathered, very low-low strength | -- | Class 4 Sandstone |
| Unit 7 | Bedrock | SANDSTONE, fine to medium grained, pale grey, grey, moderately weathered, medium strength | -- | Class 3 Sandstone |

3.3 Groundwater

According to the borehole data associated with Table 1, groundwater seepage was observed coming from the fill soils over the bedrock in some of the boreholes. This seepage is considered to be a perched, possibly intermittent, water table.

It is noted that the groundwater observation may have been made before water levels had stabilised. No long-term groundwater monitoring was carried out.

4. DISCUSSIONS & RECOMMENDATIONS

4.1 Key Geotechnical Site Constraints

Based on a basement finished floor level of RL 127.2 AHD, and from the results of this preliminary study, it is assessed that the basement level and would be within sandstone bedrock. It is unlikely to be affected by groundwater, but this should be verified by site specific ground investigation.

Key geotechnical constraints to the development include shallow rock excavation conditions, temporary shoring, permanent retaining, and foundation conditions. Preliminary recommendations for design and construction of the development are provided in the following sections.

¹ Pells, P.J.N., Mostyn, G. & Walker, B.F., *Foundations on Sandstone and Shale in the Sydney Region*, Australian Geomechanics Journal, December 1998

4.2 Earthworks

4.2.1 Excavation

The excavation for the proposed development is anticipated to be partially within soils, and mostly within sandstone bedrock. Excavation within the soils and extremely weathered bedrock would be achievable using conventional earthmoving equipment (i.e. hydraulic excavator bucket).

Excavation within the less weathered bedrock will likely require use of ripper tooth fitted to a hydraulic excavator bucket, a dozer fitted with ripper tooth, or a hydraulic hammer fitted to an excavator, possibly supplemented by rock saw and rock splitting techniques.

4.2.2 Vibration Management

Australian Standard AS 2187: Part 2-2006 recommends the frequency dependent guideline values and assessment methods given in BS 7385 Part 2-1993 "Evaluation and measurement for vibration in buildings Part 2" as they "are applicable to Australian conditions". The standard sets guide values for building vibration based on the lowest vibration levels above which damage has been credibly demonstrated. These levels are judged to give a minimum risk of vibration-induced damage, where minimal risk for a named effect is usually taken as a 95% probability of no effect.

Sources of vibration that are considered in the standard include demolition, blasting (carried out during mineral extraction or construction excavation), piling, ground treatments (e.g. compaction), construction equipment, tunnelling, road and rail traffic and industrial machinery.

For residential structures, BS 7385 recommends vibration criteria of 7.5 mm/s to 10 mm/s for frequencies between 4 Hz and 15 Hz, and 10 mm/s to 25 mm/s for frequencies between 15 Hz to 40 Hz and above. These values would normally be applicable for new residential structures or residential structures in good condition. Higher values would normally apply to commercial structures, and more conservative criteria would normally apply to heritage structures.

However, structures can withstand vibration levels significantly higher than those required to maintain comfort for their occupants. Human comfort is therefore likely to be the critical factor in vibration management.

Excavation methods should be adopted which limit ground vibrations at the adjoining developments to not more than 10mm/sec. Vibration monitoring is recommended to verify that this is achieved. However, if the contractor adopts methods and / or equipment in accordance with the recommendations in Table 2 for a ground vibration limit of 5mm/sec, vibration monitoring may not be required.

The limits of 5mm/sec and 10mm/sec are expected to be achievable if rock breaker equipment or other excavation methods are restricted as indicated in Table 2.

Table 2 – Recommendations for Rock Breaking Equipment

| Distance from adjoining structure (m) | Maximum Peak Particle Velocity 5mm/sec | | Maximum Peak Particle Velocity 10mm/sec* | |
|---------------------------------------|--|---|--|---|
| | Equipment | Operating Limit (% of Maximum Capacity) | Equipment | Operating Limit (% of Maximum Capacity) |
| 1.5 to 2.5 | Hand operated jackhammer only | 100 | 300 kg rock hammer | 50 |
| 2.5 to 5.0 | 300 kg rock hammer | 50 | 300 kg rock hammer | 100 |
| | | | or 600 kg rock hammer | 50 |
| 5.0 to 10.0 | 300 kg rock hammer | 100 | 600 kg rock hammer | 100 |
| | or 600 kg rock hammer | 50 | or 900 kg rock hammer | 50 |

* Vibration monitoring is recommended for 10mm/sec vibration limit.

At all times, the excavation equipment must be operated by experienced personnel, per the manufacturer's instructions, and in a manner, consistent with minimising vibration effects.

Use of other techniques (e.g. chemical rock splitting, rock sawing), although less productive, would reduce or possibly eliminate risks of damage to adjoining property through vibration effects transmitted via the ground. Such techniques may be considered if an alternative to rock breaking is necessary. If rock sawing is carried out around excavation boundaries in not less than 1m deep lifts, a 900kg rock hammer could be used at up to 100% maximum operating capacity with an assessed peak particle velocity not exceeding 5 mm/sec, subject to observation and confirmation by a Geotechnical Engineer at the commencement of excavation.

It is pointed out that the rock classification system used in Table 1 from the adjacent site is not intended to be used to directly assess rock excavation characteristics. Excavation contractors should refer to the detailed engineering logs, core photographs, laboratory strength tests, and inspection of rock core (once undertaken), and should not rely solely on the preliminary rock classifications presented in this report, when assessing the suitability of their excavation equipment for the proposed development. Further geotechnical advice must be sought if rock excavation characteristics are critical to the proposed development.

It should be noted that vibrations that are below threshold levels for building damage may be experienced at adjoining developments. Rock excavation methodology should also consider acceptable noise limits as per the "Interim Construction Noise Guideline" (NSW EPA).

4.2.3 Subgrade Preparation

The following general recommendations are provided for subgrade preparation for earthworks, pavements, slab-on-ground construction, and minor structures:

- Strip existing fill and topsoil. Remove unsuitable materials from site (e.g. material containing deleterious matter). Stockpile remainder for re-use as landscaping material or remove from site.
- Excavate natural soils and rock, stockpiling for re-use as engineered fill or remove to spoil. Rock could be stockpiled separately from clayey soils, for select use beneath pavements.
- Where rock is exposed in bulk excavation level beneath pavements, rip a further 150mm.
- Where rock is exposed at footing invert level, it should be free of loose, "drummy" and softened material before concrete is poured.
- Where soil is exposed in bulk excavation level, compact the upper 150mm depth to a density index (AS1289.5.6.1-1998) not less than 80%. Areas which show visible heave under compaction equipment should be over-excavated a further 0.3m and replaced with approved fill compacted to a density index not less than 80%.

Any waste soils being removed from the site must be classified in accordance with current regulatory authority requirements to enable appropriate disposal to an appropriately licensed landfill facility. Further advice should be sought from a specialist environmental consultant, if required.

4.2.4 Potential for Contamination

Based on the findings of this preliminary geotechnical assessment, the historical evidence of the site indicates the previous uses of the site are unlikely to raise any significant contamination issues. There is always a risk of uncontrolled tipping or burial of waste having occurred that we have no evidence of. A lack of substantial soil cover also reduces the likelihood of any significant risks. A formal Stage 1 Preliminary Site Investigation should be undertaken if risk management is required. This would further assess the potential risk from off-site sources.

4.2.5 Filling

Where filling is required, place in horizontal layers over prepared subgrade and compact as per Table 3.

Table 3 – Compaction Specifications

| Parameter | Cohesive Fill | Non Cohesive Fill |
|---|-----------------|-------------------|
| Fill layer thickness (loose measurement): | | |
| • Within 1.5m of rear of retaining walls | 0.2m | 0.2m |
| • Elsewhere | 0.3m | 0.3m |
| Density: | | |
| • Beneath Pavements | ≥ 95% Std | ≥ 70% ID |
| • Beneath Structures | ≥ 98% Std | ≥ 80% ID |
| • Upper 150mm of subgrade | ≥ 100% Std | ≥ 80% ID |
| Moisture content during compaction | ± 2% of optimum | Moist but not wet |

Filling within 1.5m of the rear of any retaining walls should be compacted using light weight equipment (e.g. hand-operated plate compactor or ride-on compactor not more than 3 tonnes static weight) to limit compaction-induced lateral pressures.

Any soils to be imported onto the site for back-filling and re-instatement of excavated areas should be free of contamination and deleterious material and should include appropriate validation documentation in accordance with current regulatory authority requirements which confirms its suitability for the proposed land use. Further advice should be sought from a specialist environmental consultant if required.

4.2.6 Batter Slopes

Recommended maximum slopes for permanent and temporary batters are presented in Table 4.

Table 4 – Recommended Maximum Dry Batter Slopes

| Unit | Maximum Batter Slope (H : V) | |
|-----------------------------------|------------------------------|------------|
| | Permanent | Temporary |
| Residual silty Sand / clayey Sand | 2 : 1 | 1 : 1 |
| Class 5 Sandstone | 1.5 : 1 | 0.75 : 1 |
| Class 4 (or better) Sandstone | vertical * | vertical * |

* subject to inspection by a Geotechnical Engineer and carrying out remedial works as recommended (e.g. shotcrete, rock bolting).

4.3 Site Classification

Where the foundations are founded on the underlying sandstone bedrock, the site may be classified as a Class A Site in accordance with AS 2870–2011 “Residential Slabs and Footings”. Footings should be designed as per the recommendations given in Section 4.4.

4.4 Footings

Suitable footings might comprise a slab on ground for the basement area and pad and strip footings supporting the upper building loads. It is recommended that all footings are founded on bedrock to reduce the risk of differential settlement due to variable founding conditions.

Edge beams for slab, pad footings (and rock socketed piles, if required) may be designed for the parameters in Table 5.

Table 5 – Preliminary Footing Design Parameters

| Founding Stratum | Maximum Allowable (Serviceability) Values (kPa) | | | Ultimate Strength Limit State Values (kPa) | | | Typical E_{field} MPa |
|-------------------|---|--------------------------------|--------------------------|--|--------------------------------|---------------------------|-------------------------|
| | End Bearing | Shaft Friction – Compression # | Shaft Friction – Tension | End Bearing | Shaft Friction – Compression # | Shaft Friction – Tension* | |
| Class 5 Sandstone | 900 | 90 | 45 | 1,800 | 180 | 90 | 100 |
| Class 4 Sandstone | 1500 | 150 | 75 | 4,500 | 450 | 225 | 200 |
| Class 3 Sandstone | 3,500 | 350 | 175 | 10,500 | 1,050 | 525 | 500 |

Note:

* Uplift capacity of piles in tension loading should also be checked for inverted cone pull out mechanism.

clean socket of roughness category R2 or better is assumed

In accordance with AS2159-2009 “Piling–Design and Installation”, for limit state design, the ultimate geotechnical pile capacity shall be multiplied by a geotechnical reduction factor (Φ_g). This factor is derived from an Average Risk Rating (ARR) which considers geotechnical uncertainties, redundancy of the foundation system, construction supervision, and the quantity and type of pile testing (if any). Where testing is undertaken, or more comprehensive ground investigation is carried out, it may be possible to adopt a larger Φ_g value that results in a more economical pile design. Further geotechnical advice will be required in consultation with the pile designer and piling contractor, to develop an appropriate Φ_g value.

Settlements for footings on rock are anticipated to be about 1% of the minimum footing dimension, based on serviceability parameters as per Table 5.

Options for piles, if required, include:

Bored Piles. It is assessed that the construction of sockets would require the use of a truck mounted drilling rig. It is also assessed that the bored pile holes would not require liners to support the overburden soils, although some over break and minor fretting should be allowed for. Groundwater may be expected within bored pile holes and dewatering by down-hole pump may be required to limit softening of the bases prior to concreting.

Continuous Flight Auger (CFA) Piles. CFA piles are constructed by drilling a hollow stemmed continuous flight auger to the required founding depth. Concrete is then injected under pressure through the auger stem as the auger is extracted from the soil. The reinforcing cage is then inserted upon completion of the concreting process. Pile diameters vary from 300mm to 1200mm. Drilled spoil is produced during CFA piling, and must subsequently be removed from site. CFA piles are considered non-displacement piles as defined in AS2159.

Should piled foundations be anticipated, a site-specific ground investigation that includes boreholes taken at least 1.5m deeper than the anticipated pile toe depth must be undertaken.

4.5 Groundwater Control

Limited groundwater observations made for the nearby investigation are described in Section 0. The observations indicate that groundwater is unlikely to be a constraint to this proposed development. However, good practice should be followed to cater for potential groundwater, such as designing retaining walls with adequate subsoil drainage. Further geotechnical advice must be sought if significant groundwater is encountered during construction.

4.6 Excavation Support

Excavation of soil and rock results in stress changes in the remaining material, and some ground movement is inevitable. The magnitude and extent of lateral and vertical ground movements will depend on the design and construction of the excavation support system. Experience and published data suggest that lateral movements of an adequately designed and installed retention system in soil and weathered rock will typically be in the range of 0.2% to 0.5% of the retained height. The extent of the horizontal movement behind the excavation face typically varies from 1.5 to 3 times the excavated height.

4.6.1 Excavation Support Construction Methodology

Having anticipated shallow sandstone bedrock, it is considered likely that temporary excavation batters could be adopted for the site. Therefore, it is considered likely that permanent retaining walls could be constructed without temporary shoring subject to regular inspection by a Geotechnical Engineer during excavation.

Design of retaining walls will need to consider both long-term (i.e. permanent) and short-term (i.e. during construction) loading conditions, as well as the possible impact on adjoining developments.

In the long-term, the ground floor slab will provide bracing at the top of the wall and the basement floor slab will provide bracing at the bottom of the wall. Therefore, basement retaining walls should be designed as braced walls for the long-term loading condition.

In the short-term (i.e. during construction), the design of the basement retaining wall will depend on the method of construction adopted. Two common construction techniques include top-down and bottom-up construction.

If bottom-up construction is considered, we recommend the use of temporary anchored walls where the retained height is 3.5m or more, and cantilever walls where the retained height is less than 3.5m.

4.6.2 Excavation Support Design Parameters

Support system design may be based on the parameters given in Table 6. Cantilever walls or walls with only a single row of anchors / props may be designed for a triangular earth pressure distribution with the lateral pressure being determined as follows:

$$\sigma_z = K_{o,a,p} z \gamma$$

where σ_z = lateral earth pressure (kPa) at depth z
 $K_{o,a,p}$ = earth pressure coefficient
 o = 'at rest', a = 'active', p = 'passive'
 z = depth (m)
 γ = unit weight of soil / rock (kN/m³)

Table 6 – Preliminary Excavation Support Design Parameters

| Material | Moist Unit Weight (γ_m) kN/m ³ | 'Active' Lateral Earth Pressure Coefficient ⁽¹⁾ (K_a) | 'At Rest' Coefficient ⁽¹⁾ (K_o) | 'Passive' Coefficient ⁽²⁾ (K_p) |
|-----------------------------------|---|--|---|---|
| Residual silty Sand / Clayey Sand | 17.0 | 0.35 | 0.5 | N/A |
| Class 5 Sandstone ⁽³⁾ | 21.0 | 0.2 | 0.4 | 6 |
| Class 4 Sandstone ⁽³⁾ | 22.0 | 0.1 | 0.3 | 15 |
| Class 3 Sandstone ⁽³⁾ | 24.0 | 0.1 | 0.1 | 30 |

Notes to table:

1. These values assume that some wall movement and relaxation of horizontal stress will occur due to the excavation. Actual in-situ K_o values may be higher, particularly in the rock units.
2. Includes a reduction factor to the ultimate value of K_p to consider strain incompatibility between active and passive pressure conditions. Parameters assume horizontal backfill and no back of wall friction.
3. The values for rock assume no adversely dipping joints or other defects are present in the bedrock. All excavation rock faces should be inspected regularly by an experienced Geotechnical Engineer / Engineering Geologist as excavation proceeds.

The parameters for the 'at rest' condition (K_o) should be used for design of lateral earth pressures where adjacent footings/structures are located within the 'zone of influence' of the wall. The 'zone of influence' may be taken as a line extending upwards and outwards at 45° above horizontal from the base of the wall. Piles for cantilever walls should be socketed below bulk excavation level by a depth at least equal to the retained height. For assessment of passive restraint embedded below excavation level, we recommend a triangular pressure distribution.

4.6.3 Surcharge

Allowance must also be made for surcharge loadings and footing loads from adjacent structures.

4.6.4 Hydrostatic Pressure

Where an adequate subsoil drainage system designed by an appropriately qualified and experienced Hydraulic / Stormwater Engineer is provided behind non-tanked retaining walls, no allowance for hydrostatic pressure would be necessary.

Where tanked retaining walls are to be adopted, they should be designed for a hydrostatic pressure based on an appropriate design groundwater level.

5. RECOMMENDATION FOR FURTHER GEOTECHNICAL INVESTIGATION

A minimum of two boreholes per major structures should be sunk to at least 1.5m below the anticipated depth of foundations. With anticipated shallow sandstone bedrock, rock coring will allow core samples to be recovered for laboratory testing for strength verification. The further investigation should be carried out as part of detailed design development.

6. LIMITATIONS

In addition to the limitations inherent in site investigations (refer to the attached Information Sheets), it must be pointed out that the recommendations in this report are based on assessed subsurface conditions from limited off-site investigations. To confirm the inferred soil and rock properties in this report, further investigation by coring and strength testing of rock should be carried out.

It is recommended that a qualified and experienced Geotechnical Engineer be engaged to provide further input and review during the design development; including site visits during construction to verify the site conditions and provide advice where conditions vary from those assumed in this report. Development of an appropriate inspection and testing plan should be carried out in consultation with the Geotechnical Engineer.

This report may have included preliminary geotechnical recommendations for design and construction of temporary works (e.g. temporary batter slopes or temporary shoring of excavations). Such temporary works are expected to perform adequately for a relatively short period only, which could range from a few days (for temporary batter slopes) up to six months (for temporary shoring). This period depends on a range of factors including but not limited to: site geology; groundwater conditions; weather conditions; design criteria; and level of care taken during construction. If there are factors which prevent temporary works from being completed and/or which require temporary works to function for periods longer than originally designed, further advice must be sought from the Geotechnical Engineer and Structural Engineer.

This report and details for the proposed development should be submitted to relevant regulatory authorities that have an interest in the property (e.g. Council) or are responsible for services that may be within or adjacent to the site (e.g. Sydney Water), for their review.

Asset accepts no liability where our recommendations are not followed or are only partially followed. The document "Important Information about your Geotechnical Report" in Appendix A provides additional information about the uses and limitations of this report.

FIGURES

Figure 1 – Site Locality



APPROXIMATE ONLY –
SUBJECT TO DETAIL SURVEY.

SOURCE: GOOGLE MAPS

THIS DRAWING IS USED TO
ILLUSTRATE TEST LOCATIONS
ONLY, AND MUST NOT BE
USED FOR ANY OTHER
PURPOSE. COPYRIGHT OF
SOURCE DRAWING REMAINS
WITH GOOGLE

0 1:1000 A4 10m

| issue | date | description |
|-------|---------|---------------|
| A | 31.5.18 | INITIAL ISSUE |

Asset Geotechnical Engineering Pty Ltd
2.05/56 Delhi Rd, North Ryde NSW 2113
t: 02 9878 6005
e: info@assetgeo.com.au

PROPOSED NEW DEVELOPMENT AT
THE ALLAMBIE HEIGHTS VILLAGE LTD
181 ALLAMBIE ROAD, ALLAMBIE
HEIGHTS NSW
for
ALLAMBIE HEIGHTS VILLAGE LTD
SITE LOCALITY

drawn: SK
date: 30.05.2018
checked: MAG
scale: 1:1000 A4

job no.:
5002
fig: 1
issue: A

APPENDIX A

Important Information about your Geotechnical Report
CSIRO BTF 18
Soil & Rock Explanation Sheets

SCOPE OF SERVICES

The geotechnical report ("the report") has been prepared in accordance with the scope of services as set out in the contract, or as otherwise agreed, between the Client and Asset Geotechnical Engineering Pty Ltd ("Asset"), for the specific site investigated. The scope of work may have been limited by a range of factors such as time, budget, access and/or site disturbance constraints.

The report should not be used if there have been changes to the project, without first consulting with Asset to assess if the report's recommendations are still valid. Asset does not accept responsibility for problems that occur due to project changes if they are not consulted.

RELIANCE ON DATA

Asset has relied on data provided by the Client and other individuals and organizations, to prepare the report. Such data may include surveys, analyses, designs, maps and plans. Asset has not verified the accuracy or completeness of the data except as stated in the report. To the extent that the statements, opinions, facts, information, conclusions and/or recommendations ("conclusions") are based in whole or part on the data, Asset will not be liable in relation to incorrect conclusions should any data, information or condition be incorrect or have been concealed, withheld, misrepresented or otherwise not fully disclosed to Asset.

GEOTECHNICAL ENGINEERING

Geotechnical engineering is based extensively on judgment and opinion. It is far less exact than other engineering disciplines. Geotechnical engineering reports are prepared for a specific client, for a specific project and to meet specific needs, and may not be adequate for other clients or other purposes (e.g. a report prepared for a consulting civil engineer may not be adequate for a construction contractor). The report should not be used for other than its intended purpose without seeking additional geotechnical advice. Also, unless further geotechnical advice is obtained, the report cannot be used where the nature and/or details of the proposed development are changed.

LIMITATIONS OF SITE INVESTIGATION

The investigation program undertaken is a professional estimate of the scope of investigation required to provide a general profile of subsurface conditions. The data derived from the site investigation program and subsequent laboratory testing are extrapolated across the site to form an inferred geological model, and an engineering opinion is rendered about overall subsurface conditions and their likely behavior with regard to the proposed development. Despite investigation, the actual conditions at the site might differ from those inferred to exist, since no subsurface exploration program, no matter how comprehensive, can reveal all subsurface details and anomalies.

The engineering logs are the subjective interpretation of subsurface conditions at a particular location and time, made by trained personnel. The actual interface between materials may be more gradual or abrupt than a report indicates.

Therefore, the recommendations in the report can only be regarded as preliminary. Asset should be retained during the project implementation to assess if the report's recommendations are valid and whether or not changes should be considered as the project proceeds.

SUBSURFACE CONDITIONS ARE TIME DEPENDENT

Subsurface conditions can be modified by changing natural forces or man-made influences. The report is based on conditions that existed at the time of subsurface exploration. Construction operations adjacent to the site, and natural events such as floods, or ground water fluctuations,

may also affect subsurface conditions, and thus the continuing adequacy of a geotechnical report. Asset should be kept apprised of any such events, and should be consulted to determine if any additional tests are necessary.

VERIFICATION OF SITE CONDITIONS

Where ground conditions encountered at the site differ significantly from those anticipated in the report, either due to natural variability of subsurface conditions or construction activities, it is a condition of the report that Asset be notified of any variations and be provided with an opportunity to review the recommendations of this report. Recognition of change of soil and rock conditions requires experience and it is recommended that a suitably experienced geotechnical engineer be engaged to visit the site with sufficient frequency to detect if conditions have changed significantly.

REPRODUCTION OF REPORTS

This report is the subject of copyright and shall not be reproduced either totally or in part without the express permission of this Company. Where information from the accompanying report is to be included in contract documents or engineering specification for the project, the entire report should be included in order to minimize the likelihood of misinterpretation from logs.

REPORT FOR BENEFIT OF CLIENT

The report has been prepared for the benefit of the Client and no other party. Asset assumes no responsibility and will not be liable to any other person or organisation for or in relation to any matter dealt with or conclusions expressed in the report, or for any loss or damage suffered by any other person or organisation arising from matters dealt with or conclusions expressed in the report (including without limitation matters arising from any negligent act or omission of Asset or for any loss or damage suffered by any other party relying upon the matters dealt with or conclusions expressed in the report). Other parties should not rely upon the report or the accuracy or completeness of any conclusions and should make their own inquiries and obtain independent advice in relation to such matters.

DATA MUST NOT BE SEPARATED FROM THE REPORT

The report as a whole presents the site assessment, and must not be copied in part or altered in any way.

Logs, figures, drawings, test results etc. included in our reports are developed by professionals based on their interpretation of field logs (assembled by field personnel) and laboratory evaluation of field samples. These data should not under any circumstances be redrawn for inclusion in other documents or separated from the report in any way.

PARTIAL USE OF REPORT

Where the recommendations of the report are only partially followed, there may be significant implications for the project and could lead to problems. Consult Asset if you are not intending to follow all of the report recommendations, to assess what the implications could be. Asset does not accept responsibility for problems that develop where the report recommendations have only been partially followed if they have not been consulted.

OTHER LIMITATIONS

Asset will not be liable to update or revise the report to take into account any events or emergent circumstances or fact occurring or becoming apparent after the date of the report.

Foundation Maintenance and Footing Performance: A Homeowner's Guide



CSIRO

BTF 18
replaces
Information
Sheet 10/91

Buildings can and often do move. This movement can be up, down, lateral or rotational. The fundamental cause of movement in buildings can usually be related to one or more problems in the foundation soil. It is important for the homeowner to identify the soil type in order to ascertain the measures that should be put in place in order to ensure that problems in the foundation soil can be prevented, thus protecting against building movement.

This Building Technology File is designed to identify causes of soil-related building movement, and to suggest methods of prevention of resultant cracking in buildings.

Soil Types

The types of soils usually present under the topsoil in land zoned for residential buildings can be split into two approximate groups – granular and clay. Quite often, foundation soil is a mixture of both types. The general problems associated with soils having granular content are usually caused by erosion. Clay soils are subject to saturation and swell/shrink problems.

Classifications for a given area can generally be obtained by application to the local authority, but these are sometimes unreliable and if there is doubt, a geotechnical report should be commissioned. As most buildings suffering movement problems are founded on clay soils, there is an emphasis on classification of soils according to the amount of swell and shrinkage they experience with variations of water content. The table below is Table 2.1 from AS 2870, the Residential Slab and Footing Code.

Causes of Movement

Settlement due to construction

There are two types of settlement that occur as a result of construction:

- Immediate settlement occurs when a building is first placed on its foundation soil, as a result of compaction of the soil under the weight of the structure. The cohesive quality of clay soil mitigates against this, but granular (particularly sandy) soil is susceptible.
- Consolidation settlement is a feature of clay soil and may take place because of the expulsion of moisture from the soil or because of the soil's lack of resistance to local compressive or shear stresses. This will usually take place during the first few months after construction, but has been known to take many years in exceptional cases.

These problems are the province of the builder and should be taken into consideration as part of the preparation of the site for construction. Building Technology File 19 (BTF 19) deals with these problems.

Erosion

All soils are prone to erosion, but sandy soil is particularly susceptible to being washed away. Even clay with a sand component of say 10% or more can suffer from erosion.

Saturation

This is particularly a problem in clay soils. Saturation creates a bog-like suspension of the soil that causes it to lose virtually all of its bearing capacity. To a lesser degree, sand is affected by saturation because saturated sand may undergo a reduction in volume – particularly imported sand fill for bedding and blinding layers. However, this usually occurs as immediate settlement and should normally be the province of the builder.

Seasonal swelling and shrinkage of soil

All clays react to the presence of water by slowly absorbing it, making the soil increase in volume (see table below). The degree of increase varies considerably between different clays, as does the degree of decrease during the subsequent drying out caused by fair weather periods. Because of the low absorption and expulsion rate, this phenomenon will not usually be noticeable unless there are prolonged rainy or dry periods, usually of weeks or months, depending on the land and soil characteristics.

The swelling of soil creates an upward force on the footings of the building, and shrinkage creates subsidence that takes away the support needed by the footing to retain equilibrium.

Shear failure

This phenomenon occurs when the foundation soil does not have sufficient strength to support the weight of the footing. There are two major post-construction causes:

- Significant load increase.
- Reduction of lateral support of the soil under the footing due to erosion or excavation.
- In clay soil, shear failure can be caused by saturation of the soil adjacent to or under the footing.

GENERAL DEFINITIONS OF SITE CLASSES

| Class | Foundation |
|--------|---|
| A | Most sand and rock sites with little or no ground movement from moisture changes |
| S | Slightly reactive clay sites with only slight ground movement from moisture changes |
| M | Moderately reactive clay or silt sites, which can experience moderate ground movement from moisture changes |
| H | Highly reactive clay sites, which can experience high ground movement from moisture changes |
| E | Extremely reactive sites, which can experience extreme ground movement from moisture changes |
| A to P | Filled sites |
| P | Sites which include soft soils, such as soft clay or silt or loose sands; landslip; mine subsidence; collapsing soils; soils subject to erosion; reactive sites subject to abnormal moisture conditions or sites which cannot be classified otherwise |

Tree root growth

Trees and shrubs that are allowed to grow in the vicinity of footings can cause foundation soil movement in two ways:

- Roots that grow under footings may increase in cross-sectional size, exerting upward pressure on footings.
- Roots in the vicinity of footings will absorb much of the moisture in the foundation soil, causing shrinkage or subsidence.

Unevenness of Movement

The types of ground movement described above usually occur unevenly throughout the building's foundation soil. Settlement due to construction tends to be uneven because of:

- Differing compaction of foundation soil prior to construction.
- Differing moisture content of foundation soil prior to construction.

Movement due to non-construction causes is usually more uneven still. Erosion can undermine a footing that traverses the flow or can create the conditions for shear failure by eroding soil adjacent to a footing that runs in the same direction as the flow.

Saturation of clay foundation soil may occur where subfloor walls create a dam that makes water pond. It can also occur wherever there is a source of water near footings in clay soil. This leads to a severe reduction in the strength of the soil which may create local shear failure.

Seasonal swelling and shrinkage of clay soil affects the perimeter of the building first, then gradually spreads to the interior. The swelling process will usually begin at the uphill extreme of the building, or on the weather side where the land is flat. Swelling gradually reaches the interior soil as absorption continues. Shrinkage usually begins where the sun's heat is greatest.

Effects of Uneven Soil Movement on Structures

Erosion and saturation

Erosion removes the support from under footings, tending to create subsidence of the part of the structure under which it occurs. Brickwork walls will resist the stress created by this removal of support by bridging the gap or cantilevering until the bricks or the mortar bedding fail. Older masonry has little resistance. Evidence of failure varies according to circumstances and symptoms may include:

- Step cracking in the mortar beds in the body of the wall or above/below openings such as doors or windows.
- Vertical cracking in the bricks (usually but not necessarily in line with the vertical beds or perpend).

Isolated piers affected by erosion or saturation of foundations will eventually lose contact with the bearers they support and may tilt or fall over. The floors that have lost this support will become bouncy, sometimes rattling ornaments etc.

Seasonal swelling/shrinkage in clay

Swelling foundation soil due to rainy periods first lifts the most exposed extremities of the footing system, then the remainder of the perimeter footings while gradually permeating inside the building footprint to lift internal footings. This swelling first tends to create a dish effect, because the external footings are pushed higher than the internal ones.

The first noticeable symptom may be that the floor appears slightly dished. This is often accompanied by some doors binding on the floor or the door head, together with some cracking of cornice mitres. In buildings with timber flooring supported by bearers and joists, the floor can be bouncy. Externally there may be visible dishing of the hip or ridge lines.

As the moisture absorption process completes its journey to the innermost areas of the building, the internal footings will rise. If the spread of moisture is roughly even, it may be that the symptoms will temporarily disappear, but it is more likely that swelling will be uneven, creating a difference rather than a disappearance in symptoms. In buildings with timber flooring supported by bearers and joists, the isolated piers will rise more easily than the strip footings or piers under walls, creating noticeable doming of flooring.

Trees can cause shrinkage and damage



As the weather pattern changes and the soil begins to dry out, the external footings will be first affected, beginning with the locations where the sun's effect is strongest. This has the effect of lowering the external footings. The doming is accentuated and cracking reduces or disappears where it occurred because of dishing, but other cracks open up. The roof lines may become convex.

Doming and dishing are also affected by weather in other ways. In areas where warm, wet summers and cooler dry winters prevail, water migration tends to be toward the interior and doming will be accentuated, whereas where summers are dry and winters are cold and wet, migration tends to be toward the exterior and the underlying propensity is toward dishing.

Movement caused by tree roots

In general, growing roots will exert an upward pressure on footings, whereas soil subject to drying because of tree or shrub roots will tend to remove support from under footings by inducing shrinkage.

Complications caused by the structure itself

Most forces that the soil causes to be exerted on structures are vertical – i.e. either up or down. However, because these forces are seldom spread evenly around the footings, and because the building resists uneven movement because of its rigidity, forces are exerted from one part of the building to another. The net result of all these forces is usually rotational. This resultant force often complicates the diagnosis because the visible symptoms do not simply reflect the original cause. A common symptom is binding of doors on the vertical member of the frame.

Effects on full masonry structures

Brickwork will resist cracking where it can. It will attempt to span areas that lose support because of subsided foundations or raised points. It is therefore usual to see cracking at weak points, such as openings for windows or doors.

In the event of construction settlement, cracking will usually remain unchanged after the process of settlement has ceased.

With local shear or erosion, cracking will usually continue to develop until the original cause has been remedied, or until the subsidence has completely neutralised the affected portion of footing and the structure has stabilised on other footings that remain effective.

In the case of swell/shrink effects, the brickwork will in some cases return to its original position after completion of a cycle, however it is more likely that the rotational effect will not be exactly reversed, and it is also usual that brickwork will settle in its new position and will resist the forces trying to return it to its original position. This means that in a case where swelling takes place after construction and cracking occurs, the cracking is likely to at least partly remain after the shrink segment of the cycle is complete. Thus, each time the cycle is repeated, the likelihood is that the cracking will become wider until the sections of brickwork become virtually independent.

With repeated cycles, once the cracking is established, if there is no other complication, it is normal for the incidence of cracking to stabilise, as the building has the articulation it needs to cope with the problem. This is by no means always the case, however, and monitoring of cracks in walls and floors should always be treated seriously.

Upheaval caused by growth of tree roots under footings is not a simple vertical shear stress. There is a tendency for the root to also exert lateral forces that attempt to separate sections of brickwork after initial cracking has occurred.

The normal structural arrangement is that the inner leaf of brickwork in the external walls and at least some of the internal walls (depending on the roof type) comprise the load-bearing structure on which any upper floors, ceilings and the roof are supported. In these cases, it is internally visible cracking that should be the main focus of attention, however there are a few examples of dwellings whose external leaf of masonry plays some supporting role, so this should be checked if there is any doubt. In any case, externally visible cracking is important as a guide to stresses on the structure generally, and it should also be remembered that the external walls must be capable of supporting themselves.

Effects on framed structures

Timber or steel framed buildings are less likely to exhibit cracking due to swell/shrink than masonry buildings because of their flexibility. Also, the doming/dishing effects tend to be lower because of the lighter weight of walls. The main risks to framed buildings are encountered because of the isolated pier footings used under walls. Where erosion or saturation cause a footing to fall away, this can double the span which a wall must bridge. This additional stress can create cracking in wall linings, particularly where there is a weak point in the structure caused by a door or window opening. It is, however, unlikely that framed structures will be so stressed as to suffer serious damage without first exhibiting some or all of the above symptoms for a considerable period. The same warning period should apply in the case of upheaval. It should be noted, however, that where framed buildings are supported by strip footings there is only one leaf of brickwork and therefore the externally visible walls are the supporting structure for the building. In this case, the subfloor masonry walls can be expected to behave as full brickwork walls.

Effects on brick veneer structures

Because the load-bearing structure of a brick veneer building is the frame that makes up the interior leaf of the external walls plus perhaps the internal walls, depending on the type of roof, the building can be expected to behave as a framed structure, except that the external masonry will behave in a similar way to the external leaf of a full masonry structure.

Water Service and Drainage

Where a water service pipe, a sewer or stormwater drainage pipe is in the vicinity of a building, a water leak can cause erosion, swelling or saturation of susceptible soil. Even a minuscule leak can be enough to saturate a clay foundation. A leaking tap near a building can have the same effect. In addition, trenches containing pipes can become watercourses even though backfilled, particularly where broken rubble is used as fill. Water that runs along these trenches can be responsible for serious erosion, interstrata seepage into subfloor areas and saturation.

Pipe leakage and trench water flows also encourage tree and shrub roots to the source of water, complicating and exacerbating the problem.

Poor roof plumbing can result in large volumes of rainwater being concentrated in a small area of soil:

- Incorrect falls in roof guttering may result in overflows, as may gutters blocked with leaves etc.

- Corroded guttering or downpipes can spill water to ground.
- Downpipes not positively connected to a proper stormwater collection system will direct a concentration of water to soil that is directly adjacent to footings, sometimes causing large-scale problems such as erosion, saturation and migration of water under the building.

Seriousness of Cracking

In general, most cracking found in masonry walls is a cosmetic nuisance only and can be kept in repair or even ignored. The table below is a reproduction of Table C1 of AS 2870.

AS 2870 also publishes figures relating to cracking in concrete floors, however because wall cracking will usually reach the critical point significantly earlier than cracking in slabs, this table is not reproduced here.

Prevention/Cure

Plumbing

Where building movement is caused by water service, roof plumbing, sewer or stormwater failure, the remedy is to repair the problem. It is prudent, however, to consider also rerouting pipes away from the building where possible, and relocating taps to positions where any leakage will not direct water to the building vicinity. Even where gully traps are present, there is sometimes sufficient spill to create erosion or saturation, particularly in modern installations using smaller diameter PVC fixtures. Indeed, some gully traps are not situated directly under the taps that are installed to charge them, with the result that water from the tap may enter the backfilled trench that houses the sewer piping. If the trench has been poorly backfilled, the water will either pond or flow along the bottom of the trench. As these trenches usually run alongside the footings and can be at a similar depth, it is not hard to see how any water that is thus directed into a trench can easily affect the foundation's ability to support footings or even gain entry to the subfloor area.

Ground drainage

In all soils there is the capacity for water to travel on the surface and below it. Surface water flows can be established by inspection during and after heavy or prolonged rain. If necessary, a grated drain system connected to the stormwater collection system is usually an easy solution.

It is, however, sometimes necessary when attempting to prevent water migration that testing be carried out to establish watertable height and subsoil water flows. This subject is referred to in BTF 19 and may properly be regarded as an area for an expert consultant.

Protection of the building perimeter


It is essential to remember that the soil that affects footings extends well beyond the actual building line. Watering of garden plants, shrubs and trees causes some of the most serious water problems.

For this reason, particularly where problems exist or are likely to occur, it is recommended that an apron of paving be installed around as much of the building perimeter as necessary. This paving

CLASSIFICATION OF DAMAGE WITH REFERENCE TO WALLS

| Description of typical damage and required repair | Approximate crack width limit (see Note 3) | Damage category |
|---|---|-----------------|
| Hairline cracks | <0.1 mm | 0 |
| Fine cracks which do not need repair | <1 mm | 1 |
| Cracks noticeable but easily filled. Doors and windows stick slightly | <5 mm | 2 |
| Cracks can be repaired and possibly a small amount of wall will need to be replaced. Doors and windows stick. Service pipes can fracture. Weathertightness often impaired | 5–15 mm (or a number of cracks 3 mm or more in one group) | 3 |
| Extensive repair work involving breaking-out and replacing sections of walls, especially over doors and windows. Window and door frames distort. Walls lean or bulge noticeably, some loss of bearing in beams. Service pipes disrupted | 15–25 mm but also depend on number of cracks | 4 |

Gardens for a reactive site



- Water that is transmitted into masonry, metal or timber building elements causes damage and/or decay to those elements.
- High subfloor humidity and moisture content create an ideal environment for various pests, including termites and spiders.
- Where high moisture levels are transmitted to the flooring and walls, an increase in the dust mite count can ensue within the living areas. Dust mites, as well as dampness in general, can be a health hazard to inhabitants, particularly those who are abnormally susceptible to respiratory ailments.

The garden

The ideal vegetation layout is to have lawn or plants that require only light watering immediately adjacent to the drainage or paving edge, then more demanding plants, shrubs and trees spread out in that order.

Overwatering due to misuse of automatic watering systems is a common cause of saturation and water migration under footings. If it is necessary to use these systems, it is important to remove garden beds to a completely safe distance from buildings.

Existing trees

Where a tree is causing a problem of soil drying or there is the existence or threat of upheaval of footings, if the offending roots are subsidiary and their removal will not significantly damage the tree, they should be severed and a concrete or metal barrier placed vertically in the soil to prevent future root growth in the direction of the building. If it is not possible to remove the relevant roots without damage to the tree, an application to remove the tree should be made to the local authority. A prudent plan is to transplant likely offenders before they become a problem.

Information on trees, plants and shrubs

State departments overseeing agriculture can give information regarding root patterns, volume of water needed and safe distance from buildings of most species. Botanic gardens are also sources of information. For information on plant roots and drains, see Building Technology File 17.

Excavation

Excavation around footings must be properly engineered. Soil supporting footings can only be safely excavated at an angle that allows the soil under the footing to remain stable. This angle is called the angle of repose (or friction) and varies significantly between soil types and conditions. Removal of soil within the angle of repose will cause subsidence.

Remediation

Where erosion has occurred that has washed away soil adjacent to footings, soil of the same classification should be introduced and compacted to the same density. Where footings have been undermined, augmentation or other specialist work may be required. Remediation of footings and foundations is generally the realm of a specialist consultant.

Where isolated footings rise and fall because of swell/shrink effect, the homeowner may be tempted to alleviate floor bounce by filling the gap that has appeared between the bearer and the pier with blocking. The danger here is that when the next swell segment of the cycle occurs, the extra blocking will push the floor up into an accentuated dome and may also cause local shear failure in the soil. If it is necessary to use blocking, it should be by a pair of fine wedges and monitoring should be carried out fortnightly.

This BTF was prepared by John Lewer FAIB, MIAMA, Partner, Construction Diagnosis.

should extend outwards a minimum of 900 mm (more in highly reactive soil) and should have a minimum fall away from the building of 1:60. The finished paving should be no less than 100 mm below brick vent bases.

It is prudent to relocate drainage pipes away from this paving, if possible, to avoid complications from future leakage. If this is not practical, earthenware pipes should be replaced by PVC and backfilling should be of the same soil type as the surrounding soil and compacted to the same density.

Except in areas where freezing of water is an issue, it is wise to remove taps in the building area and relocate them well away from the building – preferably not uphill from it (see BTF 19).

It may be desirable to install a grated drain at the outside edge of the paving on the uphill side of the building. If subsoil drainage is needed this can be installed under the surface drain.

Condensation

In buildings with a subfloor void such as where bearers and joists support flooring, insufficient ventilation creates ideal conditions for condensation, particularly where there is little clearance between the floor and the ground. Condensation adds to the moisture already present in the subfloor and significantly slows the process of drying out. Installation of an adequate subfloor ventilation system, either natural or mechanical, is desirable.

Warning: Although this Building Technology File deals with cracking in buildings, it should be said that subfloor moisture can result in the development of other problems, notably:

The information in this and other issues in the series was derived from various sources and was believed to be correct when published.

The information is advisory. It is provided in good faith and not claimed to be an exhaustive treatment of the relevant subject.

Further professional advice needs to be obtained before taking any action based on the information provided.

Distributed by

CSIRO PUBLISHING PO Box 1139, Collingwood 3066, Australia

Freecall 1800 645 051 Tel (03) 9662 7666 Fax (03) 9662 7555 www.publish.csiro.au

Email: publishing.sales@csiro.au

© CSIRO 2003. Unauthorised copying of this Building Technology file is prohibited

LOG ABBREVIATIONS AND NOTES

METHOD

borehole logs

| | |
|----|-------------------|
| AS | auger screw * |
| AD | auger drill * |
| RR | roller / tricone |
| W | washbore |
| CT | cable tool |
| HA | hand auger |
| D | diatube |
| B | blade / blank bit |
| V | V-bit |
| T | TC-bit |

* bit shown by suffix e.g. ADV

excavation logs

| | |
|----|--------------------|
| NE | natural excavation |
| HE | hand excavation |
| BH | backhoe bucket |
| EX | excavator bucket |
| DZ | dozer blade |
| R | ripper tooth |

coring

NMLC, NQ, PQ, HQ

SUPPORT

borehole logs

| | |
|----|---------|
| N | nil |
| M | mud |
| C | casing |
| NQ | NQ rods |

excavation logs

| | |
|---|---------|
| N | nil |
| S | shoring |
| B | benched |

CORE—LIFT

| | |
|---|------------------|
| | casing installed |
| ⊢ | barrel withdrawn |

NOTES, SAMPLES, TESTS

| | |
|-----|---|
| D | disturbed |
| B | bulk disturbed |
| U50 | thin-walled sample, 50mm diameter |
| HP | hand penetrometer (kPa) |
| SV | shear vane test (kPa) |
| DCP | dynamic cone penetrometer (blows per 100mm penetration) |
| SPT | standard penetration test |
| N* | SPT value (blows per 300mm) |
| | * denotes sample taken |
| Nc | SPT with solid cone |
| R | refusal of DCP or SPT |

USCS SYMBOLS

| | |
|----|---|
| GW | Well graded gravels and gravel-sand mixtures, little or no fines. |
| GP | Poorly graded gravels and gravel-sand mixtures, little or no fines. |
| GM | Silty gravels, gravel-sand-silt mixtures. |
| GC | Clayey gravels, gravel-sand-clay mixtures. |
| SW | Well graded sands and gravelly sands, little or no fines. |
| SP | Poorly graded sands and gravelly sands, little or no fines. |
| SM | Silty sand, sand-silt mixtures. |
| SC | Clayey sand, sand-clay mixtures. |
| ML | Inorganic silts of low plasticity, very fine sands, rock flour, silty or clayey fine sands. |
| CL | Inorganic clays of low to medium plasticity, gravelly clays, sandy clays, silty clays. |
| OL | Organic silts and organic silty clays of low plasticity. |
| MH | Inorganic silts of high plasticity. |
| CH | Inorganic clays of high plasticity. |
| OH | Organic clays of medium to high plasticity. |
| PT | Peat muck and other highly organic soils. |

MOISTURE CONDITION

| | |
|----|---------------|
| D | dry |
| M | moist |
| W | wet |
| Wp | plastic limit |
| Wl | liquid limit |

CONSISTENCY

| | |
|-----|------------|
| VS | very soft |
| S | soft |
| F | firm |
| St | stiff |
| VSt | very stiff |
| H | hard |
| Fb | friable |

DENSITY INDEX

| | |
|----|--------------|
| VL | very loose |
| L | loose |
| MD | medium dense |
| D | dense |
| VD | very dense |

GRAPHIC LOG

Soil

| | |
|--|----------------|
| | Fill |
| | Peat, Topsoil |
| | Clay |
| | Silty Clay |
| | Gravelly Clay |
| | Sandy Clay |
| | Silt |
| | Sandy Silt |
| | Clayey Silt |
| | Gravelly Silt |
| | Gravel |
| | Sandy Gravel |
| | Clayey Gravel |
| | Silty Gravel |
| | Sand |
| | Gravelly Sandy |
| | Silty Sand |
| | Clayey Sand |

Rock

| | |
|--|------------------|
| | Sandstone |
| | Shale |
| | Clayey Shale |
| | Siltstone |
| | Conglomerate |
| | Claystone |
| | Dolerite, Basalt |
| | Granite |
| | Limestone |
| | Tuff |
| | Porphyry |
| | Pegmatite |
| | Gneiss, Schist |
| | Quartzite |
| | Coal |

Other

| | |
|--|----------|
| | Asphalt |
| | Concrete |
| | Brick |

Water

| | |
|--|--------------------|
| | Level |
| | Inflow |
| | Outflow (complete) |
| | Outflow (partial) |

Boundaries

| | |
|--|----------|
| | Known |
| | Probable |
| | Possible |

WEATHERING

| | |
|----|----------------------|
| XW | extremely weathered |
| HW | highly weathered |
| MW | moderately weathered |
| SW | slightly weathered |
| FR | fresh |

STRENGTH

| | |
|----|----------------|
| EL | extremely low |
| VL | very low |
| L | low |
| M | medium |
| H | high |
| VH | very high |
| EH | extremely high |

RQD (%)

$$= \frac{\text{sum of intact core pieces} > 2 \times \text{diameter}}{\text{total length of section being evaluated}} \times 100$$

DEFECTS:

type

| | |
|----|------------|
| JT | joint |
| PT | parting |
| SZ | shear zone |
| SM | seam |

coating

| | |
|----|---------|
| cl | clean |
| st | stained |
| ve | veener |
| co | coating |

shape

| | |
|----|------------|
| pl | planar |
| cu | curved |
| un | undulating |
| st | stepped |
| ir | irregular |

roughness

| | |
|----|--------------|
| po | polished |
| sl | slickensided |
| sm | smooth |
| ro | rough |
| vr | very rough |

inclination

measured above axis and perpendicular to core

AS1726-1993

Soils and rock are described in the following terms, which are broadly in accordance with AS1726-1993.

SOIL

MOISTURE CONDITION

| Term | Description |
|-------|---|
| Dry | Looks and feels dry. Cohesive and cemented soils are hard, friable or powdery. Un-cemented granular soils run freely through the hand. |
| Moist | Feels cool and darkened in colour. Cohesive soils can be moulded. Granular soils tend to cohere. |
| Wet | As for moist, but with free water forming on hands when handled. Moisture content of cohesive soils may also be described in relation to plastic limit (W_p) or liquid limit (W_L) [$>>$ much greater than, $>$ greater than, $<$ less than, $<<$ much less than]. |

CONSISTENCY OF COHESIVE SOILS

| Term | S_u (kPa) | Term | S_u (kPa) |
|-----------|-------------|------------|-------------|
| Very soft | < 12 | Very Stiff | 100 – 200 |
| Soft | 12 – 25 | Hard | > 200 |
| Firm | 25 – 50 | Friable | - |
| Stiff | 50 – 100 | | |

DENSITY OF GRANULAR SOILS

| Term | Density Index (%) | Term | Density Index (%) |
|--------------|-------------------|------------|-------------------|
| Very Loose | < 15 | Dense | 65 – 85 |
| Loose | 15 – 35 | Very Dense | >85 |
| Medium Dense | 35 – 65 | | |

PARTICLE SIZE

| Name | Subdivision | Size (mm) |
|-------------|-------------|-------------|
| Boulders | | > 200 |
| Cobbles | | 63 – 200 |
| Gravel | coarse | 20 – 63 |
| | medium | 6 – 20 |
| | fine | 2.36 – 6 |
| Sand | coarse | 0.6 – 2.36 |
| | medium | 0.2 – 0.6 |
| | fine | 0.075 – 0.2 |
| Silt & Clay | | < 0.075 |

MINOR COMPONENTS

| Term | Proportion by Mass: | |
|-------|---------------------|--------------|
| | coarse grained | fine grained |
| Trace | = 5% | = 15% |
| Some | 5 – 2% | 15 – 30% |

SOIL ZONING

| | |
|---------|---|
| Layers | Continuous exposures. |
| Lenses | Discontinuous layers of lenticular shape. |
| Pockets | Irregular inclusions of different material. |

SOIL CEMENTING

| | |
|------------|--|
| Weakly | Easily broken up by hand. |
| Moderately | Effort is required to break up the soil by hand. |

USCS SYMBOLS

| Symbol | Description |
|--------|---|
| GW | Well graded gravels and gravel-sand mixtures, little or no fines. |
| GP | Poorly graded gravels and gravel-sand mixtures, little or no fines. |
| GM | Silty gravels, gravel-sand-silt mixtures. |
| GC | Clayey gravels, gravel-sand-clay mixtures. |
| SW | Well graded sands and gravelly sands, little or no fines. |
| SP | Poorly graded sands and gravelly sands, little or no fines. |
| SM | Silty sand, sand-silt mixtures. |
| SC | Clayey sand, sand-clay mixtures. |
| ML | Inorganic silts of low plasticity, very fine sands, rock flour, silty or clayey fine sands. |
| CL | Inorganic clays of low to medium plasticity, gravelly clays, sandy clays, silty clays. |
| OL | Organic silts and organic silty clays of low plasticity. |
| MH | Inorganic silts of high plasticity. |
| CH | Inorganic clays of high plasticity. |
| OH | Organic clays of medium to high plasticity. |
| PT | Peat muck and other highly organic soils. |

ROCK

SEDIMENTARY ROCK TYPE DEFINITIONS

| Rock Type | Definition (more than 50% of rock consists of |
|--------------|--|
| Conglomerate | ... gravel sized (>2mm) fragments. |
| Sandstone | ... sand sized (0.06 to 2mm) grains. |
| Siltstone | ... silt sized (<0.06mm) particles, rock is not laminated. |
| Claystone | ... clay, rock is not laminated. |
| Shale | ... silt or clay sized particles, rock is laminated. |

LAYERING

| Term | Description |
|------------------|--|
| Massive | No layering apparent. |
| Poorly Developed | Layering just visible. Little effect on properties. |
| Well Developed | Layering distinct. Rock breaks more easily parallel to layering. |

STRUCTURE

| Term | Spacing (mm) | Term | Spacing |
|--------------------|--------------|---------------------|-------------|
| Thinly laminated | <6 | Medium bedded | 200 – 600 |
| Laminated | 6 – 20 | Thickly bedded | 600 – 2,000 |
| Very thinly bedded | 20 – 60 | Very thickly bedded | > 2,000 |
| Thinly bedded | 60 – 200 | | |

STRENGTH (NOTE: Is50 = Point Load Strength Index)

| Term | Is50 (MPa) | Term | Is50 (MPa) |
|---------------|------------|----------------|------------|
| Extremely Low | <0.03 | High | 1.0 – 3.0 |
| Very low | 0.03 – 0.1 | Very High | 3.0 – 10.0 |
| Low | 0.1 – 0.3 | Extremely High | >10.0 |
| Medium | 0.3 – 1.0 | | |

WEATHERING

| Term | Description |
|------------------|---|
| Residual Soil | Soil derived from weathering of rock; the mass structure and substance fabric are no longer evident. |
| Extremely | Rock is weathered to the extent that it has soil properties (either disintegrates or can be remoulded). Fabric of original rock is still visible. |
| Highly | Rock strength usually highly changed by weathering; rock may be highly discoloured. |
| Moderately | Rock strength usually moderately changed by weathering; rock may be moderately discoloured. |
| Slightly | Rock is slightly discoloured but shows little or no change of strength from fresh rock. |
| Fresh | Rock shows no signs of decomposition or staining. |

DEFECT DESCRIPTION

| Type | Description |
|--------------|---|
| Joint | A surface or crack across which the rock has little or no tensile strength. May be open or closed. |
| Parting | A surface or crack across which the rock has little or no tensile strength. Parallel or sub-parallel to layering/bedding. May be open or closed. |
| Sheared Zone | Zone of rock substance with roughly parallel, near planar, curved or undulating boundaries cut by closely spaced joints, sheared surfaces or other defects. |
| Seam | Seam with deposited soil (infill), extremely weathered insitu rock (XW), or disoriented usually angular fragments of the host rock (crushed). |

Shape

| | |
|------------|------------------------------------|
| Planar | Consistent orientation. |
| Curved | Gradual change in orientation. |
| Undulating | Wavy surface. |
| Stepped | One or more well defined steps. |
| Irregular | Many sharp changes in orientation. |

Roughness

| | |
|--------------|--|
| Polished | Shiny smooth surface. |
| Slickensided | Grooved or striated surface, usually polished. |
| Smooth | Smooth to touch. Few or no surface irregularities. |
| Rough | Many small surface irregularities (amplitude generally <1mm). Feels like fine to coarse sandpaper. |
| Very Rough | Many large surface irregularities, amplitude generally >1mm. Feels like very coarse sandpaper. |

Coating

| | |
|---------|--|
| Clean | No visible coating or discolouring. |
| Stained | No visible coating but surfaces are discolored. |
| Veneer | A visible coating of soil or mineral, too thin to measure; may be patchy |
| Coating | Visible coating =1mm thick. Thicker soil material described as seam. |