

GEOTECHNICAL INVESTIGATION REPORT PROPOSED POOL HOUSE, SWIMMING POOL AND TERRACE 90 CABBAGE TREE ROAD, BAYVIEW, NEW SOUTH WALES MS YASMINA ELSHAFEI AND MR FORD ENNALS

MMGEO2024YEFE_AB REVISION A JUNE 2024

Revision	Details	Date	Prepared By	Reviewed By
A	Electronic Copy Issued to Client	28 June 2024	Dr Ramesh Gedela	Muliadi Merry

© MM Geomechanics [2024].

Copyright in the drawings, information and data recorded in this document (the Information) is the property of MM Geomechanics. This document and the information are solely for the use of the authorised recipient (the Client). This document may not be used, copied or reproduced in whole or part for any purpose other than that for which MM Geomechanics supplied it. MM Geomechanics makes no representation, undertakes no duty and accepts no responsibility to any third party who may use or rely upon this document or the information.

MM Geomechanics ABN 78 624 459 534 www.mmgeomechanics.com.au

MM Geomechanics PTY ITD

ABN 78 624 459 534 | ACN 624 459 534

T +61 481 265 169 E info@mmgeomechanics.com.au W http://www.mmgeomechanics.com.au

Sydney

South Coast

Level 2, 25 Ryde Road Pymble NSW 2073

Office 19, Corporate House Suite 1, Ground Floor, Enterprise 1 Innovation Campus, Squires Way North Wollongong NSW 2500



Sydney, 28 June 2024

Ms Yasmina Elshafei and Mr Ford Ennals c/- Mr Ryan Western **Casey Brown Architecture** Level 1, 63 William Street East Sydney NSW 2010

Dear Yasmina and Ford,

This report presents the results from a geotechnical investigation undertaken by MM Geomechanics within a property located at 90 Cabbage Tree Road in Bayview, New South Wales (also known as Lot 22 in Deposited Plan 602041). The site investigation was specific to the area to the east of the main house on which a pool house will be constructed. The investigation works was implemented to assess the subsurface conditions across the development site. The investigation data will be relied upon to assist with the project planning and design processes. The geotechnical investigation report was also complementary to the development application process.

MM Geomechanics, a specialist geotechnical consultant, carried out the work in general accordance with a proposal dated 23 April 2024 reference MMGEO2024YEFE AA. The property owners commissioned the work on 9 May 2024.

If you require further information, please contact the undersigned on 0400 393 008.

For and on behalf of MM Geomechanics,

-

Muliadi Merry BEng MEng FIEAust CPEng NER (Civil) RPEQ Professional Engineer (CPEng) 1401340 Registered Professional Engineer of Queensland (RPEQ) 24119 Professional Engineer Registration - #PRE0000542 Design Practitioner - #DEP0000552 Principal Design Practitioner – #PDP00001180

Distribution: Original held by MM Geomechanics Electronic copy to Ms Yasmina Elshafei and Mr Ford Ennals, also Mr Ryan Western (Casey Brown Architecture, CBA).

MMGEO2024YEFE AB Revision A.docx 6/28/24 3:02:00 PM

CONTENTS

ASS	SESSMENT SUMMARY	
1.	INTRODUCTION	1
2.	SITE LOCALITY	2
3.	INVESTIGATION METHODOLOGY	2
	3.1. Desktop Study	2
	3.2. Fieldwork	2
4.	SITE CONDITIONS	4
5.	SITE GEOLOGY	4
6.	POTENTIAL OCCURRENCE OF ACID SULFATE SOILS	4
7.	SUBSURFACE CONDITIONS	5
8.	GEOTECHNICAL RISK APPRAISALS	7
	8.1 Qualitative Risk Estimation for Property	7
	8.2 Quantitative Risk Estimation for Loss of Life	8
9.	EARTHWORKS	9
10.	EXCAVATION CONDITIONS	9
11.	GROUNDWATER	9
12.	TEMPORARY CUT BATTERS AND RETAINING STRUCTURES	10
13.	FOUNDATIONS	11
14.	EARTHQUAKE ACTIONS	12
15.	CONCRETE EXPOSURE	12
16.	CONSTRUCTION INSPECTION REQUIREMENTS	12
17.	SITE MAINTENANCE REQUIREMENTS	12
18.	LIMITATIONS	13
19.	REFERENCE	14

LIST OF FIGURES

Figure 1	 – Site 	Locality
----------	----------------------------	----------

- Figure 2 Geotechnical Test Location Plan
- Figure 3 Site Photographs Taken on 23 July 2021 (Sheet 1 of 2)
- Figure 4 Site Photographs Taken on 23 July 2021 (Sheet 2 of 2)
- Figure 5 Site Geology
- Figure 6 Potential Occurrence of Acid Sulfate Soils

LIST OF TABLES

Table 2.1: Site Geographic Position
Table 3.1: Summary of Geotechnical Tests
Table 7.1: Summary of Subsurface Conditions at Test Locations and Inferred Geotechnical Model
Table 7.2: Summary of Inferred Subsurface Stratigraphy
Table 8.1: Identification of Potential Geotechnical Hazards and Elements at Risk
Table 8.2: Qualitative Risk Estimation for Loss of Property
Table 8.3: Quantitative Risk Estimation for Loss of Life
Table 12.1: Summary of Geotechnical Design Parameters for Retaining Structures
Table 13.1: Recommended Footing Design Parameters

LIST OF DIAGRAMME

Diagramme 13.1: Required Minimum Setback for Calculation of Effective Rock Socket

APPENDICES

- Appendix A Engineering Logs and Explanation Sheets
- Appendix B Dynamic Cone Penetrometer Test Results
- Appendix C Important Information about AGS2007 Appendix C
- Appendix D CSIRO Publication Building Technology File 18-2011
- Appendix E Important Information about Your Geotechnical Report

ASSESSMENT SUMMARY

Lot No:	22		new Defer	23 July 2021 to 1 August 2021		
Deposited Plan:	602041	Assessr	nent Date:	9 May 2024 to 28 June 2024		
90 Cabbage Tree Road, Bayview, New South Wales		Assessor Name:		Muliadi Merry Fellow, Engineers Australia Chartered Professional Engineer National Engineering Register Registered Professional Engineer of Queensland Registered Principal Design Practitioner with NSW Fair Trading		
Sit	e Data		Assessm	nent Outcome		
Investigation Met	nodology	A combinatio	n of desktop rev	iew and site investigation.		
		The property is bounded by Cabbage Tree Road to the south and is surrounded by neighbouring properties to the north, west and south.				
			The property covers an area of about 3.2Ha.			
Site Topography		A two-storey dwelling house is evident at the southwestern corner of the site while the remainder of the site is consisted of vacant lands largely covered by dense vegetation.				
		A gravel driveway is present to the south of the site approximately in a west-east orientation as an extension of an easement that is connected to Cabbage Tree Road.				
		The development site is located to the east of the house and to the north of the driveway. The development will be formed on a northerly dipping slope.				
Site Geology		Hawkesbury Sandstone underlies the site locality.				
Occurrence of Ac	id Sulfate Soils	No known oc	currence of acid	sulfate soils.		
Inferred Subsurfa	ce Conditions	Topsoil, colluvium and residual soil overlying rock. Sandstone floaters may also be present.				
		HZ1	Slippage of the	e colluvium within the site.		
Geotechnical Haz		HZ2	Deep seated la	andslide within the site.		
Geotechnical Haz	aros	HZ3	Creep soil mas	s movement within the site.		
		HZ4	Erosion within	the site.		
			HZ1	Low		
Assessed Residu	al Risk Lovels	For Loss of	HZ2	Low		
Assessed Residu		Property	HZ3	Low	_	
			HZ4	Low		

		HZ1	2.5 x 10⁻ ⁶	
	E. L. C	HZ2	2.5 x 10 ⁻⁷	
Assessed Residual Risk Levels after Treatments	For Loss of Life	HZ3	2.5 x 10 ⁻⁷	
		HZ4	5 x 10 ⁻⁶	
	De vee efter			
		osoil as landscaping mater ays are unsuitable for use	-	
Earthworks	Imported fill should be a good quality non-expansive material such as sand or ripped rock.			
Excavation Conditions	A hydraulic e	xcavator and bucket is add	equate.	
	The investiga	tion works did not intercep	ot shallow groundwater.	
Groundwater	Seepage from perched water could occur, but is manageable by pumping from sumps.			
Temporary Cut Batters	Temporary unsupported batters for excavations less than 1m can be battered at an inclination of no steeper than 2H:1V.			
	Piles socketed into rock are required.			
Footing Systems	The underlying rock can support an allowable bearing pressure of 600kPa.			
	Open bored piles may be applicable. Dewatering and temporary liners may be required, if seepage occurs.			
Earthquake Actions in accordance with AS1170.4-2007	Adoption of S	Site Class C₀ and Hazard F	actor Z of 0.08.	
	If filling is needed:			
	 Assessment of the suitability of imported and in-situ materials for use as backfill. 			
Construction Inspection Requirements	 Inspectio compacti 	n and testing during fill pla on.	cement and	
	Excavation configuration	onditions for advice on saf s.	e battering	
	Footing formation for verification of suitability of exposed geomaterial as founding stratum.			

1. INTRODUCTION

The architectural drawings prepared by Casey Brown Architecture (CBA) indicates that an existing residence at 90 Cabbage Tree Road in Bayview, New South Wales (Lot 22 in Deposited Plan 602041) will be further developed, involving the following:

- Formation of a pool house to the east of an existing dwelling house.
- The pool house is a single storey building structure.
- The building will house a swimming pool, a pergola, a kitchen, a terrace, and a shower.
- The swimming pool is a suspended structure, so is the terrace platform.
- The pool house floor corresponds to an elevation of RL 39.5m AHD.

The Pittwater Local Environmental Plan 2014 Geotechnical Hazard Map Sheet GTH_011 and Sheet GTH_012 identifies that the site is linked to Geotechnical Hazard H1. Hazard Zone H1 denotes geotechnical hazards with the highest likelihood of occurrence. A geotechnical investigation and a landslide risk assessment by a suitably qualified Geotechnical Engineer was required to assess the site-specific subsurface conditions and to identify the geotechnical constraints of the site. The results from the site investigation were relied upon to assist with the project planning and design processes. The geotechnical report was complimentary to the development application (DA) process.

Ms Yasmina Elshafei and Mr Ford Ennals commissioned MM Geomechanics on 9 May 2024 to review the latest architectural drawings and to implement any necessary updates on an existing geotechnical investigation report previously prepared by MM Geomechanics (reference MMGEO2021AJ_AA Revision A). MM Geomechanics undertake the work in general accordance with a proposal reference MMGEO2024YEFE_AA dated 23 April 2024.

Presented as part the report are the findings from the site investigation, along with engineering assessment of the following aspects:

- Subsurface conditions (i.e. the nature of the in-situ soils, the depth to the underlying rock and its quality, along with the presence of groundwater table, if any).
- Possibility of encountering acid sulfate soils on site (based on a desktop review).
- Potential geotechnical hazards and risks, along with mitigation measures required for achieving Acceptable Risk for Loss of Property and Loss of Human Life as defined in the Practice Note issued by Australian Geomechanics Society (AGS) in 2007.
- Earthworks.
- Excavation conditions.
- Groundwater.
- Retaining walls and design parameters.
- Foundations and design parameters.
- Earthquake actions in accordance with AS1170.4-2007 Part 4, Earthquake Actions in Australia.
- Concrete exposure in accordance with AS5100.5-2004 Bridge Design Part 5: Concrete.
- Geotechnical inspection requirements at construction stage.

2. SITE LOCALITY

The property is located to the north of Cabbage Tree Road in Bayview, New South Wales. The geographic position of the site is identified in Table 2.1.

Table 2.1: Site Geographic Position

Site Address	Latitude	Longitude
90 Cabbage Tree Road Bayview NSW 2104	33° 40' 0" S	151° 17' 8" E

Figure 1 shows the site locality.

3. INVESTIGATION METHODOLOGY

3.1. Desktop Study

Review of the available data listed below was initially carried out:

- Published geological and acid sulfate soil maps.
- Available aerial photographs from nearmap.
- The project architectural drawings under Project Number C9216 prepared by Casey Brown Architecture.
- A site-specific topographical survey plan prepared by CMS Surveyors (reference 18022detail Issue 2 dated 18 June 2020).

3.2. Fieldwork

A Principal Geotechnical Engineer (also a Chartered Professional Engineer) from MM Geomechanics, accompanied by a geotechnician, subsequently visited the site in Bayview, New South Wales on 23 July 2021 with the aim of achieving the following:

- Gaining an appreciation of site conditions and features.
- Assessment of subsurface conditions within the site by undertaking geotechnical fieldwork.
- Carrying out a landslide risk assessment in general accordance with the landslide risk management guidelines prepared by the AGS, as follows:
 - AGS 2007a: Guideline for Landslide Susceptibility, Hazard and Risk Zoning for Land Use Planning.
 - AGS 2007b: Commentary on Guideline for Landslide Susceptibility, Hazard and Risk Zoning for Land Use Planning.
 - AGS 2007c: Practice Note Guidelines for Landslide Risk Management 2007.
 - AGS 2007d: Commentary on Practice Note Guidelines for Landslide Risk Management 2007.
 - AGS 2007e: The Australian GeoGuides for Slope Management and Maintenance

'Dial Before You Dig' information was collated prior to undertaking the fieldwork.

The investigation employed a combination of the following techniques:

- Auger drilling at three locations (namely 90CTRB-AH01, 90CTRB-AH02 and 90CTRB-AH03) approximately within the footprint of the pool house using a hand-held auger drill.
- A Dynamic Cone Penetrometer (DCP) test adjacent to each augered hole. There were three adjacent DCP tests overall (namely 90CTRB-DCP01, 90CTRB-DCP02 and 90CTRB-DCP03).
- A further standalone DCP test (90CTRB-DCP04) was also implemented.

The geotechnical tests are listed in Table 3.1.

Table 3.1: Su	mmary of Q	Geotechnical	Tests
---------------	------------	--------------	-------

Test ID	Type of Test	Termination Depth (m bgl)	Reason for Ceasing	
90CTRB-AH01		0.4	The presence of a large particle in soil.	
90CTRB-AH02	Auger drilling	1.1	Increased	
90CTRB-AH03		0.9	penetration resistance.	
90CTRB-DCP01	DCP test adjacent to 90CTRB-AH01	0.3	The presence of a large particle in soil.	
90CTRB-DCP02	DCP test adjacent to 90CTRB-AH02	1.6	 Practical refusal on either hard clay or rock. 	
90CTRB-DCP03	DCP test adjacent to 90CTRB-AH03	1.5		
90CTRB-DCP04	A standalone DCP test	2.2		

Note: bgl = below ground level

Upon completion, the augered hole was backfilled using excavated spoils. Excess spoils were disposed on site, spread level over unpaved areas.

The approximate locations of the geotechnical tests are shown in Figures 2, 3 and 4. The site photographs are presented in Figures 3 and 4 and should be read in conjunction with the photograph view angles and orientations shown in Figure 2.

4. SITE CONDITIONS

The observations we made at the time of the site visit on 23 July 2021, in conjunction with the review of the survey data prepared by CMS Surveyors, indicate the following:

- The property at 90 Cabbage Tree Road in Bayview appears to be resting on the steep flanks of a hill.
- The property is bounded by Cabbage Tree Road to the south and is surrounded by neighbouring properties to the north, west and south.
- The property covers an area of about 3.2 Ha.
- A two-storey dwelling house is evident at the southwestern corner of the site while the remainder of the site is consisted of vacant lands largely covered by dense vegetation.
- A gravel driveway is present to the south of the site approximately in a west-east orientation as an extension of an easement (a right of way) that is connected to Cabbage Tree Road.
- The development site is located to the east of the house and to the north of the driveway.
- The development site will be formed on a northerly dipping slope.
- The existence of a sandstone cliff along the southern site boundary.
- The site and surrounding neighbouring areas have been used mainly for residential purposes in the past decade. The land occupancy based on the available aerial imageries for the period between 20 October 2009 and 2 June 2021 from nearmap agrees with the site observation.

Reference should be made to the site photographs presented in Figures 3 and 4 for an appreciation of the site descriptions provided.

5. SITE GEOLOGY

The Sydney 1:100,000 Geological Series Sheet 9130 (Edition 1, 1983) infers that the Hawkesbury Sandstone geological unit (Rh) underlies the site locality and the boundary with the Newport Formation and Garie Formation geological unit (Rnn) is nearby to the east.

The Hawkesbury Sandstone is described as "medium to coarse-grained quartz sandstone, very minor shale and laminite lenses". The Newport Formation is described to comprise interbedded laminite, shale and quartz to lithic quartz sandstone, minor red claystone. The Garie Formation is consisted of clay pellet sandstone.

An excerpt of the geological map is presented in Figure 5.

6. POTENTIAL OCCURRENCE OF ACID SULFATE SOILS

Searches through the Australian Soil Resource Information System (ASRIS) for National Acid Sulfate Soils Occurrence indicates no known occurrence of acid sulfate soils within the site locality.

An excerpt of the National Acid Sulfate Soils Occurrence map is captured in Figure 6.

7. SUBSURFACE CONDITIONS

The site investigation implemented by MM Geomechanics detected topsoil (Unit 1), colluvium (Unit 2) and residual soil (Unit 3) overlying possibly rock (Unit 4).

Based on the information obtained from the investigation works, an inferred geotechnical model has been developed, and the subsurface conditions at the geotechnical test locations are summarised in Table 7.1. For a detailed description of the subsurface conditions encountered at the geotechnical test locations, refer to the Engineering Logs in Appendix A, together with Explanation Sheets describing the terms and symbols used in the preparation of the logs. The DCP test reports are presented in Appendix B. The results from the DCP tests adjacent to augered holes are also graphically presented in the logs.

Geotechnical Unit	Description	Depth to Base of Unit (m)	Thickness of Unit (m)
TopsoilTopsoil (Unit 1), typically: • Sandy SILT. • Low liquid limit. • Grey, brown and black.		0.2 to 0.4	0.2 to 0.4
Colluvium	 Colluvium (Unit 2), typically: Clayey SAND. Fine to medium grained. Yellow brown. Brown. Loose to medium dense. 	0.4 to 0.6 Only in 90CTRB-AH01 and 90CTRB-AH02	0.2 to 0.3 Only in 90CTRB-AH01 and 90CTRB-AH0
Residual Soil (Unit 3), typically:Residual SoilResidual Soil• Silty CLAY.• Medium to high plasticity.• Yellow brown.• Stiff to very stiff.		1.5 to 1.6 ¹⁾ Only in 90CTRB-AH02 and 90CTRB-AH03	0.9 to 1.2 ¹⁾ Only in 90CTRB-AH02 and 90CTRB-AH03
RockRock (Unit 4) is inferred as Class V Sandstone2).		Not known ³⁾	Not known ³⁾

Table 7.1: Summary of Subsurface Conditions at Test	Locations and Inferred Geotechnical
Model	

Note:

1) An inference was made based on the penetration resistance obtained from the DCP testing.

2) Rock class in accordance with the rock classification system established by Pells et al. in 1998.

3) Hand operated auger drilling and DCP testing does not provide a means of penetrating into rock. Class V Sandstone was assumed. Table 7.2 summarises the depth to the various geotechnical units across the site.

Development	Basis of	Top of Unit (Reduced Level in m AHD)⁺			
Area	ea Assessment		Colluvium	Residual Soil	Rock [#]
Western side of the pool house	90CTRB-AH01 and 90CTRB-DCP01	39.7	39.5	Not known	Not known
Northern side of the pool house	90CTRB-AH02 and 90CTRB-DCP02	37.5	Not encountered	37.1	35.9
Eastern side of	90CTRB-AH03 and 90CTRB-DCP03	40	39.7	39.4	38.5
the pool house.	90CTRB- DCP04	38	N <mark>ot</mark> known	Not known	35.8

Table 7.2: Summary of Inferred Subsurface Stratigraphy

Note:

+ Reliance to the available survey plan was made to estimate the geotechnical stratigraphic levels.

The practical refusal encountered during the DCP testing was inferred as the top of weathered sandstone equating to Class V Sandstone in accordance with the rock classification system established by Pells et al. in 1998.

Groundwater was not observed within the depth of augering. No watermark was noted on the DCP rods within the depth of testing. No long-term groundwater monitoring was carried out.

8. GEOTECHNICAL RISK APPRAISALS

8.1 Qualitative Risk Estimation for Property

Various potential geotechnical hazards that may affect the site were identified and are listed in Table 8.1. An assessment of the risk level corresponding to each hazard was carried out in consideration of the likelihood for the hazard to occur and the associated consequence to various on-site elements at risk (also compiled in Table 8.1).

Table 8.1: Identification of Potential Geotechnical Hazards and Elements at Risk

Hazard ID	Type of Geotechnical Hazard	Elements at Risk	
HZ1	Slippage of the colluvium within the site.		
HZ2	Deep seated landslide within the site.	The existing house.	
HZ3	Creep soil mass movement within the site.	The pool house, swimming pool, an terrace.	
HZ4	Erosion within the site.	0	

Table 8.2 summarises the results from the risk estimation for loss of property.

Table 8.2: Qualitative Risk Estimation for Loss of Property

Hazard ID	Likelihood of Occurrence	Consequence to Property	Risk Level ¹
HZ1	Unlikely	Medium	Low
HZ2	Rare	Medium	Low
HZ3	Rare	Medium	Low
HZ4	Possible	Minor	Low

Note:

1. The risk of instability was assessed to be "Low" as the development site is in natural state, protected by dense vegetation cover. The risk level would remain unaffected on the implementation of piled foundations, re-instatement of vegetation cover and runoff management.

The building is assessed to correspond to an Importance Level of Structure (ILS) of 2. For a new development that involves structures with an ILS of 2, the upper limit of acceptable risk for loss of property is taken as "Low" as defined in Table C10 part of the Commentary on the Practice Note issued by AGS in 2007. The risk estimation resulted in a finding of "Low" risk of slope instability.

8.2 Quantitative Risk Estimation for Loss of Life

For the loss of life, the individual risk can be calculated using:

 $R_{(DI)} = P_{(H)} \times P_{(S:H)} \times P_{(T:S)} \times V_{(D:T)}$

where:

R_(DI) is the risk, or annual probability of death, of an individual,

P(H) is the annual probability of the hazardous event,

P_(S:H) is the probability of spatial impact by the hazard given the event,

 $P_{(T:S)}$ is the temporal probability given the spatial impact, and

 $V_{(\text{D:T})}$ is the vulnerability of the individual.

Table 8.3 summarises the results from the quantitative risk estimation for loss of life.

Hazard ID	Р(н)	Р (S:H)	P (T:S)	V (D:T)	R _(DI) ¹
HZ1	10 ⁻⁴	0.5	0.5	0.1	2.5 x 10 ⁻⁶
HZ2	10 ⁻⁵	0.5	0.5	0.1	2.5 x 10 ⁻⁷
HZ3	10 ⁻⁵	0.5	0.5	0.1	2.5 x 10 ⁻⁷
HZ4	10 ⁻³	0.1	0.5	0.1	5 x 10⁻ ⁶

Table 8.3: Quantitative Risk Estimation for Loss of Life

Note:

1. The risk estimation is conditional upon the implementation of risk mitigation measures such as piled foundations, re-instatement of vegetation cover and runoff management.

AGS suggested the individual life loss risk criteria for the person most at risk of 10⁻⁶ per annum for acceptable risk and 10⁻⁵ per annum for tolerable risk. Generally, the risk for loss of human life induced by the various hazards was assessed to be acceptable.

Your attention is drawn to the Important Information about AGS2007 Appendix C, attached to this report for appreciation of typical responses to assessed risk levels. Also incorporated in Appendix C is Appendix G of the Practice Note Guidelines for Landslide Risk Management 2007 (AGS 2007c) that includes some guidelines for hillside construction and provides examples of both good and poor hillside practices.

9. EARTHWORKS

Topsoil should be stripped and stockpiled separately for possible reuse as landscaping material only.

The natural soils comprise mainly clays. The clays are of medium to high plasticity. As such, the clays are more than likely susceptible to volume change with variations in soil moisture. The clays were assessed to be unsuitable for re-use as backfill.

Fill, if required, should be sourced externally and brought in off site.

Imported fill should be a good quality non-expansive material such as sand or ripped rock. The maximum particle size after compaction should be 75mm. Bulk engineered fill should be compacted to a minimum of 98% Standard Maximum Dry Density Ratio (SMDDR) within 2 % of Standard Optimum Moisture Content (SOMC). If uniformly graded sand is used as bulk structural fill, it should be compacted to a Density Index of at least 70%. Fill should be placed in horizontal layers and compacted in a controlled manner, desirably under Level 1 supervision and testing in accordance with AS3798-2007 *Guidelines on Earthworks for Commercial and Residential Developments*. Loose layer thickness should be limited to 200mm maximum.

Advice from a suitably qualified geotechnical engineer should be sought for confirmation that the proposed fill is suitable from a geotechnical perspective and that the fill is free from unsuitable material such as organics, waste or oversized particles.

10. EXCAVATION CONDITIONS

Excavations are required to form the building platform. The excavation work will likely extend to a depth of up to about 1.5m below ground surface. The excavations will occur mainly within soils and possibly weathered rock (Class V Sandstone) towards the bottom of excavation. A hydraulic excavator and bucket should be adequate for excavation in soils and weathered rock. Attention is required for safe operation of the earthmoving plant while working on a slope.

11. GROUNDWATER

No shallow groundwater tables were intercepted by the various geotechnical tests. Encountering seepage inflow from water perched in the soil (especially immediately following a rain event) remains a possibility. Seepage inflow should be able to be controlled by pumping from sumps.

While the investigation did not incorporate long-term groundwater monitoring, we would not anticipate shallow groundwater table within the soil during the excavations. The DCP tests (which penetrated to depths of up to about 2.2m below the existing ground surface) do not appear to have intersected groundwater. Therefore, we assess that the excavations and associated dewatering will unlikely result in a lowering of groundwater below historic levels.

12. TEMPORARY CUT BATTERS AND RETAINING STRUCTURES

Excavations needed to take place on site are associated with the formation of the building construction platform and are expected to be less than 1.5m deep. Unsupported batters are feasible on the proviso of the following conditions:

- There is no heavy construction plant and surcharge on the ground to the rear of the excavation.
- The rear of the excavation comprises a level ground. •
- A temporary batter is formed at an inclination no steeper than 2H:1V. •

Consultation with a suitably qualified geotechnical engineer may be made for opportunities for adopting temporary batters steeper than 2H:1V, which are pending the following factors:

- The nature of the materials exposed. •
- The excavation extents.
- The surface protection treatments.
- The weather conditions. •
- The exposure duration.

Where and if required, retaining walls can be designed using the geotechnical design parameters provided in Table 12.1. Where some movement of the retaining wall towards the excavation can be tolerated, 'active' earth pressures may be used in the design of the excavation support. Where lateral movement of the wall towards the excavation is to be limited, 'at rest' earth pressures should be adopted.

Geotechnical Unit	γ (kN/m³)	c' (kPa)	Φ (°)	E' (MPa)	v	Ka ¹	K _o ²
Engineered Fill	20	0	32	30	0.35	0.31	0.5
Colluvium (loose to medium dense sand)	19	0	30	10	0.35	0.33	0.5
Residual Soil (stiff to very stiff clay)	19	2	28	20	0.35	0.35	0.5
Rock (Class V Sandstone)	20	5	30	60	0.3	0.33	0.5

Table 12.1: Summary of Geotechnical Design Parameters for Retaining Structures

Note:

- γ = Bulk Unit Weight c' = Effective Cohesion
- E' = Elastic Modulus
- v = Poisson's Ratio

K_a = Active Earth Pressure Coefficient K_o = At Rest' Earth Pressure Coefficient (After some wall movement)

- Φ = Effective Friction Angle 1. Assume no wall friction.
- 2. Values provided assume a lateral movement of the wall of about 0.2% of the wall height is allowed to occur.

For preliminary estimate purposes, published data suggests that lateral movements of an adequately designed and installed retention system in stiff clay will be between 0.2% and 0.5% of the retained height for adequately engineered walls. Vertical movements could be expected to be of a similar order to the lateral movements. The extent of the horizontal movement behind the excavation face is typically between 1.5 and 3 times the excavated height.

13. FOUNDATIONS

As the development will be formed on a sloping ground, there is a need to rely on rock as a founding stratum. Piles socketed in rock (Class V Sandstone) are required. The site investigation infers the possibility of encountering rock at depths varying from about 1.5m to 2.2m below the existing ground surface. Open bored piles should be practical. Dewatering and temporary liners may be required, if seepage occurs.

For piled foundations, our recommendations for end bearing pressures are provided in Table 13.1 for both Limit State and Working Stress design methods. Where Limit State design parameters are used, reference to Section 4.3.2 of Australian Standard AS 2159-2009 *Piling – Design and Installation* should be made for the assessment and selection of suitable geotechnical strength reduction factor, and the Serviceability Limit State deflections should be checked using the elastic moduli presented in Table 13.1.

	Working Sti Val	ress Design ues	Limit	State Design V	alues
Geotechnical Unit	Allowable End Bearing Pressures (MPa)	Allowable Shaft Adhesion (kPa)	Ultimate End Bearing (MPa) ¹	Ultimate Shaft Adhesion (kPa) ¹	Elastic Modulus (MPa)
Rock (Class V Sandstone)	0.6	50	1	100	60

Table 13.1: Recommended Footing Design Parameters

Note:

1. Nominated values are appropriate for the modulus provided. Higher values may be possible but a lower modulus would apply and higher settlements may occur.

To prevent slope instability and reduced bearing capacity from occurring, your attention is drawn to the need of applying the setback criteria shown in Diagramme 13.1 for calculation of effective rock socket length. Otherwise, there would be a need to downgrade the bearing pressure values given in Table 13.1 by a factor of 0.5.



Diagramme 13.1: Required Minimum Setback for Calculation of Effective Rock Socket

Shaft adhesion should only be adopted for piers that have a minimum embedment of at least 3 pier diameters into suitable founding material and a rough socket (at least grooves of depth 1mm to 4mm and width greater than 5mm at spacing of 50mm to 200mm). The socket should be cleaned and roughened by a suitable scraper such as a tooth, orientated perpendicular to the auger shaft.

A reduction factor of 0.6 should be introduced to the shaft adhesion value for uplift capacity. In addition to shaft adhesion, the uplift capacity should be checked for a cone pullout failure mode assuming a cone angle of 70° considering the submerged weight of the soil or rock and adopting a factor of safety of 1 against pullout.

An experienced geotechnical engineer should observe the boring of the piles and in order to assess the rock levels and to confirm that the rock quality is consistent with the adopted design parameters. The possibility of encountering sandstone floaters cannot be precluded. Potentially unstable floaters cannot be relied upon as bearing strata.

14. EARTHQUAKE ACTIONS

We recommend that the site be classified as Class C_e in accordance with the site sub-soil classes defined in AS1170.4-2007 *Part 4, Earthquake Actions in Australia*. A hazard factor Z of 0.08 is suggested.

15. CONCRETE EXPOSURE

The desktop review indicates no occurrence of acid sulfate soils within the site locality. Exposure classification of B1 in accordance with AS5100.5-2004 *Bridge Design – Part 5: Concrete* may be adopted.

16. CONSTRUCTION INSPECTION REQUIREMENTS

Advice from an experienced Geotechnical Engineer should be sought at construction stage for the observations of the following aspects:

- Where filling is involved:
 - Assessment of the suitability of imported and in-situ materials for use as backfill.
 - Inspection and testing during fill placement and compaction.
- Excavation conditions for advice on safe battering configurations.
- Footing formation for verification of suitability of exposed geomaterial as founding stratum.

17. SITE MAINTENANCE REQUIREMENTS

House owners should be made aware that residential structures constructed to normal standards are likely to suffer some movement and consequent damage. Footings for residential buildings designed in accordance with the standard design guidelines of AS2870-2011 *Residential Slabs and Footings* and those designed in accordance with engineering principles where site characteristics require more rigorous analyses are expected to achieve acceptable probabilities of serviceability and safety during its design life.

The CSIRO publishes a document entitled "Foundation Maintenance and Footing Performance: A Homeowners Guide", which provided advice on maintenance issues. We recommend that all homeowners follow the guidelines in this document to reduce the risk of damage to their homes. Lots, which suffer abnormal factors or that, are not maintained in accordance with the guidelines of Appendix B of AS2870-2011 and the CSIRO publication may experience damage that exceeds the degree and frequency of damage that would normally be expected and may require repairs other than superficial. A copy of the CSIRO publication is attached in Appendix D.

18. LIMITATIONS

MM Geomechanics has prepared this report for a residential development project at 90 Cabbage Tree Road in Bayview, New South Wales in accordance with a proposal dated 23 April 2024 reference MMGEO2021YEFE_AA and acceptance received from Ms Yasmina Elshafei and Mr Ford Ennals on 9 May 2024. The report is provided for the exclusive use of Ms Yasmina Elshafei and Mr Ford Ennals for this project only and for the purpose(s) described in the report. The report cannot be used for other projects or by third parties unless a written consent from MM Geomechanics is obtained (except for Casey Brown Architecture).

In preparing this report, MM Geomechanics has necessarily relied upon information provided by the client and/or their agents, and from third parties. The information may not be verified and MM Geomechanics assumes no responsibility for the adequacy, incompleteness, inaccuracies, or reliability of this information. MM Geomechanics does not assume any responsibility for assessments made partly, or entirely based on information provided by third parties.

The results provided in the report are indicative of the subsurface conditions only at the specific sampling or testing locations, and then only to the depths investigated and at the time the work was carried out. Subsurface conditions can change abruptly due to variable geological processes and because of anthropogenic influences. Such changes may occur after the fieldwork performed by MM Geomechanics.

The advice given by MM Geomechanics in this report is based upon the conditions encountered during this investigation. The accuracy of the advice provided by MM Geomechanics in this report may be limited by undetected variations in ground conditions between sampling locations. The advice may also be limited by budget constraints imposed by others or by site accessibility. Relying on on-site verifications through regular inspections by a suitably qualified Geotechnical Engineer during construction can minimise such a risk.

Project and design changes may affect the validity of the advice given in this report. We recommend that consultation with MM Geomechanics be made should significant changes be identified.

This report must be read in conjunction with all the attached notes and should be kept in its entirety without separation of individual pages or sections. MM Geomechanics cannot be held responsible for interpretations or conclusions made by others unless they are supported by an expressed statement, interpretation, outcome or conclusion given in this report. This report, or sections from this report, should not be used as part of a specification for a project, without review and agreement by MM Geomechanics. This is because this report has been written as advice and opinion rather than instructions for construction.

Contamination assessment and testing is excluded from the current investigation scope.

Your attention is drawn to the Important Information about Your Geotechnical Report attached to this report (as Appendix E), which presents additional information on the uses and limitation of this report.

19. REFERENCE

Australian Geomechanics Society (2007). "Guidelines for Landslide Susceptibility, Hazard and Risk Zoning for Land Use Planning". Australian Geomechanics, Vol. 42, No. 1, pp. 13-36. Reference AGS 2007a.

Australian Geomechanics Society (2007). "Commentary on Guidelines for Landslide Susceptibility, Hazard and Risk Zoning for Land Use Planning". Australian Geomechanics, Vol. 42, No. 1, pp. 37-62. Reference AGS 2007b.

Australian Geomechanics Society (2007). "Practice Note Guidelines for Landslide Risk Management 2007". Australian Geomechanics, Vol. 42, No. 1, pp. 63-114. Reference AGS 2007c.

Australian Geomechanics Society (2007). "Commentary on Practice Note Guidelines for Landslide Risk Management 2007". Australian Geomechanics, Vol. 42, No. 1, pp. 115-158. Reference AGS 2007d.

Australian Geomechanics Society (2007). "The Australian GeoGuides for Slope Management and Maintenance". Australian Geomechanics, Vol. 42, No. 1, pp. 159-182. Reference AGS 2007e.

Australian Standard Limited (2004). "AS 5100.5-2004 Bridge Design – Part 5: Concrete". SAI Global.

Australian Standard Limited (2011). "AS2870-2011 Residential Slabs and Footings". SAI Global.

Australian Standard Limited (2007). "AS1170.4-2007 Part 4, Earthquake Actions in Australia". SAI Global.

Australian Standard Limited (2017). "AS1726-2017 Geotechnical Site Investigations". SAI Global.

Carter, M. and Bentley, S. P. (1991). "Correlation of Soil Properties". Billing & Sons Ltd, Worcester, United Kingdom.

Centre for Geotechnical Research (1998). "Soil Mechanics Data Sheets". The University of Sydney.

CSIRO (2011). "Foundation Maintenance and Footing Performance: A Homeowner's Guide". Building Technology File 18-2011. CSIRO Publishing.

Decourt, L. (1995). "Prediction of Load-Settlement Relationships for Foundations on the basis of the SPT-T". Ciclo de Conferencias Intern. "Leonardo Zeevaert", UNAM, Mexico, pp. 85-104.

Pells et al. (1998). "Foundations on Sandstone and Shale in the Sydney Region". Aust. Geomech. Jnl. Dec 1998.

Terzaghi, K. and Peck, R.B. (1948). "Soil Mechanics in Engineering Practice", John Wiley and Sons.









PHOTOGRAPH 1 - APPROXIMATE LOCATION OF 90CTRB-AH01 AND 90CTRB-DCP01 (VIEW TO SOUTH)



PHOTOGRAPH 2 - APPROXIMATE LOCATION OF 90CTRB-AH03 AND 90CTRB-DCP03 (VIEW TO WEST)

drawn	SN		client:	MS YASMINA ELSHAFE	I AND MR FORD ENNALS
approved	ММ	de D	project:	PROPOSED POOL HOUSE, S	SWIMMING POOL AND TERRACE
date	28/6/24			90 CABBAGE TREE ROAD	D, BAYVIEW, NEW SOUTH WALES
scale	As Shown		title:	SITE PHOTOGRAPHS TAKE	N ON 23 JULY 2021 (SHEET 1 OF 2)
original size	A4		project no:	MMGEO2024YEFE_AB	figure no: FIGURE 3



PHOTOGRAPH 3 - APPROXIMATE LOCATIONS OF 90CTRB-AH02, 90CTRB-DCP02 AND 90CTRB-DCP04 (VIEW TO SOUTH)



PHOTOGRAPH 4 - SANDSTONE CLIFF (VIEW TO SOUTH)

drawn	SN		client: MS YASMINA ELSHAFEI AND MR FORD ENNALS
approved	ММ	GEO	PROPOSED POOL HOUSE, SWIMMING POOL AND TERRACE
date	28/6/24		90 CABBAGE TREE ROAD, BAYVIEW, NEW SOUTH WALES
scale	As Shown		title: SITE PHOTOGRAPHS TAKEN ON 23 JULY 2021 (SHEET 2 OF 2)
original size	A4		project no: MMGEO2024YEFE_AB figure no: FIGURE 4





Appendix A

Engineering Logs and Explanation Sheets



Enginee	ering Log - Auger Hole		
Borehole No: 90CTRB_AH01	Client: MS YASMINA ELSHAFEI AND MR FORD E	INNALS	dechanics Mechanics
Project No: MMGEO2024YEFE_AB	Principal: MS YASMINA ELSHAFEI AND MR FORI		
Project ID: 90 CABBAGE TREE ROAD, BAYVIEV	N, NEW SOUTH WALES		
Borehole Location: See Site Plan	Date started: 23/07/2021 Logged b	y: MM	I II
Sheet: 1 of 1	Date completed: 23/07/2021 Checked	by: MM	
drill model and mounting: Hand Augers hole diameter: 300mm	Easting: Not Surveyed slope: -90 Northing: Not Surveyed bearing:	RL Surface: 39.7m Datum: AHD	(Inferred from survey plan)
Drilling Information	Mat	erial Substance	
method support water sample depth (m) depth (m) graphic log	material description soil type: plasticity or particle characteristics, colour, secondary and minor components	benetration resistance (blow/100mm) 112345677890	so oc transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed transformed
1 2 3 4 % 5 5 8 HA N N	TOPSOIL: SANDY SILT: Low liquid limit, brown, with some	D	
	grass root.		
<u>0.2</u> 39.5	CLAYEY SAND: Fine grained, brown, with some sandstone cobble and boulders.	M L	COLLUVIUM
0.3 			R
	90CTRB_AH01 encountered refusal at 0.4m.		POSSIBLE ROCK
method Support not As auger scriwing RR A auger scriwing (clientricone RR A casing control Not control Not control RR rollentricone (clientricone RR 1 2 3 4 ranging to Not ranging to Not restate loof Not restate restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not restate Not Restate Not Restate Not Restate Not Restate Not Restate Not Restate Not Restate Not Restate Not Restate Not Restate Not Restate Not Restate Not Restate Not Restate Not Restate Not Restate Not Restate Not Restate Not Restate Not Restate Not Restate Not Restate Not Restate Not Restate Not Restate Not Restate Restate Restate Restate Restate Restate Restate Restate Restate R	is, samples, tects test notes undisturbed sample 50mm diameter R refusal UB double bounce disturbed sample 53mm diameter DB double bounce disturbed sample GSMm diameter DB double bounce disturbed sample GSMm diameter (VPa) SPT with solid core for solid sample and/comments asmple falling head permeability falling head permeability	classification symbols sand on university catasification symbols based on university classification system molsture D d motet w mot W motet W motet W, palaste limit WL Rejudi limit	consistency / density index VS very soft F firm St stiff VSt very still H hard F0 firm Vt very still H0 herd F0 firmal- MD medium dense D dense VD very dense

							Er	ngi	inee	ering Log - Au	ger Hole								Si
В	orehole	No: 9	юст	RB	AHO)2				Client: MS YASMINA EL	SHAFEI AND MR FORD	ENNA	LS				_		dechanics Mechanics
	roject N				_		_AB				ELSHAFEI AND MR FOR			s					
P	roject ID	D: 90	CAB	BA	GE T	REE), В	AYVIE	W, NEW SOUTH WALES									
в	orehole	Loca	tion:	See	e Site	e Pla	n			Date started: 23/07/2021	Logged	by: Ml	М					4	
s	heet: 1	of 1								Date completed: 23/07/20	021 Checked	by: N	1M						
	ll model a le diamet			ıg: H	land A	Auger	ſS			Easting: Not Surveyed Northing: Not Surveyed	slope: -90 bearing:				urface m: A⊦		im (I	nferred	from survey plan)
				nforr	matio	n				Northing. Not Ourveyed		terial S							
				1			ê	g	Inda	material	description		_					ŝ	
method	penetratio	support	water	sample	sample notes	RL	depth (m)	graphic log	classification symbol		particle characteristics,	e conc	ancy/de	pene (tration	resistar 00mm)	nce	test notes	structure and additional observations
E	123		5	S	samp		deb	grap	classific	colour, secondary a	and minor components	moisture condition	consistency/density			6 7 8 9	0 H N	test	
HA		N	N				=	<u>, </u>		TOPSOIL: SANDY SILT: Low	liquid limit, dark grey, sand is of sandstone gravel and cobble.	W					510		TOPSOIL
							0.1	4		The to medium grained, trace t	or sandstone graver and cobble.								
							Ξ	<u>\ (</u>											
							0.2	<u>/</u>											
							=	<u>```</u>											
							0.3	Ľ.,											
								· · · · · · · · · · · · · · · · · · ·											
						37.1	0.4			SILTY CLAY: Medium to high	plasticity, yellow brown motted	м	St						RESIDUAL SOIL
							0.5			grey.									Hole diameter changed to 50mm at 0.4m.
							0.6												
							Ξ												
							0.7												
							=		СН										
							0.8												
							0.9												
							0.9												
							1.0												
							=												
						36.4	1.1				-f., -l -h d d.,	_			+++				
						30.4	Ξ			90CTRB_AH02 encountered r	erusai at 1.1m.								
							1.2												
							=												
							1.3												
							1.4												
							1.5												
							Ξ												
							1.6											R	POSSIBLE ROCK
							Ξ											r.	POSSIBLE NOON
							1.7												
							1.8												
							1.9							$\left \right \right $					
meth						suppo				tes, samples, tects	test notes	alc	sificat	tion syn			Ц	conci-r	u (danaitu inday
4.0	auger screw auger drilling roller/tricone	a l				M C penetrati	mud N casing	nil	Uba	tes, samples, tects undisturbed sample 50mm diameter undisturbed sample 63mm diameter disturbed sample	test notes R refusal DB double bounce PD pre-drilling	and	soil de	escripti					y / density index ft
AD RR W CT HA	washbore cable tool hand auger					1 2	nor	esistano ging to Isal	De N N* No	standard penetration test (SPT) SPT - sample recovered SPT with solid cone	PD pre-drilling 15/50 15 blows for 50mm penetration							VSt verystil H hard	II
V T	diatube blank bit V bit TC bit					water	10/2/16 water I on date shown water inflow		P	vane shear (kPa) pressuremeter bulk sample environmental sample		D .	dry moist wet plastic						DSe
* bit s e.g.	shown by suffix ADT						water inflow water outflow Not Observed		มีแต่เรื่อง	falling head permeability rising head permeability		W _P W _L	plastic liquid li	limit imit			ļ	MD mediur D dense VD very de	

				Er	ngi	nee	ering Log - Auger	Hole								
Borehole No:	90CTRI	B_AHO)3				Client: MS YASMINA ELSHAFI	EI AND MR FORD EI	NNA	LS						(FE)
Project No: N	IMGEO2	2024YI	EFE	_AB			Principal: MS YASMINA ELSHA	AFEI AND MR FORD	ENM	ALS	5					
Project ID: 90	CABB	AGE T	REE), ВA	AYVIE	W, NEW SOUTH WALES								V	
Borehole Loc							Date started: 23/07/2021	Logged by	: MN	1					1	
Sheet: 1 of 1							Date completed: 23/07/2021	Checked b								
drill model and n	nounting:	Hand A	Auger	rs			Easting: Not Surveyed	slope: -90	,	R			0m (I	nferre	d from	i survey plan)
nole diameter: 2	00mm						Northing: Not Surveyed	bearing:		D)atum: .	AHD				
Dri	illing Info		n I I			-		Mate	rial S		ince			<u> </u>		
	water sample	sample notes	RL	depth (m)	graphic log	classification symbol	material descript soil type: plasticity or particle colour, secondary and mino	characteristics.	moisture condition	nsisten		v/100m	ım)	test r		structure and additional observations
1234 IA N	N	0		0.1		0	TOPSOIL: SANDY SILT: Low liquid lim tree root.	nit, grey black, trace of	W	0	1234	567	891	0	Т	OPSOIL
			39.7	0.3		SC	CLAYEY SAND: Fine to medium grain sandstone cobble.	ed, brown, trace of	M	MD					H	OLLUVIUM lole diameter changed to 0mm at 0.4m.
			39.4	0.6		СН	SILTY CLAY: Medium plasticity, yellow	/ brown.	D	VSt					R	ESIDUAL SOIL
			39.1	0.9 1.0 1.1 1.2 1.2 1.3 1.4 1.5 1.6 1.7 1.6 1.7 1.7 1.8 1.9 1.9			90CTRB_AH03 encountered refusal at	i 0.9m.						R	P	OSSIBLE ROCK
ethod ethod s auger scrawing suger drilling roller/ticona washbore sashbore sashbore tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool tool too			water	mud N casing kon 3 4 no r	ievel	U ₅₀ U ₆₃ D	bes, samples, tects undisturbed sample 50mm diameter UB double undisturbed sample 50mm diameter UB double undisturbed sample S7m with solid cone S7F with solid cone S7F with solid cone ware shear (kPa) pressuremeter balk sample environmental sample falling head permeability falling head permeability		and s based classi D of M of W v	on unifie fication sy	nit	s		VS v S s F fin St s VSt v H h Fb fi VL v L k MD r D d	stency / d ery soft oft iff ery still ard ery loose oose medium de lense ery dense	lensity index



Soil Description Explanation Sheet (1 of 2)

DEFINITION:

In engineering terms soil includes every type of uncemented or partially cemented inorganic or organic material found in the ground. In practice, if the material can be remoulded or disintegrated by hand in its field condition or in water it is described as a soil. Other materials are described using rock description terms.

CLASSIFICATION SYMBOL & SOIL NAME

Soils are described in accordance with the Unified Soil Classification (UCS) as shown in the table on Sheet 2.

PARTICLE SIZE DESCRIPTIVE TERMS

NAME	SUBDIVISION	SIZE					
Boulders		>200 mm					
Cobbles	0	63 mm to 200 mm					
Gravel	coarse	20 mm to 63 mm					
	medium	6 mm to 20 mm					
	fine	2.36 mm to 6 mm					
Sand	coarse	600 µm to 2.36 mm					
	medium	200 µm to 600 µm					
	fine	75 μm to 200 μm					

MOISTURE CONDITION

- Dry Looks and feels dry. Cohesive and cemented soils are hard, friable or powdery. Uncemented granular soils run freely through hands.
- Moist Soil feels cool and darkened in colour. Cohesive soils can be moulded. Granular soils tend to cohere.
- Wet As for moist but with free water forming on hands when handled.

CONSISTENCY OF COHESIVE SOILS

TERM	UNDRAINED STRENGTH S _U (kPa)	FIELD GUIDE							
Very Soft	<12	A finger can be pushed well into the soil with little effort.							
Soft	12 - 25	- 25 A finger can be pushed into the soil to about 25mm depth.							
Firm	25 - 50 The soil can be indented about 5mm with the thumb, but not penetrated.								
Stiff	50 - 100 The surface of the soil can be indented with the thumb, but not penetrated.								
Very Stiff	100 - 200	The surface of the soil can be marked, but not indented with thumb pressure.							
Hard >200 The surface of the soil can be marked only with the thumbnail.									
Friable	-	Crumbles or powders when scraped by thumbnail.							

DENSITY OF GRANULAR SOILS

DENSITY INDEX (%)
Less than 15
15 - 35
35 - 65
65 - 85
Greater than 85

MINOR COMPONENTS

TERM	ASSESSMENT GUIDE	PROPORTION OF MINOR COMPONENT IN:
Trace of	Presence just detectable by feel or eye, but soil properties little or no different to general properties of primary component.	Coarse grained soils: <5% Fine grained soils: <15%
With some	Presence easily detected by feel or eye, soil properties little different to general properties of primary component.	Coarse grained soils: 5 - 12% Fine grained soils: 15 - 30%

SOIL STRUCTURE

	ZONING	CE	MENTING
Layers	Continuous across exposure or sample.	Weakly cemented	Easily broken up by hand in air or water.
Lenses	Discontinuous layers of lenticular shape.	Moderately cemented	Effort is required to break up the soil by hand in air or water.
Pockets	Irregular inclusions of different material.		

GEOLOGICAL ORIGIN

WEATHERED I	N PLACE SOILS
Extremely weathered material	Structure and fabric of parent rock visible.
Residual soil	Structure and fabric of parent rock not visible.
TRANSPORTE	D SOILS
Aeolian soil	Deposited by wind.
Alluvial soil	Deposited by streams and rivers.
Colluvial soil	Deposited on slopes (transported downslope by gravity).
Fill	Man made deposit. Fill may be significantly more variable between tested locations than naturally occurring soils.
Lacustrine soil	Deposited by lakes.
Marine soil	Deposited in ocean basins, bays, beaches and estuaries.



Soil Description Explanation Sheet (2 of 2)

(Exclu	Iding		LD IDENTIF s larger than 6					tin	nated mass)	L	ISC	PRIMARY	NAME											
(2)		arse .0 mm	CLEAN RAVELS (Little or no fines)		Wide range in grain size and substantial amounts of all intermediate particle sizes.				à	GW	GRAVEL													
in m		ELS If of co	CLEAN GRAVELS (Little or no fines)		ominantly on more interme					ŝ	GP	GRAVEL												
SOILS than 60	eye)	GRAVELS More than half of coarse fraction is larger than 2.0 mm	GRAVELS WITH FINES (Appreciable amount of fines)		Non-plastic fines (for identification procedures see ML below)					GM	SILTY GRAVEL													
AllNED rials less 0.075 m	e naked	More	GRAN WITH (Appre amo		ic fines (for i CL below)	dentificat	ion pr	00	cedures	5	GC	CLAYEY GRAVE	L											
COARSE GRAIINED SOILS More than 50% of materials less than 63 mm is larger than 0.075 mm	(A 0.075 mm particle is about the smallest particle visible to the naked eye)	arse 2.0 mm	CLEAN SANDS (Little or no fines)		range in gra ints of all int					3	SW	SAND												
COARS) n 50% of n larger t larger t cle visible DS DS f of coarse t f of coarse t f of coarse t f an 2.0 n CLEAN CLEAN CLEAN COARS				Predo with s	Predominantly one size or a range of sizes with some intermediate sizes missing.					SP	SAND													
COARSE G More than 50% of matr larger than larger that the smallest particle visible to t SANDS More than half of coarse fraction is smaller than 2.0 mm cannos			SANDS WITH FINES (Appreciable amount of fines)	Non-plastic fines (for identification procedures see ML below).						SM	SILTY SAND													
	More More SAT WITH Appre amc amc				Plastic fines (for identification procedures see CL below).				2	SC	CLAYEY SAND													
	out		IDENTIFICAT	ION P	ROCEDURE	S ON FR	ACTIC	DN	IS <0.2 mm.															
L a	s ab		DRY STREN	GTH	DILATAN	CY	τοι	U	GHNESS															
FINE GRAINED SOILS More than 50% of material less than 63 mm is smaller than 0.075 mm	rticle i	CLAYS limit in 50	None to Low		Quick to slow Nor		Non	ne			ML	SILT												
FINE GRAINED SOILS in 50% of material less is smaller than 0.075 i	nm pa	SILTS & CLAYS Liquid limit Breater than 50 Less than 50										TS & (iquid ss tha	TS & iquid	Medium to H	ligh	None		Med	diu	um		CL	CLAY	
SRAIN 6 of m aller th	.075 r											Low to medi	um	Slow to ver	Slow to very slow L		Low			OL	ORGANIC SILT			
FINE (In 50% is sm	(A O											Low to medi	um	Slow to ver	ry slow	Low to medium	1	ИН	SILT					
ore the		SILTS & CLAYS Liquid limit greater than 50	High		None		High	h			СН	CLAY												
Ř		SILT Brea	Medium to H	ligh	None		Low	/ t	to medium		ОН	ORGANIC CLAY												
HIGHLY	YOF	RGANIC	Readily ident frequently by			our, spong	gy fee	la	and		Pt	PEAT												
• Low p	lasti	city – Liqu	uid Limit W _L les	s than	35%. • Med	lium plasti	city – N	W	L between 35	% and 50%	5.													
C	ON	MON	DEFECTS	N SO	IL																			
TERM			DEFINIT	ION		DIAGRA	M		TERM		DEFINI	TION	DIAGRA											

SOIL CLASSIFICATION INCLUDING IDENTIFICATION AND DESCRIPTION

SOFTENED A zone in clayey soil, usually adjacent to a defect in which the soil has a PARTING A surface or crack across which the soil has little or no tensile strength. Parallel or sub parallel to layering (eg bedding). May be open or closed. higher moisture content than elsewhere. Tubular cavity. May occur singly or as one of a large number of separate or inter-connected tubes. Walls often coated with clay or strengthened by denser packing of grains. May contain organic matter TUBE JOINT A surface or crack across which the soil has little or no tensile strength but which is not parallel or sub parallel to layering. May be open or closed. The term 'fissure' may be used for irregular joints <0.2 m in length Zone in clayey soil with roughly parallel near planar, curved or undulating SHEARED TUBE Roughly cylindrical elongated body of soil ZONE CAST different from the soil mass in which it boundaries containing closely spaced, smooth or slickensided, curved intersecting occurs. In some cases the soil which makes up the tube cast is cemented. joints which divide the mass into lenticular or wedge shaped blocks. Sheet or wall like body of soil substance or mass with roughly planar to irregular near parallel boundaries which cuts through a soil mass. Formed by infilling of SHEARED A near planar curved or undulating, smooth, SURFACE polished or slickensided surface in clayey INFILLED - AU-06-08 SEAM soil. The polished or slickensided surface indicates that movement (in many cases 72810 very little) has occurred along the defect. open joints.

Appendix B

Dynamic Cone Penetrometer Test Results







Appendix C

Important Information about AGS2007 Appendix C



INTRODUCTION

This sheet provides important information on Appendix C from "Practice Note Guidelines for Landslide Risk Management 2007". The "Practice Note" and accompanying "Commentary" (References 1 and 2, hereafter referred to as AGS2007) are part of a series of documents on landslide risk management prepared on behalf of, and endorsed by, the Australian Geomechanics Society. These documents are primarily applicable to residential or similar development.

AGS2007 defines landslides as "the movement of a mass of rock, debris or earth down a slope". Such definition includes falls, topples, slides, spreads and flows from both natural and artificial slopes.

LANDSLIDE LIKELIHOOD ASSESSMENT

The assessment of the likelihood of landsliding requires evidence-based judgements.

Judging how often and how much an existing landslide will move is difficult. Judging the likelihood of a new landslide occurring is even harder. Records of past landslides can provide some information on what has happened, but are invariably incomplete and often provide little or no guidance on less frequent events that may occur. Often judgements have to be made about the likelihood of infrequent events with serious consequences, with little or no help from historical records. Slope models, which reflect evidence-based knowledge of how a slope was formed, how it behaved in the past and how it might behave in the future, are used to support judgements about what might happen. Because of the difficulties in assessing landslide likelihood, different assessors may make different judgements when presented with the same information.

The likelihood terms in Appendix C can be taken to imply that it is possible to distinguish between low probability events (e.g. between events having a probability of 1 in 10,000 and 1 in 100,000). In many circumstances it will not be possible to develop defensibly realistic judgements to do so, and so joint terms need to be used (e.g. Likely or Possible).

CONSEQUENCES OF LANDSLIDES

There can be direct (e.g. property damage, injury / loss of life) and indirect (e.g. litigation, loss of business confidence) consequences of a landslide. The assessment of the importance (seriousness) of the consequences is a value judgement best made by those most affected (e.g. client, owner, regulator, public). The main role of the expert is usually to understand and explain what and who might be affected, and what damage or injury might occur.

Appendix C implies that we can anticipate total cost (direct and indirect) of landslide damage to about half an order of magnitude (e.g. the difference between \$30,000 and \$100,000). This involves predicting the location, size, travel distance and speed of a landslide, the response of a building (often before it has been built), the nature and the extent of damage, repair costs as well as indirect consequences such as legal costs, accommodation etc. There can be other direct and indirect consequences of a landslide, which can be difficult to anticipate, let alone quantify and cost. The situation is analogous to the cost of work place accidents where the hidden costs can range from less than one to more than 20 times the visible direct costs.

In many circumstances it will not be possible to develop defensibly realistic judgements to enable use of a single consequence descriptor from Appendix C, and so joint terms need to be used (e.g. Minor or Medium). In our experience, explicit descriptions of potential consequences (e.g. rocks up to 0.5m across may fall on a parked car) help those affected to make their own judgements about the seriousness of the consequences.

RISK MATRIX

The main purpose of a risk matrix is to help rank risks, set priorities and help the decision making process. The risk terms should be regarded only as a guide to the relative level of risk as they are the product of an evidence-based quantitative judgement of likelihood and a value judgement about consequences, both of which involve considerable uncertainty. Different assessors may arrive at different judgements on the risk level. Using Appendix C, many existing houses on sloping land will be assessed to have a Moderate Risk.

RISK LEVEL IMPLICATIONS

In general, it is the responsibility of the client and/or owner and/or regulatory authority and/or others who may be affected to decide whether to accept or treat the risk. The risk assessor and/or other advisers may assist by making risk comparisons, discussing treatment options, explaining the risk management process, advising how others have reacted to risk in similar situations, and making recommendations. Attitudes to risk vary widely and risk evaluation often involves considering more than just property damage (e.g. environmental effects, public reaction, political consequences, business confidence etc.).

The risk level implications in Appendix C represent a very specific example and are unlikely to be generally applicable. In our experience the typical response of regulators to assessed risk is as follows:

Assessed risk	Typical response of client/ owner/ regulator/ person affected
Very High, High ¹	Treats seriously. Usually requires action to reduce risk. Will generally avoid development.
Moderate	May accept risk. Usually looks for ways to reduce risk if reasonably practicable.
Low, Very Low ¹	Usually regards risk as acceptable. May reduce risk if reasonably practicable.

1 The distinctions between Very High and High and between Low and Very Low risks are usually used to help set priorities.

REFERENCES

- 1. AGS (2007). "Practice Note Guidelines for Landslide Risk Management 2007". Australian Geomechanics, Vol. 42, No. 1, pp. 63-114.
- AGS (2007). "Commentary on Practice Note Guidelines for Landslide Risk Management 2007". Australian Geomechanics, Vol. 42, No. 1, pp. 115-158.

PRACTICE NOTE GUIDELINES FOR LANDSLIDE RISK MANAGEMENT 2007

APPENDIX C: LANDSLIDE RISK ASSESSMENT

QUALITATIVE TERMINOLOGY FOR USE IN ASSESSING RISK TO PROPERTY

QUALITATIVE MEASURES OF LIKELIHOOD

Approximate Annual ProbabilityImplied Indicative LandslIndicativeNotionalRecurrence IntervalValueBoundaryRecurrence Interval			Description	Descriptor	Level	
10-1	5x10 ⁻²	10 years		The event is expected to occur over the design life.	ALMOST CERTAIN	А
10-2		100 years	20 years	The event will probably occur under adverse conditions over the design life.	LIKELY	В
10-3	$5x10^{-3}$	1000 years	200 years 2000 years	The event could occur under adverse conditions over the design life.	POSSIBLE	С
10-4	5×10^{-4}	10,000 years	20,000 years	The event might occur under very adverse circumstances over the design life.	UNLIKELY	D
10-5	5x10 ⁻⁵ 5x10 ⁻⁶	100,000 years		The event is conceivable but only under exceptional circumstances over the design life.	RARE	Е
10-6	5x10	1,000,000 years	200,000 years	The event is inconceivable or fanciful over the design life.	BARELY CREDIBLE	F

Note: (1) The table should be used from left to right; use Approximate Annual Probability or Description to assign Descriptor, not vice versa.

QUALITATIVE MEASURES OF CONSEQUENCES TO PROPERTY

	e Cost of Damage	Description	Descriptor	Level
Indicative Value	Indicative Notional		2000.000	
200%		Structure(s) completely destroyed and/or large scale damage requiring major engineering works for stabilisation. Could cause at least one adjacent property major consequence damage.	CATASTROPHIC	1
60%	100%	Extensive damage to most of structure, and/or extending beyond site boundaries requiring significant stabilisation works. Could cause at least one adjacent property medium consequence damage.	MAJOR	2
20%	40% 10%	Moderate damage to some of structure, and/or significant part of site requiring large stabilisation works. Could cause at least one adjacent property minor consequence damage.	MEDIUM	3
5%	1%	Limited damage to part of structure, and/or part of site requiring some reinstatement stabilisation works.	MINOR	4
0.5%	170	Little damage. (Note for high probability event (Almost Certain), this category may be subdivided at a notional boundary of 0.1%. See Risk Matrix.)	INSIGNIFICANT	5

Notes: (2) The Approximate Cost of Damage is expressed as a percentage of market value, being the cost of the improved value of the unaffected property which includes the land plus the unaffected structures.

(3) The Approximate Cost is to be an estimate of the direct cost of the damage, such as the cost of reinstatement of the damaged portion of the property (land plus structures), stabilisation works required to render the site to tolerable risk level for the landslide which has occurred and professional design fees, and consequential costs such as legal fees, temporary accommodation. It does not include additional stabilisation works to address other landslides which may affect the property.

(4) The table should be used from left to right; use Approximate Cost of Damage or Description to assign Descriptor, not vice versa

PRACTICE NOTE GUIDELINES FOR LANDSLIDE RISK MANAGEMENT 2007

APPENDIX C: – QUALITATIVE TERMINOLOGY FOR USE IN ASSESSING RISK TO PROPERTY (CONTINUED)

LIKELIHO	CONSEQUENCES TO PROPERTY (With Indicative Approximate Cost of Damage)					
	Indicative Value of Approximate Annual Probability	1: CATASTROPHIC 200%	2: MAJOR 60%	3: MEDIUM 20%	4: MINOR 5%	5: INSIGNIFICANT 0.5%
A – ALMOST CERTAIN	10 ⁻¹	VH	VH	VH	Н	M or L (5)
B - LIKELY	10 ⁻²	VH	VH	Н	М	L
C - POSSIBLE	10-3	VH	Н	М	М	VL
D - UNLIKELY	10 ⁻⁴	Н	М	L	L	VL
E - RARE	10-5	М	L	L	VL	VL
F - BARELY CREDIBLE	10-6	L	VL	VL	VL	VL

QUALITATIVE RISK ANALYSIS MATRIX – LEVEL OF RISK TO PROPERTY

Notes: (5) For Cell A5, may be subdivided such that a consequence of less than 0.1% is Low Risk.

(6) When considering a risk assessment it must be clearly stated whether it is for existing conditions or with risk control measures which may not be implemented at the current time.

RISK LEVEL IMPLICATIONS

Risk Level		Example Implications (7)		
VH	VERY HIGH RISK	Unacceptable without treatment. Extensive detailed investigation and research, planning and implementation of treatment options essential to reduce risk to Low; may be too expensive and not practical. Work likely to cost more than value of the property.		
Н	HIGH RISK	Unacceptable without treatment. Detailed investigation, planning and implementation of treatment options required to reduce risk to Low. Work would cost a substantial sum in relation to the value of the property.		
М	MODERATE RISK	May be tolerated in certain circumstances (subject to regulator's approval) but requires investigation, planning and implementation of treatment options to reduce the risk to Low. Treatment options to reduce to Low risk should be implemented as soon as practicable.		
L	LOW RISK	Usually acceptable to regulators. Where treatment has been required to reduce the risk to this level, ongoing maintenance is required.		
VL	VERY LOW RISK	Acceptable. Manage by normal slope maintenance procedures.		

Note: (7) The implications for a particular situation are to be determined by all parties to the risk assessment and may depend on the nature of the property at risk; these are only given as a general guide.

Appendix D

CSIRO Publication Building Technology File 18-2011



Foundation Maintenance and Footing Performance: A Homeowner's Guide



BTF 18 replaces Information Sheet 10/91

Buildings can and often do move. This movement can be up, down, lateral or rotational. The fundamental cause of movement in buildings can usually be related to one or more problems in the foundation soil. It is important for the homeowner to identify the soil type in order to ascertain the measures that should be put in place in order to ensure that problems in the foundation soil can be prevented, thus protecting against building movement.

This Building Technology File is designed to identify causes of soil-related building movement, and to suggest methods of prevention of resultant cracking in buildings.

Soil Types

The types of soils usually present under the topsoil in land zoned for residential buildings can be split into two approximate groups – granular and clay. Quite often, foundation soil is a mixture of both types. The general problems associated with soils having granular content are usually caused by erosion. Clay soils are subject to saturation and swell/shrink problems.

Classifications for a given area can generally be obtained by application to the local authority, but these are sometimes unreliable and if there is doubt, a geotechnical report should be commissioned. As most buildings suffering movement problems are founded on clay soils, there is an emphasis on classification of soils according to the amount of swell and shrinkage they experience with variations of water content. The table below is Table 2.1 from AS 2870, the Residential Slab and Footing Code.

Causes of Movement

Settlement due to construction There are two types of settlement that occur as a result of construction:

- Immediate settlement occurs when a building is first placed on its foundation soil, as a result of compaction of the soil under the weight of the structure. The cohesive quality of clay soil mitigates against this, but granular (particularly sandy) soil is susceptible.
- Consolidation settlement is a feature of clay soil and may take place because of the expulsion of moisture from the soil or because of the soil's lack of resistance to local compressive or shear stresses. This will usually take place during the first few months after construction, but has been known to take many years in exceptional cases.

These problems are the province of the builder and should be taken into consideration as part of the preparation of the site for construction. Building Technology File 19 (BTF 19) deals with these problems.

Erosion

All soils are prone to erosion, but sandy soil is particularly susceptible to being washed away. Even clay with a sand component of say 10% or more can suffer from erosion.

Saturation

This is particularly a problem in clay soils. Saturation creates a boglike suspension of the soil that causes it to lose virtually all of its bearing capacity. To a lesser degree, sand is affected by saturation because saturated sand may undergo a reduction in volume – particularly imported sand fill for bedding and blinding layers. However, this usually occurs as immediate settlement and should normally be the province of the builder.

Seasonal swelling and shrinkage of soil

All clays react to the presence of water by slowly absorbing it, making the soil increase in volume (see table below). The degree of increase varies considerably between different clays, as does the degree of decrease during the subsequent drying out caused by fair weather periods. Because of the low absorption and expulsion rate, this phenomenon will not usually be noticeable unless there are prolonged rainy or dry periods, usually of weeks or months, depending on the land and soil characteristics.

The swelling of soil creates an upward force on the footings of the building, and shrinkage creates subsidence that takes away the support needed by the footing to retain equilibrium.

Shear failure

This phenomenon occurs when the foundation soil does not have sufficient strength to support the weight of the footing. There are two major post-construction causes:

- Significant load increase.
- Reduction of lateral support of the soil under the footing due to erosion or excavation.
- In clay soil, shear failure can be caused by saturation of the soil adjacent to or under the footing.

	GENERAL DEFINITIONS OF SITE CLASSES
Class	Foundation
А	Most sand and rock sites with little or no ground movement from moisture changes
S	Slightly reactive clay sites with only slight ground movement from moisture changes
М	Moderately reactive clay or silt sites, which can experience moderate ground movement from moisture changes
Н	Highly reactive clay sites, which can experience high ground movement from moisture changes
Е	Extremely reactive sites, which can experience extreme ground movement from moisture changes
A to P	Filled sites
Р	Sites which include soft soils, such as soft clay or silt or loose sands; landslip; mine subsidence; collapsing soils; soils subject to erosion; reactive sites subject to abnormal moisture conditions or sites which cannot be classified otherwise

Tree root growth

Trees and shrubs that are allowed to grow in the vicinity of footings can cause foundation soil movement in two ways:

- Roots that grow under footings may increase in cross-sectional size, exerting upward pressure on footings.
- Roots in the vicinity of footings will absorb much of the moisture in the foundation soil, causing shrinkage or subsidence.

Unevenness of Movement

The types of ground movement described above usually occur unevenly throughout the building's foundation soil. Settlement due to construction tends to be uneven because of:

- Differing compaction of foundation soil prior to construction.
- Differing moisture content of foundation soil prior to construction.

Movement due to non-construction causes is usually more uneven still. Erosion can undermine a footing that traverses the flow or can create the conditions for shear failure by eroding soil adjacent to a footing that runs in the same direction as the flow.

Saturation of clay foundation soil may occur where subfloor walls create a dam that makes water pond. It can also occur wherever there is a source of water near footings in clay soil. This leads to a severe reduction in the strength of the soil which may create local shear failure.

Seasonal swelling and shrinkage of clay soil affects the perimeter of the building first, then gradually spreads to the interior. The swelling process will usually begin at the uphill extreme of the building, or on the weather side where the land is flat. Swelling gradually reaches the interior soil as absorption continues. Shrinkage usually begins where the sun's heat is greatest.

Effects of Uneven Soil Movement on Structures

Erosion and saturation

Erosion removes the support from under footings, tending to create subsidence of the part of the structure under which it occurs. Brickwork walls will resist the stress created by this removal of support by bridging the gap or cantilevering until the bricks or the mortar bedding fail. Older masonry has little resistance. Evidence of failure varies according to circumstances and symptoms may include:

- Step cracking in the mortar beds in the body of the wall or above/below openings such as doors or windows.
- Vertical cracking in the bricks (usually but not necessarily in line with the vertical beds or perpends).

Isolated piers affected by erosion or saturation of foundations will eventually lose contact with the bearers they support and may tilt or fall over. The floors that have lost this support will become bouncy, sometimes rattling ornaments etc.

Seasonal swelling/shrinkage in clay

Swelling foundation soil due to rainy periods first lifts the most exposed extremities of the footing system, then the remainder of the perimeter footings while gradually permeating inside the building footprint to lift internal footings. This swelling first tends to create a dish effect, because the external footings are pushed higher than the internal ones.

The first noticeable symptom may be that the floor appears slightly dished. This is often accompanied by some doors binding on the floor or the door head, together with some cracking of cornice mitres. In buildings with timber flooring supported by bearers and joists, the floor can be bouncy. Externally there may be visible dishing of the hip or ridge lines.

As the moisture absorption process completes its journey to the innermost areas of the building, the internal footings will rise. If the spread of moisture is roughly even, it may be that the symptoms will temporarily disappear, but it is more likely that swelling will be uneven, creating a difference rather than a disappearance in symptoms. In buildings with timber flooring supported by bearers and joists, the isolated piers will rise more easily than the strip footings or piers under walls, creating noticeable doming of flooring.



As the weather pattern changes and the soil begins to dry out, the external footings will be first affected, beginning with the locations where the sun's effect is strongest. This has the effect of lowering the external footings. The doming is accentuated and cracking reduces or disappears where it occurred because of dishing, but other cracks open up. The roof lines may become convex.

Doming and dishing are also affected by weather in other ways. In areas where warm, wet summers and cooler dry winters prevail, water migration tends to be toward the interior and doming will be accentuated, whereas where summers are dry and winters are cold and wet, migration tends to be toward the exterior and the underlying propensity is toward dishing.

Movement caused by tree roots

In general, growing roots will exert an upward pressure on footings, whereas soil subject to drying because of tree or shrub roots will tend to remove support from under footings by inducing shrinkage.

Complications caused by the structure itself

Most forces that the soil causes to be exerted on structures are vertical – i.e. either up or down. However, because these forces are seldom spread evenly around the footings, and because the building resists uneven movement because of its rigidity, forces are exerted from one part of the building to another. The net result of all these forces is usually rotational. This resultant force often complicates the diagnosis because the visible symptom is binding of doors on the vertical member of the frame.

Effects on full masonry structures

Brickwork will resist cracking where it can. It will attempt to span areas that lose support because of subsided foundations or raised points. It is therefore usual to see cracking at weak points, such as openings for windows or doors.

In the event of construction settlement, cracking will usually remain unchanged after the process of settlement has ceased.

With local shear or erosion, cracking will usually continue to develop until the original cause has been remedied, or until the subsidence has completely neutralised the affected portion of footing and the structure has stabilised on other footings that remain effective.

In the case of swell/shrink effects, the brickwork will in some cases return to its original position after completion of a cycle, however it is more likely that the rotational effect will not be exactly reversed, and it is also usual that brickwork will settle in its new position and will resist the forces trying to return it to its original position. This means that in a case where swelling takes place after construction and cracking occurs, the cracking is likely to at least partly remain after the shrink segment of the cycle is complete. Thus, each time the cycle is repeated, the likelihood is that the cracking will become wider until the sections of brickwork become virtually independent.

With repeated cycles, once the cracking is established, if there is no other complication, it is normal for the incidence of cracking to stabilise, as the building has the articulation it needs to cope with the problem. This is by no means always the case, however, and monitoring of cracks in walls and floors should always be treated seriously.

Upheaval caused by growth of tree roots under footings is not a simple vertical shear stress. There is a tendency for the root to also exert lateral forces that attempt to separate sections of brickwork after initial cracking has occurred. The normal structural arrangement is that the inner leaf of brickwork in the external walls and at least some of the internal walls (depending on the roof type) comprise the load-bearing structure on which any upper floors, ceilings and the roof are supported. In these cases, it is internally visible cracking that should be the main focus of attention, however there are a few examples of dwellings whose external leaf of masonry plays some supporting role, so this should be checked if there is any doubt. In any case, externally visible cracking is important as a guide to stresses on the structure generally, and it should also be remembered that the external walls must be capable of supporting themselves.

Effects on framed structures

Timber or steel framed buildings are less likely to exhibit cracking due to swell/shrink than masonry buildings because of their flexibility. Also, the doming/dishing effects tend to be lower because of the lighter weight of walls. The main risks to framed buildings are encountered because of the isolated pier footings used under walls. Where erosion or saturation cause a footing to fall away, this can double the span which a wall must bridge. This additional stress can create cracking in wall linings, particularly where there is a weak point in the structure caused by a door or window opening. It is, however, unlikely that framed structures will be so stressed as to suffer serious damage without first exhibiting some or all of the above symptoms for a considerable period. The same warning period should apply in the case of upheaval. It should be noted, however, that where framed buildings are supported by strip footings there is only one leaf of brickwork and therefore the externally visible walls are the supporting structure for the building. In this case, the subfloor masonry walls can be expected to behave as full brickwork walls.

Effects on brick veneer structures

Because the load-bearing structure of a brick veneer building is the frame that makes up the interior leaf of the external walls plus perhaps the internal walls, depending on the type of roof, the building can be expected to behave as a framed structure, except that the external masonry will behave in a similar way to the external leaf of a full masonry structure.

Water Service and Drainage

Where a water service pipe, a sewer or stormwater drainage pipe is in the vicinity of a building, a water leak can cause erosion, swelling or saturation of susceptible soil. Even a minuscule leak can be enough to saturate a clay foundation. A leaking tap near a building can have the same effect. In addition, trenches containing pipes can become watercourses even though backfilled, particularly where broken rubble is used as fill. Water that runs along these trenches can be responsible for serious erosion, interstrata seepage into subfloor areas and saturation.

Pipe leakage and trench water flows also encourage tree and shrub roots to the source of water, complicating and exacerbating the problem.

Poor roof plumbing can result in large volumes of rainwater being concentrated in a small area of soil:

 Incorrect falls in roof guttering may result in overflows, as may gutters blocked with leaves etc.

- · Corroded guttering or downpipes can spill water to ground.
- Downpipes not positively connected to a proper stormwater collection system will direct a concentration of water to soil that is directly adjacent to footings, sometimes causing large-scale problems such as erosion, saturation and migration of water under the building.

Seriousness of Cracking

In general, most cracking found in masonry walls is a cosmetic nuisance only and can be kept in repair or even ignored. The table below is a reproduction of Table C1 of AS 2870.

AS 2870 also publishes figures relating to cracking in concrete floors, however because wall cracking will usually reach the critical point significantly earlier than cracking in slabs, this table is not reproduced here.

Prevention/Cure

Plumbing

Where building movement is caused by water service, roof plumbing, sewer or stormwater failure, the remedy is to repair the problem. It is prudent, however, to consider also rerouting pipes away from the building where possible, and relocating taps to positions where any leakage will not direct water to the building vicinity. Even where gully traps are present, there is sometimes sufficient spill to create erosion or saturation, particularly in modern installations using smaller diameter PVC fixtures. Indeed, some gully traps are not situated directly under the taps that are installed to charge them, with the result that water from the tap may enter the backfilled trench that houses the sewer piping. If the trench has been poorly backfilled, the water will either pond or flow along the bottom of the trench. As these trenches usually run alongside the footings and can be at a similar depth, it is not hard to see how any water that is thus directed into a trench can easily affect the foundation's ability to support footings or even gain entry to the subfloor area.

Ground drainage

In all soils there is the capacity for water to travel on the surface and below it. Surface water flows can be established by inspection during and after heavy or prolonged rain. If necessary, a grated drain system connected to the stormwater collection system is usually an easy solution.

It is, however, sometimes necessary when attempting to prevent water migration that testing be carried out to establish watertable height and subsoil water flows. This subject is referred to in BTF 19 and may properly be regarded as an area for an expert consultant.

Protection of the building perimeter

It is essential to remember that the soil that affects footings extends well beyond the actual building line. Watering of garden plants, shrubs and trees causes some of the most serious water problems.

For this reason, particularly where problems exist or are likely to occur, it is recommended that an apron of paving be installed around as much of the building perimeter as necessary. This paving

Description of typical damage and required repair	Approximate crack width limit (see Note 3)	Damage category
Hairline cracks	<0.1 mm	0
Fine cracks which do not need repair	<1 mm	1
Cracks noticeable but easily filled. Doors and windows stick slightly	<5 mm	2
Cracks can be repaired and possibly a small amount of wall will need to be replaced. Doors and windows stick. Service pipes can fracture. Weathertightness often impaired	5–15 mm (or a number of cracks 3 mm or more in one group)	3
Extensive repair work involving breaking-out and replacing sections of walls, especially over doors and windows. Window and door frames distort. Walls lean or bulge noticeably, some loss of bearing in beams. Service pipes disrupted	15–25 mm but also depend on number of cracks	4



should extend outwards a minimum of 900 mm (more in highly reactive soil) and should have a minimum fall away from the building of 1:60. The finished paving should be no less than 100 mm below brick vent bases.

It is prudent to relocate drainage pipes away from this paving, if possible, to avoid complications from future leakage. If this is not practical, earthenware pipes should be replaced by PVC and backfilling should be of the same soil type as the surrounding soil and compacted to the same density.

Except in areas where freezing of water is an issue, it is wise to remove taps in the building area and relocate them well away from the building – preferably not uphill from it (see BTF 19).

It may be desirable to install a grated drain at the outside edge of the paving on the uphill side of the building. If subsoil drainage is needed this can be installed under the surface drain.

Condensation

In buildings with a subfloor void such as where bearers and joists support flooring, insufficient ventilation creates ideal conditions for condensation, particularly where there is little clearance between the floor and the ground. Condensation adds to the moisture already present in the subfloor and significantly slows the process of drying out. Installation of an adequate subfloor ventilation system, either natural or mechanical, is desirable.

Warning: Although this Building Technology File deals with cracking in buildings, it should be said that subfloor moisture can result in the development of other problems, notably:

- Water that is transmitted into masonry, metal or timber building elements causes damage and/or decay to those elements.
- High subfloor humidity and moisture content create an ideal environment for various pests, including termites and spiders.
- Where high moisture levels are transmitted to the flooring and walls, an increase in the dust mite count can ensue within the living areas. Dust mites, as well as dampness in general, can be a health hazard to inhabitants, particularly those who are abnormally susceptible to respiratory ailments.

The garden

The ideal vegetation layout is to have lawn or plants that require only light watering immediately adjacent to the drainage or paving edge, then more demanding plants, shrubs and trees spread out in that order.

Overwatering due to misuse of automatic watering systems is a common cause of saturation and water migration under footings. If it is necessary to use these systems, it is important to remove garden beds to a completely safe distance from buildings.

Existing trees

Where a tree is causing a problem of soil drying or there is the existence or threat of upheaval of footings, if the offending roots are subsidiary and their removal will not significantly damage the tree, they should be severed and a concrete or metal barrier placed vertically in the soil to prevent future root growth in the direction of the building. If it is not possible to remove the relevant roots without damage to the tree, an application to remove the tree should be made to the local authority. A prudent plan is to transplant likely offenders before they become a problem.

Information on trees, plants and shrubs

State departments overseeing agriculture can give information regarding root patterns, volume of water needed and safe distance from buildings of most species. Botanic gardens are also sources of information. For information on plant roots and drains, see Building Technology File 17.

Excavation

Excavation around footings must be properly engineered. Soil supporting footings can only be safely excavated at an angle that allows the soil under the footing to remain stable. This angle is called the angle of repose (or friction) and varies significantly between soil types and conditions. Removal of soil within the angle of repose will cause subsidence.

Remediation

Where erosion has occurred that has washed away soil adjacent to footings, soil of the same classification should be introduced and compacted to the same density. Where footings have been undermined, augmentation or other specialist work may be required. Remediation of footings and foundations is generally the realm of a specialist consultant.

Where isolated footings rise and fall because of swell/shrink effect, the homeowner may be tempted to alleviate floor bounce by filling the gap that has appeared between the bearer and the pier with blocking. The danger here is that when the next swell segment of the cycle occurs, the extra blocking will push the floor up into an accentuated dome and may also cause local shear failure in the soil. If it is necessary to use blocking, it should be by a pair of fine wedges and monitoring should be carried out fortnightly.

This BTF was prepared by John Lewer FAIB, MIAMA, Partner, Construction Diagnosis.

The information in this and other issues in the series was derived from various sources and was believed to be correct when published.

The information is advisory. It is provided in good faith and not claimed to be an exhaustive treatment of the relevant subject.

Further professional advice needs to be obtained before taking any action based on the information provided.

Distributed by

CSIRO PUBLISHIN G PO Box 1139, Collingwood 3066, Australia Freecall 1800 645 051 Tel (03) 9662 7666 Fax (03) 9662 7555 www.publish.csiro.au

Email: publishing.sales@csiro.au

© CSIRO 2003. Unauthorised copying of this Building Technology file is prohibited

Appendix E

Important Information About Your Geotechnical Report



Your report is based on project specific criteria

Your report has been developed on the basis of your unique project specific requirements as understood by MM Geomechanics and applies only to the site investigated. Project criteria typically include the general nature of the project; its size and configuration; the location of any structures on the site; and the additional risk imposed by scope-of-service limitations imposed by the client. Your report should not be used if there are any changes to the project without first asking MM Geomechanics to assess how factors that changed subsequent to the date of the report affect the report's recommendations. MM Geomechanics cannot accept responsibility for problems that may occur due to changed factors if they are not consulted.

Your report is prepared for specific purposes and persons

To avoid misuse of the information contained in your report, it is recommended that you confer with MM Geomechanics before passing your report on to another party who may not be familiar with the background and the purpose of the report. Your report should not be applied to any project other than that originally specified at the time the report was issued.

Unless expressly stated, it is not intended that this report be used for the purpose of tendering works. Consult MM Geomechanics for advice on the applicability of your report for tendering purposes.

Sampling Constraints

Unless otherwise stated in this report, the scope is limited to fixed and installed materials and excludes buried waste materials, contaminated dusts and soils. While the assessment has attempted to locate the asbestos-containing materials within the building(s), the investigation was limited to only a visual assessment and limited sampling program. MM Geomechanics notes that sampling is representative only and that due to the lack of homogeneity of building materials, it is possible that sampling has not detected all asbestos within the nominated locations.

Given that a representative sampling program has been adopted, not all materials suspected of containing asbestos at the time of the investigation were sampled and assessed. Some asbestos materials may have been suspected to contain asbestos based on their similar appearance to previously sampled materials. Therefore, it is possible that asbestos materials, which may be concealed within inaccessible areas/voids, may not have been located during the investigation. Such areas include, but are not limited to:

- Materials concealed behind structural members and within inaccessible building voids;
- Areas inaccessible without the aid of scaffolding or lifting devices;
- Areas below ground and buried elements;
- Inaccessible ceiling or wall cavities;
- Areas requiring substantial demolition to access;
- Areas beneath floor covering where asbestoscontaining materials were not expected to exist;
- Materials contained within plant and not accessible without dismantling the plant; and
- Areas where access is restricted due to locked doors, safety risks, ownership concerns, or being occupied at the time of the investigation.

Information supplied by Third Parties

MM Geomechanics cannot guarantee the accuracy or completeness of any information supplied by others. Our scope does not cover an independent verification of such information. You therefore waive any claim against the company and agree to indemnify MM Geomechanics for any loss, claim or liability arising from inaccuracies or omissions in information provided to MM Geomechanics by third parties.

Interpretation by other professionals

Only MM Geomechanics, who prepared the report, is fully familiar with the background information needed to assess whether or not the report's recommendations are valid and whether or not changes should be considered as the project develops. If another party undertakes the implementation of the recommendations of this report, there is a risk that the report will be misinterpreted and MM Geomechanics cannot be held responsible for such misinterpretation.

Costly problems can occur when other design professionals develop their plans based on misinterpretations of a report. To help avoid misinterpretations, retain MM Geomechanics to work with other project design professionals who are affected by the report. Have MM Geomechanics explain the report implications to design professionals affected by them and then review plans and specifications produced to see how they incorporate the report findings.

Data should not be separated from the report

The report as a whole presents the findings of the site assessment and the report should not be copied in part or altered in any way.

Registers, figures, drawings, etc. are customarily included in our reports and are developed by scientists; hence, they should not under any circumstances be extracted for inclusion in other documents or separated from the report in any way.

Future Works

During future works at the site, care should be taken when entering or working in any previously inaccessible areas or areas mentioned above and it is imperative that works cease immediately pending further investigation and sampling (if necessary) if any unknown materials are encountered. Therefore, during any refurbishment or demolition works, further investigation, sampling and/or assessment may be required should any suspect or unknown material be observed in previously inaccessible areas or areas not fully inspected, i.e. carpeted or tiled floors.

Rely on MM Geomechanics for additional assistance

MM Geomechanics is experienced with a variety of techniques and approaches that can be used to help reduce risks for all parties to a project, from design to construction. It is common that not all approaches will be necessarily dealt with in your site assessment report due to concepts proposed at that time. As the project progresses through design towards construction, consideration should be given to retain the services of MM Geomechanics to develop alternative approaches to problems that may be of genuine benefit both in time and cost.

MM Geomechanics ABN 78 624 459 534