

**ARBORICULTURAL TREE
SERVICES PTY LTD**

**A.B.N. NUMBER: 57 093 391 407
A.C.N. NUMBER: 093 391 407**

**P.O. Box 751
Newport Beach
NSW 2106**

**Email; gbrookstreecare@hotmail.com
Mobile: 0412 281 580
www.treesafety.net**

**Graham Brooks dip arb
Arboriculture Australia Consulting Arborist
Tree care and Consultancy**

**Advanced Level 3 Tree Risk Assessment
Botanical Observations, SoT, ERT & Confirmation Resistance Test Data Sheet**

Prepared for;

**Peak Arboriculture
3 Cutler Parade
North Ryde
NSW 2113**

**Reference;
30 Herbert Avenue
Newport
NSW 2106**

November 2022

Introduction: This Scientific data sheet has been requested by Mr. David Peake – Peak Arboriculture.
Background: An ISA Tree Risk Assessment was requested by Mr. David Peake on the subject tree's visible defective tree parts.

Tree Genus Species: *Eucalyptus punctata*

Data Collection:

Advanced level 3 scientific decay analysis conducted from;

- (i) 0.05m agl – Basal Stem Trunk Wound

Other specific tree data was recorded on Sonic PiCUS Tomography (SoT), Electric Resistance Tomography (ERT), IML PD500 Resistance test machine and a digital camera.

Documents Provided.

No documents were provided.

Site Visits: 22nd November 2022

Time: 8am – 10am

Weather condition: Fine

Present: Mr. Graham Brooks. Consulting Arborist. Mr. David Peake.

Analysis Conducted: Level 2 basic tree risk assessment.


- (i) Escalated to advanced level 3 scientific decay analysis testing of; 0.05m agl – Basal Stem Trunk Wound, SoT, ERT and Confirmation Resistance Testing. Collection of data.

Photograph 1. Subject tree – Street View. Northern aspect.



Photograph Set 2. Visible Botanical Structural Defects – Bark Vascular Cambium Disease – Visibly identified as *Armillaria luteobubalina* – Australian Honey Fungus




 Pathogenic disease indicator symptomatic of *Armillaria luteobubalina*

Armillaria luteobubalina – Pathogenic wood decay fungi (PWDF)


Area affected; Basal Stem and root System.
Comment; Native pathogen. Very destructive pathogen.




 Vascular cambium damage, discolouration and spread of *Armillaria luteobubalina* around structural stem circumference.



Stem circumference = 3.6m
Damaged bark vascular cambium tissue wound margin = 1.9m

 Therefore 53% of stem circumference displays necrotic bark vascular cambium tissue.




 Canopy and Stem Loading = NE

Target = Residential Neighbouring Home

Likelihood of Failure = Probable
(ISA matrix 1) Likelihood matrix

Photograph 3. Visible Botanical Structural Defects – Upper Canopy Defects.




High canopy stress raiser and open decay cavity in 2nd order structural stem.

Decayed stub with epicormic growth and cambium wound in collar.












Photograph Set 4. Sonic SoT and ERT with Confirmation Resistance Test annotated into Tomograms.

Sonic PiCUS Tomograph – 0.05m agl

ERT- 0.05m agl



ERT type 1 Decision Table

SoT – Sonic Velocity [m/s]	ERT Resistivity [$\Omega \cdot m$]	Wood status	# in Tomogram
High (brown) 	High (red) 	Sound wood, response growth	(1)
High (brown)  	Low (blue) 	Still safe, but early decay	(2)
Low (blue/purple)  	High (red) 	Cavity / crack / dead decay	(3)
Low (blue/purple)  	Low (blue) 	Decay	(4)

Interpretation of SoT, ERT and Confirmation Resistance Tests. Internal Cracks;

*The scientific data within the SoT as confirmed by confirmation resistance drill tests identify the tomography data as **inaccurate**. Lesser residual wall thickness and a greater volume of decay and incipient wood identified within structural basal stem (SoT) than actually displayed within tomography data. **Causation of minor anomaly** = Sound waves disrupted around circumference through denser response adaptive wood and not across the cross section. (Argus Scientist)


Spread of pathogenic wood decay fungi identified (incipient wood) large volume.


Longevity of subject tree = SHORT <7yrs

Recent or Planned Change in Load Factors = None Known

At the time of assessment; 'Likelihood of Failure' – Windthrow tree was categorised as **Probable** (ISA Matrix 1. Likelihood matrix)

Photograph Set 5. Compromised Structural Stem



 Actual decay volume within basal structural stem as confirmed by resistance testing with IML PD500 resistograph. (Decay, incipient & compromised wood)

Note: *Armillaria luteobubalina* – Pathogenic wood decay fungi (PWDF)


Area affected; Basal Stem and root System.
Comment; Native pathogen. Very destructive pathogen.

Decay volume is greater within the root crown.

Likelihood of Failure = Probable
(ISA matrix 1) Likelihood matrix

Target = Neighbouring Residential Home

Risk Rating = High Risk



Yellow lines within tomograph identifies internal cracking which can be visibly seen externally between MP2 – MP3 and MP3 – MP4

Cracking is caused by stem segmentation (decay) and tortional forces upon structural stem

Recommendations:

- **Predominant Defective Tree Part** = Basal Structural Stem and Root Crown colonized with *Armillaria luteobubalina* = 26m Lever Arm (Windthrow)
- **Target** = Neighbouring Residential Property and Recreational areas.
- **Likelihood of Failure** = **Probable.**
- **Consequence** = **Severe**

Arboricultural Action

- Removal of HIGH RISK - Short longevity <7yrs subject tree
- Replacement Planting of 2 x Same Genus species trees.

Yours faithfully,

Arboricultural Tree Services Pty Ltd



Graham Brooks dip arb

Managing director

Arboriculture Australia Approved Consulting Arborist No: 1983









Member International Society of Arboriculture Mem No: 173140

ISA Tree Risk Assessment Qualified 2014-2024

www.treesafety.net

Appendix 1. Confirmation Resistance Tests.

Resistance Test (RT) 1,2,3,4,5,7,8 and 9 (Comparative test Rt5)





Basic Tree Risk Assessment Form

Client _____ Date _____ Time _____
Address/Tree location _____ Tree no. _____ Sheet _____ of _____
Tree species _____ dbh _____ Height _____ Crown spread dia. _____
Assessor(s) _____ Time frame _____ Tools used _____

Target Assessment

Target number	Target description	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
		Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1							
2							
3							
4							

Site Factors

History of failures _____ Topography Flat ☐ Slope ☐ _____ % Aspect _____
Site changes None ☐ Grade change ☐ Site clearing ☐ Changed soil hydrology ☐ Root cuts ☐ Describe _____
Soil conditions Limited volume ☐ Saturated ☐ Shallow ☐ Compacted ☐ Pavement over roots ☐ _____ % Describe _____
Prevailing wind direction _____ Common weather Strong winds ☐ Ice ☐ Snow ☐ Heavy rain ☐ Describe _____

Tree Health and Species Profile

Vigor Low ☐ Normal ☐ High ☐ Foliage None (seasonal) ☐ None (dead) ☐ Normal _____ % Chlorotic _____ % Necrotic _____ %
Pests _____ Abiotic _____
Species failure profile Branches ☐ Trunk ☐ Roots ☐ Describe _____

Load Factors

Wind exposure Protected ☐ Partial ☐ Full ☐ Wind funneling ☐ _____ Relative crown size Small ☐ Medium ☐ Large ☐
Crown density Sparse ☐ Normal ☐ Dense ☐ Interior branches Few ☐ Normal ☐ Dense ☐ Vines/Mistletoe/Moss ☐ _____
Recent or planned change in load factors _____

Tree Defects and Conditions Affecting the Likelihood of Failure

— Crown and Branches —

Unbalanced crown ☐ LCR _____ % Cracks ☐ _____ Lightning damage ☐
Dead twigs/branches ☐ _____ % overall Max. dia. _____ Codominant ☐ _____ Included bark ☐
Broken/Hangers Number _____ Max. dia. _____ Weak attachments ☐ _____ Cavity/Nest hole _____ % circ.
Over-extended branches ☐ Previous branch failures ☐ _____ Similar branches present ☐
Pruning history
Crown cleaned ☐ Thinned ☐ Raised ☐ Dead/Missing bark ☐ Cankers/Galls/Burls ☐ Sapwood damage/decay ☐
Reduced ☐ Topped ☐ Lion-tailed ☐ Conks ☐ Heartwood decay ☐ _____
Flush cuts ☐ Other _____ Response growth _____
Main concern(s) _____

Load on defect N/A ☐ Minor ☐ Moderate ☐ Significant ☐ _____
Likelihood of failure Improbable ☐ Possible ☐ Probable ☐ Imminent ☐ _____

— Trunk —

Dead/Missing bark ☐ Abnormal bark texture/color ☐
Codominant stems ☐ Included bark ☐ Cracks ☐
Sapwood damage/decay ☐ Cankers/Galls/Burls ☐ Sap ooze ☐
Lightning damage ☐ Heartwood decay ☐ Conks/Mushrooms ☐
Cavity/Nest hole _____ % circ. Depth _____ Poor taper ☐
Lean _____ ° Corrected? _____
Response growth _____
Main concern(s) _____

Load on defect N/A ☐ Minor ☐ Moderate ☐ Significant ☐
Likelihood of failure Improbable ☐ Possible ☐ Probable ☐ Imminent ☐

— Roots and Root Collar —

Collar buried/Not visible ☐ Depth _____ Stem girdling ☐
Dead ☐ Decay ☐ Conks/Mushrooms ☐
Ooze ☐ Cavity ☐ _____ % circ.
Cracks ☐ Cut/Damaged roots ☐ Distance from trunk _____
Root plate lifting ☐ Soil weakness ☐
Response growth _____
Main concern(s) _____

Load on defect N/A ☐ Minor ☐ Moderate ☐ Significant ☐
Likelihood of failure Improbable ☐ Possible ☐ Probable ☐ Imminent ☐

Risk Categorization																							
Condition number	Tree part	Conditions of concern	Part size	Fall distance	Target number	Target protection	Likelihood												Consequences				Risk rating of part (from Matrix 2)
							Failure				Impact				Failure & Impact (from Matrix 1)								
							Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant	Severe	
1																							
2																							
3																							
4																							

Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impacting Target			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely

Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low

Notes, explanations, descriptions _____

Mitigation options _____ Residual risk _____

_____ Residual risk _____

_____ Residual risk _____

_____ Residual risk _____

Overall tree risk rating Low ☐ Moderate ☐ High ☐ Extreme ☐

Work priority 1 ☐ 2 ☐ 3 ☐ 4 ☐

Overall residual risk Low ☐ Moderate ☐ High ☐ Extreme ☐

Recommended inspection interval _____

Data ☐ Final ☐ Preliminary Advanced assessment needed ☐ No ☐ Yes-Type/Reason _____

Inspection limitations ☐ None ☐ Visibility ☐ Access ☐ Vines ☐ Root collar buried Describe _____

