

23 October 2017

General Manager Northern Beaches Council PO Box 882 Mona Vale NSW 1660

Dear Sir/Madam,

Development Application No. N0008/17
42 McCarrs Creek Road, Church Point

For Council's information, please find enclosed Construction Certificate No. 2017/5909 issued for alterations & additions to a dwelling (construction of an inclinator) at the above address, accompanied by:

- Copy of Construction Certificate application form
- Notice of Commencement of Work and Appointment of Principal Certifying Authority
- Home Warranty Insurance Certificate
- Cheque for \$36.00 being the prescribed fee to receive the above certificate.

NB: Please forward receipt for the above fee to Insight Building Certifiers, PO Box 326, Mona Vale 1660.

Yours Faithfully,

Tom Bowden Insight Building Certifiers

P. AM 287.



Construction Certificate Determination

issued under the Environmental Planning and Assessment Act 1979 Section 109C (1) (b), 81A (2) and 81A (4)

Certificate No. 2017/5909

Council	Northern Beaches
Determination	
Date of issue	23 October 2017
Subject land	
Address	42 McCarrs Creek Road, Church Point
Lot No, DP No.	Lot 16 DP 11691
Applicant	
Name	Ms Susan Crimmins
Address	42 McCarrs Creek Road, Church Point NSW 2105
Contact No.	9997 3383 / 0414 499 463
Owner	
Name	Ms Susan Crimmins
Address	42 McCarrs Creek Road, Church Point NSW 2105
Contact No.	9997 3383 / 0414 499 463
Description of Development	
Type of Work	Alterations & Additions to a Dwelling (Construction of an Inclinator)
Builder or Owner/Builder	
Name	1. Garry Brook
	Site Preparation, Construction of Foundations &
	Landings & Installation of an Inclinator
Contractor Licence No/Permit	64101 <i>C</i>
Name	2. PR King & Sons Pty Ltd
	Supply of Inclinator
Contractor Licence No/Permit	n/a
Value of Work	
Building	\$144,000.00

Attachments

- Copy of completed Construction Certificate Application Form
- Long Service Corporation receipt no's. 296456 dated 4 August 2017 & 00301278 & 00301279 dated 11 September 2017

Plans & Specifications certified

The development is to be carried out in compliance with the following plans and documentation listed below and endorsed with *Insight Building Certifiers* stamp.

- Architectural Plans & Construction Specification reference no. 6416/1B, sheet no's. 2 of 2, prepared by P.R. King & Sons Pty Ltd dated 21 August 2016
- Structural Details reference no. 30879, drawing no's. C1, C2 & C3, prepared & endorsed by Jack Hodgson Consultants Pty Ltd dated 19 September 2017
- Completed Form 2 (Parts A & B) of Northern Beaches Council Geotechnical Risk Management Policy, endorsed by Jack Hodgson Consultants Pty Ltd dated 20 September 2017, respectively
- Dilapidation Report (Council Infrastructure) prepared by Jim's Building Inspections, undated
- · Dilapidation Report (Waterfront Crown) prepared by Jim's Building Inspections, undated
- Dilapidation Report (40 McCarrs Creek Road) prepared by Jim's Building Inspections, undated
- Sydney Water approval dated 1 August 2017

Certificate

I hereby certify that the above Plans, documents or Certificates, satisfy:

- The relevant provisions of the Building Code of Australia
- The relevant conditions of this Development Consent

and that work completed in accordance with the documentation accompanying the application for this Certificate (and any modifications as verified by me and shown on that documentation) will comply with the requirements of the Environmental Planning & Assessment Regulation referred to in Section 81A(5) of the Environmental Planning & Assessment Act, 1979.

Signed

Date of endorsement

Certificate No.

23 OCT 2017

2017/5909

Certifying Authority

Name of Accredited Certifier

Accreditation No.

Accreditation Authority

Contact No. Address

Tom Bowden BPB0042

Building Professionals Board

(02) 9999 0003

13/90 Mona Vale Road, Mona Vale NSW 2103

Development Consent

Development Application No. Date of Determination

N0008/17 25 May 2017

BCA Classification

10b



BY: ... Construction Certificate

APPLICATION FOR A CONSTRUCTION CERTIFICATE Environmental Planning and Assessment Act 1979 & Environmental Planning and Assessment Regulation 2000				
Description of Building Work				
	dwelling (construction of an inclinar			
Estimated cost of work	BCA Classification(s)			
\$144,000.00	106			
Development Consent Reference no.	Date of Issue			
N0008/17	25-05-2017			
Modified Consent Reference no. (If applicable)	Date of Issue (If applicable)			
Property Address Unit/Street no. Street name				
42 M'Carrs Creek	Road			
Suburb	Post code 2/05			
Church Point	2703			
Lot no. DP no.				
16 1/691				
Accompanying Documents i. Appropriate Architectural Plans and Specifications				
ii. All information required by Part 3 of Schedule 1 Forms of	the Regulation (see over)			
I/We, the owner/s of the abovementioned property, hereby make Certifiers Pty Ltd (Insight) for a Construction Certificate for the that the documents provided and asserted by me as a copy of same as issued by the relevant consent authority or the Land as	building work descibed above and, in doing so, I/we also declare a development consent and incorporated plans are a true copy of			
Owner 1 Name:	Owner 2 Name:			
Owner's Signature:	Owner's Signature:			
Date: 7/8/17	Date:			
Owner's Address: 42 MCCARRS CRE	JEK RP. CHURCH POINT			
Daytime Telephone: 0414 499463 9997338 [Office Use Only]: [

Suite 13/90 Mona Vale Road Mona Vale NSW 2103 PO Box 326 Mona Vale NSW 1660 ph; 9999 0003 fax: 9979 1555 email: info@insightcert.com.au web: www.insightbuildingcertifiers.com.au ABN 54 115 090 456

Environmental Planning & Assessment Regulations 2000 Schedule 1 – Part 3(6) – Documents to accompany application for Construction Certificates

- (1) An application for a construction certificate must be accompanied by the following documents:
 - (a) if the development involves building work (including work in relation to a dwelling-house or a building or structure that is ancillary to a dwelling-house):
 - (i) a detailed description of the development, and
 - (ii) appropriate building work plans and specifications,
 - (b) if the development involves building work (other than work in relation to a dwelling-house or a building or structure that is ancillary to a dwelling-house or work that relates only to fire link conversion):
 - (i) a list of any existing fire safety measures provided in relation to the land or any existing building on the land, and
 - (ii) a list of the proposed fire safety measures to be provided in relation to the land and any building on the land as a consequence of the building work,
 - (c) if the development involves subdivision work, appropriate subdivision work plans and specifications,
 - (d) in the case of development to which clause 6A applies, such other documents as any BASIX certificate for the development requires to accompany the application.
- (2) A detailed description of the development referred to in subclause (1) (a) (i) must indicate the following matters:
 - (a) for each proposed new building:
 - (i) the number of storeys (including underground storeys) in the building,
 - (ii) the gross floor area of the building (in square metres),
 - (iii) the gross site area of the land on which the building is to be erected (in square metres),
 - (b) for each proposed new residential building:
 - (i) the number of existing dwellings on the land on which the new building is to be erected,
 - (ii) the number of those existing dwellings that are to be demolished in connection with the erection of the new building,
 - (iii) the number of dwellings to be included in the new building,
 - (iv) whether the new building is to be attached to any existing building,
 - (v) whether the new building is to be attached to any other new building,
 - (vi) whether the land contains a dual occupancy,
 - (vii) the materials to be used in the construction of the new building (using the abbreviations set out in clause 7 of this Schedule).
- (3) Appropriate building work plans and specifications referred to in subclause (1) (a) (ii) include the following:
 - (a) detailed plans, drawn to a suitable scale and consisting of a block plan and a general plan, that show:
 - (i) a plan of each floor section, and
 - (ii) a plan of each elevation of the building, and
 - (iii) the levels of the lowest floor and of any yard or unbuilt on area belonging to that floor and the levels of the adjacent ground, and
 - (iv) the height, design, construction and provision for fire safety and fire resistance (if any),
 - (b) Specifications for the development:
 - (i) that describe the construction and materials of which the building is to be built and the method of drainage, sewerage and water supply, and
 - that state whether the materials to be used are new or second-hand and (in the case of second-hand materials) give particulars of the materials to be used,
 - (c) a statement as to how the performance requirements of the *Building Code of Australia* are to be complied with (if an alternative solution, to meet the performance requirements, is to be used),
 - (d) a description of any accredited building product or system sought to be relied on for the purposes of section 79C (4) of the Act,
 - (e) copies of any compliance certificate to be relied on,
 - (f) if the development involves building work to alter, expand or rebuild an existing building, a scaled plan of the existing building,
 - (g) in the case of development to which clause 6A applies, such other matters as any BASIX certificate for the development requires to be included in the plans and specifications.
- (3A) An application for a construction certificate that relates only to fire link conversion need only be accompanied by a document that describes the design and construction, and mode of operation, of the new fire alarm communication link.
- (4) Appropriate subdivision work plans and specifications referred to in subclause (1) (c) include the following:
 - (a) details of the existing and proposed subdivision pattern (including the number of lots and the location of roads),
 - (b) details as to which public authorities have been consulted with as to the provision of utility services to the land concerned,
 - (c) details engineering plans as to the following matters:
 - (i) earthworks,
 - (ii) roadworks,
 - (iii) road pavement,
 - (iv) road furnishings,
 - (v) stormwater drainage,
 - (vi) water supply works,
 - (vii) sewerage works,
 - (viii) landscaping works,
 - (ix) erosion control works.
 - (d) copies of any compliance certificates to be relied on.

6A BASIX certificate required for certain development

- (1) This clause applies to:
 - (a) BASIX affected development, and
 - (b) BASIX optional development in relation to which a person made a development application that has been accompanied by a BASIX certificate or BASIX certificates (despite there being no obligation under clause 2A for it to be so accompanied).
- (2) In addition to the documents required by clause 6, an application for a construction certificate for any development to which this clause applies must also be accompanied by a BASIX certificate or BASIX certificates for the development, being either the BASIX certificate applicable to the development when the relevant development consent was granted or some other BASIX certificate or BASIX certificates that has or have been issued no earlier than 3 months before the date on which the application is made.
- (3) If the proposed development involves the alteration, enlargement or extension of a BASIX affected building that contains more than one dwelling, a separate BASIX certificate is required for each dwelling concerned.

Levy Online Payment Receipt



Building and Construction

SUSAN CRIMMINS 42 MCCARRS CREEK RD CHURCH POINT NSW 2105

Application Details:

Applicant Name:

SUSAN CRIMMINS

Levy Number:

5176324

Application Type:

CC

Application Number:

N0008/17

Approving Authority:

NORTHERN BEACHES COUNCIL-CENTRAL

Work Details:

Site Address:

42 MCCARRS CREEK RD

CHURCH POINT NSW 2105

Value of work:

\$53,350

Levy Due:

\$186.00

Payment Details:

LSC Receipt Number:

296456

Payment Date:

4/08/2017 2:53:22 PM

Bank Payment Reference:

123394645

Levy Paid:

\$186.00

Credit card surcharge:

\$0.74

Total Payment Received:

\$186.74

This plan / document

Construction Certificat:

no. 2017/5909



11 September 2017

SUSAN CRIMMINS 42 MCCARRS CREEK RD CHURCH POINT NSW 2105 ABN 93 646 090 808

**** 13 14 41

🔁 info@longservice.nsw.gov.au

www.longservice.nsw.gov.au

> Level 1, 19-21 Watt Street Gosford NSW 2250

As per your request for a copy of your receipt no. 00301278 dated 11 September 2017, the following information is provided:

Received from: (Name of person or organisation paying for levy)

the amount of

SUSAN CRIMMINS

\$131.00

Payment details:

Direct Depos

\$131.00

being payment for Long Service Levy as detailed below

Levy Payment Form number 5176324

Council/Department/Authority NORTHERN BEACHES COUNCIL-CENTRAL

C.C. Number N0008/17

Work address 42 MCCARRS CREEK RD

CHURCH POINT NSW 2105

Estimated value of work \$144,000.00

Levy payable (No exemption) \$504.00

Total levy paid \$504.00

Credit Card Surcharge (non-refundable) \$0.00

Total Amount Paid \$131.00

Signed:

312938

This plan / document forms part of

Construction Certificate

no. 2017/5909



ABN 93 646 090 808

**** 13 14 41

info@longservice.nsw.gov.au

www.longservice.nsw.gov.au

> Level 1, 19-21 Watt Street Gosford NSW 2250

As per your request for a copy of your receipt no. 00301279 dated 11 September 2017, the following information is provided:

Received from:

(Name of person or organisation paying for levy)

the amount of

SUSAN CRIMMINS

11 September 2017

SUSAN CRIMMINS

42 MCCARRS CREEK RD

CHURCH POINT NSW 2105

\$187.00

Payment details:

Direct Depos

\$187.00

being payment for Long Service Levy as detailed below

Levy Payment Form number

5176324

Council/Department/Authority

NORTHERN BEACHES COUNCIL-CENTRAL

C.C. Number

N0008/17

Work address

42 MCCARRS CREEK RD

CHURCH POINT NSW 2105

Estimated value of work

\$144,000.00

Levy payable (No exemption)

\$504.00

Total levy paid

\$504.00

Credit Card Surcharge (non-refundable)

\$0.00

Total Amount Paid

\$187.00

Signed:

312940

This plan / document forms part of Construction Certificate no. 2017/5909



HBCF Policy No: HBCF17043250

Policy Date:

14/08/2017

statement of cover			
Gary Russell Brook	DON HUTTON INSURANCE BROKERS PTY LTD		
59 Whitby Road	500 FOREST ROAD		
KINGS LANGLEY NSW 2147	PENSHURST NSW 2222		

Note: This document contains an extract of details kept on the HBCF Certificates Register. To confirm the authenticity of this document as proof of a valid contract of insurance, please visit the Certificates Register at www.hbcf.nsw.gov.au. The Register will also list whether any claims have been made on this insurance cover and any other relevant information.

CERTIFICATE IN RESPECT OF INSURANCE RESIDENTIAL BUILDING WORKS BY CONTRACTORS

A contract of insurance complying with sections 92 and 96 of the Home Building Act 1989 (the Act) has been issued by Insurance and Care NSW (icare) which provides services to the NSW Self Insurance Corporation in the management of the Home Building Compensation Fund (HBCF)

In respect of	Single Dwelling Alterations / Additions - Structural			
At				
	42 Mccarrs Creek Road			
	Church Point New South Wales 2105			
Site plan No	NA			
Site plan type	NA			
Homeowner	Susan Crimmins			
Carried out by	Gary Russell Brook			
Builder job No				
Licence number	64101C			
Contract sum	\$55,000.00			
Contract date	22/07/2017			
Premium paid	\$267.74			

Subject to the Act, the Home Building Regulation 2014 and the conditions of the insurance contract, cover will be provided to a beneficiary described in the contract and successors in title to the beneficiary. This Certificate is to be read in conjunction with the policy wording current as at the policy date and available at the Home Building Compensation Fund website at www.hbcf.nsw.gov.au

Certificate No HBCF17043250

Issued on

14/08/2017

Issued by

Residential Builders Underwriting Agency Pty Ltd as agent for Great Lakes Reinsurance (UK) SE

Issued on behalf of NSW Self Insurance Corporation (ABN 97 369 689 650)

GEOTECHNICAL RISK MANAGEMENT POLICY FOR PITTWATER FORM NO. 2 – PART A - To be submitted with detailed design for Construction Certificate

	Development Application forName of Applicant
	Address of site _42 McCARRS CREEK ROAD, CHURCH POINT
<u>PAR</u>	T – A: Declaration made by Structural or Civil Engineer in relation to the incorporation of the Geotechnical issues into the project design
l, –	PETER THOMPSON on behalf of JACK HODGSON CONSULTANTS (trading or company name)
certif the a polic	is the 20 TH SEPTEMBER, 2017 (date) If that I am a Structural or Civil Engineer as defined by the Geotechnical Risk Management Policy for Pittwater - 2009. I am authorised by above organization/company to issue this document and to certify that the organization/company has a current professional indemnity by of at least \$2million. I also certify that I have prepared the below listed structural documents in accordance with the recommendations in the Geotechnical Report for the above development and that
Plea	se mark appropriate box
	the structural design meets the recommendations as set out in the Geotechnical Report or any revision thereto the structural design has considered the requirements set out in the Geotechnical Report for Excavation and Landfill for both the Excavation/construction phase and the final installation in accordance with Clause 3.2 (b)(iv) of the Geotechnical Risk Management Policy
Geo	technical Report Details :
	Report Title: RISK ANALYSIS & MANAGEMENT FOR PROPOSED INCLINAOTR AT 42 McCARRS CREEK ROAD, CHURCH POINT – MR 30879
	Report Date: 3 RD NOVEMBER, 2016
	Author: PETER THOMPSON
	Author's Company/Organisation: JACK HODGSON CONSULTANTS PTY LTD
	Structural Documents list: DRAWING NO 30879-C1 TO C3 DATED 19-9-17 PREPARED BY JACK HODGSON CONSULTANTS
certif addr	also aware that Pittwater Council relies on the processes covered by the Geotechnical Risk Management Policy, including this fication as the basis for ensuring that the geotechnical risk management aspects of the proposed development have been adequately essed to achieve an "Acceptable Risk Management" level for the life of the structure taken as at least 100 years unless otherwise stated ustified.

Name PETER THOMPSON

Chartered Professional Status MIE Aust CPEng

Membership No. 146800

Company JACK HODGSON CONSULTANTS



This plan / document forms part of Construction Certificate no. 2017/5909

GEOTECHNICAL RISK MANAGEMENT POLICY FOR PITTWATER FORM NO. 2 – PART B - To be submitted with detailed design for construction certificate

PART B Declaration made by Geotechnical Engineer or Engineering Geologist and/or Coastal Engineer (where applicable) in relation to the incorporation of the Geotechnical issues into the project design

I,	Peter Thompson	on behalf of	Jack Hodgson Consultants Pty Ltd
	(insert name)		(trading or company name)
on th	nis the 20 TH SEPTEMBER, 2017 (date)		
Polic orga	y for Pittwater - 2009 and I am author	orised by the abound indemnity policy	t and/or Coastal Engineer as defined by the Geotechnical Risk Management or organization/company to issue this document and to certify that the of at least \$2million. I also certify that I have reviewed the design plans and the Stage and that I am satisfied that:
Plea	se mark appropriate box		
\boxtimes	the structural design has considered the	requirements set ou	in the Geotechnical Report or any revision thereto t in the Geotechnical Report for Excavation and Landfill both n in accordance with Clause 3.2 (b)(iv) of the Geotechnical Risk
	Geotechnical Report Details :		
	Report Title: RISK ANALYSIS & CREEK ROAD, CHURCH POIN		IT FOR PROPOSED INCLINED LIFT AT 42 McCARRS
	Report Date: 3 RD NOVEMBER, 20	16	
	Author: PETER THOMPSON		
	Documentation which relates to		
	OCTOBER 2016	ARED BY P R KIN	G & SONS JOB NO: 6416/1 ON 2 SHEETS DATED
	STRUCTURAL ENGINEERING P TO C3 DATED 19-9-17	LANS PREPARED	BY JACK HODGSON CONSULTANTS DWG NO: 30879-C1

I am also aware that Pittwater Council relies on the processes covered by the Geotechnical Risk Management Policy, including this certification as the basis for ensuring that the geotechnical risk management aspects of the proposed development have been adequately addressed to achieve an "Acceptable Risk Management" level for the life of the structure taken as at least 100 years unless otherwise stated and justified.

Signature

Name Peter Thompson

Chartered Professional Status MIE Aust CPEng

Membership No. 146800

Company Jack Hodgson Consultants Pty Ltd

Policy of Operations and Procedures Cou

Council Policy - No 178

This plan / document
Page 22

forms part of

Construction Certificate

no. 2017/5909



Building plan assessment application

Application number: 287919

Property address: 42 Mccarrs Creek Rd, Church Point 2105

Lot details: Lot 16, Deposited Plan 11691

01/08/2017

Dear susan crimmins

Your building plan assessment application has been

APPROVED

This Approval is provided subject to the Conditions and Important Information issued to you by Sydney Water, which you are taken to have accepted by using the approval.

This Approval is based on the information you provided to us through Sydney Water Tap in.

If any of the information you have provided is incorrect or incomplete, Sydney Water may revoke this Approval.

This approval is valid until 01/08/2018 (one year).

ANY QUESTIONS?

Email us swtapin@sydneywater.com.au

Call us 1300 082 746

STRUCTURES

The structures and information you supplied are displayed below.

Structure(s) that will not impact Sydney Water infrastructure

Structure 1 Inclinator 32.0 m x 1.0 m x 2.0 m


This plan / document forms part of Construction Certificate

no. 2017/5909

Structure 1 of 1: Inclinator

Application number: 287919

Property address: 42 Mccarrs Creek Rd, Church Point 2105 Lot details: Lot 16, Deposited Plan 11691



CONDITIONS AND IMPORTANT INFORMATION


Conditions and Important Information


Attention: You must read the information below.

- 1 The approval of your building plan by Sydney Water (Approval) has been generated by an automated system based on the information you have provided to Sydney Water through the Sydney Water Tap in. Sydney Water does not make any representation or give any guarantee, warranty or undertaking (express or implied) as to the currency, accuracy, completeness, effectiveness or reliability of the Approval.
- 2 It is your responsibility to ensure that the information is correct and complete when submitting your building plan for approval through Sydney Water Tap in and, if any of the information is incorrect or incomplete, to resubmit information that is correct and complete. If any of the information that you have provided is incorrect or incomplete, this may result in the revocation of the Approval.
- 3 The Approval is provided on each of the following conditions which you are taken to have accepted by using the Approval. To the fullest extent permitted by law:
 - (a) all conditions and guarantees concerning the Approval (whether as to quality, outcome, fitness, care, skill or otherwise) expressed or implied by statute, common law, equity, trade, custom or usage or otherwise are expressly excluded and to the extent that those statutory guarantees cannot be excluded, the liability of Sydney Water to you is limited to either of the following as nominated by Sydney Water in its discretion, which you agree is your only remedy:
 - i. the supplying of the Approval again; or
 - ii. payment of the cost of having the Approval supplied again;
 - (b) in no event will Sydney Water be liable for, and you release Sydney Water from all Losses arising out of or in connection with you providing incorrect or incomplete information to Sydney Water in connection with the Approval:
 - i. whether arising under statute or in contract, tort or any other legal doctrine, including any negligent act, omission or default (including wilful default) by Sydney Water; and
 - regardless of whether Sydney Water is or ought to have been aware of, or advised of, the possibility of such loss, costs or damages;
 - (c) you will indemnify, defend and hold harmless Sydney Water from and against all Losses of Sydney Water in respect of, or in connection with loss or damage to any property, personal injury (including death or illness of any person), arising out of or in connection with:
 - i. you providing incorrect or incomplete information to Sydney Water in connection with the Approval; or
 - ii. any third party claim against Sydney Water; and
 - (d) you assume all risks associated with the use of the Sydney Water Tap in and Sydney Water websites, including risk to your computer, software or data being damaged by any virus, and you release and discharge Sydney Water from all Losses which might arise in respect of your use of the websites.


- 4 Subject to condition numbered 3(c) in this document, your liability under condition numbered 3(c) in this document is reduced to the extent that the loss, liability, expense or damage:
 - (a) is caused solely and directly by any negligent act or omission of Sydney Water; or
 - (b) could not reasonably be foreseen and was not reasonably within the contemplation of you and Sydney Water at the time of the loss, liability, expense or damage.
- 5 The position of the proposed building/building works in relation to Sydney Water's pipes and structures is satisfactory. You are responsible for, amongst other things:
 - (a) protecting underground structures, including Sydney Water's pipelines, from damage and interference;
 - (b) maintaining minimum clearances between Sydney Water's structures and structures belonging to others;
 - (c) preventing loss or damage to any property, personal injury (including death or illness of any person) arising out of or in connection with you providing incorrect or incomplete information to Sydney Water in connection with the Approval;
 - (d) repairing or making good loss or damage to any property or the environment arising out of or in connection with you providing incorrect or incomplete information to Sydney Water in connection with the Approval;
 - (e) ensuring that connections to Sydney Water's sewer, watermain or stormwater are only be made following the issue of a permit to a licensed plumber/drainer;
 - (f) ensuring that all proposed fittings will drain to Sydney Water's sewer;
 - (g) ensuring that all plumbing and/or drainage Work is to be carried out in accordance with the NSW Code of Practice, AS 3500 and the Sydney Water Act 1994;
 - ensuring that gullies, inspection shafts and boundary traps are not placed under any roof, balcony, verandah, floor or other cover unless otherwise approved by Sydney Water; and
 - notifying Sydney Water immediately of any damage caused or threat of damage to Sydney Water's structures.
- "Sydney Water" means Sydney Water Corporation and its employees, agents, representatives and contractors. References to "you" include references to your employees, agents, representatives, contractors, executors, administrators, successors, substitutes, assigns and anyone else using the Approval. References to "Losses" means all liabilities, losses, damages, expenses, compensations, fines, penalties, charges and costs (including legal costs on a full indemnity basis and whether incurred or awarded) of any kind or nature however they arise and whether they are present or future, fixed or unascertained, actual or contingent and including any loss of profits, loss of revenue or loss of opportunity. To the extent of any inconsistency, the conditions numbered 1 to 6 in this document will prevail over any other information provided or made available to you by Sydney Water.


In an emergency, or to notify Sydney Water of damage or threats to its structures, call 13 20 92 (24 hours, 7 days).






3.5 3.0 2.5 2.0 1.5 1.0 0.5 0.7 0.8 WIDTH OF FOOTING














INCLINATOR FOOTING DETAILS







TYPICAL FOUNDATION BOLT DETAIL



and support chairs supplied by P.R KING and SONS PTY LTD

R6 Ties at 200 Cover 65.

This plan / document forms part of Construction Certificate

2017/5909 no.

STEELWORK NOTES

1. Fabricate and erect all structural steelwork in accordance with AS 36601, AS 4100, AS 1554 and the Spacification.

2. Do not obtain dimensions by scaling the structural elements.

3. Chip all welds free of slag.

4. All steelwork to be Hot Dipped Galvanised. Unless Otherwise Noted.

5. Unless otherwise noted use
a) 6mm continuous fillet weld
b) 10mm thick gusset, fin and end plates, weld all round.
c) 16mm dia. 4.6.7 s botts

6. Minimum end bearing 150mm.

Description

TimBER NOTES:

I. All work linduding bracing, wind bracing & tie downs) shall be carried out in accordance with AS 36801, AS 1694-2, and the specification.

Ref 1201 and the specification.

Ref 1201 and the specification and the specification for all timber sizes or these to brawings.

All timber sizes on the specification for all timber sizes of Coun voins, pockets, knots holes or splits within 255mm of any connection specification for preservatives and finishes to timbers.

All botts, nuts, washers and timber connectors shall be hot dip galvanised unless noted otherwise.

B. All F5 timber shown are nominal sizes only.

CONCRETE & BLOCK NOTES

CONCRETE & BLOCK NOTES

1. All concrete work to be in accordance with AS 3600.

2. Fo Refer to table.

3. Maximum aggregate size = 20 for footings, slabs & beams.

10 for block filling.

4. Slump = 80.

5. All concrete, including block filling, to be vibrated.

6. Slabs to be kept damp for at least 14 days after placing.

7. All blockwork to be in accordance with SAA Masonry Code AS 3700.

8. All cavities of block work to be thoroughly cleaned out, using knock out blocks or other suitable means, before filling with grout or concrete.

8. All cavities of block work to be thoroughly cleaned out, using knock out blocks or other suitable means, before Silling with grout or concrete.

9. 200 & 300 blocks to be hollow retaining wall blocks with a characteristic strength of 15 MPa.

10. Reinforcing Steel to comply with AS./NZS 467t2001, and to be D500N unless noted otherwise, (where 500 = strength grade in megapascals & N = Normal ductility class).

Steel Reinforcement to be cut & bent in accordance with AS 3600. It bar chairs to be no more than 800m centre to centre spacings.

12. Reinforcement to be tided at every other intersection minimum.

13. Metal roofing being used as formwork (not Bondeck or similar). Depth of Slab must be taken from the Top of the Roof Rib. Spacified bottom cover must be taken from the Top of the Roof Rib. Appaced to the cover must be taken from the Top of the Roof Rib.

14. Moisture Vapour Membrane to be 200 Microns Hibik.

15. UV. Resistant and to be in accordance with AS 2670-1998. Acceptable manufacturers and processors of steel reinforcement must hold a valid certificate of approval, issued by the Australian Certification Authority for Reinforcing Steel Lit (ACRS), or to an equivalent certification system as may be approved in writing by the specifier. Evidence of compliance withith clause must be obtained when the contract bids are received. Flament Cover (mm) Fo at 28 days

Cigiliani	Cover minn)		FC at 20 days	
	Protected	Exposed	Protected	Exposed
Plers	1 6	35	25	MPa
Footings	5	50	25 MPa	
Block Filling	refer t	o detall	25	MPa
Slab on Ground			32 MPa	32 MPa
- Top	30	45		
- Bottom				
Beams	50	50	40 MPa	40 MPa
Columns	30	45	40 MPa	40 MPa
Slabs	30	45	40 MPa	40 MPa
Walls	30	45	40 MPa	40 MPa

IMPORTANCE OF CURING CONCRETE



No. Amendment

PLAN OR DOCUMENT CERTIFICATION

am a qualified......CIVII. GEOTECHNICAL & STRUCTURAL ENGINEER... hold the following qualifications or licence No...B.Eng.Sc......M.I.E. Aust.....

Further I am appropriately qualified to certify this component of the proj I hereby state that these plans or details comply with the conditions of development consent, the provisions of the Building Code of Australia.

A.S.1170., A.S.1170.1, A.S.1170.2, A.S.1684., A.S.2870.1, A.S.3500., A.S.3600, A.S. 3700., A.S.4100 & A.S.1163. On behalf of Jack Hodgson Consultants

Name Date Signature

INCLINATOR RAIL AND LANDING DETAILS

PROPOSED INCLINATOR

Our design and drawings are based upon and derived from information fincluding levels, surveys, stol provided by the owner/architect/designer/builder (PR king and Sone, PTY LTD. Plan 64(8/10 Jats: OCT 20/8) Should the Information provided to us be found to be deficient, unreliable, incorrect or inaccurate then our design/drawings may require modification. We take no responsibility for verifying the accuracy of the Information that forms the basis of our brief and it is your obligation to verify it prior to the commencement of building operations.


The Structural Details shown on this Drawing are NOT to change under any ofcommencement.

any circumstance. NO Certificate will be Issued for work NOT in accordance with the Drawing

JACK HODGSON CONSULTANTS PTY, LIMTED, onsulting Civil, Geotechnical, and Structural Engineers. 20.6 s. duble Avenus, Warfewood, P.O. Box 388 p-bat Code 1860. elephone (02) 9979 6733 Facstrate (02) 9979 6828. mathor/elachodepancomanu workswaylachodepancomanu was ACN. 053 405

GH MJC 30879-*GH GH

19 SEPTEMBER 2017 Scale £100





Dilapidation Inspection Report

Inspection Date: Mon, 14 Aug 2017

Property Address: 40 Mccarrs Creek Rd, Church Point NSW 2105,

Australia



Contents

The parties

Section A Results of inspection - summary

Section B General

Section C Accessibility

Section D Significant items

Section E Additional comments

Section F Annexures to this report

Definitions to help you better understand this report

Terms on which this report was prepared

Special conditions or instructions

If you have any queries with this report or require further information, please do not hesitate to contact the person who carried out the inspection.

This Report contains reference to material that is the copyright of Standards Australia. That content is reproduced under agreement with SAI Global to Jim's Building Inspections (Australia).

The Parties

Name of Client:	Sue Crimmins
Name of Principal (if applicable):	External Only South
Job Address:	40 Mccarrs Creek Rd, Church Point NSW 2105, Australia
Client's Email Address:	scrimmins9@gmail.com
Client's Phone Number:	0414499463
Consultant:	Tiho Lerota Ph: 0401 300 056 Email: mosman@jimsbuildinginspections.com.au
	287867C
Company Name:	Jim's Building Inspections (Mosman)
Company Address and Postcode:	,
Company Email:	mosman@jimsbuildinginspections.com.au
Company Contact Numbers:	0401 300 056

Special conditions or instructions

A report may be conditional on information provided by the person, agents or employees of the person requesting the report, apparent concealment of possible defects and a range of other factors.

The following apply: Refer summary at end of report

Section A Results of inspection - summary

A summary of your inspection is outlined below; please also refer to the Report.



Additional specialist inspections:

- Not Applicable

In summary the building, compared to others of similar age and construction is in the condition documented in this report.

Section B General

General description of the property

Building Type:	Residential, Detached
Number of Storeys:	Double
Main building – floor construction:	N/A
Main building – wall construction:	N/A
Main building – roof construction:	N/A
Other timber building elements:	N/A
Other building elements:	N/A
Occupancy status:	Unoccupied
Furnished:	Furnished
Strata or company title properties:	No
Orientation (to establish the way the property was viewed):	West
Prevailing weather conditions at the time of inspection:	Fine

Section C Accessibility

Areas Inspected

The following areas were inspected. As documented in your Pre-Inspection Agreement, obstructions and limitations to the accessible areas for inspection are to be expected in any inspection. Refer also to our listing of obstructions and limitations.

- Exterior
- The Site

The inspection excludes areas which are affected by obstructions or where access is limited or unsafe. We do not move obstructions and building defects may not be obvious unless obstructions or unsafe conditions are removed to provide access.

The following areas were inaccessible:

- Not Applicable

Any areas which are inaccessible at the time of inspection present a high risk for undetected building defects. The client is strongly advised to make arrangements to access inaccessible areas urgently.

Obstructions and Limitations

Building defects may be concealed by the following obstructions which prevented full inspection:

- Not Applicable

The presence of obstructions increases the risk of undetected defects. The client should make arrangement to remove obstructions where ever possible and re-inspect these areas as a matter of urgency. See also overall risk rating for undetected defects.

Undetected defect risk

A risk rating is provided to help you understand the degree to which accessibility issues and the presence of obstructions have limited the scope of the inspection.

The risk of undetected defects is: Medium

When the risk of undetected defects is high we strongly recommend further inspection once access is provided or if the obstruction can be removed. Contact us for further advice.

Section D Significant Items

Safety Hazard

No evidence was found.

Major Defect

No evidence was found.

Minor Defect

Defects 3.01

Building: Yard

Location: Yard - Side > Rear Left

Finding: Concrete paving - Cracking [Dilapidation]

Information: Cracking to the paving in this area was identified at the time of inspection.

This type of cracking is often consistent with general dilapidation of the property, and may

continue to develop if left unmaintained.

Frequent monitoring should be carried out to identify any further damage.






Section D Significant Items







Defects 3.02

Building: Yard

Location: Yard - Side > Centre Left

Finding: Concrete paving - Cracking [Dilapidation]

Information: Cracking to the paving in this area was identified at the time of inspection.

This type of cracking is often consistent with general dilapidation of the property, and may

continue to develop if left unmaintained.

Frequent monitoring should be carried out to identify any further damage.









Section D Significant Items

Defects 3.03

Building: Yard

Location: Yard - Front > Front Left

Finding: Concrete paving - Cracking [Dilapidation]

Information: Cracking to the paving in this area was identified at the time of inspection.


This type of cracking is often consistent with general dilapidation of the property, and may

continue to develop if left unmaintained.

Frequent monitoring should be carried out to identify any further damage.









Section D Significant Items

D4 Further Inspections

We advise that you seek additional specialist inspections from a qualified and, where appropriate, licensed -

- Not Applicable

Jim's Building Inspections can put you in contact with qualified and licensed providers of these and other trades services. Please contact your inspector for recommendations, or visit www.jims.net.

D5 Conclusion - Assessment of overall condition of property

Dilapidation report - neighbouring property 40 McCarrs Rd Church Point north side of proposed works at number 42 McCarrs Rd Church Point.

Areas noted within report with reference to minor cracking to concrete surfaces.

All inspected areas where accessible for inspection although expected obstructions were present which you should take note of.

This report must be read in full to clearly understand all items identified as defects listed within the report.

For further information, advice and clarification please contact Tiho Lerota on 0401 300 056

Section E Attachments and Further Comments

The following items were noted as - For your information

Noted Item

Building: Yard

Location: Yard - Side > Rear Left
Finding: Additional Photos

Information: Additional photos are provided for your general reference. Arrows have been included to

highlight areas of importance.

Please discuss these photos with your building consultant for clarification.















Noted Item

Building: Yard

Location: Yard - Side > Front Left
Finding: Additional Photos

Information: Additional photos are provided for your general reference. Arrows have been included to

highlight areas of importance.

Please discuss these photos with your building consultant for clarification.











Noted Item

Building: Yard

Location: Yard - Side > Centre Left

Finding: Additional Photos

Information: Additional photos are provided for your general reference. Arrows have been included to

highlight areas of importance.

Please discuss these photos with your building consultant for clarification.





















Noted Item

Building: Yard

Location: Yard - Side > Rear Left
Finding: Additional Photos

Information: Additional photos are provided for your general reference. Arrows have been included to

highlight areas of importance.

Please discuss these photos with your building consultant for clarification.



















Noted Item

Building: Main Building

Location: Exterior walls - left side

Finding: Additional Photos

Information: Additional photos are provided for your general reference. Arrows have been included to

highlight areas of importance.

Please discuss these photos with your building consultant for clarification.













Noted Item

Building: Yard

Location: Yard - Back
Finding: Additional Photos

Information: Additional photos are provided for your general reference. Arrows have been included to

highlight areas of importance.

Please discuss these photos with your building consultant for clarification.





Noted Item

Building: Garage
Location: > Front Left
Finding: Additional Photos

Information: Additional photos are provided for your general reference. Arrows have been included to

highlight areas of importance.

Please discuss these photos with your building consultant for clarification.







Definitions to help you better understand this report

Access hole (cover) An opening in flooring or ceiling or other part of a structure (such as service hatch, removable

panel) to allow for entry to carry out an inspection, maintenance or repair.

Accessible area An area of the site where sufficient, safe and reasonable access is available to allow inspection

within the scope of the inspection.

Appearance defect Fault or deviation from the intended appearance of a building element.

Building element Portion of a building that, by itself or in combination with other such parts, fulfils a characteristic

function. NOTE: For example supporting, enclosing, furnishing or servicing building space.

Client The person or other entity for whom the inspection is being carried out.

Defect Fault or deviation from the intended condition of a material, assembly, or component.

Dilapidation The state or process of falling into decay or being in disrepair.

Inspection Close and careful scrutiny of a building carried out without dismantling, in order to arrive at a

reliable conclusion as to the condition of the building.

Inspector Person or organisation responsible for carrying out the inspection.

Limitation Any factor that prevents full or proper inspection of the building.

Major defect A defect of sufficient magnitude where rectification has to be carried out in order to avoid unsafe

conditions, loss of utility or further deterioration of the property.

Minor defect A defect other than a major defect.

Roof space Space between the roof covering and the ceiling immediately below the roof covering.

Serviceability defect Fault or deviation from the intended serviceability performance of a building element.

Significant item An item that is to be reported in accordance with the scope of the inspection.

Site Allotment of land on which a building stands or is to be erected.

Structural defect Fault or deviation from the intended structural performance of a building element.

Structural element Physically distinguishable part of a structure. NOTE: For example wall, columns, beam, connection.

Subfloor space Space between the underside of a suspended floor and the ground.

SERVICE As requested by the Client, the inspection carried out by the Building Inspection Consultant ("the Consultant") was a "Dilapidation Inspection Report". A Pre-Inspection Agreement was issued for this service and forms part of the service agreement.

PURPOSE The purpose of this inspection is to provide advice to the client or other interested party regarding the condition of the property at the time of inspection. It serves as a baseline for comparison prior to planned construction or civil engineering works in areas adjoining or near to the property inspected.

SCOPE OF INSPECTION The inspection shall comprise visual assessment of the property and limited assessment of serviceability to identify major defects, urgent and serious safety hazards and to document the condition of the property at the time of inspection. An estimate of the costs of rectification of defects is not required in an inspection report.

The inspection was limited to Readily Accessible Areas of the Building and Site. The Client shall arrange right of entry, facilitate physical entry and supply necessary information to enable the inspector to undertake the inspection and prepare a report. The Inspector is not responsible for arranging entry to property or parts of the property, where reasonable access or entry is denied those areas are excluded from and do not form part of the inspection.

Should re-inspection be required after the completion of construction works you should separately re-engage the Consultant

ACCEPTANCE CRITERIA Unless noted in "Special Conditions or Instructions", the building being inspected was compared with a similar building. To the Consultant's knowledge the similar building used for comparison was constructed in accordance with generally accepted practice at the time of construction and which has been maintained such that there is no significant loss of strength and serviceability.

A report may be conditional on the following:

- (a) Information provided by the person, the employees or agents of the person requesting the report.
- (b) Apparent concealment of possible defects.
- (c) Any other factor limiting the preparation of the report.

EXTENT OF REPORTING

Significant items to be reported are as follows:

- (a) Major defects.
- (b) A documentation of the extent of minor defects.
- (c) Any major defect that is an urgent and serious safety hazard.

LIMITATIONS

The Client acknowledges:

- 1. That this Report is prepared in accordance with AS 4349-2007 but that it is not a Certificate of Compliance of the property within the requirements of any Act, regulation, ordinance, local law or by-law and is not a warranty against problems developing in the future.
- 2. This Report does not include the inspection and assessment of matters outside the scope of the requested inspection and report.
- 3. The inspection only covered the Readily Accessible Areas of the Building and Site. The inspection did not include

areas which were inaccessible, not readily accessible, and unsafe to access or obstructed at the time of inspection. Obstructions are defined as any condition or physical limitation which inhibits or prevents inspection and may include - but are not limited to - roofing, fixed ceilings, wall linings, floor coverings, fixtures, fittings, furniture, clothes, stored articles/materials, thermal insulation, sarking, pipe/duct work, builder's debris, vegetation, pavements or earth.

4. This Report has been produced for the use of the Client. The Consultant or their firm or company are not liable for any reliance placed on this report by any third party.

EXCLUSIONS

This report excludes assessment of: Footings below ground, concealed damp proof course, electrical installations, concealed plumbing, adequacy of roof drainage, gas fittings and fixtures, air-conditioning, automatic garage doors, pools and related equipment, alarm systems, operation of fireplaces and chimneys, flues and solid fuel heaters, alarm and intercom systems, soft floor coverings, appliances, paint coating, health hazards, timber and metal framing size and adequacy, concealed tie downs and bracing, timber pest activity, other mechanical or electrical equipment such as soil conditions, control joints, sustainable development provisions, concealed timber frames, landscaping, rubbish, floor coverings, furniture and accessories, stored items, insulation, environmental matters or lighting and energy efficiency.

IMPORTANT SAFETY INFORMATION - SMOKE DETECTORS

We cannot comment on smoke detector installation and testing as it is not within the scope of this report and requires specialist inspection services. It is however strongly recommended that all existing detectors in the property be tested prior to occupation and advice be sought as to the suitability of their number, placement and operation.

IMPORTANT SAFETY INFORMATION - ASBESTOS

We cannot comment on the presence or absence of Asbestos from this building as it is not within the scope of this report and requires specialist inspection services. It is however strongly advised that the presence of Asbestos be presumed until otherwise definitely known.

Asbestos containing materials may include sheet type building materials, roofing materials, insulations and linings and more. Especially in buildings that were built or modified pre-1992 further inspection should be undertaken prior to works like renovations, extensions, repairs and maintenance or where any materials which could contain Asbestos become damaged or worn.

An Asbestos Inspection And Condition Audit is always advised.

IMPORTANT SAFETY INFORMATION - SAFETY GLASS

Glazing standards in contemporary or recently constructed buildings are governed by the Building Code of Australia (National Construction Code) and will almost always be constructed using glazing designed to minimise injury if impacted or broken. Glazing in older homes is highly unlikely to be 'Safety Glass' and may cause significant injury if damaged. Exercise care and caution around glass in older homes in particular.

This Report only records the observations and conclusions of the Consultant about the readily observable state of the property at the time of inspection.

If the Client has any doubt about the purpose, scope and acceptance criteria on which this Report was based



please discuss your concerns with the Consultant on receipt of this Report.

The Client acknowledges that, unless stated otherwise, the Client as a matter of urgency should implement any recommendation or advice given in this Report.

Privacy Policy:

We value your personal information, we will ensure it is secure and never share or sell your personal details and contact information. We do however use data collected during inspections for research, commercial, training and educational purposes.

For more information please review our Privacy Policy online at www.jimsbuildinginspections.com.au.

Compliments, Complaints and Concerns:

Your feedback, both positive and negative, can assist us to improve our services. We encourage you to please contact us with any compliments or concerns directly and as soon as you are able.

The process for managing customer feedback is documented below:

- 1. Contact your inspector directly to provide feedback or make any complaint as soon as you are able.
- 2. If your inspector cannot resolve it or it involves our insurers they will escalate it to their Regional Franchisor (Manager) and / or insurer as applicable.
- 3. You can also contact their Regional Franchisor (Manager) directly on 131 546 ask to speak to your Inspectors Regional Franchisor (Manager) or email info@jimsbuildinginspections.com.au

Should you have any queries about our terms and conditions, the inclusions and exclusions of this report please contact your Inspector.



Dilapidation Inspection Report

Inspection Date: Mon, 14 Aug 2017

Property Address: 40/42/44 McCarrs Rd Church Point NSW



Contents

The parties

Section A Results of inspection - summary

Section B General

Section C Accessibility

Section D Significant items

Section E Additional comments

Section F Annexures to this report

Definitions to help you better understand this report

Terms on which this report was prepared

Special conditions or instructions

If you have any queries with this report or require further information, please do not hesitate to contact the person who carried out the inspection.

This Report contains reference to material that is the copyright of Standards Australia. That content is reproduced under agreement with SAI Global to Jim's Building Inspections (Australia).

The Parties

Name of Client:	Sue Crimmins	
Name of Principal (if applicable):	Council Assets -	
Job Address:	40/42/44 McCarrs Rd Church Point NSW	
Client's Email Address:	scrimmins9@gmail.com	
Client's Phone Number:	0414499463	
Consultant:	Tiho Lerota Ph: 0401 300 056 Email: mosman@jimsbuildinginspections.com.au	
	287867C	
Company Name:	Jim's Building Inspections (Mosman)	
Company Address and Postcode:	1	
Company Email:	mosman@jimsbuildinginspections.com.au	
Company Contact Numbers:	0401 300 056	

Special conditions or instructions

A report may be conditional on information provided by the person, agents or employees of the person requesting the report, apparent concealment of possible defects and a range of other factors.

The following apply: Refer summary at end of report

Section A Results of inspection - summary

A summary of your inspection is outlined below; please also refer to the Report.

	Found	Not Found
Safety Hazard		✓
Major Defect		✓
Minor Defect		✓

Additional specialist inspections:

- Not Applicable

In summary the building, compared to others of similar age and construction is in good condition

Section B General

General description of the property

Building Type:	Commercial
Number of Storeys:	
Main building – floor construction:	N/A
Main building – wall construction:	N/A
Main building – roof construction:	N/A
Other timber building elements:	N/A
Other building elements:	N/A
Occupancy status:	Unoccupied
Furnished:	Unfurnished
Strata or company title properties:	No
Orientation (to establish the way the property was viewed):	East
Prevailing weather conditions at the time of inspection:	Fine

Section C Accessibility

Areas Inspected

The following areas were inspected. As documented in your Pre-Inspection Agreement, obstructions and limitations to the accessible areas for inspection are to be expected in any inspection. Refer also to our listing of obstructions and limitations.

- Exterior
- The Site

The inspection excludes areas which are affected by obstructions or where access is limited or unsafe. We do not move obstructions and building defects may not be obvious unless obstructions or unsafe conditions are removed to provide access.

The following areas were inaccessible:

- Not Applicable

Any areas which are inaccessible at the time of inspection present a high risk for undetected building defects. The client is strongly advised to make arrangements to access inaccessible areas urgently.

Obstructions and Limitations

Building defects may be concealed by the following obstructions which prevented full inspection:

- Not Applicable

The presence of obstructions increases the risk of undetected defects. The client should make arrangement to remove obstructions where ever possible and re-inspect these areas as a matter of urgency. See also overall risk rating for undetected defects.

Undetected defect risk

A risk rating is provided to help you understand the degree to which accessibility issues and the presence of obstructions have limited the scope of the inspection.

The risk of undetected defects is: Medium

When the risk of undetected defects is high we strongly recommend further inspection once access is provided or if the obstruction can be removed. Contact us for further advice.

Section D Significant Items

Safety Hazard

No evidence was found.

Major Defect

No evidence was found.

Minor Defect

No evidence was found.

D4 Further Inspections

We advise that you seek additional specialist inspections from a qualified and, where appropriate, licensed -

- Not Applicable

Jim's Building Inspections can put you in contact with qualified and licensed providers of these and other trades services. Please contact your inspector for recommendations, or visit www.jims.net.

D5 Conclusion - Assessment of overall condition of property

Dilapidation report -Council Assets street frontage at 40, 42 and 44 McCarrs Creek Rd Church Point.

All inspected areas where accessible for inspection although expected obstructions were present which you should take note of.

This report must be read in full to clearly understand all items identified as defects listed within the report.

For further information, advice and clarification please contact Tiho Lerota on 0401 300 056

Section E Attachments and Further Comments

The following items were noted as - For your information

Noted Item

Building:

Location: Property No. 40 > Front

Finding: Additional Photos

Information: Additional photos are provided for your general reference. Arrows have been included to

highlight areas of importance.

Please discuss these photos with your building consultant for clarification.















Noted Item

Building:

Location: Property No. 42 > Front

Finding: Additional Photos

Information: Additional photos are provided for your general reference. Arrows have been included to

highlight areas of importance.


Please discuss these photos with your building consultant for clarification.















































Noted Item

Building:

Location: Property No. 44 > Front Finding: Additional Photos

Information: Additional photos are provided for your general reference. Arrows have been included to

highlight areas of importance.

Please discuss these photos with your building consultant for clarification.

















Definitions to help you better understand this report

Access hole (cover) An opening in flooring or ceiling or other part of a structure (such as service hatch, removable

panel) to allow for entry to carry out an inspection, maintenance or repair.

Accessible area An area of the site where sufficient, safe and reasonable access is available to allow inspection

within the scope of the inspection.

Appearance defect Fault or deviation from the intended appearance of a building element.

Building element Portion of a building that, by itself or in combination with other such parts, fulfils a characteristic

function. NOTE: For example supporting, enclosing, furnishing or servicing building space.

Client The person or other entity for whom the inspection is being carried out.

Defect Fault or deviation from the intended condition of a material, assembly, or component.

Dilapidation The state or process of falling into decay or being in disrepair.

Inspection Close and careful scrutiny of a building carried out without dismantling, in order to arrive at a

reliable conclusion as to the condition of the building.

Inspector Person or organisation responsible for carrying out the inspection.

Limitation Any factor that prevents full or proper inspection of the building.

Major defect A defect of sufficient magnitude where rectification has to be carried out in order to avoid unsafe

conditions, loss of utility or further deterioration of the property.

Minor defect A defect other than a major defect.

Roof space Space between the roof covering and the ceiling immediately below the roof covering.

Serviceability defect Fault or deviation from the intended serviceability performance of a building element.

Significant item An item that is to be reported in accordance with the scope of the inspection.

Site Allotment of land on which a building stands or is to be erected.

Structural defect Fault or deviation from the intended structural performance of a building element.

Structural element Physically distinguishable part of a structure. NOTE: For example wall, columns, beam, connection.

Subfloor space Space between the underside of a suspended floor and the ground.

SERVICE As requested by the Client, the inspection carried out by the Building Inspection Consultant ("the Consultant") was a "Dilapidation Inspection Report". A Pre-Inspection Agreement was issued for this service and forms part of the service agreement.

PURPOSE The purpose of this inspection is to provide advice to the client or other interested party regarding the condition of the property at the time of inspection. It serves as a baseline for comparison prior to planned construction or civil engineering works in areas adjoining or near to the property inspected.

SCOPE OF INSPECTION The inspection shall comprise visual assessment of the property and limited assessment of serviceability to identify major defects, urgent and serious safety hazards and to document the condition of the property at the time of inspection. An estimate of the costs of rectification of defects is not required in an inspection report.

The inspection was limited to Readily Accessible Areas of the Building and Site. The Client shall arrange right of entry, facilitate physical entry and supply necessary information to enable the inspector to undertake the inspection and prepare a report. The Inspector is not responsible for arranging entry to property or parts of the property, where reasonable access or entry is denied those areas are excluded from and do not form part of the inspection.

Should re-inspection be required after the completion of construction works you should separately re-engage the Consultant

ACCEPTANCE CRITERIA Unless noted in "Special Conditions or Instructions", the building being inspected was compared with a similar building. To the Consultant's knowledge the similar building used for comparison was constructed in accordance with generally accepted practice at the time of construction and which has been maintained such that there is no significant loss of strength and serviceability.

A report may be conditional on the following:

- (a) Information provided by the person, the employees or agents of the person requesting the report.
- (b) Apparent concealment of possible defects.
- (c) Any other factor limiting the preparation of the report.

EXTENT OF REPORTING

Significant items to be reported are as follows:

- (a) Major defects.
- (b) A documentation of the extent of minor defects.
- (c) Any major defect that is an urgent and serious safety hazard.

LIMITATIONS

The Client acknowledges:

- 1. That this Report is prepared in accordance with AS 4349-2007 but that it is not a Certificate of Compliance of the property within the requirements of any Act, regulation, ordinance, local law or by-law and is not a warranty against problems developing in the future.
- 2. This Report does not include the inspection and assessment of matters outside the scope of the requested inspection and report.
- 3. The inspection only covered the Readily Accessible Areas of the Building and Site. The inspection did not include

areas which were inaccessible, not readily accessible, and unsafe to access or obstructed at the time of inspection. Obstructions are defined as any condition or physical limitation which inhibits or prevents inspection and may include - but are not limited to - roofing, fixed ceilings, wall linings, floor coverings, fixtures, fittings, furniture, clothes, stored articles/materials, thermal insulation, sarking, pipe/duct work, builder's debris, vegetation, pavements or earth.

4. This Report has been produced for the use of the Client. The Consultant or their firm or company are not liable for any reliance placed on this report by any third party.

EXCLUSIONS

This report excludes assessment of: Footings below ground, concealed damp proof course, electrical installations, concealed plumbing, adequacy of roof drainage, gas fittings and fixtures, air-conditioning, automatic garage doors, pools and related equipment, alarm systems, operation of fireplaces and chimneys, flues and solid fuel heaters, alarm and intercom systems, soft floor coverings, appliances, paint coating, health hazards, timber and metal framing size and adequacy, concealed tie downs and bracing, timber pest activity, other mechanical or electrical equipment such as soil conditions, control joints, sustainable development provisions, concealed timber frames, landscaping, rubbish, floor coverings, furniture and accessories, stored items, insulation, environmental matters or lighting and energy efficiency.

IMPORTANT SAFETY INFORMATION - SMOKE DETECTORS

We cannot comment on smoke detector installation and testing as it is not within the scope of this report and requires specialist inspection services. It is however strongly recommended that all existing detectors in the property be tested prior to occupation and advice be sought as to the suitability of their number, placement and operation.

IMPORTANT SAFETY INFORMATION - ASBESTOS

We cannot comment on the presence or absence of Asbestos from this building as it is not within the scope of this report and requires specialist inspection services. It is however strongly advised that the presence of Asbestos be presumed until otherwise definitely known.

Asbestos containing materials may include sheet type building materials, roofing materials, insulations and linings and more. Especially in buildings that were built or modified pre-1992 further inspection should be undertaken prior to works like renovations, extensions, repairs and maintenance or where any materials which could contain Asbestos become damaged or worn.

An Asbestos Inspection And Condition Audit is always advised.

IMPORTANT SAFETY INFORMATION - SAFETY GLASS

Glazing standards in contemporary or recently constructed buildings are governed by the Building Code of Australia (National Construction Code) and will almost always be constructed using glazing designed to minimise injury if impacted or broken. Glazing in older homes is highly unlikely to be 'Safety Glass' and may cause significant injury if damaged. Exercise care and caution around glass in older homes in particular.

This Report only records the observations and conclusions of the Consultant about the readily observable state of the property at the time of inspection.

If the Client has any doubt about the purpose, scope and acceptance criteria on which this Report was based



please discuss your concerns with the Consultant on receipt of this Report.

The Client acknowledges that, unless stated otherwise, the Client as a matter of urgency should implement any recommendation or advice given in this Report.

Privacy Policy:

We value your personal information, we will ensure it is secure and never share or sell your personal details and contact information. We do however use data collected during inspections for research, commercial, training and educational purposes.

For more information please review our Privacy Policy online at www.jimsbuildinginspections.com.au.

Compliments, Complaints and Concerns:

Your feedback, both positive and negative, can assist us to improve our services. We encourage you to please contact us with any compliments or concerns directly and as soon as you are able.

The process for managing customer feedback is documented below:

- 1. Contact your inspector directly to provide feedback or make any complaint as soon as you are able.
- 2. If your inspector cannot resolve it or it involves our insurers they will escalate it to their Regional Franchisor (Manager) and / or insurer as applicable.
- 3. You can also contact their Regional Franchisor (Manager) directly on 131 546 ask to speak to your Inspectors Regional Franchisor (Manager) or email info@jimsbuildinginspections.com.au

Should you have any queries about our terms and conditions, the inclusions and exclusions of this report please contact your Inspector.




Dilapidation Inspection Report

Inspection Date: Mon, 14 Aug 2017

Property Address: 42 Mccarrs Creek Rd, Church Point NSW 2105,

Australia



Contents

The parties

Section A Results of inspection - summary

Section B General

Section C Accessibility

Section D Significant items

Section E Additional comments

Section F Annexures to this report

Definitions to help you better understand this report

Terms on which this report was prepared

Special conditions or instructions

If you have any queries with this report or require further information, please do not hesitate to contact the person who carried out the inspection.

This Report contains reference to material that is the copyright of Standards Australia. That content is reproduced under agreement with SAI Global to Jim's Building Inspections (Australia).

The Parties

Name of Client:	Sue Crimmins	
Name of Principal (if applicable):	Waterfront Crown	
Job Address:	42 Mccarrs Creek Rd, Church Point NSW 2105, Australia	
Client's Email Address:	scrimmins9@gmail.com	
Client's Phone Number:	0414499463	
Consultant:	Tiho Lerota Ph: 0401 300 056 Email: mosman@jimsbuildinginspections.com.au	
	287867C	
Company Name:	Jim's Building Inspections (Mosman)	
Company Address and Postcode:	,	
Company Email:	mosman@jimsbuildinginspections.com.au	
Company Contact Numbers:	0401 300 056	

Special conditions or instructions

A report may be conditional on information provided by the person, agents or employees of the person requesting the report, apparent concealment of possible defects and a range of other factors.

The following apply: Refer summary at end of report

Section A Results of inspection - summary

A summary of your inspection is outlined below; please also refer to the Report.

	Found	Not Found
Safety Hazard		✓
Major Defect		✓
Minor Defect		✓

Additional specialist inspections:

- Not Applicable

In summary the building, compared to others of similar age and construction is in good condition

Section B General

General description of the property

Building Type:	Residential, Detached
Number of Storeys:	Double
Main building – floor construction:	N/A
Main building – wall construction:	N/A
Main building – roof construction:	N/A
Other timber building elements:	N/A
Other building elements:	N/A
Occupancy status:	Occupied
Furnished:	Furnished
Strata or company title properties:	No
Orientation (to establish the way the property was viewed):	West
Prevailing weather conditions at the time of inspection:	Fine

Section C Accessibility

Areas Inspected

The following areas were inspected. As documented in your Pre-Inspection Agreement, obstructions and limitations to the accessible areas for inspection are to be expected in any inspection. Refer also to our listing of obstructions and limitations.

- Exterior
- The Site

The inspection excludes areas which are affected by obstructions or where access is limited or unsafe. We do not move obstructions and building defects may not be obvious unless obstructions or unsafe conditions are removed to provide access.

The following areas were inaccessible:

- Not Applicable

Any areas which are inaccessible at the time of inspection present a high risk for undetected building defects. The client is strongly advised to make arrangements to access inaccessible areas urgently.

Obstructions and Limitations

Building defects may be concealed by the following obstructions which prevented full inspection:

- Not Applicable

The presence of obstructions increases the risk of undetected defects. The client should make arrangement to remove obstructions where ever possible and re-inspect these areas as a matter of urgency. See also overall risk rating for undetected defects.

Undetected defect risk

A risk rating is provided to help you understand the degree to which accessibility issues and the presence of obstructions have limited the scope of the inspection.

The risk of undetected defects is: Medium

When the risk of undetected defects is high we strongly recommend further inspection once access is provided or if the obstruction can be removed. Contact us for further advice.

Section D Significant Items

Safety Hazard

No evidence was found.

Major Defect

No evidence was found.

Minor Defect

No evidence was found.

D4 Further Inspections

We advise that you seek additional specialist inspections from a qualified and, where appropriate, licensed -

- Not Applicable

Jim's Building Inspections can put you in contact with qualified and licensed providers of these and other trades services. Please contact your inspector for recommendations, or visit www.jims.net.

D5 Conclusion - Assessment of overall condition of property

Dilapidation report - Crown Land waterfront (mean water line) of number 42.

All inspected areas where accessible for inspection although expected obstructions were present which you should take note of.

This report must be read in full to clearly understand all items identified as defects listed within the report.

For further information, advice and clarification please contact Tiho Lerota on 0401 300 056

Section E Attachments and Further Comments

The following items were noted as - For your information

Noted Item

Building: Yard

Location: Yard - Back

Finding: Additional Photos


Information: Additional photos are provided for your general reference. Arrows have been included to

highlight areas of importance.

Please discuss these photos with your building consultant for clarification.




























Noted Item

Building: Yard

Location: Yard - Back

Finding: Additional Photos

Information: Additional photos are provided for your general reference. Arrows have been included to

highlight areas of importance.

Please discuss these photos with your building consultant for clarification.



















Definitions to help you better understand this report

Access hole (cover) An opening in flooring or ceiling or other part of a structure (such as service hatch, removable

panel) to allow for entry to carry out an inspection, maintenance or repair.

Accessible area An area of the site where sufficient, safe and reasonable access is available to allow inspection

within the scope of the inspection.

Appearance defect Fault or deviation from the intended appearance of a building element.

Building element Portion of a building that, by itself or in combination with other such parts, fulfils a characteristic

function. NOTE: For example supporting, enclosing, furnishing or servicing building space.

Client The person or other entity for whom the inspection is being carried out.

Defect Fault or deviation from the intended condition of a material, assembly, or component.

Dilapidation The state or process of falling into decay or being in disrepair.

Inspection Close and careful scrutiny of a building carried out without dismantling, in order to arrive at a

reliable conclusion as to the condition of the building.

Inspector Person or organisation responsible for carrying out the inspection.

Limitation Any factor that prevents full or proper inspection of the building.

Major defect A defect of sufficient magnitude where rectification has to be carried out in order to avoid unsafe

conditions, loss of utility or further deterioration of the property.

Minor defect A defect other than a major defect.

Roof space Space between the roof covering and the ceiling immediately below the roof covering.

Serviceability defect Fault or deviation from the intended serviceability performance of a building element.

Significant item An item that is to be reported in accordance with the scope of the inspection.

Site Allotment of land on which a building stands or is to be erected.

Structural defect Fault or deviation from the intended structural performance of a building element.

Structural element Physically distinguishable part of a structure. NOTE: For example wall, columns, beam, connection.

Subfloor space Space between the underside of a suspended floor and the ground.

Terms on which this report was prepared

SERVICE As requested by the Client, the inspection carried out by the Building Inspection Consultant ("the Consultant") was a "Dilapidation Inspection Report". A Pre-Inspection Agreement was issued for this service and forms part of the service agreement.

PURPOSE The purpose of this inspection is to provide advice to the client or other interested party regarding the condition of the property at the time of inspection. It serves as a baseline for comparison prior to planned construction or civil engineering works in areas adjoining or near to the property inspected.

SCOPE OF INSPECTION The inspection shall comprise visual assessment of the property and limited assessment of serviceability to identify major defects, urgent and serious safety hazards and to document the condition of the property at the time of inspection. An estimate of the costs of rectification of defects is not required in an inspection report.

The inspection was limited to Readily Accessible Areas of the Building and Site. The Client shall arrange right of entry, facilitate physical entry and supply necessary information to enable the inspector to undertake the inspection and prepare a report. The Inspector is not responsible for arranging entry to property or parts of the property, where reasonable access or entry is denied those areas are excluded from and do not form part of the inspection.

Should re-inspection be required after the completion of construction works you should separately re-engage the Consultant

ACCEPTANCE CRITERIA Unless noted in "Special Conditions or Instructions", the building being inspected was compared with a similar building. To the Consultant's knowledge the similar building used for comparison was constructed in accordance with generally accepted practice at the time of construction and which has been maintained such that there is no significant loss of strength and serviceability.

A report may be conditional on the following:

- (a) Information provided by the person, the employees or agents of the person requesting the report.
- (b) Apparent concealment of possible defects.
- (c) Any other factor limiting the preparation of the report.

EXTENT OF REPORTING

Significant items to be reported are as follows:

- (a) Major defects.
- (b) A documentation of the extent of minor defects.
- (c) Any major defect that is an urgent and serious safety hazard.

LIMITATIONS

The Client acknowledges:

- 1. That this Report is prepared in accordance with AS 4349-2007 but that it is not a Certificate of Compliance of the property within the requirements of any Act, regulation, ordinance, local law or by-law and is not a warranty against problems developing in the future.
- 2. This Report does not include the inspection and assessment of matters outside the scope of the requested inspection and report.
- 3. The inspection only covered the Readily Accessible Areas of the Building and Site. The inspection did not include

Terms on which this report was prepared

areas which were inaccessible, not readily accessible, and unsafe to access or obstructed at the time of inspection. Obstructions are defined as any condition or physical limitation which inhibits or prevents inspection and may include - but are not limited to - roofing, fixed ceilings, wall linings, floor coverings, fixtures, fittings, furniture, clothes, stored articles/materials, thermal insulation, sarking, pipe/duct work, builder's debris, vegetation, pavements or earth.

4. This Report has been produced for the use of the Client. The Consultant or their firm or company are not liable for any reliance placed on this report by any third party.

EXCLUSIONS

This report excludes assessment of: Footings below ground, concealed damp proof course, electrical installations, concealed plumbing, adequacy of roof drainage, gas fittings and fixtures, air-conditioning, automatic garage doors, pools and related equipment, alarm systems, operation of fireplaces and chimneys, flues and solid fuel heaters, alarm and intercom systems, soft floor coverings, appliances, paint coating, health hazards, timber and metal framing size and adequacy, concealed tie downs and bracing, timber pest activity, other mechanical or electrical equipment such as soil conditions, control joints, sustainable development provisions, concealed timber frames, landscaping, rubbish, floor coverings, furniture and accessories, stored items, insulation, environmental matters or lighting and energy efficiency.

IMPORTANT SAFETY INFORMATION - SMOKE DETECTORS

We cannot comment on smoke detector installation and testing as it is not within the scope of this report and requires specialist inspection services. It is however strongly recommended that all existing detectors in the property be tested prior to occupation and advice be sought as to the suitability of their number, placement and operation.

IMPORTANT SAFETY INFORMATION - ASBESTOS

We cannot comment on the presence or absence of Asbestos from this building as it is not within the scope of this report and requires specialist inspection services. It is however strongly advised that the presence of Asbestos be presumed until otherwise definitely known.

Asbestos containing materials may include sheet type building materials, roofing materials, insulations and linings and more. Especially in buildings that were built or modified pre-1992 further inspection should be undertaken prior to works like renovations, extensions, repairs and maintenance or where any materials which could contain Asbestos become damaged or worn.

An Asbestos Inspection And Condition Audit is always advised.

IMPORTANT SAFETY INFORMATION - SAFETY GLASS

Glazing standards in contemporary or recently constructed buildings are governed by the Building Code of Australia (National Construction Code) and will almost always be constructed using glazing designed to minimise injury if impacted or broken. Glazing in older homes is highly unlikely to be 'Safety Glass' and may cause significant injury if damaged. Exercise care and caution around glass in older homes in particular.

This Report only records the observations and conclusions of the Consultant about the readily observable state of the property at the time of inspection.

If the Client has any doubt about the purpose, scope and acceptance criteria on which this Report was based



Terms on which this report was prepared

please discuss your concerns with the Consultant on receipt of this Report.

The Client acknowledges that, unless stated otherwise, the Client as a matter of urgency should implement any recommendation or advice given in this Report.

Privacy Policy:

We value your personal information, we will ensure it is secure and never share or sell your personal details and contact information. We do however use data collected during inspections for research, commercial, training and educational purposes.

For more information please review our Privacy Policy online at www.jimsbuildinginspections.com.au.

Compliments, Complaints and Concerns:

Your feedback, both positive and negative, can assist us to improve our services. We encourage you to please contact us with any compliments or concerns directly and as soon as you are able.

The process for managing customer feedback is documented below:

- 1. Contact your inspector directly to provide feedback or make any complaint as soon as you are able.
- 2. If your inspector cannot resolve it or it involves our insurers they will escalate it to their Regional Franchisor (Manager) and / or insurer as applicable.
- 3. You can also contact their Regional Franchisor (Manager) directly on 131 546 ask to speak to your Inspectors Regional Franchisor (Manager) or email info@jimsbuildinginspections.com.au

Should you have any queries about our terms and conditions, the inclusions and exclusions of this report please contact your Inspector.