

19 SEP 2014

RECEIVED
2 3 SEP 2014
PITTWATER COUNCIL

General Manager Pittwater Council PO Box 882 Mona Vale NSW 1660

Dear Sir/ Madam

Development Consent No. N0300/10 Construction Certificate No. 2011/4267

For Council's information, please find enclosed the following:

- 1. Interim Occupation Certificate No. 2011/4267.
- 2. A cheque for \$36.00 being Council's administration fee to accept the above. Please send receipt to Insight Building Certifiers, PO Box 326, Mona Vale 1660.

Yours faithfully,

Tom Bowden Insight Building Certifiers Pty Ltd

\$36 REC(36785) 23/9/14



Interim Occupation Certificate

issued under the Environmental Planning and Assessment Act 1979 Section 109C (1)(c)(i) and 109H Environmental Planning and Assessment Regulation 2000 Clause 151 & 155

Certificate No. 2011/4267

Applicant	Mr Cameron Jurd		
Address	1 Monterey Road, Bilgola NSW 2107		
Owner	Mr Cameron & Mrs Sandra Jurd		
Address	1 Monterey Road, Bilgola NSW 2107		
Development Consent No.	N0300/10		
Date Of Determination of			
Development Consent	12 August 2010		
Construction Certificate No.	2011/4267		
Date of Issue of	5 April 2011		
Construction Certificate			
Location of Development Site	1 Monterey Road, Bilgola		
	Lot No. 90 DP No. 28862		
	Alterations and Additions to an Existing Dwelling		
Building Details	including a Detached Carport		
Determination:	* This certificate has been issued as APPROVED.		
Determination:	* This certificate is issued subject to the following condition		

Complete:

• The detached Studio in accordance with the above Development Consent.

Date of Determination:

19 SEP 2014

Interim Occupation Certificate

I approve the issuing of this Interim Occupation Certificate and certify that:

- I have been appointed as the Principal Certifying Authority under Section 109E.
- I have taken into consideration the health and safety of the occupants of the building.
- A Development Consent is in force with respect to the building.
- A Construction Certificate has been issued with respect to the plans and specifications for the building.
- The building is suitable for occupation or use in accordance with its classification under the Building code of Australia.
- Where required, a final Fire Safety Certificate has been issued for the building.
- When required, a report from the Commissioner of Fire Brigades has been considered.
- A BASIX completion report has been issued for this project.
- Refer to the attached Schedule of critical stage inspections.

Dowar

Signed

Certifying Authority
Name of Accredited Certifier
Accreditation No.
Accreditation Authority
Contact No.
Address

Tom Bowden BPB0042 Building Professionals Board (02) 9999 0003 13/90 Mona Vale Road, Mona Vale NSW 2103

Schedule of critical stage inspections carried out or missed by the Principal Certifying Authority (Clause 151, 162A, 162B & 162C of the Environmental Planning & Assessment Regulations 1994)

Critical Stage Inspections	Inspected or Missed	Date Inspected
Prior to issue of a Construction Certificate	Inspected	01/04/2011
Excavation for footings	Inspected	11/10/2012
Prior to pouring of any in-situ reinforced concrete	Inspected	06/06/2011 & 11/10/2012
Prior to the covering of any framework	Inspected	29/08/2011
Prior to covering waterproofing in any wet area	Missed	
Prior to covering any stormwater drainage connections	Inspected	16/04/2014
Other required inspections	n/a	n/a
Final Inspection	Inspected	16/04/2014

Schedule of Compliance Certificates or other documentary evidence relied upon to issue the Interim Occupation Certificate

Termite Protection	Certificate of Treatment issued by PestLogic Pty Ltd dated 11 June 2011.
Smoke Alarms	Certificate of Installation issued by Anthony Colella Electrical Pty Ltd dated 28 April 2014.
BASIX Compliance Statement	Issued by Bosco Building Pty Ltd dated 10 June 2014.
Structural Engineers Compliance Certificate	Issued by Waddington Consulting Pty Ltd dated 10 November 2011.
Waterproofing Compliance Certificate	Issued by Damien Cummins dated 8 June 2014.
Stormwater Management Compliance Certificate	Issued by O'Toole Plumbing Pty Ltd dated 23 June 2014.

BASIX Completion Receipt

Receipt no.: CR-1411264018943-A83777

This receipt is confirmation that the certifying authority identified below has satisfied the requirements of clause 154C of the Environmental Planning and Assessment Regulation 2000 for the development described in the 'BASIX Certificate details' section below.

Director-General Date of issue: Sunday, 21/09/2014



Principal certifying authority

Name:

Tom

Accreditation scheme:

врв

Accreditation number:

0042

Final Inspection

Date of final inspection:

Wednesday, 16/04/2014

BASIX Certificate details

BASIX Certificate no.	A83777
Project name	CAMERON JURD
Project name	CAMERON JURD
Street address	1 MONTEREY Road
Suburb	BILGOLA PLATEAU
Postcode	2107
Local Government Area	Pittwater Council



BUILDING INSPECTION REPORT

Land to inich this Building Inspection R	eport result sheet applies:	
Council Area :	Date of Inspection	6/6/11
Address ! Monterer		
DA No		
Requested by:		0793628
Critical Stage Inspections		
Site Assessment - Pre CC/ CDC Issue	Footings and Excavation	Waterproofing
PCA Signage	Steel Placement	Stormwater
Sediment Controls	Floor Framing / Slab	Pool Fence
Tree Protection Measures	Wall Framing	Final Inspection
Building Commencement	Roof Framing	Photographic record
Other (specify)		
and has been found to be in comp Construction Certificate/Complying D	pliance with the plans and specification evelopment Certificate.	has been carried out ons as approved in that
Complete the work detailed hereunde	r.	
Complete the work detailed hereund re-inspection. NB A re-inspection feather the RE-INSPECTION BEING CARR	er and contact the Principal Certifying e of \$ will be charged, where the country of the c	g Authority to arrange a nich is payable PRIOR TO
Steel mit completed &	monieur pentiticale v	reguired
	0	
Signed: Accredited Building Surveyor	creditation No. <u>blb0015</u> Date	6/6/11/

Suite 13/90 Mona Vale Road Mona Vale NSW 2103 PO Box 326 Mona Vale NSW 1660 ph: 9999 0003 fax: 9979 1555 Email: info@insightcert.com.au web: www.insightbuildingcertifiers.com.au ABN 54 115 090 456



BUILDING INSPECTION REPORT

No. nuested by: ritical Stage Inspections Site Assessment - Pre CC/ CDC Issue PCA Signage Sediment Controls	CC No. Ph No.	CDC No
ritical Stage Inspections Site Assessment - Pre CC/ CDC Issue PCA Signage	Footings and Excavation	
ritical Stage Inspections Site Assessment - Pre CC/ CDC Issue PCA Signage	Footings and Excavation	
Site Assessment - Pre CC/ CDC Issue PCA Signage		Waterproofing
PCA Signage		Waterproofing
	Steel Placement	water proofing
Sediment Controls	Steel incentent	Stormwater
	Floor Framing / Slab	Pool Fence
Tree Protection Measures	Wall Framing	Final Inspection
Building Commencement	Roof Framing	Photographic record
Other (specify)		
Complete the work detailed hereunde	er.	
Complete the work detailed hereund re-inspection. NB A re-inspection fe THE RE-INSPECTION BEING CAR	ee of \$ will be char	rtifying Authority to arrange of ged, which is payable PRIOR TO
OR		

Suite 13/90 Mona Vale Road Mona Vale NSW 2103 PO Box 326 Mona Vale NSW 1660 ph: 9999 0003 fax: 9979 1555 Email: info@insightcert.com.au web: www.insightbuildingcertifiers.com.au ABN 54 115 090 456

•	SA PARIS ARREST AND ARREST
INICIO	t building certifiers pty ltd
	■ Labuilding certifiers pty ltd

BUILDING INSPECTION REPORT

Land to which this Building Inspection F		
Council Area : Pittwater	Date of Ins	spection 29/8/11
Address ! Montana	Local Bilgo	la Plateau
DA No	CC No. 2011/4265	CDC No
Requested by:	Ph No	80410 793 628
Critical Stage Inspections		
Site Assessment - Pre CC/ CDC Issue	Footings and Excavation	Waterproofing
PCA Signage	Steel Placement	Stormwater
Sediment Controls	Floor Framing / Slab	Pool Fence
Tree Protection Measures	Wall Framing	Final Inspection
Building Commencement	Roof Framing	Photographic record
Other (specify)		
An inspection of wall was and has been found to be in comp Construction Certificate/Complying D	oliance with the plans and spec evelopment Certificate.	ifications as approved in that
Complete the work detailed hereunde	r.	
Complete the work detailed hereund re-inspection. NB A re-inspection fer THE RE-INSPECTION BEING CARE	e of \$ will be chard	rtifying Authority to arrange a ged, which is payable PRIOR TO
- my factory		
Signed: Accredited Building Surveyor	creditation No. Blb.0915*	Date: 29/8/11

Suite 13/90 Mona Vale Road Mona Vale NSW 2103 PO Box 326 Mona Vale NSW 1660 ph: 9999 0003 fax: 9979 1555 Email: info@insightcert.com.au web: www.insightbuildingcertifiers.com.au ABN 54 115 090 456

Anthony & Colella Electrical

Anthony Colella Electrical Pty Ltd ABN - 59156206905

Licence No. 150268C

72 Abbott Road, North Curl Curl NSW 2099 Australia Telephone: (02) 9401 1139 Fax: (02) 9400 9626

Mobile: 0423 119 360 Email: anthonycolella@bigpond.com

Compliance certificate

Bosco Building 1 Monterey ave Bilgola

Date: 28/4/14

The smoke detectors on each level are hard wired and have been installed in accordance with wiring rules As3785 All bathroom/laundryexhaust extraction fans have been ducted and install according AS3000 wiring rules

Any question feel free to call

Anthony Colella



I Monterey Rd Bilgola NSW 2107

Basix Compliance Statement 10/6/2014

To whom it may concern,

As the Builder responsible for the recent renovation works at the above address I can confirm that all conditions listed in the Basix statement (Cert No A83777 dated 11 May 2010) have been adhered to.

The following items are listed and have been provided/installed in accordance with the requirements of Basix Cert No A83777.

- Hot water system.
- Lighting.
- Fixtures and fittings.
- Insulation requirements.
- Windows and Glazed doors glazing requirements. Including all required shading devices. (Fixed or adjustable)

For further information or to discuss this Compliance Statement please contact me via email at steve@boscobuilding.com.au.

Regards
Steve Talbot Salled

0410332100



23rd June 2014.

CERTIFICATION

RE: STORMWATER CERTIFICATION.
1 MONTEREY STREET BILGOLA PLATEAU, 2107.

To Whom it may concern;

This letter is to certify that all stormwater works completed at the above address have been completed to meet all rules and regulations as set out in Pittwater Councils stormwater management plan, Australian Standard's 3500 and the NSW Plumbing Code of Practice.

We trust that the above information is sufficient; however you should require anything further please do not hesitate to contact us.

Yours faithfully

IN ON

Anthony O'Toole

O'Toole Plumbing Pty Ltd Unit 29/6 Jubilee Ave, Warriewood. NSW 2102 PH 0299860033 Fax 99976033 email otooleplumbing@bigpond.com www.otooleplumbing.com.au ABN 51125384312 Licence 169346c



Waddington Consulting Pty Ltd

ACN 130 522 851 Structural and Civil Engineering Suite 506, Level 5 22 Central Ave, Manly NSW P.O. Box 1044 Manly NSW 1655

> P (02) 9976 0070 F (02) 9976 0095

10 November 2011

Mr and Mrs Jurd 1 Monterey Rd, Bilgola Plateau NSW 2107

Dear Cameron and Sandra,

Subject:

Alterations and Additions at 1 Monterey Rd, Bilgola Plateau ENGINEERS CERTIFICATE FOR INSPECTIONS

I certify that I carried out the structural engineering inspections of the structural work listed below for the alterations and additions to the residence at the above address (excluding carport and garage) and that at the time of the inspection the structure appeared to be in accordance with the design intent of the structural details provided.

During construction, I carried out the following engineering inspections. The date of the inspection is given in brackets.

- Foundation material (06/06/2011)
- Steel reinforcement for the lower ground floor reinforced concrete slab on ground and footings (06/06/2011)
- Structural steel and timber framing for main residence (05/09/2011)

This certificate assumes the construction was carried out by a licensed builder who has experience in this type of work. The above inspections do not, in any way whatsoever, relieve the builder of his responsibility.

The above inspections do not include inspections for contract administration purposes (e.g. progress payments), cosmetic matters and work that, once the competence of the builder has been established, is reasonable for the builder to supervise.

Yours sincerely,

Simon Waddington

Simo libeth goo

MIEAust CPEng NPER (Structural)
Director

Waddington Consulting Pty Ltd



Damien Cummins 32 Oceanview Rd, Freshwater, Sydney, 2096. 0403-268-974

damiencummins73@gmail.com

ABN: 61076866831

For

Bosco Building Pty Ltd PO Box 1145, Brookvale, NSW, 2100. PONO: 2 Date: 08/06/2014

Oescription -Job address 1 Monterey Rd. Bilgola Plateau.	Quantity	Rate	Amount
Waterproofing used was Davco K10 Plus. Areas applied to where all internal wet areas. Product was installed to manufactureres instructions & Australian Standards.	0	\$0.00	\$0.00

* Indicates non-taxable item

De

 Subtotal
 \$0.00

 GST (10.00%)
 \$0.00

 Total
 \$0.00

Certificate of Installation in accordance with AS 3660.1-2000

Terms and Conditions

DISCLAIMER OF LIABILITY TO THIRD PARTIES: - Compensation will only be payable for losses arising in contract or tort sustained by the Client named on the front of this Certificate of Installation. Any third party acting or relying on this Certificate of Installation, in whole or in part, does so entirely at their own risk. This disclaimer does not apply to persons responsible for Building Approvals.

- 1. Prior to the site being prepared the builder should have ensured that all termite activity found was eradicated in accordance with AS 3660.1-2000. Prior to work commencing, the builder should have arranged for a qualified licensed person to inspect the site to investigate and eradicate all economically important termite nests found. The failure to have this inspection carried out may mean that termite nests may not have been found and eradicated and may still be active under the construction. See clauses 3 and 10 below.
- 2. The effectiveness of this installation is dependent upon the provision of a complete (full) termite management system being installed in accordance with AS 3660.1-2000 using approved termiticides, systems and/or products. If the system(s) are disturbed, breached or bridged then concealed entry by subterranean termites is possible.
- 3. No liability is accepted for any failure of a termite management system and this firm warrants only too provide such remedial action as may be necessary during the first 12 months from the date of this Certificate. No such warranty is provided if there are limitations listed on this Certificate or if the system is an incomplete barrier or treated zone or if the builder has not arranged for the termite eradication in clause 1 above.
- 4. The barrier(s) and/or treated zone(s) installed, as detailed on this Certificate and in the diagram, provide a barrier against subterranean termites only. The barrier or treated zone is not a barrier against any other pest(s) and in particular does not provide any barrier against "drywood (KALOTERMITIDAE) or dampwood termites.
- 5. No responsibility is accepted, or warranty implied, for any termite damage that may occur as the result of termite activity, either past, current or in the future.
- 6. The termite management system(s) can be rendered ineffective due to building alterations, renovations, additions (pergolas, awnings, verandas etc), introducing infested materials, timber offcuts, wood chips and formwork left on site, materials stored against the building. External barriers and/or treated zones can be destroyed by the installation of lawns, gardens, pathways, landscaping etc adjacent to the building. When making such changes you should first contact this firm. Where such changes are made a further termite barrier installation and/or treated zone is essential.
- 7. When installing paths, lawn, gardens etc it is very important not to cover air vents or weep holes. If the slab edge is exposed by 75 mm to form part of the termite management system then it is equally important not to cover the slab edge unless another form of barrier and/or treated zone is installed. Again contact this firm before carrying out any such covering. Where such changes are made a further termite barrier and/or treated zone installation is essential.
- 8. Do not use untreated timbers for garden edges or retaining walls. Untreated timber attracts termites.
- 9. Good ventilation and drainage are important, as poor ventilation and drainage greatly increases the risk of termite attack.
- 10. This firm takes NO RESPONSIBILITY for the concealed entry by termites resulting from poor building design or poor building practices.

Version: 12.08 V1-1

17. It is the building owner's responsibility to ensure that the inspections, recommended in AS 3660.2-2000, are performed. Please contact this firm.

VERY IMPORTANT

If you become aware of the presence of termites within the grounds or on or within the building you should contact this firm or another termite management firm immediately. You should also notify this firm if you become aware that the installed barrier and/or treated zone has been breached or bridged in any way.

The Australian Standard recommends that inspections be carried out by a suitably qualified person, at intervals no greater than 12 months and where timber pest "pressure" is greater, this interval should be shortened. Inspections WILL NOT stop infestation of timber pests; however, the damage which may be caused will be reduced when the infestation is found at an early stage. Termites can build around termite management systems; but can be detected during the recommended inspections.

Modern termiticides have a limited life expectancy. The liquid termiticide barrier and/or treated zones will need to be re-installed. The timing can only be determined by regular, competent inspections as recommended by AS 3660.2-2000 and carried out by a qualified experienced termite inspector competent in Unit 8 "Inspect and Report on Timber Pests" of the National Pest Management Competency Standards or equivalent.

IMPORTANT INFORMATION: Termite management systems installed during construction of the building are designed to discourage termites from gaining concealed entry to the property. Termite management systems may be bridged by termites, however the evidence of the termite entry will normally be evident to the inspector. A treatment in accordance with AS 3660.2-2000 to eradicate such an infestation will be required.

Certificate of Installation in accordance with AS 3660.1-2000 - New Construction

Name of owner/builder: Bosco Building

Property Address: 1 Monterey St. Bilgola

State: NSW Post Code 2107

The Termite Management System(s) Installed:

Note: The term treated zone used in this document refers to liquid termiticides when used to form part of a termite management system(s) referred to in AS3660.1-2000 as "Termite Barrier Systems".

AS 3660.1Termite work: Repellent-Liquid Termiticide Treated Zone

A Liquid Termiticide Barrier was installed to the following area(s) - lower level underslab, using the liquid termiticide(s) Biflex Duo which contain the active constituent(s) Biflex Duo which contain the active constituent(s) Biflex Duo which contain the active constituent(s) Biflex Duo which contain the liquid termiticide/s spray mixture used was 0.5% and the total volume used was 400 Lt.

Another type of Management System was installed in the following area(s) - service penetrations using Homeguard. The method(s) of installation was Homeguard Blue Collars.

The above system(s) are integrated with each other.

The system(s) are integrated with the concrete poured by the builder to form the termite barrier.

The resulting Combined termite management system(s) is an incomplete barrier or zone, if the barrier or zone is not complete further work may be required as partial barriers and/or treated zones are not effective and may allow undetected Termite entry. You should consult with the builder. See the limitations below.

The Termite Management System were installed on the 3rd day of June 2011 and a durable notice was placed in meter box.

A qualified Timber Pest Inspector should inspect the building and its surrounds at least every twelve (12) months.

It is strongly recommended by the Australian Standard AS 3660.2 that more frequent inspections (3 to 6 monthly) should be carried out.

We recommend an inspection prior to the installation of gardens, paths, lawns and other landscaping and again on completion of this work to ensure that this work does not breach any termite management system installed or allow concealed termite entry to the property.

We recommend an inspection of the building and the surrounds every 12 Months.


Termiticide Liquid Barriers and/or treated zones degrade (break down) over time and should be replenished in the future. After one of the required regular inspections of the property, the inspector may advise you of the need to re-install the Treated Zone or Liquid Termiticide Barrier.

If the above barrier(s) and/or treated zone(s) is/are integrated with the concrete then the concrete forms an integral part of the termite management system to this structure. In this case, the Builder should be asked for a Certificate from the concrete firm that the concrete has been poured in accordance with AS 3600 or AS2870-1996 and amendments.

Terms and Conditions on Page 1 and important information on page 2 form an important part of this Certificate.

Limitations that apply to the above installation are: Trench footings of slab - excessive pooled water. Edge of western slab where new work is yet to be done.

Diagram (not to scale) showing the location of the installed Termite Management System(s). The direction of North is indicated by the formula symbol.



It is very important that the Termite Barrier and/or Treated Zone is not bridged or breached. This can happen when installing garden beds, lawn or other landscaping or building works. You should contact this firm prior to carrying out any such work. DC NOT disturb the freated areas in any way.

Frequent inspections are very important. Termite Management Systems do not kill off or stop termites. The barriers and treated zones are installed to prevent concealed access only. The barriers and/or treated zones are designed to force the termites into the open. Thus the mud tubes that they use to gain access may be seen during inspections. For this reason such inspections should be carried out at least annually. A Termite treatment in accordance with AS 3660.2 2000 can then be carried out to eradicate the termites.

If you become aware of any activity do not disturb the termites in any way. You should notify this firm as soon as possible. Please contact us if ever you have any concerns about Termites or the effectiveness of the Termite Management System(s) installed.

Installation Firm:

PestLogic Pty Ltd

Name of Installer.

Tony Smyth

Installer's Licence No:

100596

Insurance Termite Accreditation No 5413

Signature:

Telephone. 0418 683156 Date: 11th June 2011

Page 4 of 4

@ Copyright 1916 FAPID Solutions

Version: 12.09 V1 1