

ATTACHMENT 1: SEDIMENT & EROSION CONTROL METHOD



SANDBAG KERB INLET SEDIMENT TRAP





Mr Carports Sydney Northern 2/667 New South Head Road Rose Bay NSW 2029

Phone: 0404 848 074 Fax: 02 9371 5436

E: brett_mrcarports@aapt.net.au

Licence:161613C mrcarports.com.au

DILAPIDATION REPORT

16th April 2009

Planning & Development Council

To Whom it may concern,

Re: Brief Report - Dilapidation Report for Gable Carport at 33 Herbert Street, Manly NSW 2095.

Inspection Date: 1/4/09

I Brett Nitschke, hereby confirm that I inspected the site of the above proposed works on the inspection date stated, for the purpose of reviewing the present state and condition of the councils assets and preparing this brief report as a record. The Existing Council assets are considered to be the road surface in front of the property, concrete kerb, gutter, layback and footpath crossing.

This was a visual inspection only and digital photographs are available for review by any concerned parties by applying by email and a return email will include an attachment with the full photographic record.


OBSERVATION REPORT



Mr Carports Pty Ltd
Head Office: 9 Hoylake Avenue, Stirling SA 5152
ABN: 72 070 618 745 Licence No: 161613C









The above Photographs indicate that the existing concrete kerb, gutter, crossing, footpath and bituminous surface have a few small defects due to aging and wear. There is evidence of mostly finite size cracks within a number of these assets and scrapes from tow bars on the crossing surface, as can be seen in the photos taken directly in front of the property of concern.

Yours Faithfully,


Brett Nitschke

Mr Carports Sydney Northern






Front Elevation 1:100



Side Elevation 1:100



Floor Plan 1:100