

# Utility Locating- Service Docket & Report

Total Surveying Solutions - 22 Suffolk Ave  
Collaroy

Complete

Score	0 / 0 (0%)	Flagged items	0	Actions	0
Locate Down Under Job Number					857
Client / Site conducted				Total Surveying Solutions - 22 Suffolk Ave Collaroy	
Conducted on				27.03.2025 00:24 GMT	

## Table of Contents

<b>Disclaimer</b>	<b>3</b>
<b>Job Details - 0 / 0 (0%)</b>	<b>4</b>
General comments for job	4
Locator Sign Off	5
Locating Disclaimer	5
Classification of AS5488.1 Quality Levels	5
<b>Media summary</b>	<b>7</b>

## Disclaimer

The assessors believe the information contained within this risk assessment report to be correct at the time of printing. The assessors do not accept responsibility for any consequences arising from the use of the information herein. The report is based on matters which were observed or came to the attention of the assessors during the day of the assessment and should not be relied upon as an exhaustive record of all possible risks or hazards that may exist or potential improvements that can be made.

Information on the latest workers compensation and OHS / WHS laws can be found at the relevant State WorkCover / WorkSafe Authority.

## Job Details

0 / 0 (0%)

### Description of work

Carry out CCTV inspection on the stormwater easement running through 22 Suffolk Avenue Collaroy.

### Attach picture of DBYD front cover page



Photo 1




Photo 2

### Type of service located?

Stormwater

### Is there any special requirements for this service?

Yes

### Equipment used?

CCTV Push rod camera

### SUI Quality levels used for this service type?

QL-A

QL-C

### Photos of located services?



Photo 3




Photo 4




Photo 5



Photo 6



Photo 7




Photo 8



Photo 9



Photo 10

### Comments:

Carry out CCTV inspection (dilapidation report) for the stormwater easement running through the property of 22 Suffolk Avenue Collaroy using the CCTV crawler.

Please note the two pits (SPP19823 & SPP19824) shown on the northern beaches council plans appear to have been removed.

The stormwater easement was marked a quality level A at the pits and a quality level C at each mark between the pits.

### General comments for job

## General comments for job

Carry out CCTV inspection (dilapidation report) for the stormwater easement running through the property of 22 Suffolk Avenue Collaroy using the CCTV crawler.

The easement was located using the cctv crawler & sonde.

The cctv footage and report was given to Dave onsite.

All stormwater connnections were located.

No other services were required to be located or inspected using the CCTV crawler.

Locator Sign Off

**Client representative to sign if the technician has explained the locate findings, limitations & recommendations?**

.

**Signed by service locator**

Billy

**Date & Time of signing**

27.03.2025 04:55 GMT

Locating Disclaimer

**This site report is only indicative of the presence or absence of an underground service and does not verify the presence or absence of an underground service, and that the presence or absence of an underground service can only be verified through non destructive excavation, otherwise known as 'potholing'. The information, advice and recommendations in this site report is only accurate at the time of the provision of the our services. We cannot accept responsibility for any damages, as we cannot actually see into the ground. Any results / markings are indicative only and would require visual confirmation. All work will be carried out in accordance with Australian standards AS 5488.1- 2019. Electronic tracing is a guide only and all duty of care should be adhered to when working in and around underground utilities, potholing may be required and if so should be undertaken prior to any ground disturbance and in accordance with service providers requirements and "Duty of Care" All risk remains with the customer we are engaged to help minimise your risk, not eliminate.**

27.03.2025 04:55 GMT

Classification of AS5488.1 Quality Levels

**Quality Level A- Validated- Potholed & sighted is absolute spatial position in three dimensions horizontally and vertically.**  
**Quality Level B- Traced- Electronically traced with good signal with a depth given horizontal tolerance + 300mm and vertical tolerance + 500mm.**  
**Quality Level C- Aligned- Aligned using surface features & historical records electronically traced without depth & or poor scratchy signal.**  
**Quality Level D- Indicative- Indicative location (ONLY) using BYDA/ Historical records.**


---

27.03.2025 04:55 GMT

Media summary

3:45 PM Thu 27 Mar 1 of 2

Job No 38885286

byda.com.au

Contact Details

Contact number

0431 275 034

Company

Enquiry ID

3348488

Contact

Billy Cameron

Email

info@locatedunder.com.au

Address

8 Phillip Street  
Shelly Beach NSW 2261

Job Site and Enquiry Details

WARNING: The map below only displays the location of the proposed job site and does not display any asset owners' pipe or cables. The area highlighted has been used only to identify the participating asset owners, who will send information to you directly.

Enquiry date

17/03/2025

Start date

17/03/2025

End date

21/04/2025

On behalf of

Private

Job type

Excavation

Location

Both Road, Footpath, Nature Strip

Other assets

Manual Excavation

Check that the location of the job site is correct. If not, you must submit a new enquiry.

If the scope of works change or plan validity dates expire, you must submit a new enquiry.

Do NOT dig without plans. Safe excavation is your responsibility. If you don't understand the plans or how to proceed safely, please contact the relevant asset owners.

User Reference

22 SUFFOLK AVENUE

Address

22 SUFFOLK AVENUE  
COLLAROY NSW 2097

Notes/Description

Your Responsibility and Duty of Care

Lodging an enquiry does not authorise project commencement. Before starting work, you must obtain all necessary information from all affected asset owners.

- If you don't receive plans within 2 business days, contact the asset owner & quote their sequence number.
- Always follow the 5% of Safe Excavation (page 2) and locate assets before commencing work.
- Ensure you comply with State legislative requirements for Duty of Care and safe digging.
- If you damage an underground asset, you MUST advise the asset owner immediately.
- By using the BYDA service, you agree to the Privacy Policy and Terms of Use.
- For more information on safe digging practices, visit [www.byda.com.au](http://www.byda.com.au)

Asset Owner Details

Below is a list of asset owners with underground infrastructure in and around your job site. It is your responsibility to identify the presence of these assets. Plans issued by Members are indicative only unless specified otherwise. Note: not all asset owners are registered with BYDA. You must contact asset owners not listed here directly.

Referral ID (Seq. no)	Authority Name	Phone	Status
252396071	Ausgrid	(02) 4951 0899	NOTIFIED
252396073	Jemena Gas North	1300 880 906	NOTIFIED
252396070	NBN Co NewAct	1800 687 626	NOTIFIED
252396069	Northern Beaches Council	0464 015 284	NOTIFIED
252396072	Sydney Water	13 20 92	NOTIFIED
252396074	Telstra NSW Central	1800 453 935	NOTIFIED

END OF CONTACT LIST

Lodge your FREE enquiry online any time at [byda.com.au](http://byda.com.au)

Photo 1

Photo 2

Photo 3

Photo 4

Private & Confidential

7/9





Photo 5



Photo 6



Photo 7




Photo 8





Photo 9



Photo 10