

Anthony Protas Consulting Pty Ltd BUILDING REGULATIONS CONSULTANTS

12 April 2006

Our Ref: 051706

The General Manager Pittwater Council PO Box 882 Monal Vale NSW 1660

Dear Sir,

Re: 1193 Barrenjoey Road, Palm Beach Occupation Certificate

Pursuant to the requirements of the Environmental Planning and Assessment Amendment Act please find attached a copy of our Occupation Certificate issued in respect of the subject premises, together with other relevant documents.

Should you have any questions please do not hesitate to contact the undersigned.

Yours faithfully

Anthony Protas Anthony Protas Consulting Pty Ltd

18/14/06 \$30

CONSTRUCTION CERTIFICATES • OCCUPATION CERTIFICATES • COMPLIANCE CERTIFICATES • BUILDING AUDITS • DESIGN ASSESSMENT • REGULATIONS ADVICE





Anthony Protas Consulting Pty Ltd sub one regulations consultants

Occupation Certificate

1. Details of the applicant

 \boxtimes

	Mr 🖾 Ms 🗖 Mrs	Dr 🗌	Other			
	First name		Family name	e		· · · · · · · · · · · · · · · · · · ·
	Stefan		Leibena			
	Flat/street no.		Street name	e		
	5		Queen	s Avenue		
	Suburb or town				State	Postcode
	Avalon Beach				NSW	2107
	Daytime telephone		Fax	,	Mobile	
	9918 4340					
	Email		CONTRACTO DE LAS ANTAL SA TAN MÁN A CANADA ANTANA			
2.	Details of the b	uilding				
	Flat/Street no.	Street name)			
	1193	Barrenj	oey Road	1		
	Suburb or town					Postcode
	Palm Beach					2108
	Description of the buil	ding or part of	f the building			
	single storey k	<u>ciosk & ca</u>	afe			
	Lot no.	Section				
	7005	Govenc	or Phillip I	Park	······	
	DP/MPS no.			Volume/folio		
	752046					
	Development applicat	ion or complyi	ing developme	ent certificate no.		
	330/03		····			
3.	Decision of the	certifying	authority	,		
	Type of certificate issu	led:				
	an interim	occupation c	ertificate			
	🛛 🛛 a final occ	cupation certifi		- 		
	Date of this decision	12 A	pril 2006			
4.	Information atta	ached to t	his decisi	on		
	🛛 The final f	fire safety cert	ificate or an ir	nterim fire safety ce	rtificate (as rele	vant)

The final fire safety certificate or an interim fire safety certificate (as relevant) Other relevant paperwork

CONCIDENTIAL CERTIFICATES • OCCUPATION CERTIFICATES • COMPLIANCE CERTIFICATES • BUILDING AUDITS • DESIGN ASSESSMENT • REGULATIONS ADVICE

Locked Eag 1001 Wateemba NSW 2046 • Suite 1, 104 William Street Five Dock NSW 2046 • Ph 02 9715 5333 • Fax 02 9715 5666 Email mail@protas.net.au • Web www.pretas.net.au • ABN 37 079 830 756

certifies that:

Final occupation certificate

Anthony Protas

a current development consent has been granted for the development

- a current complying development certificate has been issued for the development
- a current construction certificate has been issued with respect to the plans and specifications for the building
- the building is suitable for occupation or use in accordance with its classification under the Building Code of Australia as a class 6 building
- a final fire safety certificate has been issued for the building
- a final report from the Commissioner of Fire Brigades has been considered.

Occupation certificate no.

OC 1760/05		
Date of the certificate		
12 April 2006		

Signature

For this certificate to be valid, it must be signed by the certifying authority.

Signature	
Name	
Anthony Protas	
Flat/Street no. Street name	
Suite 1, 104 William Stree	ət
Suburb or town	State Postcode
Five Dock	NSW 2046
Telephone	Fax
9715 5333	9715 5666
If the certifier is an accredited certifier:	
Accreditation body of the certifier	Accreditation no. of the certifier
Planning NSW	2442

Property: 1 Lot 7005 DP 752046 GOVERNOR PHILLIP PARK 1193 BARRENJOEY ROAD PALM BEACH NSW 2108

Owner: DEPARTMENT OF LANDS PO BOX 3720 PARRAMATTA NSW 2124

PITTWATER COUNCIL

		FETY CERTIFI	
TYPE OF CERTIFICATE: 🗇 Ir	nterim 🗘	Final	
OWNER/OWNER'S AGENT'S DE	CLARATION		
of 5 QUEENS AN		ient's Name) J 2.10 I ent's Address)	······
certify that:			· ·
 (a) each of the essential fire safety meas has been assessed by a person (chosen be was found when it was assessed, to have required by the most recent firefsafety sch (b) the information contained i Signed: Dated this Note: Only the owner or the agent engaged 	by me) who was property of been properly implemente redule (copy attached) for in this Certificate is, to the rice hugh	ed and to be capable of performed and to be capable of performed the building for which the or best of my knowledge and for the capable of my knowledge and for the capable of the capable	ertificate is issued. behalf, true and accurate. wner/Owner's Agent)
actually performed the assessments			· · · · · · · · · · · · · · · · · · ·
CERTIFICATE RELATES TO:	Whole of B	uilding 🗆 Pa	art of Building
Description of part (where applicabl	o)		
ESSENTIAL FIRE SAFETY MEA Note: A copy of the most recent Fire Safety Sc	SURES LIST chedule must be attached.		
(Essential Fire Safety Measures (S	tandard of Perform Standard of performance to esignated in the Fire Safet AS 2414	be achieved as y Schedule)	of Assessment $2.2 3 0.6$

4

- a copy of this certificate together with the relevant fire safety schedule must be forwarded to Council and the NSW Fire Brigades. A copy of this certificate together with the relevant fire safety schedule must be prominently displayed in the building.

Our ref: 040-47

31 March 2006

C & S Lebenatus 5 Queens Avenue Avalon NSW 2107

Attn: Cathy Lebenatus

Dear Cathy,

RE: PROPOSED ALTERATIONS AND ADDITIONS 'THE COTTAGE' GOVERNOR PHILLIP PARK PALM BEACH STRUCTURAL CERTIFICATE

We certify that the design shown on drawings 04-47/S1 and S2B complies with:

- 1. The relevant clauses of Section B of the Building Code of Australia.
- 2. The following Australian Standards: AS1170, AS1720, AS3600, AS3700 and AS4100.
- 3. Accepted Engineering Practice and Principles.

No standards or practices other than the relevant Australian Standards have been relied upon for this certification.

We also certify that we have carried out inspections of the details documented on the above drawings in accordance with accepted engineering practice and principles during construction of the project. At the times of the inspections the work approved conformed with the intent of our Structural Engineering design, refer attached copy of our Engineering Reports.

This certification shall not be construed as relieving any other party of their responsibilities, liabilities or contractual obligations.

Yours faithfully,

WOOLACOTTS

r

Stephen Branch BE(Hons) MEngSc FIE Aust NPER Structural and Civil – Membership No. 312987

Enc.

Woolacott Hale Corlett & Jumikis Consulting Engineers Pty Ltd ACN 002 791 620 ABN 48 660 773 136 2a Broughton Read Artarmon NSW 2064 PO Box 322 Artarmon NSW 1570 Australia Telephone 02 9413 1399 Facsimile 02 9413 1132 Email office@woolacotts.com.au www.woolacotts.com.au

Philip Crane BE MEngSc FIEAust Stephen Branch BE (Hons) MEngSc FIEAust Kevin Christesen BE (Hons) MIEAust Associates Clare Woods BE (Hons) MIEAust Douglas Fletcher BE (Hons) MIEAust

Directors

onlar



Lott Hale Corlett & Jumikis Sulting Engineers Pty Ltd UN 002 791 620 2a Broughton Road Attarmon NSW 2064 Telephone 02 9413 1399 Facsimile 02 9413 1132 Email office@woolacotts.com.au www.woolacotts.com.au



INGINEERING REPORT		Y	<u> </u>
OD Name: THE COTTAGE PALM BLACH	Engineers Job No.	04-47	
Architect: M+ SA ARCHITETTS	Inspector	Date	Time
Builder: NEWARK CONST.	SETS	20/05	7-45 k
Vork Covered:	**	······································	Report
FOOTINGS A B PL, P2, A	15 SHONN		Numbe
JN DNG SI'			[]
Approved Items:		·····	
AS A DOVE SUBJECT TO THE	FLIGNNA		
All these Items are approved subject to the following instructions being carried out. Approvals cover only the structual soundness of the work and do not include set-out or	co-ordination of oll	er trades (n.) equiceme	nits.
Approvals cover only the structual soundness of the work and do not include value of the If the Builder considers that execution of any work resulting from the instructions belo in conformity with the Contract requirements.	ow involves a variatio	in, he shall obtain appr	oval from the Archite
Instructions to Builder:			
1. MAINTAIN COVER TO RENF.			
2. MAINTAIN MIN. PODTING JUDTH			
			· · · · · · · · · · · · · · · · · · ·
	· · · · · · · · · · · · · · · · · · ·		
	· · · · · · · · · · · · · · · · · · ·		
			1
		······································	
			· · · · · · · · · · · · · · · · · · ·
			:
	<u></u>	_ have	
For Builder		For	WOOLACOTTS
Office Use Only:			
			<i>,</i>
	······································		

Artarmon NSW 2064

1

Telephone 02 9413 1399 Facsimile 02 9413 1132 Email office@woolacotts.com.au www.woolacotts.com.au



ENGINE	ERING REPORT		. *	
Job Name:	THE WITHER PHEM SLITCH	Engineers Job No.	04-47	
Architect:	M + BA ARCHIDERT	thspector	Date	Time
Builder:	NEW ARK CONST.	5653	15/11/05	7-45 itu
Work Cover	ed :			Repor
	REINFORCED BLOCK withis ARDIN	10 J/-	4	Numbe
	As Daja SI			- 2
Approved It		·····		
	GIIIS.			
	AS ANOVE SUBJERT TO THE F	DELOWIN	4	
Approvals cove	are approved subject to the following instructions being carried out. If only the structual soundness of the work and do not include set-out or co- considers that execution of any work resulting from the instructions below in	ordination of othe nvolves a variation	er trades or requirement 1, he shall obtain approv	s. al from the Archite
in conformity Instructions	with the Contract regulrements.	***	· · · · · · · · · · · · · · · · · · ·	
	The VLETICAL GARS TO STREADE			
2.	ENJSURE VERTICA MARS AND MA	INTA IND	76 178 46	
	IN CARD DOWNG GLOUTING			
				·····
				_
······				
	- -			i
<u></u>				
		A.	Sector and and a sector of the	-
	For Builder		For W	OOLACOTTS.
Office Use	Only:			
	_			

.cott Hale Corlett & Jumikis .sulting Engineers Pty Ltd .CN 002 791 620 2a Broughton Road Artarmon NSW 2064 Telephone 02 9413 1399 Facsimile 02 9413 1132 Email office@woolacotts.com.au www.woolacotts.com.au



ł

Job Name:	THE COTTAGE PARM GENTEN	Engineers Job No.	()+++)	7
Architect:	M-1 BA ARCHATICTS	Inspector	Date	Time
Builder:	NEWARK CONST.	Set is	\$ /1: 1 55	7.30 44
Nork Covered	d:	A		Repor
	SLAIDS 51-54 (DASG 31)			Numbe
				3
Approved Ite	ms:	· · · · · · · · · · · · · · · · · · ·		······································
	AS ADDE DUBLETT TO THE 1	2660241464	· · · · · · · · · · · · · · · · · · ·	
s.				
Approvals cover If the Builder co	re approved subject to the following instructions being carried out, only the structual soundness of the work and do not include set-out or onsiders that execution of any work resulting from the instructions belo	co-ordination of other w involves a variation,	trades or requirement he shall obtain appri	nts. oval from the Archite
nstructions t	ith the Contract requirements. to Builder:	·		
1.	HOD ADDITONIA MESH 1	0.825 777	COMBLES	E
	RUNF TO 50 mm FROM			
	AND LOGIS OF CONCRETE			. 4
2.	CLEMN DUT FORMS	••••		
3.	CHARS Massa To Provide	1 DARDENT	Contain of	· 30 m.
	BOTOM OF SUTIS			
				· · · · · · · · · · · · · · · · · · ·
	······································			
				1
				,,,,,
	*		***	
		Statel of	1	
	For Builder	<u> </u>		NOOLACOTTS.
Office Use O				

Telephone 02 9413 1399 Facsimile 02 9413 1132 Email office@woolacotts.com.au www.woolacotts.com.au



ENGINEERING REPORT			· · · · · · · · · · · · · · · · · · ·
JOB Name: THE COTTHEE PALM DEACH	Engineers Job No.	04-47	<u> </u>
Architect: M 7 BA ARCHITECTS	Inspector	Date	Time
Builder: NEWARK CONST.	SCT 6	10/1/06	7-30 AM
Work Covered:			Report
TIMBER GROUND FLOOR - DWG SI			Number
ROOF FRAMING - DWG 52/B		<u></u>	- 4
Approved Items:			
AS ABOVE SUBJECT TO THE FOLLOWIN	17		
	~ L4 ,		
All these items are approved subject to the following instructions being carried out. Approvals cover only the structual soundness of the work and do not include set-out or if the Builder considers that execution of any work resulting from the instructions bel in conformity with the Contract requirements.	r co-ordination of oth ow involves a variatio	er trades or requiremen n, he shall obtain appro	ts. val from the Architect
Instructions to Builder:			
1. ADD BOLTS TO END CONNECTIONS OF EI	5 B19 4	B20	
2. ADD 2 TRIP. L-GRIPS TO END OF BG	, 		
3. ADD GALV STRAP TIE DOWN FROM BI	2 72 DOUS	LE STUDE A	VD FADIA
DOUSIE STUDS TO GOTTOM P. 472			
4. CONCRETE ENCASE BASE OF CILIMA	5 69 4 6	10	
5. REPLACE NOT PACKS SUTH STELL PIL	RD AT L	17 10 83	CONNECTION
6. PACK FROM UNDERSIDE OF DI2 12			
ADD FIN PLATE + 2M12 FROM BI	~	_	
7. ADD & R BASE SUPPORT TO B2			BIT
AND OUT OFF ERCESS FIN PLATE -			
		3 Ptr	TE IT
8. ADD 8 R ANOLE SASE SUPPORTS TO		SUPP SUPP	
B6 - B12 AT B16_			<u>.</u>
	<u>[\$157)</u> F/N	NG PLATED	,,,
SASE JUPPORT			
CASE JUNPON STATE		1 TT.	
For Builder		- Jak For V	WOOLACOTTS.
Office Use Only:	<i>[/</i>		
			<u></u>

Mark Eriksson, Landscape Architect 8am to 5:30pm Mon - Thurs, 8am to 5pm Fri Phone 9970 1356 Mobile 0417 219 541

10 April 2006

Andrew Protas Consulting Lot 30 Locked Bag 1001 WAREEMBA NSW 2046

mail@protas.net.au

Dear Sir

Re: Certification of Set-out, Ground Floor Levels and Landscape Works Dunes Café Kiosk Governor Phillip Park, Palm Beach

I Mark Eriksson am a Principal Officer in the Reserves, Recreation & Building Services Unit and have been responsible for overseeing construction and set-out works of the Dunes Café facility. In relation to certification of works as developed to date:-

Building Set-out

I have reviewed plans and the current location of the building and associated landscape works all of which are in accordance with adopted plans for the site and development.

Ground Floor Levels

I have reviewed plans and works on-site and works are in accordance with approved plans for the site.

• Landscaping

I have reviewed plans and subsequent works on-site and confirm all landscape works are generally in accordance with adopted plans for the site.

Yours faithfully

Mark Eriksson





Component Certificat

DA No: N0330/03

CC No:

at

Property: GOVERNOR PHILLIP PARK 1193 B/ RR ENJOEY ROAD PALM BEACH NSW 2108

Disabled Facilities (Public Buildings/SEPP 5)

Linding (Name)

(Mailing Address)

being an accredited access adviser, my qualifications being:

Civil Engineet member 1.11

hereby certify that the completed building complice with the approved plane and the requirements of DCP No 26 "Accessibility", and the relevant to conditions of Development Consent, pursuant to the recommendations of the inspection report dated 74 April 66

Further, I am appropriately qualified and experienced to provide the certification for this component of the project.

Signature 4

Date 7th April 2006

of Morris Lesting Accessibility Consulting (Business)



7th April 2006

Cathie Leibenatus Dunes Restaurant & Klosk 1193 Barrenjoey Road Palru Beach NSW 2108

Dear Cathie

RE: RESTAURANT & KIOSK – PALM BEACH

From the site inspection on the 7th April 2006, please find current issues report with regards to the Dunes Restaurant and Kiosk.

- (i) Provide a smaller grab rail beside the accessible toilet eistern. The top of the grab rail shall be positioned 800mm FFL.
- (ii) Ensure the top of the wash basin is 800mm FFL, compliant with AS1428.1.
- (iii) Ensure the soap/paper towel dispensers are placed between 900mm 1100mm FFL. The dispensing units shall be within arms reach when in from of the wash basin.
- (iv) Ensure there is a "D" shaped door handle inside the accessible bathroom. The handle shall be between 900mm 1100mm FFL.

Please do hesitate to call if you have any further questions.

Sincerely ----A

Anthony Leuzzi Morris-Goding Accessibility Consulting

morris goding accessibility consulting

The Cooperage Studio 6, Levell, 56 Bowman Street P. mont I. SW 2009, Tr 9602 9322, Fr 9602 9433 Www.mgac.com.au ABN 70 414 330 060

ACOUSTIC LOGIC CONSULTANCY noise and vibration consultants abn 11 068 954 343

Reference: 2006279/0504A/R0/TB 5 April, 2006

Stefan & Cathy Leibenatus 5 Queens Avenue Avalon NSW 2107 No. Pages: 5 Fax: 9918-4340 Email: sc_leibenatus@iprimus.com.au

ATTN: CATHY & STEFAN LEIBENATUS

DUNES RESTAURANT & KIOSK, PALM BEACH - COMPLIANCE NOISE MEASUREMENTS

1. INTRODUCTION

A compliance assessment has been undertaken of the impact of the new mechanical plant installed at the Dunes Kiosk & Restaurant at Palm Beach. An environmental noise assessment for this development originally called "The Cottage" was carried out in April 2003, refer to ALC report 2003281/0704A/R0/WH. This report covered the operational noise emissions from the patrons and covered indicative treatment for mechanical plant for at the time these plant items had not been finalised.

Compliance measurements of the installed plant were carried out to predict the noise levels at the residents. These figures would be added to the predicted entertainment noise levels. The overall noise level will be compared to the Council Criteria presented in the original report.

2. PROPOSED DEVELOPMENT

2.1 GENERAL DESCRIPTION

The proposed restaurant is a redevelopment of an existing 1 storey residential building located in Governor Phillip Park, Palm Beach. Patrons will generally be seated with most tables located externally in front of the Northern Facade. Pre-recorded background music is to be played internally with no outside speakers and no facilities for live music. The restaurant is to be BYO.

It is proposed to operate the outdoor kiosk area 7 days, from 8.00am to 7.00pm during summer and 8.00am to 5.00pm during winter. The outdoor restaurant area to the north of the building is to operate

Sydney | Ph 02 S338 9888 | fax 02 8338 8399 | 9 Sarah Street Mascot NSW 2020 Motourne | Ph 03 3614 3199 | fax 03 9614 3755 | Level 7, 31 Queen Street Melbourne VIC 3000 Canberra | Ph 02 5162 5797 | fax 02 5162 9711 | Unit 14/71 Leichhard! Street Kingston ACT 2604

20060405ta_R0_env

Directors | Malthew Palavidis | Victor Fattoretto

Tuesday to Sunday between 8.00am and midnight during summer and winter. Last food service is to be at 11.00pm.

The nearest potentially affected properties are residents located on the southern side of Beach Road, approximately 103m from the proposed development. (The original report states the distance as 80m. it was remeasured at 88m to Beach Rd from the current green shade cloth fence).

3. NOISE MEASUREMENTS

3.1 BACKGROUND NOISE MEASUREMENT

The background noise measurements to be used in the assessment are from the original assessment. Table 1 lists the representative minimum repeatable background noise levels at the development.

TIME OF DAY	L ₉₀ ,dB(A)
Day time (7.00am to 6.00pm)	45
Evening (6.00pm to 10.00pm)	45
Night time (10.00pm to midnight)	43
Night time (midnight to 7.00am)	42

Table 1 – Unattended Monitoring Noise Levels

3.2 MECHANICAL PLANT NOISE MEASUREMENTS

Mechanical plant noise measurements were taken near the building and then corrected for distance attenuation alone to predict the noise level at the residential boundary. The measurements were taken close-in to reduce the effects of extraneous noise sources.

3.2.1 Measurement Locations

The roof top plant noise measurements were taken at a distance of 10m from the building and at a height of approximately 3m. This would be approximately 13-16m from the mechanical plant items. The height was chosen so that there were clear views of the rooftop plant and to negate the need for any directivity corrections. The toilet exhausts located on the Western facade were measured at ground level, 4m away from the wall. The noise measurements of the machinery were taken individually with backgrounds recorded in between.

3.2.2 Measurement Equipment

The measurements were taken with a Norsonic 118 Type 1 sound level meter. The equipment was calibrated at the beginning and the end of the measurement using a Norsonics Sound Calibrator type 1251; no significant drift was detected. All measurements were taken on A-weighted fast response mode.

20060405ta_R0_env

3.2.3 Measurement Period

Manned noise measurements were conducted on the 4th of April 2006 between 6:30pm and 8pm. The surf was tiny and there was no wind.

3.2.4 Measured Noise Levels

The measured noise levels are listed below in Table 2. The descriptor used for the assessment is L_{Aeq} for the equivalent noise level. The continuous machinery and background noise levels are described by the L_{A90} descriptor. The actual noise emission from each machine is the corrected noise level; it has been corrected for the background noise level.

Plant Item/s	Noise Level L _{Aeq} dB(A)	Noise Level L _{A90} dB(A)	Corrected Noise Level L _{Aeq} dB(A)
Condenser On (full load)	51	49	50
Condenser Off	-	42	-
Dishwasher & Range Hood exhausts On	49	48	*53
Dishwasher & Range Hood exhausts Off	-	42	-
Toilet exhausts On	41	40	37
Toilet exhausts Off	-	39	-

Table 2 – Measured Noise Levels dB(A)

*Tonality penalty applied (+5dB)

4. NOISE OBJECTIVES

The original noise assessment objectives were determined from the ambient noise monitoring and the relevant guidelines.

TIME OF DAY	L ₉₀ , dB(A)
Day time (7.00am to 6.00pm)	50
Evening (6.00pm to 10.00pm)	50
Night time (10.00pm to midnight)	48
Night time (midnight to 7.00am)	47

Table 3 - Noise Level Objectives

5. ASSESSMENT OF NOISE IMPACT

5.1 NOISE SOURCES

Table 4 gives the entertainment noise levels from the original report at the boundary.

Table 5 gives the combined noise levels due to the addition of the mechanical plant noise component. An additional table entry has been added for the cool room condenser operation throughout the night.

Dining Area in Use	Time of Day	Noise Level at Residents L _{eq} ,dB(A)	Criteria ,dB(A)	Complies
Kiosk and Restaurant	Day (7.00am to 6.00pm)	44	50	Yes
Kiosk and Restaurant	Evening (summer only) (6.00pm to 7.00pm)	44	50	Yes
Restaurant	Evening (6.00pm to 10.00pm)	35	50	Yes
Restaurant	Night (10.00pm to midnight)	35	48	Yes

Table 4 - Entertainment Noise Levels at Residential Boundary

Table 5 - Combined Noise Levels at Residential Boundary

Dining Area in Use	Time of Day	Noise Level at Residents L _{eq} ,dB(A)	Criteria ,dB(A)	Complies
Kiosk and Restaurant	Day (7.00am to 6.00pm)	45	50	Yes
Kiosk and Restaurant	Evening (summer only) (6.00pm to 7.00pm)	45	50	Yes
Restaurant	Evening (6.00pm to 10.00pm)	40	50	Yes
Restaurant	Night (10.00pm to midnight)	40	48	Yes
CLOSED	Night (Midnight to 7am)	32	47	Yes

20060405ta_R0_env

6. CONCLUSION

Potential noise impacts from the Dunes Restaurant and Kiosk at Governor Phillip Park, Palm Beach have been assessed at the nearest residents.

The potential impacts of noise emissions have been assessed against noise objectives determined using Council guidelines, as reported in the original environmental impact assessment ALC report: 2003281/0704A/R0/TB.

Noise measurements of the installed mechanical plant were taken and then combined with the predicted entertainment noise levels.

The combined operating noise levels at the residents have been have been found to comply with the Council Guidelines.

We trust this information is satisfactory. Please contact us should you have any further queries.

Yours faithfully,

. on Scheian

ACOUSTIC LOGIC CONSULTANCY PTY LTD Tom Bohdan

20060405ta_R0_env



A JELD WEN Company

S&C LEIBENATUS 1193 BARRENJOEY ROAD PALM BEACH NSW 2108

Thursday 30th March 2006

JOB #034337 - S&C LEIBENATUS

Rc: 1193 BARRENJOEY RD PALM BEACH NSW 2108

Airlite Windows and Sliding Doors are manufactured to meet the wind loading/structural and water performance requirements specified at the time of ordering. The products are labelled to indicate the AS2047 performance ratings which they meet. This conforms to the requirements of the Australian Building Code Amendment No.9 for Class 1 Buildings. This amendment requires window manufacturers to label windows and sliding doors with the wind loading/structural and water performance ratings of the window/door.

AS1288 is specified within AS2047, therefore products which are labelled as meeting AS2047 must also be glazed to meet AS1288.

All Airlite products are glazed to meet the requirements of AS1268 based on information supplied at the time the windows/doors are ordered.

In some instances the positioning of a window will determine the type of glazing required for the glazing to meet AS1288. Thus it is important that windows are installed in the locations specified at the time of ordering. Windows which are broken at site must be reglazed to meet AS1288 for the location and the Class of Building in which they are installed.

Based on the above details it is not necessary for Airlite to issue a glazing certificate. Airlite are unable to issue a glazing certificate without carrying out a detailed inspection and an associated charge for that inspection to verify that windows have not been replaced, exchanged, installed in incorrect locations or reglazed incorrectly.

Yours faithfully

AIRLITE PTY LIMITED

AIRLITE WINDOWS Pty Ltd ABN 31 000 324 676 62 Drommond Street SOUTH WINDSOR NSW 2756 Ph: 4577-4577 Fax: 4577-4967 www.airlite.com.au

1 Central Park, Central Ave THORNLEIGH NSW 2120 Ph: 9980-6455 Fax: 9980-6427

27-29 Burwood Road BURWOOD NSW 2134 Ph: 9745-3044 Fax: 9745-6044

Don/2001-157



SPEEDY VENTILATION PTY LTD ABN: 69 114 807 466

SPEEDY For * Service

* Manufacture

* Installations

Reference No: 2020-06

CERTIFICATE OF COMPLIANCE

I here by certify that the mechanical exhaust system at The Cottage, 1193 Barrenjoey Rd Palm Beach was designed, manufactured and installed to satisfy Australian standards, 1668 Part 2 - 2002.

Main Canopy size: 4560mm x 1000mm / Min. Air flow requirement = 2300 l/s Total tested = 2600 l/s.

Dish-Wash Canopy size: 1000 mm x 1000 mm / Min.Air flow requirement = 300 l/sTotal tested = 500 l/s.

Total Tested Exhausted Air: 3100 l/s

Main Exhaust / Motor Details: .37kw / 1440 rpm / s / phase.

Dishwasher Exhaust / Motor Details: .58 amps / 1440 rpm / s / phase.

System Cleaning Requirements are as follows: Clean main duct system, internally, at intervals of approx. 12 months.

Dated this day 31th March 2006

Tracey Fellows

Mechanical Engineer for Speedy Ventilation Pty Ltd.

17 York Boud, Inglebern NSW 2565 Paone (02) 9618 3366 Fav:(02) 9829 15 3 6 March 2006

Dunes Restaurant & Cafe Attention: Cathie Wright Lot 18 Barrenjoey Rd PALM BEACH NSW 2108

Dear Customer,

Re:Dunes Restaurant & CaféProperty:Lot 18 Barrenjoey Rd Palm Beach NSW 2108

Please find enclosed your Commercial Trade Wastewater Permit covering the discharge of trade wastewater to our sewer.

The Permit identifies the conditions that apply to our continued acceptance of your trade wastewater to our sewer, please familiarise yourself with this document and keep it in a safe place.

The attached table provides some information to assist you in understanding your commitments relating to this Commercial Trade Wastewater Permit.

If you have any questions please call me on 0419 256 397 and I will be happy to assist.

Yours sincerely

.

Mal Cowant

Mal Stewart Customer Service Representative Commercial and Industrial Customer Services

Sydney

WATER

PROPERTY No: 3400024 CONNECTION No: 1



SYDNEY WATER CORPORATION

COMMERCIAL TRADE WASTEWATER PERMIT

For a commercial property or small business producing mainly residential types of substances in its trade waste.

ITEM 1	
Sydney Water grants this Permission to the owner of the premises:	
The Customer: PITTWATER COUNCIL NO.1	
Postal Address of Customer: PITTWATER COUNCIL NO.1 P.O. BOX 882 MONA VALE 2103	
l'el:	
Name of the business at the premises: DUNES RESTAURANT & CAFE	
Address of Business (where discharge occurs): LOT 18 BARRENJOEY RD, PALM BEACH 2108	
Tel:	
Name of the contact(s) at the premises: CATHIE WRIGHT	
Tel: (040) 3 933 890	
Commencement date of this Permit: 02/03/06	
Term of Permit: Current until cancelled by either Sydney Water or the Customer.	
Mad Lewant	
for Manager, Commercial and Industrial Customer Services, Sydney Water	

This permission allows trade wastewater to be discharged from the Premises into our sewer as long as the requirements and conditions of the Permit are met.

> THIS PERMIT IS AN IMPORTANT LEGAL DOCUMENT PLEASE READ IT AND KEEP IT IN A SAFE PLACE

If you DO NOT understand any part, PLEASE CONTACT US (See ITEM 13)

.... NAME: MSR20060302000000101

PERMIT No:

31119

PROPERTY No: 3400024 CONNECTION No: 1



ITEM 2

Business Activities: (generating trade waste) undertaken at the Premises

(AA36) - DUNES RESTAURANT & CAFE - 320 KL/YR

ITEM 3

Pre-Treatment: (equipment that is required at the premises to treat trade wastewater)

PIT 1 - 1,500 LITRE HALGAN MODULAR GREASE TRAP (DUNES RESTAURANT & CAFE)

ITEM 4

Not Applicable

ITEM 5

Sydney Water's Sewerage Treatment Plant For The Area:

Name: WARRIEWOOD

Level of Treatment we provide: SECONDARY

ITEM 6

Discharge Point at the premises:

BOUNDARY TRAP

ITEM 7

Sampling Point: (where the quality of the trade wastewater may be checked)

PRETREAT.DISCHARGE EXCL. DOMESTIC SEWAGE

ITEM 8

General Requirements for ALL trade wastewater discharged into sewer.

CHARACTERISTIC Temperalure

Colour

C REQUIREMENT not more than 38 Degree Celsius not noticeable when diluted 100 times in clear water between pH 7 (neutral) and pH 10 (alkaline)

pH Fibrous Material Solid Matter Discrete Oil

ITEM 9

not longer than 20millimetres, must not settle faster than 3 metres in an hour

none which could block our sewer

none to be discharged to water

Not Applicable

Sydney Water Corporation ABN 49-776-225-038 115-123 Bathurst Street Sydney NSW 2000 Australia PO Box A53 Sydney South NSW 1232 Australia Telephone 132-092 Facsimile (02) 9350-6814 DX 14 Sydney Internet www.sydneywater.com.au

······

₁ NAME RMIT No:	: MSR20060302000000101 31119	PROPERTY N CONNECTION		Sydney MATE:
	<u> </u>	ITEM 1	0.	rennen anderen anderen Anderen anderen anderen Anderen anderen
Cleaning Re	equirements for the equipment at	0io premisos.		
ltem			Requirement	
(PTEDL: FAIL	.5)		MUST BE SERVICED IN ACCOR SYSTEM, BY A CONTRACTOR L ENVIRONMENT PROTECTION A	ICENCED BY THE
PIT 1 HALC	GAN MODULAR GREASE TRAP -	1,500 LITRES	TO BE INSPECTED BY CUSTON	IER SERVICE REP.
		ITEM 1	1	· · · · · · · · · · · · · · · · · · ·
Extra Requ	irements:			
	NING CONTRACTOR FOR THE 15 ATER ON OR BEFORE 31 MARC		TRAP IS TO FORWARDED TO	_ 1-
		ITEM 1	12	
What Sydne	ey Water will charge you:			
Type of Cha	arge		Amount	
Permit Fee			\$70.00	
				Commencement Date
Trade Wast	teWater Quality Charge		See attached schedule 1	31/03/06
	A 1,500 LITRE GREASE TRAP - C	GREASY WASTE	TO BE DETERMINED	
PROCE	ESSING CHARGE			
* Please No	-1			
Unless 30 (days written notice is given advi mit Fees, Quality Charges and W			
		ITEM	13	•
Contacts:				
	al and Industrial Customer Services PO BOX 947, ARTARMON 1570		DN	
	9622 2244	Fax: (02)99	904 8507	
Please ask	for the Customer Service Represe	entative responsible fo	or Territory Number: 34	
Note: Offi	ice hours - 8:30am to 5:00pm, WE	EKDAYS		

-

4

SUMMARY OF INFORMATION (2005/2006)

CLEANING REQUIREMENTS

ITEM 10 Customers who discharge trade wastewater to Sydney Water's sewer via a grease trap must arrange for a contractor, who is licensed by the Department of Environment and Conservation (DEC) to transport grease trap waste and registered with Sydney Water's Wastesafe system, to regularly clean and completely pump out each device. Customers must advise Sydney Water of their chosen licensed contractor and of any change of contractor that may occur.

Sydney Water's Customer Service Representatives will assess whether the customer's grease trap is cleaned frequently enough and where necessary make alterations to the servicing frequency

EXTRA REQUIREMENTS HEMH

Some customers may be required to install additional preficatment and 7 or follow particular procedures to ensure that the wastewater discharged from the premises may be accepted for discharge to our sewer. These customers may be given some time to comply with this requirement.

WHAT SYDNEY WATER WILL CHARGE YOU

ITEM 12

1

Permit Fee:

Permit fees cover the cost of Sydney Water's monitoring of permits to discharge trade wastewater to sewer, including the cost of inspections, sampling, analysis and administration of permits.

First process	\$17.50 per quarter
Each additional process	\$ 5.83 per quarter

Waste Quality charges:

Quality charges cover the cost of accepting, transporting and treating trade wastewater. They are based on the mass of substances discharged and the potential risk this presents to Sydney Water's sewerage systems.

Assessed concentrations for commercial processes are based on representative sampling carried out by Commercial and Industrial Customer Services. Where the property is not separately metered, the volume is also assessed on the basis of a representative sample of similar businesses. A minimum charge of \$58.77 applies where volume discharged is assessed; however, there is no minimum charge for volume based on a trade waste discharge factor applied to a flow measured by a water meter.

ommercial Trade Wastewater Permission Number (e tachment 1 What Sydney Water will o	harge you *	
	\$/kL	flat charge/annum
Process description		
RESTAURANT (AA36)	1.08	
-		

 $2 \frac{1}{2} = 1 + 2 \frac{1}{2} \frac{1}{2} \frac{1}{2} + 2 \frac{1}{2} \frac{1}{2} \frac{1}{2} \frac{1}{2} + \frac{1}{2} \frac{1}$

4

Commercial Trade Wastewater Permission Number (31119)

If you require further information on the calculation of your trade waste quality charges then please contact your Customer Service Representative- Trade Waste.



Date: 15th March, 2006

To Whom It May Concern:

This is to certify that smoke detectors have been installed at the premises: *1193 Barrenjoey Road Palm Beach NSW 2108. (Seasons Catering Pty Ltd T/as Dunes Restaurant).*

The smoke detectors have been wired and connected to the 240 volt mains supply with a battery back up.

The smoke detectors have been tested and installed to the relevant standard, being AS3786 and AS1670.

In addition, these smoke detectors are also connected up to our 24/7 Monitoring Control Room.

I trust this information is sufficient and please don't hesitate to call if you have any further questions.

Kind Regards,

Steve Hansen General Manager

Bogisterial office of

Club AV Pty Ltd CAV Monitoring CAV Security CAV Finance CAV Rental Head Office Unit 15, 14 Jubitoe Aveaue Wartiewood NSW 2102 Telephone 9979 6555 Lacsimile 9979 5300 Brisbane Unit 7, 474 Lytton Road Moreingsido QLD 4170 Telephone 3399 8199 Lacsimilo 3399 8099

Bollina Telephone 6628 6628

Facsimile - 6628-6655 anloweavsecurity.com.aa cavsecurity.com.aa ASIAL Member Mister Scopity Leaner No. 301-763-298 Accessible Member Clubs OLD Supporter Member Clubs NSW ABR 13 002 501 (213



MDL Fire & Safety

Services (Australia) Pty Ltd

ABN 29 003 875 303

FREE CALL 1 SAAD SAAD SAAS

ANNUAL/SUPPLEMENTARY FIRE SAFETY STATEMENT UNDER THE ENVIRONMENTAL PLANNING & ASSESSMENT ACT 2000 (as amended) REGULATION

Type of Statement:

annual supplementary

" Annual statement:

(delete if this does not apply)

" Supplementary Statement: I/We,...MDL FIRE & SAFETY SERVICES (AUST) PTY LTD... (agent)

of,15 TARLINGTON PLACE, SMITHFIELD....... (address)

certify: (a)

- that each essential fire safety measure specified in this statement has been assessed by a properly qualified person and was found when it was assessed to be capable of performing:
 - (I) in the case of an essential fire safety measure applicable by virtue of a fire safety schedule to a standard no less than that specified in the schedule, or
 - (ii) in the case of an essential fire safety measure applicable otherwise than by virtue of a fire safety schedule, to a standard no less than that to which the measure was originally designed and implemented, and
- (b) that a properly qualified person (whether the person referred to in paragraph (a) or another person) has inspected the building and has certified that, as at the date of the inspection the condition of the building did not disclose any grounds for a prosecution under Division 7 of Part 9 of the Environmental Planning and Assessment Regulation 2000, and
- (c) the information contained in this certificate is to the best of my knowledge and belief, true and accurate.

I,....NOTAPPLICABLE.....

Of,.....

- (a) that each critical fire safety measure specified in this statement has been assessed by a properly qualified person and was found when it was assessed to be capable of performing to a standard not less than the required by the current fire safety schedule for the building for which the statement is issued, and
 (b) the information contained in this certificate is to the best of the base of the
 - the information contained in this certificate is to the best of my knowledge and belief, true and accurate.

OUR PRIORITY IS YOUR SAFETY AND SECURITY

		ces (Austr: ABN 29 003 8		
		FREE CA		
MDL				
Address of Building:	1193 B	arrenjoey Road,	Palm Beach. N	SW. 2108
Owners/Company Name:	Seasor	ns Catering Pty. L	td	
Contact Phone Number:		933-890		
.ist of essential/critical fire safely	measures:			
		Standard of P (e.g. Australia Maintenance	an Standards/	Date of Inspection / Assessment
Measure:		Mantenance	•)	• •
				: :
PORTABLE FIRE EXTINGUISHE	ERS	AS2444-1	990	22/03/2006
				:
	•		-1-	
Date of Certificate:22 nd N	larch, 2006	Signed	(Agent)	
You are further advised:-			(,	
A copy of this certificate tog	athor with the	rolovant fire cafe	ty schedule mu	st be forwarded to the
Council and the Commission	her of the Ne	w South Wales Fi	re Brigades at,	Locked Bag 12, P.O.
 Greenacre, 2190. A copy of this certificate tog displayed in the building. 	ether with the	e relevant fire safe	ety schedule mu	ist be prominently
diopidyou in the building.				

OUR PRIORITY IS YOUR SAFETY AND SECURITY

Advanced Weather Proofing

14 February 2006

Grant Newark Newark Constructions

Certificate of Compliance for: the Dunes Barrenjoey Rd Palm Beach

PRODUCT

AREAS APPLIED

Durabit System

Internal wet areas

"We hereby certify that the work carried out by us in accordance with the instructions, plans and specifications supplied to us and has been carried out in a proper and work like manner in accordance with B.C.A F1.7 and with Australian standards No. AS3740 1994. We further warrant that any material supplied in connection with the services rendered by us is fit for the purpose for which it was specified and supplied".

Jon Douglas Advanced Weather Proofing Pty Ltd

Provins - 1906 and and an applicable (1665 - 1775 - 1667 - 1667 - 1677 - 1677 - 1777

Advanced Weather Proofing

na cona de la

Wednesday, November 09, 2005

ATT: Grant Newark Newark Constructions

Grant,

Please find the following warranty details for the The Dunes Barrenjoey Rd Palm Beach project.

Internal wet areas

Date commenced; 1st February 2006 Date finished; 4th February 2006

Materials Used: Durabit System

in accordance with AS 3660.1-2000 New construction PAD 3 me of owner/builder Newark Construction perty Address 1193 Barrenjoey Road alm Beach -3660.1Termite work: Termiticide Liquid Barrier Treatment	Certificate of Installation
New construction and downed in the construction approx Address [193] Barrenice Road approx Address [193] Barrenice Road approx Address [193] Barrenice Road approx Physical Barrier or other Barrier Installation approx Physical Barrier or other Barrier Installation approx Physical Barrier was installed to the following area(s) [roller & storerrooms. Bieffex Bieffex Bieffex Bieffex Biffex Bieffex Attraction and the total volume tased was [259] Lt. Attraction and the other antegrated with each other. The endbody of installation in the above system(s) Bieffex The endbody of installation was an end of the other. The system(s) Exception antegrated with each other. The system(s) Exception antegrated with each other. The exstention before a system(s) Exception and any allow-undetected Termite entry. You should consult with the builder, see the limitations below. Appendict Thales there the installation of garders, paths, lawas and other langerier is not complete formite entry. You should consult with the builder, see the limitations below. The resulting barrier is a complete/partial (cross out one or the other) and another inspection of the tother and standard AS 3660.2 that more frequent inspections (S to 6 inonthy) should	
BLD 3 Inter of owner/Englight From the second s	
perty Address 1193 Barrenioey Road adm Beach Post Code [2108 -6660.(Fermite work: Termiticide Liquid Barrier Treatment []	
and Each Post Code 2108 3660.Thermite work: Termitticide Equid Barrier Treatment Image: Solid Tremite work: Termitticide Equid Barrier Treatment 4 or Physical Barrier or other Barrier Installation Image: Solid Tremite Barrier was installed to the following area(s) toiler & storerooms. 4 day Physical Barrier is a complete/partial constraints was multicled in the following area(s) toiler & storerooms. Iwing the Barier was installed to the following area(s) toiler & storerooms. BiFrex webick contain the active constituents) Bifenthrin The concentration of the Input termiticket's used was [Newark Construction
and Beach Sofo.Trenuite work: Termiticide Liquid Barrier Treatment 2660.Trenuite work: Termiticide Liquid Barrier Treatment Image: Sofo.Trenuite Work: Termiticide Liquid Barrier Treatment 2160.Thermite Barrier was installed to the following areats) Imit & storemons. 2160.Thermite Barrier was installed to the following areats) Imit & storemons. 2160.Thermite Barrier was installed to the following areats) Imit & storemons. 2160.Thermite Barrier was installed to the following areats) Imit & storemons. 2161.The method is a complete/partial termiticide/s used was 96 217.The method is a complete/partial termiticide/s used was 96 217.The method is a complete/partial termiticide/s used was 100 217.The store of the other integrated with each other. The above systems? 217.The store of the other integrated with each other. The above systems? 217.The store of the other integrated with each other. The above systems? 216.The was the following area as a complete/partial terms are not offective and may allow-undetected Termite entry. You should coasait with the builder. See the linutations follow: 216.There was conside on the [5] day of [December] 21 [15] and a durable notice 216.There was conside on the [5] day of [December] 21 [15] and a durable notice 216.There was tended on the followin	1193 Barrenioev Road
3660. [Termite work: Termiticide Liquid Barrier Treatment Image: Status and	alm Beach
Wiquid Termite Barrier was installed to the following area(s) Initiet & storerooms. Insing the liquid termiticide(s) Bi-Flex which contain the active constituent(s) Bifenthrin . The concentration of the liquid termiticide(s used was [3660, l'Termite work: Termiticide Liquid Barrier Treatment
Bi-Flex which contain the active constituents) Bifenttrin The concentration of the liquid termiticide's used was 1 % and the total volume used was 250 ta. A Physical or other Barrier System(s) was installed in the following area(s) Not installed	d/or Physical Barrier or other Barrier Installation
Bi-Flex which contain the active constituents) Bifenttrin The concentration of the liquid termiticide's used was 1 % and the total volume used was 250 ta. A Physical or other Barrier System(s) was installed in the following area(s) Not installed	V Liquid Termite Barrier was installed to the following area(s) toilet & storerooms.
Bifentinia The concentration of the liquid termiticide/s used was n Bifentinia The concentration of the liquid termiticide/s used was n A Physical or other Barrier System(s) was installed in the following area(s) [Not installed nsing A Physical or other Barrier System(s) was installed in the following area(s) [Not installed nsing Crease out one or the other) integrated with each other. The above system(s) ECMONENT The system(s) ECMONENT (cross out one or the other) integrated with the concrete poured by the builder to form the termite barrier. The resulting barrier is a complete/partial (cross out one or the other) barrier, if the barrier is not complete further work may be required as partial barriers are not effective and may allow-undetected Termite entry. You should consult with the builder, see the limitations below. The Termite Barrier was carried out on the [5] day of [December] 20 [05] and a durable notice was placed [Meter Box] A optidiced Timber Pest trapector should inspect the building and its surrounds at least every twelve (12) months. 1 It is strongly recommended by the Australian Standard AS 3660.2 that more frequent inspections (3 to 6 monthly) should be carried out. 5 We recommend an inspection of the building and the surrounds every 12 months. 1 Termicde Darries, degrade thrask down over time and should be replenished in the future. After one of the required regul unspections of the building and the su	using the terminence -
Bifenthrin The concentration of the liquid termiticide/s used was 1 96.1 and the total volume used was 250 ta. A Physical or other Barrier System(s) was installed in the following area(s) Not installed ising The method(s) of installation was ising The system(s) installed in the following area(s) Not installed ising The system(s) installation was The above system(s) integrated with each other. The system(s) integrated with each other. The above system(s) integrated with the concrete poured by the builder to form the termite barrier. The resulting barrier is a complete/partial (cross out one or the other) barrier, if the barrier is not complete further work may be required as partial barriers are not effective and may allow-undetected Termite entry. You should consult with the builder. See the limitations below. The Termite Barrier was carried out on the 5 day of December 20 05 and a durable notice was placed [Meter Box A qualified Timber Pest Inspector should inspect the building and its surrounds at least every twelve (12) months. It is strongly recommended by the Australian Standard AS 5660.2 that more frequent inspections (3 to 6 monthly) should be carried out. We recommend an inspection of the building and the surrounds every 12 months. Termiticle Enrices degrade Greak down) over time and should be oplenished in the future. After one of the required regulation of encodered then the concrete from san integral pant of the termit	
A Physical or other Barrier System(s) was installed in the following area(s) [NOTHINATE: ising	101
A Physical or other Barrier System(s) was installed in the following area(s) [NOTHINATE: ising	and the total volume used was 250 1.t.
The method(s) of installation was the above system(s) ECTIONS (Trans out one or the other) integrated with each other. The system(s) ECTIONS (cross out one or the other) integrated with the concrete poured by the builder to form the termite barrier. The resulting barrier is a complete/partial (cross out one or the other) barrier, if the barrier is not complete further work may be required as partial barriers are not effective and may allow-undetected Termite entry. You should consult with the builder. See the limitations below. The Termite Barrier was carried out on the 5 day of December 20 05 and a durable notice was placed Meter Box and Not installed 1 and Not installed 1 A qualified Timber Pest thespector should inspect the building and its surrounds at least every twelve (1.2) months. It is strongly recommended by the Australian Standard AS 3660.2 that more frequent inspections (3 to 6 monthly) should be carried out. We recommend an inspection prior to the installation of gurdens, paths, lawns and other landscaping and again on completion of this work does not breach any termite barrier installed or allow concealed termite entry to the property. We recommend an inspection of the building and the surrounds every 12 months.	A Physical or other Barrier System(s) was installed in the following area(s) Not installed
The above system(s) EFICE (cross out one or the other) integrated with each other. The system(s) EFICE (cross out one or the other) integrated with the concrete poured by the builder to form the termite barrier. The resulting barrier is a complete/partial (cross out one or the other) barrier, if the barrier is not complete further work may be required as partial barriers are not effective and may allow-undetected Termite entry. You should consult with the builder. See the limitations below. The Termite Barrier was carried out on the 5 day of December 20 05 and a durable notice was placed Meter Box and Not installed A qualited Timber Pest Inspector should inspect the building and its surrounds at least every twelve (12) months. It is strongly recommended by the Australian Standard AS 3660.2 that more frequent inspections (3 to 6 monthly) should be carried out. We recommend an inspection prior to the installation of gardens, paths, lawns and other landscaping and again on completion of this work to ensure that this work does not breach any termite barrier installed or allow concealed termite entry to the property. We recommend an inspection of the building and the surrounds every 12 months. Fermiticke Barriers degrade theak down) over time and should be replenished in the turne. After one of the required regular inspections of the property, the inspector may advice you of the need to re install the Treated Zone or Barrier. If the above barrier(s) is/are integrated with the concrete them the concrete forms an integral part of the termite barrier to its inconcrete should be asked for a Centificate from the concrete form that the concrete has been pour in accordance with AS 3660.1-2000. Terms and Conditions on Page 1 form an important part of this Certificate. Limitations that apply to the above installation are:	using
Letterss out one or the other) integrated with each other. The system(s) LickIOLS at (cross out one or the other) integrated with the concrete poured by the builder to form the termite barrier. The resulting barrier is a complete/partial (cross out one or the other) barrier, if the barrier is not complete further work may be required as partial barriers are not effective and may allow-undetected Termite entry. You should consult with the builder. See the limitations below. The Termite Barrier was carried out on the 5 day of December 20 95 and a durable notice was placed Meter Box and Not installed A qualified Timber Pest hispector should inspect the building and its sorrounds at least every twelve (12) months. It is strongly recommended by the Australian Standard AS 3660.2 that more frequent inspections (3 to 6 monthly) should be carried out. We recommend an inspection prior to the installation of gardens, paths, lawns and other landscaping and again on completion of this work to ensure that this work does not breach any termite barrier installed or allow concealed termite entry to the property. We recommend an inspection of the building and the surrounds every 12 months. The above barriers degrade theak down) over time and should be replenished in the luture. After one of the required regular spections of the building and the surrounds every 12 months. The above barriers is/are integrated with the concrete them the concrete forms an integral part of the termite barrier to its trutter. In this case, the Builder should be asked for a Certificate from the concrete form that the concrete has been pour in accordance with AS 3660.1-2000. Terms and Conditions on Page 1 form an important part of this Certificate. Limitations that apply to the above installation are:	
The system(s) Exercises (cross out one or the other) integrated with the concrete poured by the builder to form the termite barrier. The resulting barrier is a complete/partial (cross out one or the other) barrier, if the barrier is not complete further work may be required as partial barriers are not effective and may allow-undetected Termite entry. You should consult with the builder. See the limitations below. The Termite Barrier was carried out on the 5 day of December 20 05 and a durable notice was placed Meter Box and Not installed 105 and a durable notice. A qualified Timber Pest Inspector should inspect the building and its surrounds at least every twelve (12) months. It is strongly recommended by the Australian Standard AS 3660.2 that more frequent inspections (3 to 6 nonthly) should be carried out. We recommend an inspection prior to the installation of gardens, paths, lawns and other landscaping and again or completion of this work to ensure that this work does not breach any termite barrier installed or allow concealed termite entry to the property. We recommend an inspection of the building and the surrounds every 12 months. Fermiticide Barriers degrade (break down) over time and should be replenished in the future. After one of the required regulator regulator is a day at your of the need to re install the Treated Zine or Barrier. If the above barrier(s) is/are integrated with the concrete them the concrete forms an integral pan of the termite barrier to its functions, the Builder should be asked for a Certificate from the concrete form that the concrete has been pour in accordance with AS 3660 1-2000. Terms and Conditions on Page 1 form an important part of this Certificate. Limitations that apply to the above installation are:	The above system(s) Elemol
The system(s) Exercises (cross out one or the other) integrated with the concrete poured by the builder to form the termite barrier. The resulting barrier is a complete/partial (cross out one or the other) barrier, if the barrier is not complete further work may be required as partial barriers are not effective and may allow-undetected Termite entry. You should consult with the builder. See the limitations below. The Termite Barrier was carried out on the 5 day of December 20 05 and a durable notice was placed Meter Box and Not installed 105 and a durable notice the further Pest inspector should inspect the building and its surrounds at least every twelve (12) months. It is strongly recommended by the Australian Standard AS 3660.2 that more frequent inspections (3 to 6 monthly) should be carried out. We recommend an inspection prior to the installation of gurdens, paths, lawns and other landscaping and again or completions of this work to ensure that this work does not breach any termite barrier installed or allow concealed termite entry to the property. We recommend an inspection of the building and the surrounds every 12 months.	(cross out one or the other) integrated with each other.
further work may be required as partial barriers are not effective and thay anoweneccerce returns only should consult with the builder. See the limitations below. The Termite Barrier was carried out on the 5 day of December 20 05 and a durable notice was placed Meter Box and Not installed A qualified Timber Pest Inspector should inspect the building and its surrounds at least every twelve (12) months. It is strongly recommended by the Australian Standard AS 3660.2 that more frequent inspections (3 to 6 monthly) should be carried out. We recommend an inspection prior to the installation of gardens, paths, lawns and other landscaping and again on completion of this work to ensure that this work does not breach any termite barrier installed or allow concealed termite entry to the property. We recommend an inspection of the building and the surrounds every 12 months. Fermiticide Baniers degrade (break down) over time and should be replenished in the future. After one of the required regul inspections of the property, the inspector may advise you of the need to re install the Treated Zone or Barrier. If the above barrier(s) is/are integrated with the concrete then the concrete forms an integral part of the termite barrier to fit structure. In this case, the Builder should be asked for a Certificate from the concrete firm that the concrete has been pour in accordance with AS 3660.1-2000. Terms and Conditions on Page 1 form an important part of this Certificate. Limitations that apply to the above installation are:	termite burrier
 was placed Meter Box and Not instance A qualified Timber Pest Inspector should inspect the building and its surrounds at least every twelve (12) months. It is strongly recommended by the Australian Standard AS 3660.2 that more frequent inspections (3 to 6 monthly) should be carried out. We recommend an inspection prior to the installation of gardens, paths, lawns and other landscaping and again on completion of this work to ensure that this work does not breach any termite barrier installed or allow concealed termite entry to the property. We recommend an inspection of the building and the surrounds every 12 months. Termiticide Barriers degrade (break down) over time and should be replenished in the future. After one of the required regularity for the property, the inspector may advice you of the need to re-install the Treated Zone or Barrier. If the above barrier(s) is/are integrated with the concrete then the concrete forms an integral part of the termite barrier to its structure. In this case, the Builder should be asked for a Certificate from the concrete firm that the concrete has been pour in accordance with AS 3660.1-2000. Terms and Conditions on Page 1 form an important part of this Certificate. timitations that apply to the above installation are:	further work may be required as partial barriers are not effective and may anow difference returns of the should consult with the builder. See the limitations below.
A qualified Timber Pest Inspector should inspect the building and its surrounds at least every (weive (12) months. It is strongly recommended by the Australian Standard AS 3660.2 that more frequent inspections (3 to 6 monthly) should be carried out. We recommend an inspection prior to the installation of gardens, paths, lawns and other landscaping and again on completion of this work to ensure that this work does not breach any termite barrier installed or allow concealed termite entry to the property. We recommend an inspection of the building and the surrounds every 12 months. Fermiticide Barriers degrade (break down) over time and should be replenished in the future. After one of the required regul inspections of the property, the inspector may advise you of the need to re-install the Treated Zone or Barrier. If the above barrier(s) is/are integrated with the concrete then the concrete forms an integral part of the termite barrier to it structure. In this case, the Builder should be asked for a Certificate from the concrete firm that the concrete has been pour in accordance with AS 3660.1-2000. Terms and Conditions on Page 1 form an important part of this Certificate. Limitations that apply to the above installation are:	was placed Meter Box and Not instance
 It is strongly recommended by the Australian Standard AS 3660.2 that more frequent inspections (3 to 6 monthly) should be carried out. We recommend an inspection prior to the installation of gardens, paths, lawns and other landscaping and again on completion of this work to ensure that this work does not breach any termite barrier installed or allow concealed termite entry to the property. We recommend an inspection of the building and the surrounds every 12 months. Fermiticide Barriers degrade (break down) over time and should be replenished in the future. After one of the required regulinspections of the property, the inspector may advice you of the need to re-install the Treated Zone or Barrier. If the above barrier(s) is/are integrated with the concrete then the concrete forms an integral part of the termite barrier to flastructure. In this case, the Builder should be asked for a Certificate from the concrete firm that the concrete has been pour in accordance with AS 3660.1-2000. Terms and Conditions on Page 1 form an important part of this Certificate. Limitations that apply to the above installation are: 	A circlified Timber Pest Inspector should inspect the building and its surrounds at least every twelve (12) months.
We recommend an inspection prior to the installation of gardens, paths, lawns and other landscaping and again on completion of this work to ensure that this work does not breach any termite barrier installed or allow concealed termite entry to the property. We recommend an inspection of the building and the surrounds every 12 months. Termiticide Barriers degrade (break down) over time and should be replenished in the future. After one of the required regulations of the property, the inspector may advise you of the need to re-install the Treated Zone or Barrier. If the above barrier(s) is/are integrated with the concrete then the concrete forms an integral part of the termite barrier to it structure. In this case, the Builder should be asked for a Certificate from the concrete firm that the concrete has been pour in accordance with AS 3660.1-2000. Terms and Conditions on Page 1 form an important part of this Certificate. Limitations that apply to the above installation are:	It is strongly recommended by the Australian Standard AS 3660.2 that more frequent inspections (3 to monthly) should be carried out.
We recommend an inspection of the building and the surrounds every 12 months. Termiticide Barriers degrade (break down) over time and should be replenished in the future. After one of the required regule inspections of the property, the inspector may advise you of the need to re-install the Treated Zone or Barrier. If the above barrier(s) is/are integrated with the concrete then the concrete forms an integral part of the termite barrier to il structure. In this case, the Builder should be asked for a Certificate from the concrete firm that the concrete has been pour in accordance with AS 3660.4-2000. Terms and Conditions on Page 1 form an important part of this Certificate. Limitations that apply to the above installation are:	We recommend an inspection prior to the installation of gardens, paths, lawns and other landscaping and again o completion of this work to ensure that this work does not breach any termite barrier installed or allow concealed termi
Termiticide Barriers degrade (break down) over time and should be replenished in the future. After one of the required regul inspections of the property, the inspector may advise you of the need to re-install the Treated Zone or Barrier. If the above barrier(s) is/are integrated with the concrete then the concrete forms an integral part of the termite barrier to it structure. In this case, the Builder should be asked for a Certificate from the concrete firm that the concrete has been pour in accordance with AS 3660.1-2000. Terms and Conditions on Page 1 form an important part of this Certificate. Limitations that apply to the above installation are:	We expressed an inspection of the building and the surrounds every 12 months.
If the above barrier(s) is/are integrated with the concrete then the concrete forms an integral part of the termite barrier to il structure. In this case, the Builder should be asked for a Certificate from the concrete firm that the concrete has been pour in accordance with AS 3660.1-2000. Terms and Conditions on Page 1 form an important part of this Certificate.	the sequired reg
structure. In this case, the Builder should be asked for a Certificate from the Concrete firm that the Concrete state of the in accordance with AS 3660.4-2000. Terms and Conditions on Page 1 form an important part of this Certificate. Limitations that apply to the above installation are:	inspections of the property, the inspector may advise you of the fixed to be main one promotion of the result human terminate
Limitations that apply to the above installation are:	structure. In this case, the Builder should be asked for a Certificate from the Conciete from that the Costovers in accordance with AS 3660.1-2000.
	Terms and Conditions on Page 1 form an important part of this Certificate.
No barrier installed to suspended subfloor of area of building.	Limitations that apply to the above installation are:
	No barrier installed to suspended subfloor of area of building.

.

Į

LEGEND	North is approximately:
Plumbing States and the states of the states	
Piers	
Steps Termite Barriers	
Other:	
	FYISFING BUILDING
	OFARS + JOIST.

Diagram (not to scale) showing the location of the installed barrierts). The direction of North is indicated by the \uparrow symbol.

It is very important that the Termite Barrier is not bridged or breached. This can happen when installing garden beds. have or other landscaping or building works. You should contact this firm prior to carrying out any such work. DO NOT disturb the treated areas in any way.

Frequent inspections are very important. Termite barriers do not kill or stop termites. The barriers are installed to prevent concealed access only. The barriers are designed to force the termites into the open. Thus the mud tubes that they use to gain access may be seen during inspections. For this reason such inspections should be carried out at least annually. A Termite treatment in accordance with AS 3660,2-2000 can then be carried out to eradicate the termites.

If you become aware of any activity **do not disturb the termites** in any way. You should notify this firm as soon as possible. Please contact us if ever you have any concerns about Termites or the effectiveness of the Barrier.

Installation Firm: Alternative Pest Control	Name of Installer: Michael Sparozvich
Firm's Address: PO Box 4111	Installer's Licence No.: 1829
North Curl Curl	Insurance Termite Accreditation No.: 02387
Sydney Post Code: 2099	Signature: M. Spanozuit
Telephone: 02-99815666	Signature: \underline{M} , $\underline{Spansquik}$ Date: $\underline{O5 - 12 - 2005}$,

© Copyright RAPID Solutions 2001 - for use by RAPID Solutions clients only correct s 202

Certificate of Installation in accordance with AS 3660.1-2000

New construction

Name of owner/builder:Newark Constructions

Property Address: 1193 Barrenjoey Road Palm Beach.

State: NSW Post Code 2108

AS 3660.1Termite work: Termiticide Liquid Barrier Treatment

A Liquid Barrier Treatmentwas installed to the following area(s) Storage And coldroom using the liquid termiticide(s) Bi-Flex which contain the active constituent(s) Bifenthrin. The concentration of the liquid termiticide/s spray mixture used was 1% and the total volume used was 500 Lt.

A Physical or other Barrier System(s) was installed in the following area(s) Not applicable using Not applicable. The method(s) of installation was Not applicable. The above system(s) **are not** integrated with each other.

The system(s) are not integrated with the concrete poured by the builder to form the termite barrier.

The resulting barrier is a partial barrier, if the barrier is not complete further work may be required as partial barriers are not effective and may allow undetected Termite entry. You should consult with the builder. See the limitations below.

The Termite Barrier was carried out on the 5 day of December 2005 and a durable notice was placed in Meter box.

A qualified Timber Pest Inspector should inspect the building and its surrounds at least every twelve (12) months. It is strongly recommended by the Australian Standard AS 3660.2 that more frequent inspections (3 to 6 monthly) should be carried out.

We recommend an inspection prior to the installation of gardens, paths, lawns and other landscaping and again on completion of this work to ensure that this work does not breach any termite barrier installed or allow concealed termite entry to the property.

We recommend an inspection of the building and the surrounds every 6 months.

Termiticide Barriers and/or treated zones degrade (break down) over time and should be replenished in the future. After one of the required regular inspections of the property, the inspector may advise you of the need to re-install the Treated Zone or Barrier.

If the above barrier(s) and/or treated zone(s) is/are integrated with the concrete then the concrete forms an integral part of the termite barrier to this structure. In this case, the Builder should be asked for a Certificate from the concrete firm that the concrete has been poured in accordance with AS 3600 or AS2870-1996 and amendments.

Terms and Conditions on Page 1 and important information on page 2 form an important part of this Certificate.

Limitations that apply to the above installation are: No perimeter barrier tretment.

Certificate of Installation in accordance with AS 3660.1-2000

Terms and Conditions

DISCLAIMER OF LIABILITY TO THIRD PARTIES: - This Certificate is made solely for the benefit of the builder/owner named on the face of this Certificate and no liability or responsibility whatsoever is accepted to any third party who may rely on the Certificate either wholly or in part. Any third party acting or relying on this Certificate in whole or in part does so at their own risk. This disclaimer does not apply to persons responsible for Building Approvals.

- 1. Prior to the site being prepared the builder should have ensured that all termite activity found was eradicated in accordance with AS 3660.1-2000, Prior to work commencing, the builder should have arranged for a qualified licensed person to inspect the site to investigate and eradicate all economically important termite nests found. The failure to have this inspection carried out may mean that termite nests may not have been found and eradicated and may still be active under the construction. See clauses 3 and 10 below.
- 2. The effectiveness of this installation is dependent upon the provision of a complete (full) barrier being installed in accordance with AS 3660.1-2000 using approved termiticides, systems and/or products. If the barriers are disturbed, breached or bridged then concealed entry by subterranean termites is possible.
- 3. No liability is accepted for any failure of a termite barrier and this firm warrants only to provide such remedial action as may be necessary during the first 12 months from the date of this Certificate. No such warranty is provided if there are limitations listed on this Certificate or if the barrier is a partial barrier or if the builder has not arranged for the termite eradication in clause 1 above.
- The barrier(s) installed, as detailed on this Certificate and in the diagram, provide a barrier against subterranean termites only. The barrier is not a barrier against any other pest(s) and in particular does not provide any barrier against "drywood (KALOTERMITIDAE) or dampwood termites.
- 5. No responsibility is accepted, or warranty implied, for any termite damage that may occur as the result of termite activity, either past, current or in the future.
- O. The termite barrier(s) can be rendered ineffective due to building alterations, renovations, additions (pergolas, awnings, verandahs etc), introducing infested materials, timber offcuts, wood chips and formwork left on site, materials stored against the building. External barriers can be destroyed completely by the installation of lawns, gardens, pathways, landscaping etc adjacent to the building. When making such changes you should liest contact this firm. Where such changes are made a further termite barrier installation is essential.
- 7. When installing paths, lawn, gardens etc it is very important not to cover air vents or weep holes. If the slab edge is exposed by 75 mm to form part of the termite barrier system then it is equally important not to cover the slab edge unless another form of barrier is installed. Again contact this firm before carrying out any such covering. Where such changes are made a further termite barrier installation is essential.
- 8. Do not use untreated timbers for garden edges or retaining walk. Untreated timber attracts termites
- Good ventilation and drainage are important, as poor ventilation and drainage greatly increases the risk of termite attack.
 This firm takes NO_RESPONSIBILITY for the conceated entry by termites resulting from poor building design or poor building practices.
- 11. It is the building owner's responsibility to cosure that the inspections, recommended in AS 3660.2-2000, are performed. Please contact this firm.

VERY IMPORTANT

If you become aware of the presence of termites within the grounds or on or within the building you should contact this firm or another termite management firm immediately. You should also notify this firm if you become aware that the installed barrier has been breached or bridged in any way.

The Australian Standard AS 3660,2-2000 recommends that: "Regular, competent inspections should be carried out at least on an annual basis but more frequent inspections are strongly recommended". The Standard also recommends "The building owner should ensure that regular inspections -- are carried out by a person competent in Unit 8 Inspect and Report on Timber Pests of the National Pest Management Competency Standards, or equivalent" and has "experience in accordance with that specified in AS 4349.3 1998". Termites can build around barriers but can be detected during the recommended inspections.

Modern termiticides have a limited life expectancy. The termite barriers will need to be re-installed. The timing can only be determined by regular, competent inspections as recommended by AS 3660.2-2000 carried out by a qualified termite inspector.

IMPORTANT INFORMATION: The Australian Standard AS 3660.1-2000 Termite Management Part 4: New Buildings details the "methods to deter concealed entry by termites" and goes on to say " a termite barrier system constructed in accordance with this Standard cannot prevent termite attack, as barriers may be bridged or breached. Where termites bridge barriers the evidence may be detected during inspections." A treatment in accordance with AS 3660.2-2000 to eradicate such an infestation will be required.

Southerness & Food Selety Inform		Control Control P
Notificat Your Notification for this Food Business has been	ion Confirmation n recorded by NAFSIS.	
Please PRINT or keep your own record	of the following details:	Print
Business Notification Reference Number :	34871	
Date of Notification :		
Proprietor / Company Name :	Seasons Catering Pty Ltd	
Trading Name :	Dunes Restaurant and Kiosk	
Office Address :	1193 Barrenjoey Road	· · ·

To keep a record of this notification, either press Print or highlight the text area with your mouse, press CtrI-C, then paste the details into another application such as Microsoft Word or Excel.

Please note your Online access code (for viewing / changing details online); fba215

The above access code is confidential and is to be used in conjunction with your Notification Reference number to view / change your notification details online. We recommend you change this access code from time to time to maintain privacy and security.

Enter additional premises Change premise details

View / Edit notification details

Enter additional food types Exit to home page New business notification

http://www.foodnotify.nsw.gov.au/nafsis/system/business/reg business.cfm

20/03/2006



Pittwater Council

Component Certificate

N0330/03 DA No:

CC No:

Property: GOVERNOR PHILLIP PARK 1193 BARRENJOEY ROAD PALM **BEACH NSW 2108**

Site Stormwater Management

SW-1

- SAMVEL

MEGALOKONOMOS of CONOMOS PLOMEING (Name) (Business)

at

(Mailing Address)

being an:

accredited certifier

licensed plumber

practising civil engineer

with corporate membership of the Institute of Engineers Australia (MIE), or eligible to become a Corporate member and having appropriate experience and competence in the related field, my qualifications being:

LICENCED PRUBER - LIC Nº 150575C.

hereby certify that the stormwater disposal system has been provided in accordance with Part 3.1.2 "Drainage" of the Building Code of Australia Housing Provisions, AS/NZS 3500.3.2-1998 "National Plumbing and Drainage Code - Stormwater drainage - Acceptable solutions", and the relevant conditions of Development Consent.

Further, I am appropriately qualified and experienced to provide the certification for this component of the project.

promos Date 30 3 06 Signature ...