



WSA assessment



Date: 10/08/2022	Asset owner's job ref.: 1	Asset Owner: Civil Scan	Operator : Terry Heron	Section number: 1	Pipe Asset Id: SPI11867
Time of inspection: 11:35:54	Cleaning: not cleaned	Standard: WSA 05-2008 2.2	LRP Inside Face of the Wall	Conduit Unit Length	Method of Inspection Television Camera

Town: Suburb: Street: Asset Location	Dee Why Bix Road Private property, industrial site	Catchment: Asset Owner: Precipitation.: Flow control	Civil Scan No No measures	US MH: Survey Dir: DS MH: Inspect Length :	SPP13738 downstream SPP13737 17.29 m
---	---	---	--	---	---

Purpose of inspection : Use of Conduit: Type of Conduit: Lining Method:	Locating a conduit, connection or a maintenance storm watercourse Storm water drain	Shape : Dia/Height: Lining: Pipe Material:	Circular 600 mm Concrete pipe
--	--	---	--

Remarks :
Video Link

1:500 Position Code Observation



17.29 m

STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0	0	0	1	0	0	0	0	1



Inspection Pictures

Location/Street Bix Road	Town or suburb:	Date : 10/08/2022	Section number: 1	Sewer Ref.: SPI11867
------------------------------------	-----------------	-----------------------------	-----------------------------	--------------------------------



Photo: 122218SPI11867S_SPARE5_SPP13737703202114_D.JPG
17.29m, Junction open, good workmanship, height 100mm, width 100mm , at 2 o'clock