GEOTECHNICAL RISK MANAGEMENT POLICY FOR PITTWATER FORM NO. 1 – To be submitted with Development Application

Development Application for				
			Name of Applicant	
Address of site 3 Irrub		3 Irrubel Road	ad, Newport	
			equirements to be addressed in a Geotechnical Risk Declaration made by logist or coastal engineer (where applicable) as part of a geotechnical report	
l,	Ben White (Insert Name)	on behalf of	White Geotechnical Group Pty Ltd (Trading or Company Name)	
organisat	ngineer as defined	sue this document a	certify that I am a geotechnical engineer or engineering geologist o cal Risk Management Policy for Pittwater - 2009 and I am authorised by the above and to certify that the organisation/company has a current professional indemnity	
: Please m	nark appropriate	box		
\boxtimes			chnical Report referenced below in accordance with the Australia Geomechanics nent Guidelines (AGS 2007) and the Geotechnical Risk Management Policy fo	
\boxtimes	am willing to te	the Australian Geom	at the detailed Geotechnical Report referenced below has been prepared in omechanics Society's Landslide Risk Management Guidelines (AGS 2007) and the dicy for Pittwater - 2009	
	with Section 6.0 assessment for	of the Geotechnical F the proposed develo	posed development in detail and have carried out a risk assessment in accordance It Risk Management Policy for Pittwater - 2009. I confirm that the results of the risl elopment are in compliance with the Geotechnical Risk Management Policy for digeotechnical reporting is not required for the subject site.	
	have examined to Application only	he site and the propo involves Minor De	posed development/alteration in detail and I am of the opinion that the Developmen Development/Alteration that does not require a Geotechnical Report or Risk s in accordance with the Geotechnical Risk Management Policy for Pittwater - 2009	
	have examined the Hazard and does the Geotechnical	s not require a Geote I Risk Management F	posed development/alteration is separate from and is not affected by a Geotechnical otechnical Report or Risk Assessment and hence my Report is in accordance with the Policy for Pittwater - 2009 requirements.	
	have provided th	e coastal process an	and coastal forces analysis for inclusion in the Geotechnical Report	
_	nical Report Deta		1.1.15	
	Report Title: Geo Report Date: 23/	·	Irrubel Road, Newport	
	Author: BEN WH	HITE		
	Author's Compan	y/Organisation: WHI	HITE GEOTECHNICAL GROUP PTY LTD	
			d upon in report preparation:	
	Australian G	eomechanics So	Society Landslide Risk Management March 2007.	

I am aware that the above Geotechnical Report, prepared for the abovementioned site is to be submitted in support of a Development Application for this site and will be relied on by Pittwater Council as the basis for ensuring that the Geotechnical Risk Management aspects of the proposed development have been adequately addressed to achieve an "Acceptable Risk Management" level for the life of the structure, taken as at least 100 years unless otherwise stated and justified in the Report and that reasonable and practical measures have been identified to remove foreseeable risk.

Name

Ben White

Chartered Professional Status

MScGEOLAusIMM CP GEOL

Membership No.

222757

Company

White Geotechnical Group Pty Ltd

White Geotechnical Group company archives.



GEOTECHNICAL RISK MANAGEMENT POLICY FOR PITTWATER FORM NO. 1(a) - Checklist of Requirements for Geotechnical Risk Management Report for Development Application

Devel	opment Application fo		
		Name of Applicant	
	ess of site	3 Irrubel Road, Newport	
Report.	This checklist is to acco	e minimum requirements to be addressed in a Geotechnical Risk Management Geotechnical mpany the Geotechnical Report and its certification (Form No. 1).	,
	hnical Report Details:	ort 3 Irrubel Road, Newport	_
,		on o mason read, now port	
	t Date: 23/5/25		
	r: BEN WHITE		
Autho	or's Company/Organis	tion: WHITE GEOTECHNICAL GROUP PTY LTD	
Please	mark appropriate box		
	Comprehensive site m	pping conducted 20/5/25 (date)	
\boxtimes	Mapping details prese	ted on contoured site plan with geomorphic mapping to a minimum scale of 1:200 (as appropriate)	
\boxtimes	Subsurface investigation		
	□ No	ustification	
		ate conducted 20/5/25	
\boxtimes	Geotechnical model de	eloped and reported as an inferred subsurface type-section	
\boxtimes	Geotechnical hazards	dentified	
		site	
	oxtimes On the s	е	
	⊠ Below th	site	
	☐ Beside t		
\boxtimes	Geotechnical hazards	escribed and reported	
\boxtimes	Risk assessment cond	cted in accordance with the Geotechnical Risk Management Policy for Pittwater - 2009	
	□ Consequ	ence analysis	
		y analysis	
\boxtimes	Risk calculation		
\boxtimes	Risk assessment for p	pperty conducted in accordance with the Geotechnical Risk Management Policy for Pittwater - 2009	
\boxtimes	Risk assessment for lo	s of life conducted in accordance with the Geotechnical Risk Management Policy for Pittwater - 200)9
\boxtimes	Assessed risks have b	en compared to "Acceptable Risk Management" criteria as defined in the Geotechnical Risk	
	Management Policy fo		
\boxtimes		ded that the design can achieve the "Acceptable Risk Management" criteria provided that the	
	specified conditions ar	achieved.	
\boxtimes	Design Life Adopted:		
	⊠ 100 year		
	☐ Other	specify	
\boxtimes	Geotechnical Condition	s to be applied to all four phases as described in the Geotechnical Risk Management Policy for	
\boxtimes		ove risk where reasonable and practical have been identified and included in the report.	
		Bushfire Asset Protection Zone.	
that the Manage	geotechnical risk mana ement" level for the life	il will rely on the Geotechnical Report, to which this checklist applies, as the basis for ensuri ement aspects of the proposal have been adequately addressed to achieve an "Acceptable Ri f the structure, taken as at least 100 years unless otherwise stated, and justified in the Report al measures have been identified to remove foreseeable risk.	isk
	Signature	POFESSION ALL	
	Name	Ben White Australian Institute of Geoscientists	
		BENJAMIN WHITE	
	Chartered Professional	Status MScGEOLAusIMM CP GEOL	

222757

White Geotechnical Group Pty Ltd

Membership No.

Company



J6048. 23rd May, 2025. Page 1.

GEOTECHNICAL INVESTIGATION:

New Pool at 3 Irrubel Road, Newport

1. Proposed Development

- 1.1 Install a new pool with paved area at the downhill side of the house side by excavating to a maximum depth of ~1.8m.
- 1.2 Details of the proposed development are shown on 7 drawings prepared by Outside Living, job number 25-10, drawings numbered Sht-1 to Sht-7, Issue B, dated 14/5/25

2. Site Description

- **2.1** The site was inspected on the 20th May, 2025.
- 2.2 This residential property is on the low side of the road and has a S aspect. It is located on the gentle to moderately graded lower middle reaches of a hillslope. The natural slope falls across the property at an average angle of ~9°. The slope above the property gradually increases in grade. The slope below the property gradually decreases in grade.
- 2.3 Fill provides a level platform for the road. The fill is battered at stable angles across the road reserve. At the road frontage, a concrete driveway runs down the slope to a carport at the NE side of the house (Photo 1). The part two storey house is supported on brick walls and piers (Photos 1 & 2). The supporting walls show no significant signs of movement and the supporting piers stand vertical (Photo 3). A low concrete block retaining wall supports a fill for a lawn area at the downhill side of the house (Photo 4). The wall displays some vertical cracks, but will be mostly demolished as part of the proposed works. Another lawn area extends from the downhill side of the retaining wall to the downhill property boundary (Photos 5 & 6). No signs of slope



J6048. 23rd May, 2025. Page 2.

instability were observed on the property. The adjoining neighbouring properties were observed to be in good order as seen from the street and subject property.

3. Geology

The Sydney 1:100 000 Geological sheet indicates the site is underlain by the Newport Formation of the Narrabeen Group. This is described as interbedded laminite, shale, and quartz to lithic quartz sandstone.

4. Subsurface Investigation

One hand Auger Hole (AH) was put down to identify the soil materials. Four Dynamic Cone Penetrometer (DCP) tests were put down to determine the relative density of the overlying soil and the depth to weathered rock. The locations of the tests are shown on the site plan attached. It should be noted that a level of caution should be applied when interpreting DCP test results. The test will not pass through hard buried objects so in some instances it can be difficult to determine whether refusal has occurred on an obstruction in the profile or on the natural rock surface. This may have occurred for DCP1. Due to the possibility that the actual ground conditions vary from our interpretation there should be allowances in the excavation and foundation budget to account for this. We refer to the appended "Important Information about Your Report" to further clarify. The results are as follows:

AUGER HOLE 1 (~RL23.9) – AH1 (Photo 7)

Depth (m)	Material Encountered
0.0 to 0.4	FILL , sandy soil and clay, with some rock fragments, dark brown, orange, damp, fine to coarse grained.
0.4 to 0.6	CLAY, orange/brown, firm to stiff, moist.

End of hole @ 0.6m in firm to stiff clay. No water table encountered.



J6048. 23rd May, 2025. Page 3.

DCP TEST RESULTS – Dynamic Cone Penetrometer				
Equipment: 9kg hammer, 510mm drop, conical tip. Standard: AS1289.6.3.2 -				d: AS1289.6.3.2 -1997
Depth(m) Blows/0.3m	DCP 1 (~RL23.7)	DCP 2 (~RL24.1)	DCP 3 (~RL24.1)	DCP 4 (~RL25.2)
0.0 to 0.3	3	5	4	3
0.3 to 0.6	7	11	6	2
0.6 to 0.9	12	9	9	7
0.9 to 1.2	#	14	24	17
1.2 to 1.5		16	63	51
1.5 to 1.8		#	#	#
	Refusal @ 0.8m	Refusal on Rock @ 1.3m	End of Test @ 1.3m	End of Test @ 1.4m

#refusal/end of test. F=DCP fell after being struck showing little resistance through all or part of the interval.

DCP Notes:

DCP1 – Refusal @ 0.8m, DCP thudding, brown soil on muddy wet tip.

DCP2 – Refusal on Rock @ 1.3m, DCP thudding on rock surface, dark brown sandy soil on muddy wet tip.

DCP3 – End of Test @ 1.5m, DCP still very slowly going down, dark brown sandy soil on muddy wet tip, orange clay in collar above tip.

DCP4 – End of Test @ 1.4m, DCP still very slowly going down, brown sandy soil on damp tip, orange clay in collar above tip.

5. Geological Observations/Interpretation

The slope materials are colluvial at the near surface and residual at depth. In the test locations, the ground materials consist of fill and a thin topsoil over Firm to Stiff Clays. Fill to a maximum depth of ~0.8m provides level platforms for lawn areas across the property. In the test locations, the clays merge into the weathered zone of the underlying rock at an average depth of ~1.2m below the current surface. The weathered zone of the underlying rock is interpreted as Extremely Low to Low Strength Rock. It is to be noted that this material is a soft rock and can appear as a mottled stiff clay when it is cut up by excavation equipment.



J6048.

23rd May, 2025.

Page 4.

See Type Section attached for a diagrammatical representation of the expected ground

materials.

6. Groundwater

Ground water seepage is expected to move over the denser and less permeable clay and

weathered rock layers in the sub-surface profile. Due to the slope and elevation of the block,

the water table is expected to be many metres below the base of the proposed works.

7. Surface Water

No evidence of surface flows were observed on the property during the inspection. Normal

sheet wash from the slope above will be intercepted by the street drainage system for Irrubel

Road above.

8. Geotechnical Hazards and Risk Analysis

No geotechnical hazards were observed beside the property. The gentle to moderately

graded slope that falls across the property and continues above and below is a potential

hazard (Hazard One). The proposed excavation is a potential hazard until retaining structures

are in place (Hazard Two).

RISK ANALYSIS SUMMARY ON NEXT PAGE



J6048. 23rd May, 2025. Page 5.

Geotechnical Hazards and Risk Analysis - Risk Analysis Summary

HAZARDS	Hazard One	Hazard Two
ТҮРЕ	The gentle to moderate slope that falls across the property and continues above and below failing and impacting on the house or the proposed works.	The proposed excavation for the pool collapsing onto the worksite during the excavation process.
LIKELIHOOD	'Unlikely' (10 ⁻⁴)	'Possible' (10 ⁻³)
CONSEQUENCES TO PROPERTY	'Medium' (12%)	'Medium' (13%)
RISK TO PROPERTY	'Low' (2 x 10 ⁻⁵)	'Moderate' (2 x 10 ⁻⁴)
RISK TO LIFE	4.2 x 10 ⁻⁷ /annum	3.7 x 10 ⁻⁵ /annum
COMMENTS	This level of risk is 'ACCEPTABLE'.	This level of risk to life and property is 'UNACCEPTABLE'. To move the risk to 'ACCEPTABLE' levels, the recommendations in Section 13 are to be followed.

(See Aust. Geomech. Jnl. Mar 2007 Vol. 42 No 1, for full explanation of terms)

9. Suitability of the Proposed Development for the Site

The proposed development is suitable for the site. No geotechnical hazards will be created by the completion of the proposed development provided it is carried out in accordance with the requirements of this report and good engineering and building practice.

10. Stormwater

No significant stormwater runoff will be created by the proposed development.

11. Excavations

An excavation to a maximum depth of ~1.8m is required to install the proposed pool. The excavation is expected to be through fill, topsoil and clay. Excavations through fill, soil and clay are expected to be carried out with an excavator and toothed bucket.



J6048. 23rd May, 2025.

Page 6.

12. Vibrations

It is expected the proposed excavation will be carried out with an excavator and toothed

bucket and the vibrations produced will be below the threshold limit for building or

infrastructure damage using a domestic sized excavator up to 20 tonne.

13. Excavation Support Requirements

An excavation to a maximum depth of ~1.8m is required to install the proposed pool. The

excavation is set back sufficiently from the surrounding structures and boundaries.

The excavation is expected to stand at near-vertical angles for short periods of time until the

pool structure is installed, provided the cut batters are kept from becoming saturated. If the

cut batters remain unsupported for more than a few days before the installation of the pool

structure they are to be temporarily supported with typical pool shoring such as braced form

ply until the pool structure is in place.

During the excavation process, the geotechnical consultant is to inspect the cut face in 1.5m

intervals as it is lowered to ensure ground materials are as expected and that additional

support is not required.

Upslope runoff is to be diverted from the cut faces by sandbag mounds or other diversion

works. All unsupported cut batters are to be covered to prevent access of water in wet

weather and loss of moisture in dry weather. The covers are to be tied down with metal pegs

or other suitable fixtures so they cannot blow off in a storm. The materials and labour to

construct the pool structure are to be organised so on completion of the excavation it can be

constructed as soon as possible. The excavation is to be carried out during a dry period. No

excavations are to commence if heavy or prolonged rainfall is forecast.

All excavation spoil is to be removed from site following the current Environmental Protection

Agency (EPA) waste classification guidelines.



J6048. 23rd May, 2025. Page 7.

14. Retaining Structures

For cantilever or singly propped retaining structures it is suggested the design be based on a triangular distribution of lateral pressures using the parameters shown in Table 1.

Table 1 – Likely Earth Pressures for Retaining Structures

	Earth Pressure Coefficients			
Unit	Unit weight (kN/m³)	'Active' Ka	'At Rest' K₀	
Fill and Topsoil	20	0.40	0.55	
Residual Clays	20	0.35	0.45	

For rock classes refer to Pells et al "Design Loadings for Foundations on Shale and Sandstone in the Sydney Region".

It is to be noted that the earth pressures in Table 1 assume a level surface above the wall, do not account for any surcharge loads and assume retaining walls are fully drained. Ground Materials and relevant earth pressure coefficients are to be confirmed on site by the geotechnical consultant.

All retaining structures are to have sufficient back-wall drainage and be backfilled immediately behind the structure with free draining material (such as gravel). This material is to be wrapped in a non-woven Geotextile fabric (i.e. Bidim A34 or similar), to prevent the drainage from becoming clogged with silt and clay. If no back-wall drainage is installed in retaining structures the full hydrostatic pressures are to be accounted for in the retaining structure design.

15. Site Classification

The site classification in accordance with AS2870-2011 is Class M.



J6048. 23rd May, 2025.

Page 8.

16. Foundations

The proposed pool is expected to be seated in firm to stiff clay. This is a suitable foundation

material. A maximum allowable bearing pressure of 200kPa can be assumed for firm to stiff

clay.

If any portion of the pool excavation encounters weathered rock, piers embedded in

weathered rock will be required to maintain a uniform foundation material across the

structure. This ground material is expected at depths of between ~0.8m to ~2.0m below the

current surface, being deeper in the filled area at the uphill side of the existing concrete block

retaining wall. A maximum allowable bearing pressure of 600kPa can be assumed for footings

embedded in Extremely Low Strength Rock or better. It should be noted that this material is

a soft rock and a rock auger will cut through it so the builders should not be looking for refusal

to end the footings.

As the bearing capacity of clay and weathered rock reduces when it is wet we recommend

the footings be dug, inspected and poured in quick succession (ideally the same day if

possible). If the footings get wet, they will have to be drained and the soft layer of clay or

weathered rock on the footing surface will have to be removed before concrete is poured.

If a rapid turnaround from footing excavation to the concrete pour is not possible a sealing

layer of concrete may be added to the footing surface after it has been cleaned and inspected.

NOTE: If the contractor is unsure of the footing material required it is more cost effective to

get the geotechnical professional on site at the start of the footing excavation to advise on

footing depth and material. This mostly prevents unnecessary over excavation in clay like

shaly rock but can be valuable in all types of geology.



J6048. 23rd May, 2025. Page 9.

17. Geotechnical Review

The structural plans are to be checked and certified by the geotechnical engineer as being in accordance with the geotechnical recommendations. On completion, a Form 2B will be issued. This form is required for the Construction Certificate to proceed.

18. **Inspections**

The client and builder are to familiarise themselves with the following required inspections as well as council geotechnical policy. We cannot provide geotechnical certification for the Occupation Certificate if the following inspections have not been carried out during the construction process.

- During the excavation process, the geotechnical consultant is to inspect the cut face in 1.5m intervals as it is lowered to ensure ground materials are as expected and that additional support is not required.
- All footings are to be inspected and approved by the geotechnical consultant while the excavation equipment and contractors are still onsite and before steel reinforcing is placed or concrete is poured.

White Geotechnical Group Pty Ltd.

Dion Sheldon

BEng(Civil)(Hons) MIEAust NER,

Geotechnical Engineer.



Reviewed By:

Nathan Gardner B.Sc. (Geol. & Geophys. & Env. Stud.) AIG., RPGeo Geotechnical & Engineering.

Klandner

No. 10307

Engineering Geologist & Environmental Scientist.





J6048. 23rd May, 2025. Page 10.



Photo 1



Photo 2



J6048. 23rd May, 2025. Page 11.



Photo 3



Photo 4



J6048. 23rd May, 2025. Page 12.



Photo 5



Photo 6



J6048. 23rd May, 2025. Page 13.



Photo 7: AH1 – Downhole is from top to bottom.



J6048. 23rd May, 2025. Page 14.


Important Information about Your Report

It should be noted that Geotechnical Reports are documents that build a picture of the subsurface conditions from the observation of surface features and testing carried out at specific points on the site. The spacing and location of the test points can be limited by the location of existing structures on the site or by budget and time constraints of the client. Additionally, the test themselves, although chosen for their suitability for the particular project, have their own limiting factors. The testing gives accurate information at the location of the test, within the confines of the test's capability. A geological interpretation or model is developed by joining these test points using all available data and drawing on previous experience of the geotechnical consultant. Even the most experienced practitioners cannot determine every possible feature or change that may lie below the earth. All of the subsurface features can only be known when they are revealed by excavation. As such, a Geotechnical report can be considered an interpretive document. It is based on factual data but also on opinion and judgement that comes with a level of uncertainty. This information is provided to help explain the nature and limitations of your report.

With this in mind, the following points are to be noted:

- If upon the commencement of the works the subsurface ground or ground water conditions prove
 different from those described in this report, it is advisable to contact White Geotechnical Group
 immediately, as problems relating to the ground works phase of construction are far easier and
 less costly to overcome if they are addressed early.
- If this report is used by other professionals during the design or construction process, any questions should be directed to White Geotechnical Group as only we understand the full methodology behind the report's conclusions.
- The report addresses issues relating to your specific design and site. If the proposed project design changes, aspects of the report may no longer apply. Contact White Geotechnical if this occurs.
- This report should not be applied to any other project other than that outlined in section 1.0.
- This report is to be read in full and should not have sections removed or included in other documents as this can result in misinterpretation of the data by others.
- It is common for the design and construction process to be adapted as it progresses (sometimes
 to suit the previous experience of the contractors involved). If alternative design and construction
 processes are required to those described in this report, contact White Geotechnical Group. We
 are familiar with a variety of techniques to reduce risk and can advise if your proposed methods
 are suitable for the site conditions.

SITE PLAN – showing test locations



EXISTING BUILDING

FXISTING PAVING

PROPOSED PAVING

PROPOSED POOL

EXISTING RETAINING WALLIWALL

O EXISTING TREE RETAIN

IDENTIFY & MARK THE LOCATION OF ALL ABOVE & BELOW GROUND SERVICES PRIOR TO COMMENCING ANY WORK TAKE ALL REQUIRED PRECALITIONS TO PREVENT DAMAGE TO SERVICES

F SOUND PROOF FILTER BOX

POOL OVERFLOW TO BE PUMPED TO SEWER TO COUNCIL'S & SYDNEY WATERS REQUIREMENTS

DRAWN BY

Unit 20 12 Philip Mall West Pymble 2073 Phone 9440 5451 ABN 97 077 163 663

Fellow of the Landscape Design Institute (Aust) Idi.org.au

SCALE @ ISO A3:1:100



Landscape Design Institute

NOTES TO THE PLAN

THIS PLAN IS TO BE READ AS PART OF A COMPLETE SET OF DRAWINGS RELATING TO THE PROPOSED DEVELOPMENT

THIS PLAN RELATES TO A SPECIFIC DEVELOPMENT INFORMATION RELATING TO THE DEVELOPMENT NEEDS TO BE CONFIRMED ON SITE PRIOR TO CONSTRUCTION

ALL MEASUREMENTS ARE IN MILLIMETRES UNLESS

Kathryn and Stewart Agus

3 Irrubel Rd NEWPORT PART SITE PLAN

озест

PROPOSED POOL AND LANDSCAPING

Date of Issue A 2/05/2025


B 14/05/2025

25-10

.

Sht-3

TYPE SECTION – Diagrammatical Interpretation of expected Ground Materials



SCALE @ ISO A3:1:100

DRAWN BY Unit 20 12 Phillip Mall West Pymble 2073 Phone 9440 5451 ABN 97 077 163 663

Fellow of the Landscape Design Institute (Aust) Idi.org.au

outside~

NOTES TO THE PLAN

THIS PLAN IS TO BE READ AS PART OF A COMPLETE SET OF DRAWINGS RELATING TO THE PROPOSED DEVELOPMENT

THIS PLAN RELATES TO A SPECIFIC DEVELOPMENT INFORMATION RELATING TO THE DEVELOPMENT NEEDS TO BE CONFIRMED ON SITE PRIOR TO CONSTRUCTION

ALL MEASUREMENTS ARE IN MILLIMETRES UNLESS

Kathryn and Stewart Agus

3 Irrubel Rd NEWPORT

DRAWING POOL SECTIONS

PROPOSED POOL AND LANDSCAPING


Date of Issue

A 2/05/2025

B 14/05/2025

JOB No 25-10 ISSUE В Sht-5

EXAMPLES OF GOOD HILLSIDE PRACTICE



EXAMPLES OF POOR HILLSIDE PRACTICE

