

HIS ANNEXURE A - 67 EUROBIN AVENUE PHOTOGRAPHS
INTERIOR PHOTOGRAPHS



1. View of the sunroom in the ground floor unit.



2. View of the sunroom in the ground floor unit showing damp present on the carpet and in the walls.



3. View of the doors to the sunroom in the ground floor unit.



4. View of the front bedroom in the ground floor unit.



5. View of the bathroom in the ground floor unit.



6.View of a typical window.



7 & 8. View of the rear ground floor bedroom.



9. View of the living and dining room of the ground floor unit.



10. View of the living and dining room of the first floor unit.



11. View of the living room of the first floor unit



12. View of the living and dining room of the first floor unit



I 3. View of the kitchen in the first floor unit.



I 4. View of a first floor bedroom showing the typical details.



15 and 16 showing the first floor sunroom that was originally an open verandah on the first floor facade.



17.View of the detail on the first floor ceiling.



18. View from the living room to the sunroom on the first floor.



19. View of the front bedroom on the first floor.



20. View of the room under the single storey lean-to at the rear: