



NOTE--TO BE READ IN CONJUNCTION WITH SURVEY:
 SDG PTY LTD
 REF: 5742 ISSUE D
 DATE: 12/02/2024



NOTES:

1. MARC GAUDRY OF MGP BUILDING & INFRASTRUCTURE SERVICES PTY LTD BEING ACCREDITED TO CARRY OUT A SERVICE PROTECTION REPORT, CERTIFY THAT THE INFORMATION SHOWN ON THIS REPORT HAS BEEN PREPARED IN ACCORDANCE WITH THE RELEVANT INSTRUCTIONS AND ACCEPT FULL RESPONSIBILITY FOR THE ACCURACY OF THE INFORMATION ON THIS REPORT.
SIGN: *Marc Gaudry*
2. FOR THE PURPOSE OF THIS REPORT, "BOUNDARY" REFERS TO THE ACTUAL PROPERTY BOUNDARY AS IDENTIFIED IN THE PROPERTY SURVEY PLAN. PHYSICAL MEASUREMENTS HAVE BEEN TAKEN FROM FIXED STRUCTURES (FENCES, RETAINING WALLS, BUILDINGS ETC) AND USED TO TIE THE LOCATION OF THE SYDNEY WATER ASSET(S) TO THE PROPERTY BOUNDARY.
3. NO BOUNDARY SURVEY HAS BEEN UNDERTAKEN. BEARINGS, DIMENSIONS AND AREA ARE FROM TITLE ONLY AND ARE SUBJECT TO CONFIRMATION BY BOUNDARY SURVEY.
4. SOME SURFACE EVIDENCE MAY NOT HAVE BEEN IDENTIFIED AT THE TIME OF THE SURVEY DUE TO SITE IMPEDIMENTS.
5. SERVICES BETWEEN SURFACE EVIDENCE (SUCH AS MANHOLES) HAVE BEEN ASSUMED TO BE STRAIGHT UNLESS PLANS INDICATE OTHERWISE.
6. WHERE THE LOCATION OF A SERVICE COULD NOT BE CONFIRMED DUE TO LACK OF INTERNAL/EXTERNAL ACCESS, LACK OF ACCESS TO THE MAINTENANCE STRUCTURES, LACK OF SURFACE EVIDENCE; THE SERVICES HAVE BEEN PLOTTED FROM SYDNEY WATER RECORDS AND NOTATED ACCORDINGLY. MGP IS TO BE CONTACTED AT THE CONSTRUCTION PHASE OF THE PROJECT TO CONFIRM THE LOCATION OF THE ASSETS AND PLACEMENT OF RECOVERABLE MARKS ONCE THESE ASSETS ARE EXPOSED BY THE DEVELOPER
7. SEWER LOCATIONS MARKS ARE NOT NECESSARILY ON BOUNDARY.
8. DO NOT SCALE FROM THIS PLAN, USE DIMENSIONS ONLY.
9. ALL DIMENSIONS ARE IN METERS UNLESS OTHERWISE STATED.
10. THIS STATEMENT IS AN INTEGRAL PART OF THIS PLAN. REPRODUCTION OF THIS PLAN OR ANY PART OF IT WITHOUT THIS STATEMENT BEING INCLUDED IN FULL WILL RENDER THE INFORMATION INVALID AND NOT SUITABLE FOR USE.
11. PLEASE NOTE THE ZONE OF INFLUENCE IS 1 IN 1.
12. DATA OBTAINED IN THIS REPORT HAS BEEN TAKEN USING ON-SITE INSPECTION SONAR DETECTION, SURVEY & SYDNEY WATER HYDRA RECORDS.
13. STRATA: TBA - GEOTECH
 PIPE SIZE: 225 / 375
 PIPE TYPE: PVC / DICL

LEGEND:

SEWER MAIN		RODDING POINT		R.P.	
MAINTENANCE HOLE		VENT SHAFT (Induct or Educt)		V.S	
ASSET INDICATOR		VERTICAL RISER		VERT	
Water Servicing Coordinator		JUNCTION (PCP)		CONJUNCTION	
building & infrastructure services		CONCRETE ENCASED SECTION		CONJUNCTION	
		LAMP HOLE		LAMP HOLE	



Drawing
 SERVICE PROTECTION REPORT
 ROYAL MOTOR
 YACHT CLUB
 NEWPORT 2106

Drawn By	EC	Date	18/03/2024
Design By	MG	Scale	1:1000
Approved	MG	Sheet	1 OF 2
Job No.	2024-0086		

Suite 203, 18 Aquatic Drive, Frenchs Forest NSW 2086
 T: 02 9451 7555 F: 02 9451 8555 E: info@mgp.com.au

Dwg. No. **SPR1** Issue **1**

SITE PLAN
 SCALE 1:1000

NOTES:

1. MARC GAUDRY OF MGP BUILDING & INFRASTRUCTURE SERVICES PTY LTD BEING ACCREDITED TO CARRY OUT A SERVICE PROTECTION REPORT, CERTIFY THAT THE INFORMATION SHOWN ON THIS REPORT HAS BEEN PREPARED IN ACCORDANCE WITH THE RELEVANT INSTRUCTIONS AND ACCEPT FULL RESPONSIBILITY FOR THE ACCURACY OF THE INFORMATION ON THIS REPORT.
SIGN: *Marc Gaudry*

- FOR THE PURPOSE OF THIS REPORT, "BOUNDARY" REFERS TO THE ACTUAL PROPERTY BOUNDARY AS IDENTIFIED IN THE PROPERTY SURVEY PLAN. PHYSICAL MEASUREMENTS HAVE BEEN TAKEN FROM FIXED STRUCTURES (FENCES, RETAINING WALLS, BUILDINGS ETC) AND USED TO TIE THE LOCATION OF THE SYDNEY WATER ASSET(S) TO THE PROPERTY BOUNDARY.
- NO BOUNDARY SURVEY HAS BEEN UNDERTAKEN. BEARINGS, DIMENSIONS AND AREA ARE FROM TITLE ONLY AND ARE SUBJECT TO CONFIRMATION BY BOUNDARY SURVEY.
- SOME SURFACE EVIDENCE MAY NOT HAVE BEEN IDENTIFIED AT THE TIME OF THE SURVEY DUE TO SITE IMPEDIMENTS.
- SERVICES BETWEEN SURFACE EVIDENCE (SUCH AS MANHOLES) HAVE BEEN ASSUMED TO BE STRAIGHT UNLESS PLANS INDICATE OTHERWISE.
- WHERE THE LOCATION OF A SERVICE COULD NOT BE CONFIRMED DUE TO LACK OF INTERNAL/EXTERNAL ACCESS, LACK OF ACCESS TO THE MAINTENANCE STRUCTURES, LACK OF SURFACE EVIDENCE; THE SERVICES HAVE BEEN PLOTTED FROM SYDNEY WATER RECORDS AND NOTATED ACCORDINGLY. MGP IS TO BE CONTACTED AT THE CONSTRUCTION PHASE OF THE PROJECT TO CONFIRM THE LOCATION OF THE ASSETS AND PLACEMENT OF RECOVERABLE MARKS ONCE THESE ASSETS ARE EXPOSED BY THE DEVELOPER
- SEWER LOCATIONS MARKS ARE NOT NECESSARILY ON BOUNDARY.
- DO NOT SCALE FROM THIS PLAN, USE DIMENSIONS ONLY.
- ALL DIMENSIONS ARE IN METERS UNLESS OTHERWISE STATED.
- THIS STATEMENT IS AN INTEGRAL PART OF THIS PLAN. REPRODUCTION OF THIS PLAN OR ANY PART OF IT WITHOUT THIS STATEMENT BEING INCLUDED IN FULL WILL RENDER THE INFORMATION INVALID AND NOT SUITABLE FOR USE.
- PLEASE NOTE THE ZONE OF INFLUENCE IS 1 IN 1.
- DATA OBTAINED IN THIS REPORT HAS BEEN TAKEN USING ON-SITE INSPECTION SONAR DETECTION, SURVEY & SYDNEY WATER HYDRA RECORDS.
- STRATA: TBA - GEOTECH
PIPE SIZE: 225 / 375
PIPE TYPE: PVC / DICL



SERVICE LOCATION PRINT

NOT TO SCALE

LEGEND:	
SEWER MAIN	RODDING POINT
MAINTENANCE HOLE	VENT SHAFT (Induct or Educt)
ASSET INDICATOR	VERTICAL RISER
Water Servicing Coordinator	

mgp pty ltd
building & infrastructure services

Suite 203, 18 Aquatic Drive, Frenchs Forest NSW 2086
T: 02 9451 7555 F: 02 9451 8555 E: info@mgp.com.au

JUNCTION (PCP)	CONCRETE ENCASED SECTION	LAMP HOLE
Drawn By	EC	Date
Design By	MG	Scale
Approved	MG	Sheet
Job No.	2024-0086	
Dwg. No.	SPR1	Issue
		1

Drawing
SERVICE PROTECTION REPORT
ROYAL MOTOR
YACHT CLUB
NEWPORT 2106

08/03/2024
NTS
2 OF 2