

Appendix 1 – View Impact Photographs

Property 1 – 9 Moore Street (Woolfe)



*Figure 1 – View from first floor outdoor area, directly adjoins living room/dining room and kitchen, standing looking south-west.*



*Figure 2 – View from back of kitchen, standing and looking south-west.*



Figure 3 – Close up view from kitchen looking west, standing position.



Figure 4 – Bedroom 1 Window looking south-west, standing (left). Bedroom 2 window looking south-west, standing (right).



*Figure 5 – Down stairs living area, standing looking south-west.*

**Property 2 – 14 Moore Street (Li/Kennedy)**



*Figure 6 – Top floor living area/kitchen, standing looking south.*



*Figure 7 – Zoomed in view, standing looking south out of door between living and pool.*



*Figure 8 – Looking south from upper floor terrace area adjoining living room.*

**Property 3 – 10 Moore Street (Johnstone)**



*Figure 9 – View looking south from living room/terrace, standing position. A number of poles obscured by existing tree.*



*Figure 10 – View from kitchen/living area, looking south, standing position. Majority of poles obscured by existing trees.*



*Figure 11 – View from upper floor bedroom, looking south, standing position.*



*Figure 12 – View from terrace adjoining upper floor bedroom, looking south, standing position.*

**Property 4 – 12 Moore Street (Jonson)**



*Figure 13 – View from living room, looking south, standing position.*



*Figure 14 – View from terrace adjoining living room, looking south, standing position.*



*Figure 15 – View from kitchen/stairwell window, looking south, standing. View is currently obscured by scaffolding due to construction.*