



APPENDIX A – INSPECTION PHOTOGRAPHS

SEA WALL CONSTRUCTION

RISK ASSESSMENT REPORT

25-33 ROBERTSON ROAD, SCOTLAND ISLAND NSW

For: Jess Yue
Far East Organization

Neilly Davies & Partners Pty. Ltd.

ABN: 711 216 235 50

23 November 2020

Date:	23 Nov. 20	Status:	Final	Reference:	J200093
Project Manager:	Mahfujur Rahman				
Author:	Joshua McLeod				
Reviewer:	B. Muhunthan				
Division:	Design				

Revision Status			
Revision	Date Issued	Reviewer	Comment
A	23 Nov. 20	B. Muhunthan	Draft Issue

Confidential Information

This document is made available to the recipient on the express understanding that the information contained in it be regarded and treated by the recipient as strictly confidential. The content of this document is intended only for the sole use of the recipient and should not be disclosed or furnished to any other person.

Disclaimer of Liability

The information contained in this document is provided for the sole use of the recipient and no reliance should be placed on the information by any other person. In the event that the information is disclosed or furnished to any other person, Neilly Davies & Partners Pty Ltd accepts no liability for any loss or damage incurred by that person whatsoever as a result of using the information.

© Document Copyright

All rights reserved. No part of the content of this document may be reproduced, published, transmitted or adapted in any form or by any means without the written permission of the Neilly Davies & Partners Pty Ltd.

1. PHOTOGRAPHS & DESCRIPTION

Location	Photo Description	Photo Ref
Yamba Jetty and Boatshed	Photo displaying the general condition of Yamba wharf. This is on the neighbouring property and was used as a landing. Jetty shows signs of significant degradation, cracking, and warping of members. Jetty is being redesigned. This includes the top of the deck and the supporting pylons.	1-23
	Photo displaying the general condition of the Yamba wharf boat ramp. Ramp has show significant degradation and warping of the members.	24-28
	Photo Displaying the general condition of the existing shed on the Yamba wharf. Also includes some supplementary photos showing the general condition of the jetty.	29-53
Seawall Location	Photo displaying the existing landscape at the location of the proposed seawall. The slope of the land and the existing stonework can be seen.	54-55
	Photo Displaying the general condition of the existing boatshed and jetty.	56-58
	Photo Displaying the proposed Seawall location West of the boathouse. Rocky retaining wall can be seen.	59-67
	Photo displaying the general condition of the land in the proposed seawall on the east side of the existing boatshed.	68-71
Beach	Photo displaying beach and waterfront	72-80
Yamba Jetty	Photo displaying the general condition of the Yamba wharf and supporting pylons	81-87

There were 87 photographs taken during the inspection at 25-33 Robertson Drive, Scotland Island. All photographs are compiled below in section 2: Inspection Photographs













































































































































































