

Site Assessment Report

Donovan Associates

15 Parkes Street, Parramatta NSW 2150 Ph: (02) 9806 3000 Fax: (02) 9891 2806

ABN: 84 134 616 078



Job# 309207 Client: Design 'n' Sketch Lot No: 6 Street: Warriewood Road Client Job#: Warriewood No: Suburb: Ref:

Access Vehicle access to general area: /Yes)/ No Comment: Access onto site for delivery vehicles: (Yes)/ No / See Plan Comment: Road traffic volume: Heavy / Medium / Light Comment:

Location

Boundary pegs existing: Yes //Sopte / None

Road surface: Sealed / Under Construction / Formed / Gravel / Track / None

Kerb: Roll Top / Square / None

Damage: Yes / No NA Damage: Yes/No/(NA)

Vehicle Crossing: LHS / RHS / Centre / NA / None

Damage: Yes /No/ NA

Comment:

Footpath: (Yes / No / NA

Site Conditions

Site obstructions existing: Trees / Long Grass etc.

Comment:

\$ STEEL PROTE

Existing house Slabs on ground / Timber Floor / Vacant

Condition of existing fences: Good / Fair / Dilapidated / (Nil

Comment:

Terrain: Even / Irregular / Liable to dampness or pounding

Any visible site filling: Yes/ None Apparent

Comment:

Rock evident on site or considered to be near surface: Yes (No)

Comment:

Services

Gas: Mains in area / None apparent

Electricity: Overhead (# Wires

) / Underground / None Apparent

Water: Long / Short / Tap, meter or tag on site / Unsure / No

If Long: Conduits exist: Yes / No / Not Found / NA

Sewer: Mains in area / Septic / Enviro / None Apparent Long / Short / Tap, meter or tag on site / Insure / No

If Long: Conduits exist: Yes / No / Not Found / NA

Drainage

Site drains to: Street / Easement / Public Drain / Watercourse / Other:

If drains to street: Kerb outlet exists: Yes / No

If drains to easement, appurtenant: Yes (No)

Enclosures

Lot No:

Street:

Client Job#:

No:

Suburb:

Ref: