

Geotechnical Assessment

Project: Alterations and Additions 271 Whale Beach Road, Whale Beach, NSW.

Prepared for:

Simon Tripp C/o - Doug Westerway DMC Building Group Pty Ltd PO Box 406 Manly, NSW 1655

REF: AG 19061 28th August, 2019



Geotechnical Assessment For Alterations and Additions at

271 Whale Beach Road, Whale Beach, NSW

Document Status		Approved for Issue		
Version	Author	Reviewer	Signature	Date
2	Ben Morgan	Karen Allan	Kall	28/08/2019
		Document Distribut	ion	
Version	Copies	Format	То	Date
2	1	PDF	Simon Tripp	28/08/2019
2	1	PDF	Doug Westerway – DMC Building Group Pty Ltd	28/08/2019

Limitations

This report has been prepared for Mr Simon Tripp c/o Doug Westerway – DMC Building Group Pty Ltd in accordance with Ascent Geotechnical Consulting's (Ascent) Fee Proposal dated 3rd April, 2019.

The report is provided for the exclusive use the property owners, DMC Building Group Pty Ltd, and their nominated agents for the specific development and purpose as described in this report. This report must not be used for purposes other than those outlined in the report or applied to any other projects.

The information contained within this report is considered accurate at the time of issue with regard to the current conditions onsite as identified by Ascent and the documentation provided by others.

The report should be read in its entirety and should not be separated from its attachments or supporting notes. It should not have sections removed or included in other documents without the express approval of Ascent.



Contents

1 Ove	rview	.3
1.1	Background	3
1.2	Proposed Development	3
1.3	Relevant Instruments	3
2 Site	Description	.4
2.1	Summary	4
2.2	Geology and Geological Interpretation	5
2.3	Fieldwork	6
3 Geo	technical Assessment	.6
3.1	Site Classification	6
	Site Classification	U
3.2	Ground Water	6
3.2 3.3	Ground Water Surface Water	6 7
3.2 3.3 3.4	Ground Water Surface Water Slope Instability	6 7 7
3.2 3.3 3.4 3.5	Ground Water Surface Water Slope Instability Costal Processes	6 7 7 7
3.2 3.3 3.4 3.5 3.6	Ground Water Surface Water Slope Instability Costal Processes Geotechnical Hazards and Risk Analysis	6 7 7 7 8
3.2 3.3 3.4 3.5 3.6 3.7	Ground Water Surface Water Slope Instability Costal Processes Geotechnical Hazards and Risk Analysis Recommendations	6 7 7 7 8 9

5 Appendices

Appendix A:	Northern Beaches Council – Pittwater Geotechnical Forms 1 & 1A
Appendix B:	Site Plan/Ground Test Locations & Geological Cross Section
Appendix C:	Engineering logs
Appendix D:	Coastal Engineers Report - Horton Coastal Engineering Pty Ltd
Appendix E:	General Notes
	CSIRO Sheet BTF-18 "Foundation Maintenance and Footing Performance: A Homeowners Guide"
	Australian Geoguide LR8 – Examples of Good/Bad Hillside Construction Practice
	Australian Geomechanics Guidelines 2007 Appendix C



1 Overview

1.1 Background

This report presents the findings of a geotechnical assessment carried out at 271 Whale Beach Road, Whale Beach (the "Site"), by Ascent Geotechnical Consulting (Ascent). This assessment has been prepared to meet Northern Beaches Council lodgement requirements for Development Application (DA).

1.2 Proposed Development

Details of the proposed development are outlined in a series of architectural design plans prepared by Rob Crump Design, Job Number 2480 Issue B, Dated 22nd August, 2019: -

The proposed works comprise the following:

- Construction of new swimming pool, and Inclined lift,
- Various landscaping detail,
- The proposed development will take place on an approximately 1075.0m² residential block being Lot 179 Sec DP 15376.

1.3 Relevant Instruments

This geotechnical assessment has been prepared in accordance with the following relevant guidelines and standards:

- Northern Beaches Council Pittwater Local Environment Plan (PLEP) 2014 & Pittwater Development Control Plan (PDCP) 2013.
- Appendix 5 (to Pittwater P21) Geotechnical Risk Management Policy for Pittwater 2009.
- Pittwater 21 Development Control Plan Bluff Management Area P21DCP-BC-MDCP017T
- Australian Geomechanics Society's Landslide Risk Management Guidelines (AGS 2007).
- Australian Standard 1726:2017 Geotechnical Site Investigations.
- Australian Standard 2870:2011 Residential Slabs and Footings.
- Australian Standard 1289.6.3.2:1997 Methods of Testing Soils for Engineering Purposes.
- Australian Standard 3798:2007 Guidelines on earthworks for commercial and residential developments.

3 of 14



2 Site Description

2.1 Summary

A summary of site conditions identified at the time of our inspection is provided in the table below (Table 1.).

Parameter	Description
Site Visit	Ben Morgan & Morgan Spreadbury-Key - Ascent Geotechnical – 03/04/2019
Site Address	271 Whale Beach Road, Whale Beach, NSW – Lot 179 Sec DP 15376
Site Area m ² (approx.)	1075.0m ² (By Title)
Existing development	Three-storey brick residence, tile roof.
Aspect	South
Average gradient & RL (AHD)	~35 degrees RL ~31.0 at northern boundary to RL ~5.1 at southern boundary.
Vegetation	Established medium to large trees, shrubs and small garden beds, and lawn areas.
Retaining Structures	Stable mortared sandstone stack-rock, formed concrete and brick retaining walls are situated around the site.
	A brick retaining wall, that is situated adjacent to the north-western corner of the house, has cracked, and is bulging significantly toward the east. The variable height wall has previously been braced with two mortared brick buttresses towards the southern end. A large, roughly vertical crack is situated approximately halfway along the remaining unsupported length, corresponding to the significant budging in this area.
Neighbouring environment	Residentially developed to the east and west. Whale Beach Road to the north. Whale Beach to the south.

Table 1: Summary of site conditions.





Image 1: Site location – 271 Whale Beach Road, Whale Beach - Red Pin (© Google Maps)

2.2 Geology and Geological Interpretation

The Sydney 1:100,000 Geological Sheet 9130 (NSW Dept. Mineral Resources, 1983) indicates that the site is underlain by the Newport Formation of the upper Narrabeen Group (Rnn). The site is situated in close proximity to the boundary between the Newport Formation rocks, and the overlying Hawkesbury Sandstone (Rh). The Newport Formation geology is comprised of interbedded laminite, shale and quartz, to lithic-quartz sandstones which are similar in composition to the overlying Hawkesbury Sandstones. An exposed sandstone and shale escarpment extends across the southern portion of the block and is interpreted to represent the upper Newport Formation sandstones.

The soil profile consists of bioturbated organic sandy top soils (O & A Horizons) overlying sandy clays (B Horizon) and weathered bedrock (C Horizon). Based on our observations and the results of testing onsite, we would expect competent weathered bedrock to be found within 500-2200mm from current surface levels across the site, where not already exposed at the surface.

NOTE: The local geology is comprised of highly variable interbedded clays, shales and sandstones, with abundant detached joint blocks and sandstone floaters at surface and in the upper profile. The bedrock is often found in benched terraces, subsequently ground conditions on site may alter significantly across short distances. This variability should be anticipated and accounted for in the design and construction of any new foundations.



2.3 Fieldwork

A site investigation was undertaken on the 3rd April, 2019, which included a geotechnically focused visual assessment of the property and its surrounds, geotechnical mapping, photographic record, and subsurface investigation.

Five Dynamic Cone Penetrometer (DCP) tests were carried out to provide a continuous profile of relative density of the shallow subsurface materials, and determine depth to weathered rock (if encountered). These tests were conducted to the Australian Standard for ground testing: AS 1289.6.3.2 – 1997. Possible locations of testing were constrained by existing structures, exposed rock and vegetation. The location of these tests is shown on the site plan provided and summary of the test results is presented below, with full details in the engineering logs presented in the appendix section of this report:

Table 2: Summary DCP test resu	ılts.
--------------------------------	-------

TEST	DCP 1	DCP 2	DCP 3	DCP 4	DCP 5
SUMMARY	End of test @	Refusal @	Refusal @	End of test @	Refusal @
	1.1m. No	2.1m. No	2.2m. No	1.5m. No	1.0m. No
	significant	significant	significant	significant	significant
	seepage	seepage	seepage	seepage	seepage
	identified.	identified.	identified.	identified.	identified.

NOTE: The equipment chosen to undertake ground investigations provides the most costeffective method for understanding the subsurface conditions. Our interpretation of the subsurface conditions is limited to the results of testing undertaken and the known geology in the area. While every care is taken to accurately identify the subsurface conditions on-site, variation between the interpreted model presented herein, and the actual conditions onsite may occur. Should actual ground conditions vary from those anticipated, we would recommend the geotechnical engineer be informed as soon as possible to advise if modifications to our recommendations are required.

3 Geotechnical Assessment

3.1 Site Classification

Due to the characteristics of the soil profile on site, the site is classified as **"S"** in accordance with AS 2870:2011.

3.2 Ground Water

Normal ground water seepage is expected to move downslope through the soil profile along the interface with underling bedrock, or any impervious horizons in the profile such as clays.

6 of 14



Due to the position of the block relative to the slope, and the underlying geology, the proposed development is not interpreted to have and significant adverse effect on the standing water table or groundwater movements on site.

3.3 Surface Water

Overland or surface flows entering the site from the adjoining areas were not identified at the time of our inspection, however normal overland runoff could enter the site from above during heavy or extended rainfall.

3.4 Slope Stability

A landslide hazard assessment of the existing slope has been undertaken in accordance with the Australian Geomechanics Society Landslide Risk Management Concepts and Guidelines, 2007.

- The buttressed brick retaining wall adjacent to the north-western corner of the residence displays significant bulging, lean, and cracking in the brickwork, this damage is interpreted to be the result of inadequate structural design, failing to support the lateral earth pressures and root growth, rather than slope instability itself.
- The concrete stairs providing access to the southern boundary display significant settlement, cracking and displacement. This damage is interpreted to be the result of settlement, due to inadequate foundation materials and footing design, rather than slope instability itself.
- No evidence of significant soil creep, tension cracks, settlement, or other indicators of slope instability were identified at the time of our inspection.
- The property is classified 'Geotechnical Hazard H1' in Northern Beaches Council PLEP Geotechnical Hazard Map Sheet GTH_015 (PLEP Geotechnical Hazard Map Image 2 below).

3.5 Coastal Processes

The seaward property boundary is at 5.1m AHD, the base of the cliff is at 5.8m AHD. The pool works are located above 18.6m AHD. Coastal inundation is not considered to be a significant risk (IrJ0290, 20th August, 2019). The lower portion of the inclined lift (below 8.0m AHD may be impacted by wave runup in extreme storm events.

With reference to section 5.2 of the Horton Coastal Engineering report (IrJ0290, 20th August, 2019), the cliff directly seaward of the subject site will be affected by both chemical and mechanical weathering, with an approximate rate of regression of 5mm per year (this rate considers projected sea level rise).

Based on the geology and geomorphology of the cliff, the above-mentioned regression rate,

7 of 14

Ascent Geotechnical Consulting Pty Ltd PO Box 37 Manly NSW 1655 : 🕾 0448 255 537 www.ascentgeo.com.au : A.B.N. 71 621 428 402



and information provided in the Horton Coastal engineering report, the effects of chemical and mechanical weathering leading to coastal regression, nor, coastal inundation are considered to pose no significant risk to the subject site when applied to a design life of 100 years.





Image 2: 271 Whale Beach Road, Whale Beach – **Geotechnical Hazard H1**– Red polygon (© PLEP 2014)

3.6 Geotechnical Hazards and Risk Analysis

No significant geotechnical hazards were identified above, beside or below the subject site. The slope across the subject site has an average gradient of ~35 degrees. The soil profile is comprised of sandy top soils and sandy clays overlying weathered bedrock, with shallow marine sand profiles located at the southernmost portion of the block, confirmed by ground testing. The likelihood of the slope failing is assessed as '**UNLIKELY**', the consequences of such a failure are assessed as '**MINOR**'. The risk to property is '**LOW**'. The existing conditions and proposed development are considered to constitute an '**ACCEPTABLE**' risk to life and a '**LOW**' risk to property provided that the recommendations outlined in **Section 3.6** are adhered to.

We would consider the existing buttressed brick retaining wall located adjacent to the

8 of 14

Ascent Geotechnical Consulting Pty Ltd PO Box 37 Manly NSW 1655 : 🕾 0448 255 537 www.ascentgeo.com.au : A.B.N. 71 621 428 402



north-western corner of the block to constitute a moderate risk of collapse. Given its location, and the probability that the area be occupied at the time of potential collapse, we would recommend that temporary support be installed immediately to prevent collapse. This may be in the form of additional buttresses or bracing. Furthermore, we would recommend that the wall, including its returns, and its buttressed supports, be demolished in the short term (1 - 18 months), and an adequately designed structural retaining solution be installed.

Table 3. Risk Analysis Summary

HAZARDS	HAZARD ONE	HAZARD TWO	HAZARD THREE
ТҮРЕ	Failure of the slope that falls approximately 35 degrees N to S across the subject site.	Failure of the buttressed brick retaining wall located adjacent to the north-western corner of the block	Regression of the cliff line and costal bluff, situated seaward of the subject site, resulting in failure of the slope.
LIKELIHOOD	'Unlikely' (10 ⁻ 4)	Possible (10°)	Rare (10°)
CONSEQUENCES TO PROPERTY	'Low' (5%)	'Medium' (20%)	'Medium' (20%)
RISK TO PROPERTY	'Low' (2 x 10⁻⁵)	'Low' (2 x 10⁻⁵)	'Low' (2 x 10 ⁻⁵)
RISK TO LIFE	5 x 10 ⁻⁶ /annum	2 x 10 ⁻⁴ /annum	5 x 10 ⁻⁵ /annum
COMMENTS	The level of risk is 'Acceptable' provided the recommendations provided in section 3.7 of this report are adhered to	The level of risk is 'Unacceptable'. To bring this to an acceptable level, we would recommend that the wall, including its returns, and its buttressed supports, be demolished in the short term (1 – 18 months), and an adequately designed structural retaining solution be installed.	The level of risk is 'Acceptable', based on a design life of 100 years.



3.7 Recommendations

The proposed development is considered to be suitable for the site. No significant geotechnical hazards should result from the completion of the proposed development provided the recommendations presented in Table 4 are adhered to.

Recommendation	Description
Soil Excavation	Soil excavation will be required for the proposed pool, Inclined lift and to establish pad levels and footings across the site. It is anticipated that these excavations will encounter sandy top soils and sandy clays before weathered bedrock is encountered. Footings located at the southernmost extent of the block are likely to encounter shallow marine quartz sands.
	Any excavations resulting in a permanent batter slope exceeding 0.75 m in height should be supported by a suitably designed and installed retaining structures. Alternatively, where space/setbacks permit, batters may be permitted assuming batter angles do not exceed 1(vertical): 2(Horizontal).
	Temporary batter slopes may be considered where setbacks from existing structures and property boundaries permits. Temporary batter slopes in marine sands should not exceed 1 Vertical (V) in 1.5 Horizontal.
	All excavated material is to be removed from the site in accordance with current Office of Environment and Heritage (OEH) regulations.
Rock Excavation	All excavation recommendations as outlined below should be read in conjunction with Safe Work Australia's 'Excavation Work – Code of Practice', published March, 2015.
	The excavations required for the construction of the proposed pool are expected to encounter small amounts of fill, sandy topsoils, and minor sandy clays, with weathered sandstone bedrock expected between $\sim <0.5 - 2.2$ m across the area of the proposed works.
	It is essential that any excavation through rock that cannot be readily achieved with a bucket excavator or ripper should be carried out initially using a rock saw to minimise the vibration impact and disturbance on the adjoining properties, and adjacent structures. Any



	 rock breaking must be carried out only after the rock has been sawed and in short bursts (2-5 seconds) to prevent the vibration amplifying. The break in the rock from the saw must be between the rock to be broken and the closest adjoining structure. All excavated material is to be removed from the site in accordance with current Office of Environment and Heritage (OEH) regulations.
Vibrations	The Australian Standard AS2670.2-1990 "Evaluation of human exposure to whole-body vibrations – continuous and shock induced vibrations in buildings (1-80 Hz)" suggests a day time limit of 5 mm/s component PPV for human comfort is acceptable.
	If necessary we would suggest allowable vibration limits be set at 5mm/s PPV. It is expected that rock hammers with an approximate weight of 400-600kg will be adequate to operate within these tolerances. It may be necessary to move to smaller rock hammers or to rotary grinders or rock saws if vibrations limits cannot be met.
	The propagation of vibrations can be mitigated by pulsing the use of rock hammers, i.e. short bursts, utilising line sawing along boundaries.
Excavation Support	Vertical or sub-vertical cuts through at least low strength sandstone bedrock should stand unsupported until permanent supporting structures are installed. Provided the appropriate batter angles, mentioned above, are achieved, and any exposed soil batter is covered to prevent excessive infiltration or evaporation of moisture, no significant excavation support should be required.
	Any permanent vertical or sub-vertical cuts are to be supported by engineer designed and adequately constructed retaining structures with appropriate backfill drainage.
Sediment and Erosion Control	Appropriate design and construction methods shall be required during site works to minimise erosion and provide sediment control. In particular, any stockpiled soil will require erosion control measures, such as siltation fencing and barriers, to be designed by others.
Footings	Visual assessment and our subsurface testing carried out at the Site suggested the presence of sandy top soil and sandy clays overlying



	weathered bedrock across the site. Shallow marine sands were encountered at the southernmost portion of the site. All pad, strip or piered footings should be founded on and socketed a minimum of 300mm in to the underlying weathered bedrock utilising piers as required. For fully cleaned footings, the allowable bearable pressure is 800 kPa .
	Footings on the natural stiff clays, taken to at least 600mm below existing surface levels, can be designed for an allowable end bearing capacity of 250 kPa. Footings on compacted marine quartz sands can be designed for an end bearing capacity of 150 kPa.
	Footings for the lower landing of the inclined lift are to be socketed a minimum of 300mm into bedrock. Consideration should be given to potential coastal processes, as described in Horton Coastal Engineering report (provided in appendix of this report), when designing the structure and its foundations.
	Note: The local geology is comprised of highly variable interbedded clays, shales and sandstones, with abundant detached joint blocks and sandstone floaters in the upper profile. Subsequently ground conditions on site may alter significantly across short distances. This variability should be anticipated and accounted for in the design and construction of any new foundations. We recommend that Ascent be contacted immediately if conditions onsite are outside of those expected.
Retaining Structures	Any retaining structures to be constructed as part of the site works are to be backfilled with suitable free-draining materials wrapped in a non-woven geotextile fabric (i.e Bidim A34 or similar), to prevent the clogging of the drainage with sediment.
Fills	Any fill that may be required is to comprise local sand, clay and weathered rock. Existing organic topsoil is to be cleared in preparation for the introduction of fill.
	Any new fill material is to be placed in layers not more than 250 mm thick and compacted to not less than 95% of Standard Optimum Dry Density at plus or minus 2% of Standard Optimum Moisture Content.



	All new fill placement is to be carried out in accordance with AS 3798 – 2007 – Guidelines on earthworks for commercial and residential developments.
Stormwater Disposal	Any stormwater collected from hard surfaces is to be collected and piped to an appropriately designed stormwater system for the block through any storage tanks or on-site detention that may be required by the regulating authorities, and preferably discharged to Councils stormwater network off site, or a non-erosive on-site disposal system.
Inspections	It is essential that the foundation materials of all footing excavations be inspected and approved before steel reinforcement and concrete is placed.
Conditions Relating to Design and Construction Monitoring	To comply with Council conditions and enable the completion of Forms 2B and 3 as required in Councils Geotechnical Risk Management Policy, it will be necessary, at the following stage for Ascent to;
	Form 2B – Pre-Construction Certificate. Review and certify the geotechnical content of all structural designs.
	Form 3 – Inspected and certified all new footings and bulk excavations to confirm compliance to design with respect to allowable bearing pressure and stability. Final inspection of site, post construction.

Should you have any queries regarding this report, please do not hesitate to contact the author of this report, undersigned.

For and on behalf of, Ascent Geotechnical Consulting Pty Ltd,

Ben Morgan BSc Geol. Engineering Geologist

M

Karen Allan CPEng MIEAust Senior Civil/Geotechnical Engineer



4 References

NSW Department of Mineral Resources (1983), Sydney Australia 1: 100,000 Geological Series Sheet 9130.

Australian Geomechanics Society (March 2007), *Landslide Risk Management*, Australian Geomechanics 42 (1).

Australian Standard 1726:2017 Geotechnical Site Investigations.

Australian Standard 2870:2011 Residential Slabs and Footings.

Australian Standard 1289.6.3.2:1997 Methods of Testing Soils for Engineering Purposes.

Australian Standard 3798:2007 Guidelines for earthworks for commercial and residential developments.

Horton Coastal Engineering, Coastal Engineering Advice on 271 Whale Beach Road, Whale Beach, Irj0290 Version 2, dated 27th of August, 2019.

GEOTECHNICAL RISK MANAGEMENT POLICY FOR PITTWATER FORM NO. 1 – To be submitted with Development Application

	FORM NO. 1 – To be submitted with Development Application				
	Development Application for SIMON TRIPP				
	Name of Applicant				
	Address of site271 WHALE BEACH ROAD, WHALE BEACH				
Declara	tion made by geotechnical engineer or engineering geologist or coastal engineer (where applicable) as part of a geotechnical report				
I,	KAREN ALLAN on behalf of Ascent Geotechnical Consulting P/L (insert name) (Trading or Company Name)				
on this t as defin this doo	he				
Please r □	hark appropriate box Prepared the detailed Geotechnical Report referenced below in accordance with the Australia Geomechanics Society's Landslide Risk Management Guidelines (AGS 2007) and the Geotechnical Risk Management Policy for Pittwater - 2009				
	I am willing to technically verify that the detailed Geotechnical Report referenced below has been prepared in accordance with th Australian Geomechanics Society's Landslide Risk Management Guidelines (AGS 2007) and the Geotechnical Risk Management Policy for Pittwater - 2009				
	Have examined the site and the proposed development in detail and have carried out a risk assessment in accordance with paragraph 6.0 of the Geotechnical Risk Management Policy for Pittwater - 2009. I confirm the results of the risk assessment for the propose development are in compliance with the Geotechnical Risk Management Policy fro Pittwater - 2009 and further detailed geotechnical reporting is not required for the subject site.				
	Have examined the site and the proposed development/alteration in detail and am of the opinion that the Development Application only involves Minor Development/Alterations that do not require a Detailed Geotechnical Risk Assessment and hence my report is in accordance with the Geotechnical Risk Management Policy for Pittwater – 2009 requirements for Minor Development/Alterations.				
	Have examined the site and the proposed development/alteration is separate form and not affected by a Geotechnical Hazard and does not require a Geotechnical report or Risk Assessment and hence my Report is in accordance with the Geotechnical Risk Management Policy for Pittwater – 2009 requirements				
	Provided the coastal process and coastal forces analysis for inclusion in the Geotechnical Report				
Geotech	nical Report Details:				
	Report Title: Geotechnical Assessment Report for Alterations and Additions at 271 Whale Beach Road, Whale Beach, NSW Report Date: 28/08/2019				
	Author: Ben Morgan / Karen Allan				
	Author's Company/Organisation: Ascent Geotechnical Consulting Pty Ltd				
Docume	ntation which relate to or are relied upon in report preparation:				
Archit	ectural Design Plans prepared by Rob Crump Design, Job 2480, Issue B Dated 22 nd August, 2019				
Lrj029	0 – 271 Whale Beach Road, Whale Beach – V2 – 27 th August 2019 – Horton Coastal Engineering				
I am aw Applicatio	are that the above Geotechnical Report, prepared for the abovementioned site is to be submitted in support of a Development n for this site and will be relied on by Northern Beaches Council as the basis for ensuring that the Geotechnical Risk Management aspects				
the propo taken as identified	sed development have been adequately addressed to achieve an "Acceptable Risk Management" level for the life of the structure, at least 100 years unless otherwise stated and justified in the Report and that reasonable and practical measures have been to remove foreseeable risk.				
	Name Karen Allan				
	Chartered Professional Status MIE Aust CPEng NER				
	Membership No. 793020				
	Company Ascent Geotechnical Consulting Pty Ltd				

GEOTECHNICAL RISK MANAGEMENT POLICY FOR PITTWATER FORM NO. 1(a) - Checklist of Requirements for Geotechnical Risk Management Report for Development Application

	Development Application for Simon Tripp
	Name of Applicant Address of site
The fol Report.	lowing checklist covers the minimum requirements to be addressed in a Geotechnical Risk Management Geotechnical This checklist is to accompany the Geotechnical Report and its certification (Form No. 1).
G	eotechnical Report Details:
	Report Title: Geotechnical Assessment Report for Alterations and Additions at 271 Whale Beach Road, Whale Beach, NSW
	Report Date: 28/08/2019
	Author: Ben Morgan / Karen Allan
	Author's Company/Organisation: Ascent Geotechnical Consulting PTY LTD
Please	mark appropriate box
\boxtimes	Comprehensive site mapping conducted 08/04/2019 (date)
X X	Mapping details presented on contoured site plan with geomorphic mapping to a minimum scale of 1:200 (as appropriate) Subsurface investigation required No Justification
X	Geotechnical model developed and reported as an inferred subsurface type-section Geotechnical hazards identified Above the site Below the site Beside the site
X X	Geotechnical hazards described and reported Risk assessment conducted in accordance with the Geotechnical Risk Management Policy for Pittwater - 2009 Consequence analysis Frequency analysis
X	Risk calculation Biok approximate for property conducted in accordance with the Contrological Disk Management Deligy for Bittypter 2000
\mathbb{X}	Risk assessment for <u>property</u> conducted in accordance with the Geotechnical Risk Management Policy for Pittwater - 2009 Risk assessment for <u>loss of life</u> conducted in accordance with the Geotechnical Risk Management Policy for Pittwater - 2009 Assessed risks have been compared to "Acceptable Risk Management" criteria as defined in the Geotechnical Risk Management Policy for Pittwater - 2009
\boxtimes	Opinion has been provided that the design can achieve the "Acceptable Risk Management" criteria provided that the specified conditions are achieved
X	Design Life Adopted: ☐Other
\boxtimes	Geotechnical Conditions to be applied to all four phases as described in the Geotechnical Risk Management Policy for
\boxtimes	Additional action to remove risk where reasonable and practical have been identified and included in the report.

Risk Assessment within Bushfire Asset Protection Zone

Γ

I am aware that Pittwater Council will rely on the Geotechnical Report, to which this checklist applies, as the basis for ensuring that the geotechnical risk management aspects of the proposal have been adequately addressed to achieve an "Acceptable Risk Management" level for the life of the structure, taken as at least 100 years unless otherwise stated, and justified in the Report and that reasonable and practical measures have been identified to remove foreseeable risk.

Signature K	All			
Name Karen	Allan			
Chartered Professional Status MIE Aust CPEng				
Membership No.	793020			
Company	Ascent G	eotechnical Consulting Pty Ltd		







Po Box 37, Manly, NSW 1655, Australia Tel: 0448 255 537 Mail: Ben@ascentgeo.com.au

Dynamic Cone Penetration Test Report

Client: DMC Building Group Pt			Pty Ltd		Job No:	AG 19061			
Project: Alterations and Addition		ons		Date:	3/4/19				
Location: 271 Whale Beach Road			id, Whale Be	each, NSW	Operator:	MSK			
Test Proced	dure:	AS 1289.6.	3.2 – 1997						
				Test	Data				
Test No:	: DCP 1	Test No	DCP 2	Test No	: DCP 3	Test No	: DCP 4	Test No	: DCP 5
Test Lo	ocation:	Test Lo	cation:	Test Lo	ocation:	Test Lo	ocation:	Test Lo	cation:
Refer to S	Site Plan	Refer to S	Site Plan	Refer to S	Site Plan	Refer to	Site Plan	Refer to \$	Site Plan
RL: ~	22.4	RL: ~	21.9	RL: ~	21.9	RL: ~	- 11.0	RL: [,]	~ 8.8
Soil Class	sification:	Soil Class	sification:	Soil Class	sification:	Soil Clas	sification:	Soil Class	sification:
Ν	1	N	1	N	1	Ν	Λ	N	1
Depth (m)	Blows	Depth (m)	Blows	Depth (m)	Blows	Depth (m)	Blows	Depth (m)	Blows
0.0 - 0.3	2	0.0 - 0.3	3	0.0 - 0.3	1 D	0.0 - 0.3	3	0.0 - 0.3	1 D
0.3 - 0.6	5	0.3 - 0.6	3	0.3 - 0.6	2	0.3 - 0.6	5	0.3 - 0.6	10
0.6 - 0.9	15	0.6 - 0.9	4	0.6 - 0.9	3	0.6 - 0.9	4	0.6 - 0.9	10
0.9 - 1.2	45	0.9 - 1.2	4	0.9 - 1.2	6	0.9 - 1.2	25	0.9 - 1.2	29 Rs
1.2 - 1.5		1.2 - 1.5	6	1.2 - 1.5	6	1.2 - 1.5	45	1.2 - 1.5	
1.5 - 1.8		1.5 - 1.8	10	1.5 - 1.8	6	1.5 - 1.8		1.5 - 1.8	
1.8 - 2.1		1.8 - 2.1	10	1.8 - 2.1	7	1.8 - 2.1		1.8 - 2.1	
2.1 - 2.4		2.1 - 2.4	9 Rs	2.1 - 2.4	15 Rs	2.1 - 2.4		2.1 - 2.4	
2.4 - 2.7		2.4 - 2.7		2.4 - 2.7		2.4 - 2.7		2.4 - 2.7	
2.7 - 3.0		2.7 - 3.0		2.7 - 3.0		2.7 - 3.0		2.7 - 3.0	
3.0 - 3.3		3.0 - 3.3		3.0 - 3.3		3.0 - 3.3		3.0 - 3.3	
3.3 - 3.6		3.3 - 3.6		3.3 - 3.6		3.3 - 3.6		3.3 - 3.6	
3.6 - 3.9		3.6 - 3.9		3.6 - 3.9		3.6 - 3.9		3.6 - 3.9	
3.9 - 4.2		3.9 - 4.2		3.9 - 4.2		3.9 - 4.2		3.9 - 4.2	
4.2 - 4.5		4.2 - 4.5		4.2 - 4.5		4.2 - 4.5		4.2 - 4.5	
DCP 1: End	d of test @	DCP 2: Ref	usal @	DCP 3: Ref	fusal @	DCP 4: Re	fusal @	DCP 5: End	d of test @
1.1m in infe	erred	2.1m Bouncing on 2.2		2.2m Bouncing on		1.5m Bouncing on		1.0m in infe	erred
weathered bedrock.		inferred we	athered	inferred weathered		inferred weathered		weathered bedrock.	
Brown/yellow clays		Dedrock. Brown/wolld	w/rod	Dedrock. Brown/wolld	w/rod	bedrock.		Brown/yellow fine	
with medium quartz		clave with r	nedium	clave with n	medium	Brown/yellow/red		ciay on wet	up.
sanus on moist up.		quartz sand	ls on moist	quartz sanc	ds on moist	quartz san	ds on moist		
tip.			tip.		tip.				
Remarks:						Weight:		9	kg
Available test locations limited. No significant grou				groundwate	r	Drop:		510	mm
encountered.						Rod Diame	eter:	16	mm

Rs = Solid ring/Hammer bouncing

D = Dropped under weight of Hammer

Horton Coastal Engineering Coastal & Water Consulting

HORTON COASTAL ENGINEERING PTY LTD 18 Reynolds Cres Beacon Hill NSW 2100 +61 (0)407 012 538 peter@hortoncoastal.com.au www.hortoncoastal.com.au ABN 31 612 198 731 ACN 612 198 731

Simon Tripp C/ - DMC Building Group Pty Ltd Attention: Doug Westerway PO Box 406 Manly NSW 1655 (sent by email only to doug@dmcbuilding.com.au)

27 August 2019

Coastal Engineering Advice on 271 Whale Beach Road Whale Beach

1. INTRODUCTION AND BACKGROUND

It is proposed to construct a pool and inclinator at 271 Whale Beach Road Whale Beach, for which a Development Application (DA2019/0534) has been submitted to Northern Beaches Council. Council has noted that preparation of a coastal engineering report is required.

The property is located within a "Bluff/Cliff Instability" area designated on the *Coastal Risk Planning Map* (Sheet CHZ_015) that is referenced in *Pittwater Local Environmental Plan 2014*. Therefore, the property is subject to Chapter B3.4 of the DCP¹, and the *Geotechnical Risk Management Policy for Development in Pittwater*. Based on Chapter 6.5(i) of this policy, "a coastal engineer's report on the impact of coastal processes on the site and the coastal forces prevailing on the bluff must be incorporated into the geotechnical assessment as an appendix and the Coastal Engineer's assessment must be addressed through the Geotechnical Report and structural specification". Accordingly, this coastal engineering report is set out herein. Completed Form No. 1 as given in the *Geotechnical Risk Management Policy for Pittwater* is attached at the end of the document herein.

The report author, Peter Horton [BE (Hons 1) MEngSc MIEAust CPEng NER], is a professional Coastal Engineer with 27 years of coastal engineering experience. He has postgraduate qualifications in coastal engineering, and is a Member of Engineers Australia and Chartered Professional Engineer (CPEng) registered on the National Engineering Register. He is also a member of the National Committee on Coastal and Ocean Engineering (NCCOE) and NSW Coastal, Ocean and Port Engineering Panel (COPEP) of Engineers Australia. Peter has prepared coastal engineering reports for numerous cliff/bluff properties along the former Pittwater Council coastline in recent years, including in the Whale Beach area.

Peter Horton undertook a specific site inspection of the subject property on 7 August 2019, and has inspected the area in the vicinity of the property on numerous occasions over at least the last 10 years.

Note that all levels given herein are to Australian Height Datum (AHD). Zero metres AHD is approximately equal to mean sea level at present.

¹ The Pittwater 21 DCP up to Amendment No. 24, which came into effect on 20 October 2018, was considered herein.

2. INFORMATION PROVIDED

During the course of the investigation reported herein, Horton Coastal Engineering found that the site survey submitted with the DA had incorrect levels. A revised survey was thus provided by True North Surveys, Drawing No. 8807DTA and dated 19 August 2019 (corrected from the version submitted with the DA by lowering levels by 4.33m). Horton Coastal Engineering was also provided with a total of four Rob Crump Design drawings revised from the DA (all Issue B and dated 22 August 2019) and two Inclinator Services drawings submitted with the DA (both Issue A and dated 2 April 2019).

3. EXISTING SITE DESCRIPTION

The subject property is located at a rocky cliff/bluff north of the northern end of the sandy Whale Beach, west of Little Head. Photographs of the property are provided in Figure 1 and Figure 2, with an aerial view in Figure 3². The property is currently occupied by a 2-3 storey dwelling. A cross-section through the property, derived from Airborne Laser Scanning (ALS) data held by Horton Coastal Engineering that was collected in 2011, is depicted in Figure 4.



Figure 1: Broad view of subject property from Whale Beach on 7 August 2019, looking NNE



Figure 2: Close view of subject property from Whale Beach on 7 August 2019, looking north

² Note that the property boundary depicted in Figure 3 was derived from GIS information provided by the Department of Lands, and is not survey accurate.

Horton Coastal Engineering Coastal & Water Consulting



Figure 3: Aerial view of subject property on 30 August 2018

Horton Coastal Engineering

Coastal & Water Consulting



Figure 4: Cross-section through subject property

Based on the ALS and survey data, ground elevations at and adjacent to the subject property approximately vary as follows:

- 33m AHD at Whale Beach Road;
- 31m AHD at the northern property boundary;
- 21m AHD at the southern edge of the existing dwelling;
- 20.5m AHD at the top of the cliff south of the dwelling;
- 5.8m AHD at the bottom of the cliff south of the dwelling (average slope of 37° over the cliff section);
- 5.1m AHD at the seaward property boundary; and
- 3.5m AHD at the sand/vegetation interface.

Coffey & Partners (1987) noted that the cliff profiles from Little Head to south Palm Beach have been formed by an interbedded sequence of sandstone and interbedded siltstone/sandstone.

4. PROPOSED DEVELOPMENT

It is proposed to construct a pool (at a coping level of 20.9m AHD) south of the deck located south of the existing dwelling, and to construct an inclinator along the western boundary from the pool level down to a landing at 6.2m AHD.

5. MECHANISMS FOR CLIFF EROSION

5.1 Preamble

Erosion of sheer cliffs can occur in two forms (Public Works Department, 1985), either:

- a slow, relatively gradual attrition of cliff material due to the effects of weathering; or
- relatively infrequent but sudden collapse of large portions of cliff face, due to undercutting, wave impact forces, changed groundwater conditions, rock shattering or increased loadings related to construction, and other processes.

Weathering may induce undercutting and toppling failure of overhanging blocks if the rate of weathering is highest near the base of the cliff or at other levels below the top of the cliff. Erosion of steep slopes tends to occur suddenly in association with heavy rainfall or changes to drainage patterns, slope undercutting, and increases of load on the slope.

5.2 Weathering Rate

Both chemical and mechanical weathering can reduce the strength of cliff material (Sunamura, 1983). Chemical weathering includes hydration and solution, caused by the interaction between cliff material and sea water. Mechanical weathering comprises:

- the wetting and drying process in the intertidal zone;
- generation of repeated stresses in cliff material by periodic wave action (particularly waves that break on the cliff); and
- frost effects in cold latitudes.

Historical rates of recession for softer beds of Sydney coastline sandstone cliffs, which include chemical and mechanical weathering, have been determined to be 2mm to 5mm per year by Dragovich (2000). This is consistent with average recession rates for Sydney Northern Beaches coastline sandstone cliffs of 4mm/year determined by Crozier and Braybrooke (1992).

The base of the cliff at the subject property, at a level of about 5.8m AHD, is well above the intertidal zone (above 1m AHD) and would only potentially be impacted by wave action in extreme storms (in the order of 1% Annual Exceedance Probability).

Given this, it is considered that an erosion/weathering rate of 5mm per year is likely to be conservative, but is recommended for adoption. This rate should be considered and assessed by the geotechnical engineer. The rate is considered to be reasonable to apply over a design life of 100 years (conservative for the type of development proposed), including allowance for projected sea level rise. To be conservative, the rate can be applied over the entire exposed cliff face between about 6m and 20m AHD, although in reality it would be expected that runup would generally be below about 8m AHD in a severe coastal storm.

The geotechnical engineer should consider this rate in conjunction with an understanding of the particular nature of the cliff materials at the subject property, their resistance to erosion, and potential failure planes related to geotechnical issues such as the joint spacing³.

6. COASTAL INUNDATION

With the pool works generally above 18.5m AHD (the base of pool level), coastal inundation is not a significant risk to the pool over a planning period of well over 100 years. The lower portion of the inclinator (below about 8m AHD) may be impacted by wave runup at times of severe coastal storms.

7. RECOMMENDATIONS FOR ACHIEVING ACCEPTABLY LOW RISK TO DEVELOPMENT FROM COASTAL ENGINEERING PERSPECTIVE

To reduce the risk of the inclinator and lower landing being damaged due to undermining by coastal erosion/recession, it is recommended that the supports for these items are socketed into bedrock. Ascent Geotechnical Consulting (2019) considered that bedrock was within 0.5m to 2.2m of the ground surface where not already exposed on the site (and found bedrock within 1.5m of the ground surface over the lower portion of the site). The supports should be designed to withstand wave forces and sand slumping forces above the bedrock as estimated by a coastal engineer.

It is recommended that the deck for the inclinator lower landing has say a minimum of 5mm gaps between planks, to reduce the potential for wave uplift popping out the decking in severe coastal storms. At times of severe storms, the inclinator carriage should be positioned at the top of the inclinator rails, to reduce the risk of damage from wave runup. Materials for the inclinator should be selected that are suitable for the marine environment (mainly salt spray).

8. MERIT ASSESSMENT

8.1 Preamble

The merit assessment herein has been undertaken assuming that the geotechnical engineer has found that the proposed development is at an acceptably low risk of damage from coastal erosion/recession of the cliff seaward of the property for a design life of at least 100 years.

³ Coffey & Partners (1987) noted that the controlling feature of interbedded sandstone/siltstone cliffs (as per the subject property) was the bedding spacing and relative proportion of sandstone/siltstone.

8.2 State Environmental Planning Policy (Coastal Management) 2018

8.2.1 Preamble

Based on *State Environmental Planning Policy (Coastal Management) 2018* (SEPP Coastal) and its associated mapping, the subject property is within a "coastal environment area" (at its SE corner) and "coastal use area".

8.2.2 Clause 13

Based on Clause 13(1) of SEPP Coastal, "development consent must not be granted to development on land that is within the coastal environment area unless the consent authority has considered whether the proposed development is likely to cause an adverse impact on the following:

- (a) the integrity and resilience of the biophysical, hydrological (surface and groundwater) and ecological environment,
- (b) coastal environmental values and natural coastal processes,
- (c) the water quality of the marine estate (within the meaning of the *Marine Estate Management Act 2014*), in particular, the cumulative impacts of the proposed development on any of the sensitive coastal lakes identified in Schedule 1,
- (d) marine vegetation, native vegetation and fauna and their habitats, undeveloped headlands and rock platforms,
- (e) existing public open space and safe access to and along the foreshore, beach, headland or rock platform for members of the public, including persons with a disability,
- (f) Aboriginal cultural heritage, practices and places,
- (g) the use of the surf zone".

This is not a coastal engineering matter, but it can be noted that with regard to (a), the proposed development would not be expected to adversely affect the biophysical, hydrological (surface and groundwater) and ecological environments, being in an existing developed area and only covering a relatively small footprint. Ascent Geotechnical Consulting (2019) also noted that proposed development was not interpreted to have a significant adverse effect on the standing water table or groundwater movements at the site.

With regard to (b), the proposed development would not be expected to adversely affect coastal environmental values or natural coastal processes over an acceptably long design life, as it would be founded on bedrock and suspended above most wave action for an acceptably rare storm.

With regard to (c), the proposed development would not be expected to adversely impact on water quality, with the residential land use. No sensitive coastal lakes are located in the vicinity of the proposed development.

With regard to (d), the proposed development would not impact marine vegetation, native vegetation and fauna and their habitats (of significance, which are not known to exist at the property), undeveloped headlands and rock platforms, with none of these items in proximity to the development (being on an already developed headland). No significant impacts on marine fauna and flora would be expected as a result of the proposed development, as the development would not interact with subaqueous areas for an acceptably rare storm and acceptably long life.

With regard to (e), it can be noted that the proposed development is entirely within the subject property boundary and will not alter existing public access arrangements south of the property.

With regard to (f), a search of the Office of Environment and Heritage "Aboriginal Heritage Information Management System" (AHIMS) was undertaken on 19 August 2019. This resulted in no Aboriginal sites and no Aboriginal places being recorded or declared at the subject property.

With regard to (g), the proposed development would not interact with the surf zone for an acceptably rare storm occurring over an acceptably long life, so would not impact on use of the surf zone.

Based on Clause 13(2) of SEPP Coastal, "development consent must not be granted to development on land to which this clause applies unless the consent authority is satisfied that:

- (a) the development is designed, sited and will be managed to avoid an adverse impact referred to in subclause (1), or
- (b) if that impact cannot be reasonably avoided—the development is designed, sited and will be managed to minimise that impact, or
- (c) if that impact cannot be minimised—the development will be managed to mitigate that impact".

The proposed development has been designed and sited to avoid any potential adverse impacts referred to in Clause 13(1).

8.2.3 Clause 14

Based on Clause 14(1) of SEPP Coastal, "development consent must not be granted to development on land that is within the coastal use area unless the consent authority:

- (a) has considered whether the proposed development is likely to cause an adverse impact on the following:
 - (i) existing, safe access to and along the foreshore, beach, headland or rock platform for members of the public, including persons with a disability,
 - (ii) overshadowing, wind funnelling and the loss of views from public places to foreshores,
 - (iii) the visual amenity and scenic qualities of the coast, including coastal headlands,
 - (iv) Aboriginal cultural heritage, practices and places,
 - (v) cultural and built environment heritage, and
- (b) is satisfied that:
 - (i) the development is designed, sited and will be managed to avoid an adverse impact referred to in paragraph (a), or
 - (ii) if that impact cannot be reasonably avoided—the development is designed, sited and will be managed to minimise that impact, or
 - (iii) if that impact cannot be minimised—the development will be managed to mitigate that impact, and
- (c) has taken into account the surrounding coastal and built environment, and the bulk, scale and size of the proposed development".

With regard to Clause (a)(i), the proposed development is entirely on private property and will not affect public foreshore, beach, headland or rock platform access.

Clauses (a)(ii) and a(iii) are not coastal engineering matters so are not considered herein.

With regard to (a)(iv), as noted in Section 8.2.2, there are no Aboriginal sites or Aboriginal places recorded or declared at the subject property.

With regard to (a)(v), the nearest environmental heritage items to the subject property listed in Schedule 5 of *Pittwater Local Environmental Plan 2014* are the house "Orcades" at 309-311 Whale Beach Road Palm Beach, and Norfolk Island Pines at Whale Beach Ocean Reserve adjacent to The Strand. (both about 260m from the proposed development). The proposed development would not be expected to impact on these areas.

With regard to (b), the proposed development has been designed and sited to avoid any potential adverse impacts referred to in Clause 14(1) for the matters considered herein.

Clause (c) is not a coastal engineering matter so is not considered herein.

8.2.4 Clause 15

Based on Clause 15 of SEPP Coastal, "development consent must not be granted to development on land within the coastal zone unless the consent authority is satisfied that the proposed development is not likely to cause increased risk of coastal hazards on that land or other land".

If the recommendations outlined in Section 7 are adopted, the proposed development would be at an acceptably low risk of damage from projected coastal erosion/recession and coastal inundation for a planning period of 100 years. The proposed development would be founded on bedrock and generally suspended above or landward of coastal processes over its design life (and only interact with wave runup in severe coastal storms), so the proposed development is unlikely to cause increased risk of coastal hazards on that land or other land over its design life.

8.2.5 Synthesis

The proposed development satisfies the requirements of *State Environmental Planning Policy (Coastal Management) 2018* for the matters considered herein.

8.3 Pittwater Local Environmental Plan 2014

Clause 7.5 of *Pittwater Local Environmental Plan 2014* (LEP 2014) applies at the subject property, as the property is identified as "Bluff/Cliff Instability" on the Coastal Risk Planning Map Sheet CHZ_015. Based on Clause 7.5(3) of LEP 2014, "development consent must not be granted to development on land to which this clause applies unless the consent authority is satisfied that the development:

- (a) is not likely to cause detrimental increases in coastal risks to other development or properties, and
- (b) is not likely to alter coastal processes and the impacts of coastal hazards to the detriment of the environment, and
- (c) incorporates appropriate measures to manage risk to life from coastal risks, and
- (d) is likely to avoid or minimise adverse effects from the impact of coastal processes and the exposure to coastal hazards, particularly if the development is located seaward of the immediate hazard line, and

- (e) provides for the relocation, modification or removal of the development to adapt to the impact of coastal processes and coastal hazards, and
- (f) has regard to the impacts of sea level rise, and
- (g) will have an acceptable level of risk to both property and life, in relation to all identifiable coastline hazards".

With regard to (a) and (b), the proposed development would not increase coastal risks nor alter coastal processes and the impacts of coastal hazards, being founded on and suspended above bedrock, and well landward of typical coastal processes.

With regard to (c) and (d), it is considered that founding the proposed development on bedrock is an appropriate measure to manage risk to life from coastal risks, and to avoid or minimise adverse effects from the impact of coastal processes and the exposure to coastal hazards. Item (g) is ultimately for the geotechnical engineer to assess, with consideration of the findings herein. Assuming that they find that the proposed development is at an acceptably low risk of damage over a 100 year planning period with appropriate measures incorporated in the design and construction, Item (g) would be satisfied. On this basis, (e) should not be necessary, noting that this would be more applicable in a sandy beach environment.

With regard to (f), sea level rise has been considered herein.

9. FORM

Completed *Geotechnical Risk Management Policy for Pittwater* Form No. 1 is attached at the end of the document herein. Note that the declaration on Form No. 1 is not appropriate for a coastal report, with the revised declaration below:

"I am aware that the above Coastal Report, prepared for the abovementioned site is to be submitted to assist with a geotechnical investigation for a Development Application for this site, with that geotechnical investigation relied on by Northern Beaches Council as the basis for ensuring that the Geotechnical Risk Management aspects of the proposed development have been adequately addressed. No declaration can be made on the geotechnical investigation as this has not been prepared nor reviewed by me, and nor do I have geotechnical engineering expertise".

10. CONCLUSIONS

A conservative allowance for erosion/weathering of 5mm per year of the southern face of the cliff/bluff at 271 Whale Beach Road Whale Beach should be considered and assessed by the geotechnical engineer. The geotechnical engineer should consider this rate in conjunction with an understanding of the particular nature of the cliff materials seaward of the subject property, their resistance to erosion, and potential failure planes related to geotechnical issues such as the joint spacing.

Coastal inundation is not a significant risk to the pool over a planning period of well over 100 years. The lower portion of the inclinator (below about 8m AHD) may be impacted by wave runup at times of severe coastal storms.

If the recommendations outlined in Section 7 are followed, the proposed development would be at an acceptably low risk of damage from a coastal engineering perspective.

© 2019 Horton Coastal Engineering Pty Ltd

Assuming that the geotechnical engineer will find that the development is at an acceptably low risk of damage from erosion/recession over a 100 year design life, the proposed development satisfies the requirements of *State Environmental Planning Policy (Coastal Management) 2018* (Clauses 13, 14 and 15) and Clause 7.5 of *Pittwater Local Environmental Plan 2014* for the matters considered herein.

11. REFERENCES

Ascent Geotechnical Consulting (2019), *Geotechnical Assessment for Alterations and Additions at 271 Whale Beach Road, Whale Beach, NSW*, Version 0, 21 August

Coffey & Partners (1987), "Coastal Management Study, Assessment of Bluff Areas", *Report No. S8002/1-AA*, March, for Warringah Shire Council

Crozier, PJ and JC Braybrooke (1992), "The morphology of Northern Sydney's rocky headlands, their rates and styles of regression and implications for coastal development", *26th Newcastle Symposium on Advances in the Study of the Sydney Basin*, University of Newcastle

Dragovich, Deirdre (2000), "Weathering Mechanisms and Rates of Decay of Sydney Dimension Sandstone", pp. 74-82 in *Sandstone City, Sydney's Dimension Stone and Other Sandstone Geomaterials*, edited by GH McNally and BJ Franklin, Environmental, Engineering and Hydrogeology Specialist Group (EEHSG), Geological Society of Australia, Monograph No. 5

Public Works Department (1985), "Coastal Management Strategy, Warringah Shire, Report to Working Party", *PWD Report 85016*, June, prepared by AD Gordon, JG Hoffman and MT Kelly, for Warringah Shire Council

Sunamura, Tsuguo (1983), "Processes of Sea Cliff and Platform Erosion", Chapter 12 in *CRC Handbook of Coastal Processes and Erosion*, editor Paul D Komar, CRC Press Inc, Boca Raton, Florida, ISBN 0-8493-0208-0

12. SALUTATION

If you have any further queries, please do not hesitate to contact Peter Horton via email at peter@hortoncoastal.com.au or via mobile on 0407 012 538.

Yours faithfully HORTON COASTAL ENGINEERING PTY LTD

Peter Horton Director and Principal Coastal Engineer

This report has been prepared by Horton Coastal Engineering Pty Ltd on behalf of and for the exclusive use of Simon Tripp and DMC Building Group Pty Ltd (the client), and is subject to and issued in accordance with an agreement between the client and Horton Coastal Engineering Pty Ltd. Horton Coastal Engineering Pty Ltd accepts no liability or responsibility whatsoever for the report in respect of any use of or reliance upon it by any third party. Copying this report without the permission of the client or Horton Coastal Engineering Pty Ltd is not permitted.

Geotechnical Risk Management Policy for Pittwater Form No. 1 is attached overleaf

GEOTECHNICAL RISK MANAGEMENT POLICY FOR PITTWATER

FORM NO. 1 – To be submitted with Devel	lopment Application
---	---------------------

Development Application for Simon Tripp					
271 Whale Beach Boad Whale Beach					
Address of site					
geotechnical report					
I, on behalf of On behalf of					
(Insert Name) (Trading or Company Name)					
on this the engineer as defined by the Geotechnical Risk Management Policy for Pittwater - 2009 and I am authorised by the abo organisation/company to issue this document and to certify that the organisation/company has a current professional indemnity policy of least \$2million. I:					
Please mark appropriate box have prepared the detailed Geotechnical Report referenced below in accordance with the Australia Geomechanics Society Landslide Risk Management Guidelines (AGS 2007) and the Geotechnical Risk Management Policy for Pittwater - 2009					
am willing to technically verify that the detailed Geotechnical Report referenced below has been prepared in accordance with the Australian Geomechanics Society's Landslide Risk Management Guidelines (AGS 2007) and the Geotechnical Risk Management Policy for Pittwater - 2009					
have examined the site and the proposed development in detail and have carried out a risk assessment in accordance w Section 6.0 of the Geotechnical Risk Management Policy for Pittwater - 2009. I confirm that the results of the risk assessment for the proposed development are in compliance with the Geotechnical Risk Management Policy for Pittwater - 2009 and furth detailed geotechnical reporting is not required for the subject site.					
have examined the site and the proposed development/alteration in detail and I am of the opinion that the Development Application only involves Minor Development/Alteration that does not require a Geotechnical Report or Risk Assessment and hence my Report is in accordance with the Geotechnical Risk Management Policy for Pittwater - 2009 requirements.					
have examined the site and the proposed development/alteration is separate from and is not affected by a Geotechnical Haza and does not require a Geotechnical Report or Risk Assessment and hence my Report is in accordance with the Geotechnical Risk Management Policy for Pittwater - 2009 requirements.					
have provided the coastal process and coastal forces analysis for inclusion in the Geotechnical Report Coastal Geotechnical Report Details:					
Report Title: Coastal Engineering Advice on 271 Whale Beach Road Whale Beach Report Date 27 August 2019					
Author Deter Herten					
Author's Company/Organisation: Horton Coastal Engineering Pty Ltd					
Documentation which relate to or are relied upon in report preparation:					
+-am- aware-that-the-above-Geotechnical-Report-prepared-for-the-abovementionedsite-is-te-be-submitted-in-support-of-a-Developme					
Application for this site and will be relied on by Pittwater Gouncil as the basis for ensuring that the Geotechnical Risk-Management aspects of the proposed development have been adequately addressed to achieve an "Acceptable Risk-Management" level for the life of the structure, taken as at least 100 years unless otherwise stated and justified in the Report and that reasonable and practical measures have been					
identified to remove foreseeable risk. Signature for the factor See revised declaration in Section 9 of report					
Chartered Professional Status MIEAust CPEng NER					
Membership No. 452980					
Company. Horton Coastal Engineering Pty Ltd					
P21 DCP Appendix 5 Page 20					

P21 DCP Appendix 5 Page 20



General Notes About This Report

Introduction

These supporting notes have been prepared by Ascent Geotechnical Consultants (AGC) to assist our clients interpret and understand the limitations of this report. Not all sections below are necessarily relevant to this report.

Limitations

Geotechnical reports are based on information gained from limited sub-surface site testing and sampling, supplemented by knowledge of local geology and experience. For this reason, they must be regarded as interpretive rather than factual documents, limited to some extent by the scope of the information on which they rely.

This report has been prepared for this specific project's design proposal. This report should not be relied upon for any other project or if the design proposal of this project changes without the prior knowledge of AGC.

Subsurface Conditions

Subsurface conditions can change with time and can vary significantly between test locations and over very short distances. That actual interface between the materials may be far more gradual or abrupt than interpreted. Therefore, actual conditions in areas not tested may differ from those predicted since no subsurface investigation, no matter how comprehensive, can reveal al subsurface details and anomalies.

Groundwater

Groundwater levels indicated in our subsurface testing are recorded at specific times. The groundwater levels recorded will depend on ground permeability, seepage and environmental variations.

Site inspections

Ascent Geotechnical Consultants will always be please to provide engineering inspection services for aspects of work relating to this report. This may range from standard foundation material inspections for footings, to a full-time engineering presence on site or through one stage of the development. Ascent Geotechnical Consultants are familiar with a variety of techniques and approaches that can be used to help reduce risks for all parties to a project, from design to construction.

Anomalies

If the ground or groundwater conditions onsite prove to differ from those described in this report we would recommend that Ascent Geotechnical Consulting be contacted as a matter of priority. It is far easier and less costly to address these issues if they are addressed early on in the project.

Foundation Maintenance and Footing Performance: A Homeowner's Guide



BTF 18 replaces Information Sheet 10/91

Buildings can and often do move. This movement can be up, down, lateral or rotational. The fundamental cause of movement in buildings can usually be related to one or more problems in the foundation soil. It is important for the homeowner to identify the soil type in order to ascertain the measures that should be put in place in order to ensure that problems in the foundation soil can be prevented, thus protecting against building movement.

This Building Technology File is designed to identify causes of soil-related building movement, and to suggest methods of prevention of resultant cracking in buildings.

Soil Types

The types of soils usually present under the topsoil in land zoned for residential buildings can be split into two approximate groups – granular and clay. Quite often, foundation soil is a mixture of both types. The general problems associated with soils having granular content are usually caused by erosion. Clay soils are subject to saturation and swell/shrink problems.

Classifications for a given area can generally be obtained by application to the local authority, but these are sometimes unreliable and if there is doubt, a geotechnical report should be commissioned. As most buildings suffering movement problems are founded on clay soils, there is an emphasis on classification of soils according to the amount of swell and shrinkage they experience with variations of water content. The table below is Table 2.1 from AS 2870, the Residential Slab and Footing Code.

Causes of Movement

Settlement due to construction

There are two types of settlement that occur as a result of construction:

- Immediate settlement occurs when a building is first placed on its foundation soil, as a result of compaction of the soil under the weight of the structure. The cohesive quality of clay soil mitigates against this, but granular (particularly sandy) soil is susceptible.
- Consolidation settlement is a feature of clay soil and may take place because of the expulsion of moisture from the soil or because of the soil's lack of resistance to local compressive or shear stresses. This will usually take place during the first few months after construction, but has been known to take many years in exceptional cases.

These problems are the province of the builder and should be taken into consideration as part of the preparation of the site for construction. Building Technology Hle 19 (BTF 19) deals with these problems.

Erosion

All soils are prone to erosion, but sandy soil is particularly susceptible to being washed away. Even clay with a sand component of say 10% or more can suffer from erosion.

Saturation

This is particularly a problem in clay soils. Saturation creates a boglike suspension of the soil that causes it to lose virtually all of its bearing capacity. To a lesser degree, sand is affected by saturation because saturated sand may undergo a reduction in volume – particularly imported sand fill for bedding and blinding layers. However, this usually occurs as immediate settlement and should normally be the province of the builder.

Seasonal swelling and shrinkage of soil

All clays react to the presence of water by slowly absorbing it, making the soil increase in volume (see table below). The degree of increase varies considerably between different clays, as does the degree of decrease during the subsequent drying out caused by fair weather periods. Because of the low absorption and expulsion rate, this phenomenon will not usually be noticeable unless there are prolonged rainy or dry periods, usually of weeks or months, depending on the land and soil characteristics.

The swelling of soil creates an upward force on the footings of the building, and shrinkage creates subsidence that takes away the support needed by the footing to retain equilibrium.

Shear failure

This phenomenon occurs when the foundation soil does not have sufficient strength to support the weight of the footing. There are two major post-construction causes:

- Significant load increase
- Reduction of lateral support of the soil under the footing due to erosion or excavation.
- In clay soil, shear failure can be caused by saturation of the soil adjacent to or under the footing.

Class	Foundation				
А	Most sand and rock sites with little or no ground movement from moisture changes				
S	Slightly reactive clay sites with only slight ground movement from moisture changes				
М	Moderately reactive clay or silt sites, which can experience moderate ground movement from moisture changes				
Н	Highly reactive clay sites, which can experience high ground movement from moisture changes				
Е	Extremely reactive sites, which can experience extreme ground movement from moisture changes				
A to P	Filled sites				
Р	Sites which include soft soils, such as soft clay or silt or loose sands; landslip; mine subsidence; collapsing soils; soils subject to erosion; reactive sites subject to abnormal moisture conditions or sites which cannot be classified otherwise				

GENERAL DEFINITIONS OF SITE CLASSES

Tree root growth

Trees and shrubs that are allowed to grow in the vicinity of footings can cause foundation soil movement in two ways

- Roots that grow under footings may increase in cross-sectional size, exerting upward pressure on footings.
- Roots in the vicinity of footings will absorb much of the moisture in the foundation soil, causing shrinkage or subsidence.

Unevenness of Movement

The types of ground movement described above usually occur unevenly throughout the building's foundation soil. Settlement due to construction tends to be uneven because of:

- · Differing compaction of foundation soil prior to construction.
- · Differing moisture content of foundation soil prior to construction.

Movement due to non-construction causes is usually more uneven still. Erosion can undermine a footing that traverses the flow or can create the conditions for shear failure by eroding soil adjacent to a footing that runs in the same direction as the flow.

Saturation of clay foundation soil may occur where subfloor walls create a dam that makes water pond. It can also occur wherever there is a source of water near footings in clay soil. This leads to a severe reduction in the strength of the soil which may create local shear failure.

Seasonal swelling and shrinkage of clay soil affects the perimeter of the building first, then gradually spreads to the interior. The swelling process will usually begin at the uphill extreme of the building, or on the weather side where the land is flat. Swelling gradually reaches the interior soil as absorption continues. Shrinkage usually begins where the sunk heat is greatest.

Effects of Uneven Soil Movement on Structures

Erosion and saturation

Erosion removes the support from under footings, tending to create subsidence of the part of the structure under which it occurs. Brickwork walls will resist the stress created by this removal of support by bridging the gap or cantilevering until the bricks or the montar bedding fail. Older masonry has little resistance. Evidence of failure varies according to circumstances and symptoms may include:

- Step cracking in the mortar beds in the body of the wall or above/below openings such as doors or windows.
- Vertical cracking in the bricks (usually but not necessarily in line with the vertical beds or perpends).

Isolated piers affected by erosion or saturation of foundations will eventually lose contact with the bearers they support and may tilt or fall over. The floors that have lost this support will become bouncy, sometimes rattling ornaments etc.

Seasonal swelling/shrinkage in clay

Swelling foundation soil due to rainy periods first lifts the most exposed extremities of the footing system, then the remainder of the perimeter footings while gradually permeating inside the building footprint to lift internal footings. This swelling first tends to create a dish effect, because the external footings are pushed higher than the internal ones.

The first noticeable symptom may be that the floor appears slightly dished. This is often accompanied by some doors binding on the floor or the door head, together with some cracking of comice mitres. In buildings with timber flooring supported by bearers and joists, the floor can be bouncy. Externally there may be visible dishing of the hip or ridge lines.

As the moisture absorption process completes its journey to the innermost areas of the building, the internal footings will rise. If the spread of moisture is roughly even, it may be that the symptoms will temporarily disappear, but it is more likely that swelling will be uneven, creating a difference rather than a disappearance in symptoms. In buildings with timber flooring supported by bearers and joists, the isolated piers will rise more easily than the strip footings or piers under walls, creating noticeable doming of flooring.



As the weather pattern changes and the soil begins to dry out, the external footings will be first affected, beginning with the locations where the sun's effect is strongest. This has the effect of lowering the external footings. The doming is accentuated and cracking reduces or disappears where it occurred because of dishing, but other cracks open up. The roof lines may become convex.

Doming and dishing are also affected by weather in other ways. In areas where warm, wet summers and cooler dry winters prevail, water migration tends to be toward the interior and doming will be accentuated, whereas where summers are dry and winters are cold and wet, migration tends to be toward the exterior and the underlying propensity is toward dishing.

Movement caused by tree roots

In general, growing roots will exert an upward pressure on footings, whereas soil subject to drying because of tree or shrub roots will tend to remove support from under footings by inducing shrinkage.

Complications caused by the structure itself

Most forces that the soil causes to be exerted on structures are vertical – i.e. either up or down. However, because these forces are seldom spread evenly around the footings, and because the building resists uneven movement because of its rigidity, forces are exerted from one part of the building to another. The net result of all these forces is usually rotational. This resultant force often complicates the diagnosis because the visible symptoms do not simply reflect the original cause. A common symptom is binding of doors on the vertical member of the frame.

Effects on full masonry structures

Brickwork will resist cracking where it can. It will attempt to span areas that lose support because of subsided foundations or raised points. It is therefore usual to see cracking at weak points, such as openings for windows or doors.

In the event of construction settlement, cracking will usually remain unchanged after the process of settlement has ceased.

With local shear or erosion, cracking will usually continue to develop until the original cause has been remedied, or until the subsidence has completely neutralised the affected portion of footing and the structure has stabilised on other footings that remain effective.

In the case of swell/shrink effects, the brickwork will in some cases return to its original position after completion of a cycle, however it is more likely that the rotational effect will not be exactly reversed, and it is also usual that brickwork will settle in its new position and will resist the forces trying to return it to its original position. This means that in a case where swelling takes place after construction and cracking occurs, the cracking is likely to at least partly remain after the shrink segment of the cycle is complete. Thus, each time the cycle is repeated, the likelihood is that the cracking will become wider until the sections of brickwork become virtually independent.

With repeated cycles, once the cracking is established, if there is no other complication, it is normal for the incidence of cracking to stabilise, as the building has the articulation it needs to cope with the problem. This is by no means always the case, however, and monitoring of cracks in walls and floors should always be treated seriously.

Upheaval caused by growth of tree roots under footings is not a simple vertical shear stress. There is a tendency for the root to also exert lateral forces that attempt to separate sections of brickwork after initial cracking has occurred. The normal structural arrangement is that the inner leaf of brickwork in the external walls and at least some of the internal walls (depending on the roof type) comprise the load-bearing structure on which any upper floors, ceilings and the roof are supported. In these cases, it is internally visible cracking that should be the main focus of attention, however there are a few examples of dwellings whose external leaf of masonry plays some supporting role, so this should be checked if there is any doubt. In any case, externally visible cracking is important as a guide to stresses on the structure generally, and it should also be remembered that the external walls must be capable of supporting themselves.

Effects on framed structures

Timber or steel framed buildings are less likely to exhibit cracking due to swell/shrink than masonry buildings because of their flexibility. Also, the doming/dishing effects tend to be lower because of the lighter weight of walls. The main risks to framed buildings are encountered because of the isolated pier footings used under walls. Where erosion or saturation cause a footing to fall away, this can double the span which a wall must bridge. This additional stress can create cracking in wall linings, particularly where there is a weak point in the structure caused by a door or window opening. It is, however, unlikely that framed structures will be so stressed as to suffer serious damage without first exhibiting some or all of the above symptoms for a considerable period. The same warning period should apply in the case of upheaval. It should be noted, however, that where framed buildings are supported by strip footings there is only one leaf of brickwork and therefore the externally visible walls are the supporting structure for the building. In this case, the subfloor masonry walls can be expected to behave as full brickwork walls.

Effects on brick veneer structures

Because the load-bearing structure of a brick veneer building is the frame that makes up the interior leaf of the external walls plus perhaps the internal walls, depending on the type of roof, the building can be expected to behave as a framed structure, except that the external masonry will behave in a similar way to the external leaf of a full masonry structure.

Water Service and Drainage

Where a water service pipe, a sewer or stormwater drainage pipe is in the vicinity of a building, a water leak can cause erosion, swelling or saturation of susceptible soil. Even a minuscule leak can be enough to saturate a clay foundation. A leaking tap near a building can have the same effect. In addition, trenches containing pipes can become watercourses even though backfilled, particularly where broken nubble is used as fill. Water that runs along these trenches can be responsible for serious crosion, interstrata seepage into subfloor areas and saturation.

Pipe leakage and trench water flows also encourage tree and shrub roots to the source of water, complicating and exacerbating the problem.

Poor roof plumbing can result in large volumes of rainwater being concentrated in a small area of soil:

 Incorrect falls in roof guttering may result in overflows, as may gutters blocked with leaves etc.

- · Corroded guttering or downpipes can spill water to ground.
- Downpipes not positively connected to a proper stormwater collection system will direct a concentration of water to soil that is directly adjacent to footings, sometimes causing large-scale problems such as erosion, saturation and migration of water under the building.

Seriousness of Cracking

In general, most cracking found in masonry walls is a cosmetic nuisance only and can be kept in repair or even ignored. The table below is a reproduction of Table C1 of AS 2870.

AS 2870 also publishes figures relating to cracking in concrete floors, however because wall cracking will usually reach the critical point significantly earlier than cracking in slabs, this table is not reproduced here.

Prevention/Cure

Plumbing

Where building movement is caused by water service, roof plumbing, sewer or stormwater failure, the remedy is to repair the problem. It is prudent, however, to consider also rerouting pipes away from the building where possible, and relocating taps to positions where any leakage will not direct water to the building vicinity. Even where gully traps are present, there is sometimes sufficient spill to create erosion or saturation, particularly in modern installations using smaller diameter PVC fixtures. Indeed, some gully traps are not situated directly under the taps that are installed to charge them, with the result that water from the tap may enter the backfilled trench that houses the sewer piping. If the trench has been poorly backfilled, the water will either pond or flow along the bottom of the trench. As these trenches usually run alongside the footings and can be at a similar depth, it is not hard to see how any water that is thus directed into a trench can easily affect the foundation's ability to support footings or even gain entry to the subfloor area.

Ground drainage

In all soils there is the capacity for water to travel on the surface and below it. Surface water flows can be established by inspection during and after heavy or prolonged rain. If necessary, a grated drain system connected to the stormwater collection system is usually an easy solution.

It is, however, sometimes necessary when attempting to prevent water migration that testing be carried out to establish watertable height and subsoil water flows. This subject is referred to in BTF 19 and may properly be regarded as an area for an expert consultant.

Protection of the building perimeter

It is essential to remember that the soil that affects footings extends well beyond the actual building line. Watering of garden plants, shrubs and trees causes some of the most serious water problems.

For this reason, particularly where problems exist or are likely to occur, it is recommended that an apron of paving be installed around as much of the building perimeter as necessary. This paving

CLASSIFICATION OF DAMAGE WITH REFERENCE TO WALLS					
Description of typical damage and required repair	Approximate crack width limit (see Note 3)	Damage category			
Hairline cracks	<0.1 mm	0			
Fine cracks which do not need repair	⊲ mm	1			
Cracks noticeable but easily filled. Doors and windows stick slightly	⊲ mm	2			
Cracks can be repaired and possibly a small amount of wall will need to be replaced. Doors and windows stick. Service pipes can fracture. Weathertightness often impaired	5-15 mm (or a number of cracks 3 mm or more in one group)	3			
Extensive repair work involving breaking-out and replacing sections of walls, especially over doors and windows. Window and door frames distort. Walls lean or bulge noticeably, some loss of bearing in beams. Service pipes disrupted	15–25 mm but also depend on number of cracks	4			



should extend outwards a minimum of 900 mm (more in highly reactive soil) and should have a minimum fall away from the building of 1:60. The finished paving should be no less than 100 mm below brick yent bases.

Medium

height tree

It is prudent to relocate drainage pipes away from this paving, if possible, to avoid complications from future leakage. If this is not practical, earthen ware pipes should be replaced by PVC and backfilling should be of the same soil type as the surrounding soil and compacted to the same density.

Except in areas where freezing of water is an issue, it is wise to remove taps in the building area and relocate them well away from the building – preferably not uphill from it (see BTF 19).

It may be desirable to install a grated drain at the outside edge of the paying on the uphill side of the building. If subsoil drainage is needed this can be installed under the surface drain.

Condensation

Driveway

In buildings with a subfloor void such as where bearers and joists support flooring, insufficient ventilation creates ideal conditions for condensation, particularly where there is little clearance between the floor and the ground. Condensation adds to the moisture already present in the subfloor and significantly slows the process of drying out. Installation of an adequate subfloor ventilation system, either natural or mechanical, is desirable.

Warning: Although this Building Technology File deals with cracking in buildings, it should be said that subfloor moisture can result in the development of other problems, notably:

- Water that is transmitted into masonry, metal or timber building elements causes damage and/or decay to those elements.
- High subfloor humidity and moisture content create an ideal environment for various pests, including termites and spiders.
- Where high moisture levels are transmitted to the flooring and walls, an increase in the dust mite count can ensue within the living areas. Dust mites, as well as dampness in general, can be a health hazard to inhabitants, particularly those who are abnormally susceptible to respiratory ailments.

The garden

The ideal vegetation layout is to have lawn or plants that require only light watering immediately adjacent to the drainage or paving edge, then more demanding plants, shrubs and trees spread out in that order.

Overwatering due to misuse of automatic watering systems is a common cause of saturation and water migration under footings. If it is necessary to use these systems, it is important to remove garden beds to a completely safe distance from buildings.

Existing trees

Garden bed

covered with mulch Where a tree is causing a problem of soil drying or there is the existence or threat of upheaval of footings, if the offending roots are subsidiary and their removal will not significantly damage the tree, they should be severed and a concrete or metal barrier placed vertically in the soil to prevent future root growth in the direction of the building. If it is not possible to remove the relevant roots without damage to the tree, an application to remove the tree should be made to the local authority. A prudent plan is to transplant likely offenders before they become a problem.

Information on trees, plants and shrubs

State departments overseeing agriculture can give information regarding root patterns, volume of water needed and safe distance from buildings of most species. Botanic gardens are also sources of information. For information on plant roots and drains, see Building Technology File 17.

Excavation

Excavation around footings must be properly engineered. Soil supporting footings can only be safely excavated at an angle that allows the soil under the footing to remain stable. This angle is called the angle of repose (or friction) and varies significantly between soil types and conditions. Removal of soil within the angle of repose will cause subsidence.

Remediation

Where erosion has occurred that has washed away soil adjacent to footings, soil of the same classification should be introduced and compacted to the same density. Where footings have been undermined, augmentation or other specialist work may be required. Remediation of footings and foundations is generally the realm of a specialist consultant.

Where isolated footings rise and fall because of swell/shrink effect, the homeowner may be tempted to alleviate floor bounce by filling the gap that has appeared between the bearer and the pier with blocking. The danger here is that when the next swell segment of the cycle occurs, the extra blocking will push the floor up into an accentuated dome and may also cause local shear failure in the soil. If it is necessary to use blocking, it should be by a pair of fine wedges and monitoring should be carried out fortnightly.

This BTF was prepared by John Lewer FAIB, MIAMA, Partner, Construction Diagnosis.

The information in this and other issues in the series was derived from various sources and was believed to be correct when published.

The information is advisory. It is provided in good faith and not claimed to be an exhaustive treatment of the relevant subject.

Further professional advice needs to be obtained before taking any action based on the information provided.

Distributed by CSIRO PUBLISHING PO Box 1139, Collingwood 3066, Australia Freecall 1800 645 051 Tel (03) 9662 7666 Fax (03) 9662 7555 www.publish.csiro.au Email: publishing.sales@siro.au

© CSIRO 2003. Unauthorised copying of this Building Technology file is prohibited



EXAMPLES OF POOR HILLSIDE PRACTICE



PRACTICE NOTE GUIDELINES FOR LANDSLIDE RISK MANAGEMENT 2007 APPENDIX C: LANDSLIDE RISK ASSESSMENT QUALITATIVE TERMINOLOGY FOR USE IN ASSESSING RISK TO PROPERTY

QUALITATIVE MEASURES OF LIKELIHOOD

Approximate Annual Probability Implied Indicati Indicative Notional Recurrence Value Boundary Recurrence		ve Landslide Interval	Description	Descriptor	Level	
10 ⁻¹	5x10 ⁻²	10 years		The event is expected to occur over the design life.	ALMOST CERTAIN	Α
10-2	5.10-3	5x10 ⁻³ 20 years 5x10 ⁻³ 100 years 200 years 5x10 ⁻⁴ 1000 years 2000 years 10,000 years 2000 years 2000 years		The event will probably occur under adverse conditions over the design life.	LIKELY	В
10-3	5x10			The event could occur under adverse conditions over the design life.	POSSIBLE	С
10-4	5x10"			The event might occur under very adverse circumstances over the design life.	UNLIKELY	D
10-5	5x10 ⁻⁶	100,000 years		The event is conceivable but only under exceptional circumstances over the design life.	RARE	Е
10-6	5x10	1,000,000 years	200,000 years	The event is inconceivable or fanciful over the design life.	BARELY CREDIBLE	F

Note: (1) The table should be used from left to right; use Approximate Annual Probability or Description to assign Descriptor, not vice versa.

QUALITATIVE MEASURES OF CONSEQUENCES TO PROPERTY

Approximate Cost of Damage		Description	Descriptor	Level
Value	Notional Boundary		•	
200%	1000/	Structure(s) completely destroyed and/or large scale damage requiring major engineering works for stabilisation. Could cause at least one adjacent property major consequence damage.	CATASTROPHIC	1
60%	100%	Extensive damage to most of structure, and/or extending beyond site boundaries requiring significant stabilisation works. Could cause at least one adjacent property medium consequence damage.	MAJOR	2
20%	40%	Moderate damage to some of structure, and/or significant part of site requiring large stabilisation works. Could cause at least one adjacent property minor consequence damage.	MEDIUM	3
5%	10%	Limited damage to part of structure, and/or part of site requiring some reinstatement stabilisation works.	MINOR	4
0.5%	170	Little damage. (Note for high probability event (Almost Certain), this category may be subdivided at a notional boundary of 0.1%. See Risk Matrix.)	INSIGNIFICANT	5

Notes: (2) The Approximate Cost of Damage is expressed as a percentage of market value, being the cost of the improved value of the unaffected property which includes the land plus the unaffected structures.

(3) The Approximate Cost is to be an estimate of the direct cost of the damage, such as the cost of reinstatement of the damage portion of the property (land plus structures), stabilisation works required to render the site to tolerable risk level for the landslide which has occurred and professional design fees, and consequential costs such as legal fees, temporary accommodation. It does not include additional stabilisation works to address other landslides which may affect the property.

(4) The table should be used from left to right; use Approximate Cost of Damage or Description to assign Descriptor, not vice versa

PRACTICE NOTE GUIDELINES FOR LANDSLIDE RISK MANAGEMENT 2007

APPENDIX C: - QUALITATIVE TERMINOLOGY FOR USE IN ASSESSING RISK TO PROPERTY (CONTINUED)

QUALITATIVE RISK ANALYSIS MATRIX – LEVEL OF RISK TO PROPERTY

LIKELIHO	CONSEQUENCES TO PROPERTY (With Indicative Approximate Cost of Damage)					
	Indicative Value of Approximate Annual Probability	1: CATASTROPHIC 200%	2: MAJOR 60%	3: MEDIUM 20%	4: MINOR 5%	5: INSIGNIFICANT 0.5%
A – ALMOST CERTAIN	10 ⁻¹	VH	VH	VH	Н	M or L (5)
B - LIKELY	10 ⁻²	VH	VH	Н	М	L
C - POSSIBLE	10-3	VH	Н	М	М	VL
D - UNLIKELY	10-4	Н	М	L	L	VL
E - RARE	10-5	М	L	L	VL	VL
F - BARELY CREDIBLE	10 ⁻⁶	L	VL	VL	VL	VL

Notes: (5) For Cell A5, may be subdivided such that a consequence of less than 0.1% is Low Risk.

(6) When considering a risk assessment it must be clearly stated whether it is for existing conditions or with risk control measures which may not be implemented at the current time.

RISK LEVEL IMPLICATIONS

	Risk Level	Example Implications (7)
VH	VERY HIGH RISK	Unacceptable without treatment. Extensive detailed investigation and research, planning and implementation of treatment options essential to reduce risk to Low; may be too expensive and not practical. Work likely to cost more than value of the property.
Н	HIGH RISK.	Unacceptable without treatment. Detailed investigation, planning and implementation of treatment options required to reduce risk to Low. Work would cost a substantial sum in relation to the value of the property.
М	MODERATE RISK	May be tolerated in certain circumstances (subject to regulator's approval) but requires investigation, planning and implementation of treatment options to reduce the risk to Low. Treatment options to reduce to Low risk should be implemented as soon as practicable.
L	LOW RISK	Usually acceptable to regulators. Where treatment has been required to reduce the risk to this level, ongoing maintenance is required.
VL	VERY LOW RISK	Acceptable. Manage by normal slope maintenance procedures.

Note: (7) The implications for a particular situation are to be determined by all parties to the risk assessment and may depend on the nature of the property at risk; these are only given as a general guide.