

DRAWING SCHEDULE.

DA-A01-B EXISTING SITE PLAN AND SITE ANALYSIS PLAN.

DA-A02-C PROPOSED SITE PLAN

DA-A03-D PROPOSED PLAN AT GFL LEVEL

DA-A04-D PROPOSED PLAN AT FIRST FL LEVEL

DA-A05-C PROPOSED PLAN AT SECOND FL LEVEL

DA-A06-B PROPOSED PLAN AT THIRD FL LEVEL

DA-A07-A ROOF PLAN

DA-A08-E SECTION AA

DA-A09-E SECTION BB

DA-A10-D SECTION CC and BASIX COMMITMENTS

DA-A11-E WEST AND EAST ELEVATIONS and BASIX COMMITMENTS.

DA-A12-E PROPOSED S ELEVATION

DA-A13-E EXTERNAL FINISHES WEST AND EAST ELEVATIONS

DA-DEM-01-C DEMOLITION PLAN, WASTE AND MATERIAL STORAGE, SEDIMENT AND EROSION CONTROL MEASURES

E	В	25.7.2023	amended drawing issue.
(С	7.8.2023	amended drawing issue- OSD added .
	D	12.9.2023	amended drawing issue- OSD amended. additional works required for Fire Safety upgrade deleted from this application. rebuild partially collapsd retaining wall NW corner added.
	E	30.10.2023	amended to show BASIX COMITTMENTS

PROPOSED ALTERATIONS TO FRONT FENCE AND ENTRY
AND UNIT 4 BALCONY AND ASSOCIATED WORKS
AT 8 OCEAN ROAD
MANLY 2095
SP 14402

FOR THE OWNERS SP 14402 KUBANYI ARCHITECTS NSW REG 4087 DEP 0000592 LEVEL 1, 122 VICTORIA ROAD DRUMMOYNE 2047 PH 0412 500 240 JUDITHKUBANYI@IINET.NET.AU

DRWG No DA.A0-E

Date
April 14 2023

Drawn jk

ISSUE DA



EXISTING VIEW FROM OCEAN ROAD google earth streetview




EXISTING ENTRY TO SITE FROM OCEAN ROAD



CONDITION OF FRONT FENCE



EAST ELEVATION. rear of building



Scale 1:200

Date

April 14 2023

PROPOSED ALTERATIONS TO FRONT FENCE AND ENTRY
AND UNIT 4 BALCONY
AT 8 OCEAN ROAD
MANLY 2095
SP 14402


FOR THE OWNERS SP 14402 KUBANYI ARCHITECTS NSW REG 4087 DEP 0000592 LEVEL 1, 122 VICTORIA ROAD DRUMMOYNE 2047 PH 0412 500 240 JUDITHKUBANYI@IINET.NET.AU


issue


DA


DRWG No DA-A01-B


EXISTING SITE
PLAN and
SITE ANALYSIS


























REPLACE EXISTING DETERIORATED TILED ROOFING WITH CORRUGATED COLORBOND.
REPLACE EXISTING GUTTERS, DPS, AND DETERIORATED FASCIAS AND SOFFIT LININGS

