ACERT REGISTD. N°. 328 BPB as the ACCREDITED CERTIFIER & PCA Dev. Consent 2007/72 dated 30/11/07 CONSTRUCTION CERTIFICATE N°. 1012220 dated 25/02/08

#### CASTLEPEAKE

#### **DILAPIDATION REPORT**

1 2 1643 2083

for

#### **COUNCIL ASSETS**

at

# 16 SUMMIT AVENUE, DEE WHY

**Prepared For** 

#### **WARRINGAH COUNCIL**

(Development Application No. DA 2007/72)

**Job No 621** 

January 2008 issue A

TRUMPER RESIDENCE - 16 SUMMIT AVENUE DEE WHY

Architecture
Construction
Landscape Design
Interior Design

Sustainable Design

Peter W Tout FRAIA B Arch (Hons) UNSW Reg No 4285

Mark I Oxenham ARAIA B Arch (Hons) UTS Reg No 7130

Brien B Kwong ARAIA B Arch UTS Reg No 7125

Ground Floor
121 Alexander Street
Crows Nest NSW 2065
Phone +61 2 9437 1800
Fax +61 2 9437 1044
www.castlepeake.com.au

Castlepeake Consulting Pty Ltd ABN 85 054 612 76

#### **DILAPIDATION REPORT ON COUNCIL ASSETS**

#### 1.00 INTRODUCTION

Warringah Council has granted Development Consent for demolition of existing dwelling, construction of a new two storey house and spa pool at premises: 16 Summit Avenue, Dee Why.

Development Consent Condition No 5 requires that a Dilapidation Report on Council Assets be submitted. This report is to document and contain photographs which clearly depict any existing damage to the road, kerb, gutter, footpath, driveways, street trees, street signs or any other Council asset in the vicinity of the development.

The dilapidation report was conducted by Castlepeake Consulting Pty Ltd Archiects on 15 January 2008. During the survey, visible structural defects were noted and selected defects photographed from ground level. Areas concealed by grass ground coverings have not been surveyed.

The results of the report, with descriptions of photographic plates of relevant defects are included on the attached dilapidation report sheets.

#### 2.00 THE SITE IN SUMMARY

The site (approximately 670m<sup>2</sup>) is located at the eastern end of the cul-de-sac in Summit Avenue. See reduced copy of the Level & Feature Survey by Montek Property Surveyors and Photo 1

The width of the site fronting onto Summit Avenue is 8.51m.

#### 3.00 DESCRIPTION OF THE ROAD

- 3.01 Summit Avenue is approximately 9 meters wide.
- 3.02 Summit Avenue has a standard bitumen covering and is generally in poor condition. It varies significantly in levels with quite noticeable uneven surfaces.

  See Photos 1 to 5.
- 3.03 The road has tyre marks in several areas. See Photos 1 to 5.

#### 4.00 KERB & GUTTER

- 4.01 A small concrete kerb with exposed aggregate separates the roadway from the nature strip.
- 4.02 The kerb is broken in numerous areas along its length and is in poor condition. See Photos (majority)
- 4.03 Numerous small sections of the kerb have broken away. See Photos 6 to 28.
- 4.04 There is an existing concrete gutter between the roadway bitumen against the kerb which is generally in poor condition

  See Photo 6 to 28.

5.00	FOOTPATH & DRIVEWAY
5.01	No concrete footpath extends across the frontage of the property. There is a concrete driveway and crossing (approximately 2.7m wide) which provides vehicular access to the weatherboard clad garage on the site which is in reasonable condition.  See Photo 14
5.04	The lawn within the nature strip extending from the kerb to the street boundary is in poor condition. There is a large tree lifting the existing terrain. See Photos 15 to 18
5.05	There are several concrete pads in the lawn area south of the existing tree in the nature strip which is in poor condition. See Photos 17 & 18
	The Hydrant lid is in reasonable condition but does not close properly. See Photo 36
5.06	The lids to the grated drains in the gutters, along the southern side of the subject property are in reasonable condition. See Photos 19 & 20.
6.00	STREET TREES
6.01	There is one major street trees in the grass area along the nature strip of this development which is to be removed because its in poor condition. See Arborist Report as per DA application
7.00	STREET SIGNS AND OTHER COUNCIL ASSETS
7.01	There is an existing power pole located on the south western corner of the subject nature strip which is in poor condition. See Photos 29 to 35
7.02	There are no street signs in the vicinity. See Photo 1
8.00	CONCLUSION
8.01	Council Assets in the immediate vicinity of 16 Summit Avenue, Dee Why are generally in poor condition with the photos showing each asset as of 15 January 2008
	A REDUCED A4 COPY OF THE SUBJECT AREA SITE SURVEY PREPARED

BY MONTEK PROPERTY SURVEYORS PTY LTD & PHOTOS PREPARED BY CASTLEPEAKE CONSULTING PTY LTD ARCHITECTS OF DEFECTS

APPEAR ON FOLLOWING PAGES



**PHOTO 15** 



**PHOTO 16** 



**PHOTO 17** 



**PHOTO 18** 




**PHOTO 19** 



**PHOTO 20** 

Page: 14 of 22







**PHOTO 1** 




PHOTO 2





**PHOTO 4** 



**PHOTO 5** 



РНОТО 6



РНОТО 7



**PHOTO 8** 



РНОТО 9



**PHOTO 10** 



**PHOTO 11** 



**PHOTO 12** 



**PHOTO 13** 



**PHOTO 14** 



**PHOTO 21** 




**PHOTO 22** 



**PHOTO 23** 



**PHOTO 24** 



**PHOTO 25** 



**PHOTO 26** 

# $C\Lambda STLEPE\Lambda KE$



**PHOTO 27** 



**PHOTO 28** 



**PHOTO 29** 



**PHOTO 30** 



**PHOTO 31** 



**PHOTO 32** 



**PHOTO 33** 



**PHOTO 34** 



**PHOTO 35** 



**PHOTO 36**