

Heritage Referral Response

Application Number:	DA2022/0271

Date:	16/05/2022
То:	Thomas Burns
Land to be developed (Address):	Lot 2 DP 1163435 , 6 Bundoon Lane MANLY NSW 2095

Officer comments

HERITAGE COMMENTS

Discussion of reason for referral

The proposal has been referred to Heritage as the subject site is within the vicinity of a heritage item:

Item I163 - Group of houses - 45-49, 51B, 53 and 61-67 Kangaroo Street

Details of heritage items affected

Details of the heritage item as contained within the Manly Heritage inventory are as follows:

Item I163 - Group of houses

Statement of significance:

The streetscape has major significance in its architectural qualities/texture, consists largely of Federation styled 'Villas', its scale, height and visibility on a ridge overlooking the ocean.

Other relevant heritage listings		
Sydney Regional	No	
Environmental Plan (Sydney		
Harbour Catchment) 2005		
Australian Heritage Register	No	
NSW State Heritage Register	No	
National Trust of Aust (NSW)	No	
Register		
RAIA Register of 20th	No	
Century Buildings of		
Significance		
Other	N/A	

Consideration of Application

The proposal seeks consent for an operable roof above the existing east facing balcony. The heritage listed properties at 51B and 53 Bundoon Lane are located directly opposite the road. The installation of the motorised roof involves an aluminium post and beams for the operable louvers. Given the minor nature of the proposed works, the impact of the proposal is considered negligible.

Therefore, no objections are raised on heritage grounds and no conditions required.

Consider against the provisions of CL5.10 of MLEP 2013. Is a Conservation Management Plan (CMP) Required? No Has a CMP been provided? No

DA2022/0271 Page 1 of 2



Is a Heritage Impact Statement required? No Has a Heritage Impact Statement been provided? No

Further Comments

COMPLETED BY: Oya Guner, Heritage Advisor

DATE: 16 May 2022

The proposal is therefore supported.

Note: Should you have any concerns with the referral comments above, please discuss these with the Responsible Officer.

Recommended Heritage Advisor Conditions:

Nil.

DA2022/0271 Page 2 of 2