# HERITAGE IMPACT STATEMENT



Harbord Beach Hotel No. 29 Moore Road, Freshwater April 2020 | J4146



Level 19, 100 William Street, Woolloomooloo NSW 2011 Phone: (02) 8076 5317

#### CONTENTS

<u>1.0</u>	INTRODUCTION	1
1.1	Preamble	1
	AUTHORSHIP	1
	LIMITATIONS	1
	METHODOLOGY	2
	PHYSICAL EVIDENCE	2
	DOCUMENTARY AND ONLINE EVIDENCE	2
	SITE LOCATION	2
<u>2.0</u>	HISTORICAL DEVELOPMENT	3
2.1	Aboriginal Occupation	3
2.2	EUROPEAN DEVELOPMENT OF THE AREA	3
2.3	DEVELOPMENT HISTORY OF THE SUBJECT SITE	8
<u>3.0</u>	PHYSICAL ANALYSIS	14
3.1	ТНЕ ЅІТЕ	14
3.2	THE BUILDING	15
3.2.1	EXTERIOR	15
3.2.2	INTERIOR	16
3.3	THE SURROUNDING AREA	22
	THE GENERAL AREA	22
	Moore Street	23
3.3.3	CHARLES STREET	24
3.3.4	UNDERCLIFF ROAD	24
3.4	INTEGRITY	25
3.5	VIEW CORRIDORS	25
<u>4.0</u>	ASSESSMENT OF SIGNIFICANCE	27
4.1	SUMMARY OF EXISTING CITATIONS AND LISTINGS FOR THE SITE	27
4.1.2	SUMMARY OF STATUTORY HERITAGE LISTINGS	27
4.2	HERITAGE ITEMS IN THE VICINITY OF THE SITE	27
4.2.1	'FRESHWATER' RESTAURANT, 80 UNDERCLIFF ROAD, FRESHWATER (176).	28
<u>5.0</u>	SCOPE OF WORKS	29
<u>6.0</u>	METHOD OF ASSESSMENT	30
<u>7.0</u>	EFFECT OF WORK	30
7.1	ASSESSMENT OF HERITAGE IMPACT	30
7.2	EFFECT OF WORK ON THE SUBJECT PROPERTY	33
7.3	EFFECT OF WORK ON THE SUBJECT PROPERTY EFFECT OF WORK ON HERITAGE ITEMS WITHIN THE VICINITY	33
<i>.</i>	LITEGI OF WORK ON HERITAGE HEMIS WITHIN THE VICINITI	33
<u>8.0</u>	CONCLUSIONS	33
APPENDIX A		34
BUILDING FABRIC SURVEY		34

#### 1.0 INTRODUCTION

#### 1.1 Preamble

This Heritage Impact Statement (HIS) has been prepared in conjunction with a Development Application for alteration and addition to the Harbord Beach Hotel located at No. 29 Moore Road, Freshwater, New South Wales.

The site is located within the Northern Beaches Council Local Government Area (formerly Manly, Warringah and Pittwater Councils). The principal planning control for the site is the *Warringah Local Environmental Plan 2011 (LEP 2011)*. The site <u>is</u> listed as a heritage item by Schedule 5 the *LEP 2011*. Under Part 5.10 of the *LEP 2011*:

#### (4) Effect of proposed development on heritage significance

The consent authority must, before granting consent under this clause in respect of a heritage item or heritage conservation area, consider the effect of the proposed development on the heritage significance of the item or area concerned. This subclause applies regardless of whether a heritage management document is prepared under subclause (5) or a heritage conservation management plan is submitted under subclause (6).

#### (5) Heritage assessment

The consent authority may, before granting consent to any development:

(a) on land on which a heritage item is located, or

(b) on land that is within a heritage conservation area, or

(c) on land that is within the vicinity of land referred to in paragraph (a) or (b), require a heritage management document to be prepared that assesses the extent to which the carrying out of the proposed development would affect the heritage significance of the heritage item or heritage conservation area concerned.

The appropriate heritage management document in this instance is a Heritage Impact Statement (HIS).

This statement has been prepared at the request of the owners of the site and accompanies plans prepared by Alexander & Co.

#### 1.2 Authorship

This statement has been prepared by Louise Doherty, B.Sc.(Hons), Bldg Cons., and James Phillips, B.Sc.(Arch), B.Arch, M.Herit.Cons.(Hons), of Weir Phillips Heritage.

#### 1.3 Limitations

A detailed history of the site and a full assessment of significance to Heritage NSW standards were not provided for. The history contained in this statement has been prepared from the readily available resources listed under Section 1.6 below.

An Aboriginal history and assessment was not provided for. No historical archaeology was carried out on the site.

The description of the interior of the building is limited to the areas proposed to be altered as part of this application.

#### 1.4 Methodology

This HIS has been prepared with reference to the Heritage NSW publication *Statements of Heritage Impact* (2002 update) and with reference to the Council planning documents listed under Section 1.5 below.

#### 1.5 Physical Evidence

An inspection of the property and the surrounding streetscape took place in April 2020. The photographs contained within this statement were taken at this time.

#### 1.6 Documentary and online Evidence

#### 1.6.1 General References

- 'Advertising', *Daily Advertiser (Wagga Wagga*, NSW: 1911 1954), 2 December, 1936 p. 7. http://nla.gov.au/nla.news-article144614135
- John Sands Ltd, John Sands *Sydney and Suburban Directories*, NSW, John Sands Ltd, various years
- Northern Beaches Local studies Library information cards:
  - Harbord Beach Hotel
  - Freshwater History of name
  - Freshwater Harbord History
- Noel Butlin Archives Centre, Australian National University: Tooth and Company yellow cards, various records.

#### 1.6.2 Historic Maps, Plans, Photographs

• *(Aerial Photograph over Freshwater)* 1943. NSW Lands Department.

#### 1.6.3 Council Planning Documents

- Warringah Development Control Plan 2011.
- Warringah Local Environmental Plan 2011.

#### 1.6.4 Heritage Inventory Listing Sheets

- *Harbord Beach Hotel*, 29 Moore Road, Freshwater. Heritage Act, SHI Database No. 2610063.
- *'Freshwater' Restaurant*, 80 Undercliff Road, Freshwater. Heritage Act, SHI Database No. 2610064.

#### 1.6.5 Other

• NSW Heritage Office and DUAP, *Statements of* Heritage *Impact*, NSW, Heritage Office and DUAP, 2002 (update).

#### 1.7 Site Location

No. 29 Moore Road, Freshwater is located on the southern side of Moore Road. The western boundary of the side addresses Charles Street and Undercliff Road is located to the rear. The site is identified as Lots 1-5 Section 1 of D.P. 7022.



**Figure 1: The location of the subject site.** SIX Maps.

#### 2.0 HISTORICAL DEVELOPMENT

#### 2.1 Aboriginal Occupation

Although an Aboriginal Heritage was not provided for the traditional owners who lived, fished and gathered food right across the Northern Beaches for thousands of years are acknowledged as traditional custodians of the land.

#### 2.2 European development of the area


The first European exploration of the Northern Beaches area was led by Governor Arthur Phillip. The expedition is said to have travelled followed Manly Creek towards Manly Dam then towards Frenches Forest terminating at Middle Harbour where a waiting boat took them back to Sydney Cove.

Phillip determined that the land was unsuitable for farm pasture and turned his attention to other areas which may be more suited to providing food security to the fledgling colony.

The coast line from Manly to Palm Beach was surveyed in 1815 by Government Surveyor James Meehan. The first land grant in the area comprising 50 acres was made to Thomas Bruin to the immediate north of Freshwater Beach near to the current day location of the Harbord Diggers RSL Club. Bruin sold his grant to D'Arcy Wentworth in 1818. The surrounding area along Freshwater Beach was designated as Crown Land. Transport to the area did not develop until the late 1870s when Harbord Road was constructed and the steps over Queenscliff headland built in the following decade.<sup>1</sup>

The present-day suburb of Freshwater was surveyed in 1886 by W.M. Gordon and prepared for subdivision. The Harbord Estate was named in honour of the governor of NSW Sister in Law Judith Harbord. Harbord was accompanying the Governor-General and his wife Lady Carrington around NSW and was earning publicity at the time in the social pages. <sup>2</sup>

However, the Crown land surrounding Freshwater Beach was remained un-subdivided until the late 1890s when it was offered for sale by the Minister of Lands as detailed in Figure 2.




**Figure 2: Newspaper article advertising the 1899 sale of land at Freshwater** 'CROWN LAND SALE.', Evening News (Sydney, NSW: 1869 - 1931), 20 October, 1899 p. 3., viewed 21 Apr 2020, http://nla.gov.au/nla.news-article113690428

The earliest European name for the suburb was Freshwater, this is believed to have derived from the fresh water stream that ran to the beach.

Freshwater's popularity grew as a holiday destination for workers from the inner western suburbs of Sydney grew after the legalisation of sea bathing in 1903. Early camps were established with tents and weatherboard huts providing weekend holiday accommodation. The 'Camps' were for men only; women were permitted to visit on Sunday.

<sup>&</sup>lt;sup>1</sup> Northern Beaches Local Studies Library, Freshwater Harbord History information sheet.

<sup>&</sup>lt;sup>2</sup> Northern Beaches Local Studies Library, Freshwater History of name. information sheet.



**Figure 3: Jolly Boys Camp Freshwater.** Source Northern Beaches Council Library



**Figure 4: Dollar Princess Camp Freshwater.** Source Northern Beaches Council Library

Other businesses were established to support the camps including stores and eventually a tearoom.



Figure 5: Randells Store c.1910 Source Northern Beaches Council Library

Further services emerged in 1908 with the establishment of the Freshwater Surf Life Saving club and the Freshwater Restaurant (now Pilu Restaurant). In its early days the building was known as 'The Kiosk' was used as a venue for afternoon tea parties, meetings and dances as well as providing accommodation




Figure 6: The kiosk is shown to the centre of the image. A camp site can be seen to left of the image and small houses or huts in the distance. Source Northern Beaches Council Library

Other early services including St Marks Anglican Church which opened in 1911, and Freshwater Public School which opened the following year. The school was later renamed Harbord Public School.

In the early 20th century many of the estates were subdivided and prepared for residential development. A significant event for Freshwater and Australia's surf culture occurred in 1914 when Hawaiian Duke Kahanamolu stayed at Boomerang Camp and

demonstrated Hawaiian style surfing at Freshwater Beach on a board made from local timber.



Figure 7: Duke Kahanamolu Source: SurferToday

From 1925-1939 a tramline operated from Pittwater Road terminating at Moore Street to the immediate north of the 'Freshwater Restaurant'.

The camps at Freshwater had a rough and rowdy reputation. Many of the local residents were concerned that this reputation was negatively impacting the impression of their suburb and they successfully petitioned for the name to be changed to Harbord in recognition of one of the earliest subdivisions in the area. Not everybody agreed with the name change and the Freshwater SLSC refused to change their name resulting in the Beach and the Surf Life Saving Club bearing different names until 1980s when the Geographical Names Board was successfully petitioned by the community, Manly Warringah and Pittwater Historical Society and Warringah Council to change the name of the beach back to Freshwater. The suburb of Harbord was officially re-named Freshwater on 12 January 2008. <sup>3</sup>

During the late 1920s – 1930s two important social venues were established in the suburb: The Harbord Beach Hotel, refer to Section 2.3, and the The Harbord Legion of Ex-Diggers (known as Harbord Diggers). The Diggers opened in 5 June 1930 as a social club for returned servicemen. The first building was a hut near Freshwater Beach. The club raised money for members in distress and their families by serving billy teas to holiday makers. When the hut was washed away during a storm in 1933, it was moved to the first of several temporary sites until finally relocating to its current headland location in the late 1950s.

From the 1960s the population of Harbord increased greatly as strata title legislation was introduced resulting in smaller residential dwellings being demolished and replaced with residential flat buildings. This continued until 1973 when a resident action group petitioned Council to restrict home unit development. Planning Controls were introduced after this time to curb the development. <sup>4</sup>

<sup>&</sup>lt;sup>3</sup> Northern Beaches Local Studies Library, Freshwater History of name information sheet.

<sup>&</sup>lt;sup>4</sup> Northern Beaches Local Studies Library, Freshwater Harbord History information sheet.

#### 2.3 Development history of the subject site

Harbord Beach Hotel opened on 24<sup>th</sup> December 1928. The owner and first publican, Mr Hope-Catlin is said to have modelled the building on a design he brought back from South Africa.<sup>5</sup>

The 1928 image of the Hotel, (Figure 8), shows the original form of the building. The two storey rendered building was set beneath a wide hipped roof with a large street facing half hipped gable and smaller complete gable addressing Moore Street.

A two storey concrete verandah wrapped around the eastern end of the building. The solid concrete base of the verandah topped with a decorative band of concrete blocks, this detail is seen to both the ground and first floor balustrades. The verandah is separated into a series of bays by evenly spaced wide concrete posts. The ground floor openings are topped by arches set between the posts. The posts extend above the top of the first-floor balustrade.

The centre of the principal elevation was defined by a concrete porch supported by wide concrete posts. The building was accessed via a central set of steps within the porch.

The land to the front of the building, now enclosed courtyards, was open and elevated above the road height.



#### Figure 8: Harbord Beach Hotel soon after completion in 1928. Source: Northern Beaches Council Library

Figure 9, dating from 1930, depicts the building as viewed from the west. The twostorey verandah did not extend to the full extent of the principal elevation instead terminating one bay past the front porch. A set of steps is shown leading from Charles Street to the front entry. The entry to the steps is flanked by a pair of rectangular posts which have a hole in the top where a plant can be placed.

The Charles Street elevation is set beneath a half-hipped gable. The upper level contains three metal framed casement windows. This style of window can also be seen to the first floor of the Moore Street elevation. The ground floor contains a large metal framed

<sup>&</sup>lt;sup>5</sup> Gordon G, 2000, Harbord Queenscliff and South Curl Curl 1788-2000, p24

window to the north and a pair of entry doors to the south set beneath a cantilevered awning.



Figure 9: The western elevation of the Harbord Beach Hotel in August 1930 Source: Noel Butlin Archives

The hotel was purchased by Tooth and Co. in February 1935. The records kept by the brewery indicate that £906 was spend on constructing new garages and alterations to the public and salon bars in the following year. There were 15 bedrooms (7 single, 6 double and 2 triple) a saloon bar, a public bar, lounges and a bottle store.<sup>6</sup>

As shown in Figure 10, a 1936 advertisement for the Harbord Beach Hotel run in several regional newspapers boast details the hotel as having Tennis Courts, Garages and Good Tables.



#### Figure 10: 1936 Advertisement for the Harbord Beach Hotel

'Advertising', *Daily Advertiser (Wagga Wagga*, NSW: 1911-1954), 2 December, 1936 p. 7. http://nla.gov.au/nla.news-article144614135

<sup>&</sup>lt;sup>6</sup> Noel Butlin Archives Harbord Beach Hotel, Card 3 side 2

Figure 11 provides an aerial photograph over the site and the immediate surrounding area in 1943. The roof form does not appear to have changed since this image was taken. In addition to the main hotel there are structures to the south and east of the building. It is not clear where the tennis courts mentioned in figure 10 are located or if they had been removed by this time. The character of the area is noted as being sparsely developed. Note also the verandahs to either side of the front porch have not yet been built.



**Figure 11: Aerial photograph over the site and surrounding area in 1943. The subject site is indicated by the red arrow.** SIX Maps

By 1949, (Figure 12), The building appears to have undergone little external change particularly when viewed from the west. The photo does show the lintels above the windows matching those on the Porte Cochere. Painted signage was added to the Porte Cochere and a large freestanding Tooth's sign was installed at the street edge. Also noted is the addition of blinds to the ground floor verandah area. These were externally mounted and gave the appearance of rectangular opening where they had previously been arched.

Tooth's records for the building note that the ground floor public bar and saloon bar were tiled. Bedrooms were shown as being for staff and public with additional private quarters containing three twin rooms. The district was described by Tooths as:

'Residential. Large holiday trade and weekday and weekend surfers'<sup>7</sup>

<sup>&</sup>lt;sup>7</sup> Noel Butlin Archives Harbord Beach Hotel card 4 side 2



#### Figure 12: The Harbord Beach Hotel in 1949

Noel Butlin Archives Harbord Beach Hotel card 4 side 2

A significant phase of alteration, both internally and externally occurred in the late 1950s the changes included:

- Enclosing verandah forming new servery.
- Construct shelters, beer garden and paving to the front of the Hotel.
- Construct new bottle dept.
- the conversion of the lounge bar to act as an extension of the saloon bar.
- Enlarging the saloon bar lavatories and women's toilet block.
- Forming a lounge bar by provision of a folding screen in the dining room and other minor alterations.
- Provision of an acoustic ceiling to the lounge bar.
- Clearing of land at the rear of hotel, form ramp, construct gutter crossing and cover area with hard ashes for car parking area.<sup>8</sup>

The image of the building dating from 1960, refer Figure 13, clearly demonstrates the extent of the above external alterations. The area to the front of the hotel had been extended to the road and enclosed to create the beer garden, pergola structures were provided for shade, a small rectangular flat roofed building, accessed from Charles Street, acted as a bottle shop. The enclosure of the ground floor verandah area is also evident. Other changes include illuminated external 'saloon bar' sign, the tudor-esque painting of the gable infil and an external blind to the Charles Street window.

<sup>&</sup>lt;sup>8</sup> Noel Butlin Archives Harbord Beach Hotel card 5 side 2



**Figure 13: Harbord Beach Hotel 1960.** Noel Butlin Archives Harbord Beach Hotel card 5 side 2

By 1982, only cosmetic changed had been made to the exterior of the property, refer to Figure 14. The changes included the external painting, external awnings were mounted above the windows, additional signage installed to the Moore Street elevation and signwriting to the Charles Street awning. Also noted are the doors addressing Charles Street which are still shown in place.

In 1982, the current bottle shop was constructed to the immediate east of the property addressing Charles Street, refer to Figure 15.



**Figure 14: Harbord Beach Hotel, 1982** Northern Beaches Local Studies ref: 40\WAR40550



**Figure 15: Construction of the bottleshop, 1982** Northern Beaches Local Studies ref: 40\WAR40544

By 2020, several significant alterations had been undertaken to the exterior of the building these included:

- Removal of the Charles Street bottleshop.
- Conversion of the Charles Street door to windows
- Replacement of the first-floor metal casement windows with sliding aluminium framed windows
- Extension of the former saloon bar to the line of the ground floor verandah,
- Removal of Charles Street steps,
- Extension of the second-floor verandah to the full width of the Moore Street elevation.
- Addition of a glazed extension to the top of the perimeter walls.



Figure 16: Current external appearance of the building April 2020.

#### **Internal alterations**

In 1978, the hotel was purchased by John Thorpe and Trish King. Personal communication with their son Sean King in April 2020 revealed that when the family purchased it, it was in a poor state and had a demolition order. The family extensively renovated the building during their 42 years of ownership. Internally the building was extensively renovated by the King-Thorpe family. Sean King recollects that there were three major internal renovation stages:

- The first occurred in the late 1970s when the family took up residence at the hotel. This work included the addition of the internal panelling to the hallway constructed from tea chests used to ship the family's possessions from their previous residence at Balmain. The internal columns were previously clad with tiles.
- During the next renovation stage, in the late 1980s, replacement of the former entry door with the current glass door, enclosure of the stair was enclosed, bottom steps removed access to the stairs was enclosed, further timber panelling was added to the foyer, stairwell and hallway, the kitchen was relocated from the immediate west of the central entry door to the middle of the building.
- The last major renovation was undertaken in 2002, this work included: the updating of the kitchen and bathroom facilities, removal and replacement of the former bar, additional cosmetic changes to the interior of the bar including the timber panelling to the perimeter walls and addition of glazed timber salvaged screens. Further changes were made to the hallway including change to the location of internal walls.

Other changes undertaken during the King-Thorpe ownership included the lowering of the ceilings in the bar and hallway to facilitate sound proofing and cabling, addition of an access to the restaurant bar within the hallway, addition of decorative timber trim to the restaurant ceilings.

Sean King states that all of the timber panelling and internal decorative detailing were added during his family's 42-year ownership of the hotel and that only surviving original details are the central internal columns, excluding cladding, and the surviving stairs treads, balustrade and rails.

Further information with regards to the interior fabric is contained within Fabric Analysis included in Appendix A of this report.

#### 3.0 PHYSICAL ANALYSIS

#### 3.1 The Site

For the following, refer to Figure 17, an aerial photograph over the site, and to the survey that accompanies this application. To match the accompanying plans Moore Road is referred to as being to the north, Charles Street to the west and Undercliffe Road to the south.



**Figure 17:An aerial photograph showing the subject site and its surrounds.** SIX Maps.

The site is located on the southern corner of the intersection of Moore Road and Charles Street. The site is approximately 63m in length and 39m in width. The eastern and western boundaries, addressing King Street and the rear laneway respectively, are approximately 9m wide. The overall site area comprises approximately 4500 sq. metres. The building is located to the northern portion of the site and the southern section is used as a hard stand car park.

#### 3.2 The Building

#### 3.2.1 Exterior

The principal elevation, addressing Moore Road, is typical of an extensively modified and extended two storey, Inter-War Era Hotel. The building presents a side elevation to Charles Street.

The painted concrete rendered building is set beneath a wide half hipped gable roof clad with terracotta tiles. There is a street facing gable located over the centre of the principal elevation. The gables have timber batten infills. An open concrete verandah runs across the full width of the first floor. The balustrade is separated into a series of bay with masonry posts which extend above the balustrade. The front porch to the centre of the elevation remains evident and bears signage reading 'Harbord Beach Hotel'.

The ground floor of the principal elevation has been glazed and enclosed. A single storey addition extends from the eastern elevation.



Figure 18: The front (southern) elevation of No. 29 Moore Road, Freshwater.

The Charles Street elevation is constructed of painted concrete set beneath a hipped gable end. The sliding windows are set in aluminium frames.

The ground floor windows are set beneath fabric shade hoods. The northern most window is located within an extension added to the building after 1982. The former Charles Street entry doors located to the southern end of the building has converted to window openings.



**Figure 19:** Charles Street elevation.

#### 3.2.2 Interior

The main entry to the hotel is accessed via two sets of modern glazed metal framed doors. The doors open on to a small antechamber area located within former ground floor verandah, now enclosed. The western wall of the entry foyer was added during the 1980s renovation, refer to Figure 20 and Figure 21.



**Figure 20:** Main entry.



**Figure 21:** Former verandah, now enclosure and partitions into a series of separate spaces.

The entry foyer opens on to a central hallway which has a carpeted floor, three quarter height timber panelled walls which were added to the building during the 1980s restoration. The ceiling which was also added during the 1980s is lower than the original height and contains sound proofing and cable ducts within the cavity space.

As mentioned previously, Sean King, the son of the previous owner confirmed that his family renovated the entire interior during their occupation of the place.



**Figure 22:** The hallway panelling was added successively from the late 1970s onwards.



**Figure 23:** Detail of the hallway.



**Figure 24:** The suspended ceiling added by the previous owner.



**Figure 25:** The decorative timber and glass screen concealing the entry to the toilet facilities. was added during the 2002 construction phase.

The public bar and TAB area were extensively renovated during the 2002 renovations.





**Figure 26:** View from foyer to bar area.


#### Figure 27:

The interior of the public bar was modernised during the 2002 renovations. These works included the addition of half height panelling to the walls and reorientation of the bar.

The stair to the first floor was enclosed by the previous owners who lived upstairs. The previous owner recollects sitting on the stair as a child watching the fights in the public bar, indicating the wall to the right of the Figure 21 was added during the 1980s renovation. The half-height panelling was also added during these works.



**Figure 28:** Detail of stair to first floor.



The restaurant is a large open space retaining evidence of the former curved external wall to the north eastern corner. The concrete ceiling was embellished by the previous owner with the addition of a brown painted timber trim. The walls are painted with no decoration.

The kitchen and bathroom facilities have been modernised.



**Figure 30:** View across restaurant area



**Figure 31:** Ceiling detail within restaurant area.



**Figure 32:** View to modern bistro area.

#### 3.3 The Surrounding Area

For the following, refer to



Figure 33, an aerial photograph over the site and the surrounding area.

#### 3.3.1 The General Area

The subject building is located on the southern corner of the junction of Moore Road and Charles Street within an established residential precinct. Alfred Street to the west is the commercial hub of Freshwater Village. To the east is Freshwater Beach.



**Figure 33: Aerial photograph over the site and the surrounding area. The site is highlighted in yellow.** SIX Maps.

#### 3.3.2 Moore Street

Moore Street runs from Albert Street in the northwest and to the southernmost Freshwater Beach car park in the south east. The built form is predominantly residential and comprises of a mix of three and four storey residential flat buildings and detached two storey dwellings. The building date from the inter-war era to the present day.

As noted above, the subject building is located on the southern corner of the junction of Moore Road and Charles Street. The building to the east is the single storey bottle shop attached to the hotel. Further east the buildings are three storey residential flat buildings. Directly opposite the subject building, on the northern side of Moore Road, is a group of detached two storey dwellings all of which date from the modern era.

Figure 34-Figure 36 illustrate the general character of the street in the vicinity of the site.



**Figure 34:** General character of Moore Street to the east of the hotel.



**Figure 35:** Typical built form of Moore Road.



**Figure 36:** Residential buildings Directly opposite the Hotel.

#### 3.3.3 Charles Street

The subject property is located to the eastern side of Charles Street. Directly opposite on the western side of the street are two single storey brick cottages and the side elevation of the residential flat building known as No. 27 Moore Street, Freshwater.

Figure 37 illustrates the general character of Charles Street in the vicinity of the site.



**Figure 37:** General character of Charles Street.

#### 3.3.4 Undercliff Road

The subject property is located to the northern side of Undercliff Road. Several freestanding residential dwellings are located to the southern side of the street directly opposite the site. The residential buildings are constructed of a range of materials and are orientated towards the ocean views to the east.

Figure 38 illustrates the general character of Undercliff Road Street in the vicinity of the site.



**Figure 38:** General character of Undercliff Road.

#### 3.4 Integrity

The current building on site has been substantially altered since its 1928 construction era. The external alterations are most prominent to the Moore Street elevation, the notable changes include: the internalisation of the ground floor verandah, the extension of the first floor verandah, the construction of the perimeter walls to create internal courtyards, the removal of the original windows and the conversion of the Charles Street entry to windows. The building has also undergone significant internal change including the removal of the majority of the original fabric, enclosure of the stairwell and reconfirmation of the bar area. Other changes include the kitchen and bathroom upgrades. Further information pertaining to the condition and integrity of the interior of the building is provided within the fabric analysis, refer to Appendix A

The building demonstrates a moderate degree of architectural integrity and externally retains some key aspects of its original decorative characteristics which are predominantly exhibited through the remnant detailing to the first floor, roof scape and Charles Street elevation. Despite the diminished integrity, the building is well maintained.

#### 3.5 View Corridors

Views to the building are uninhibited. The principal view corridors are obtained are from Moore Road and Charles Street in front of the site. Secondary views to the rear of the building are obtained from Undercliff Street.

The building is a visual landmark in close proximity to Freshwater Beach.

Refer to Figure 39- Figure 42



**Figure 39:** View of the subject site from Moore Road.





**Figure 40** View of the building from the west.

**Figure 41** View of the building from the Charles Street.



**Figure 42** View of the building from the Undercliff Road.

#### 4.0 ASSESSMENT OF SIGNIFICANCE

#### 4.1 Summary of Existing Citations and Listings for the Site

#### 4.1.2 Summary of Statutory Heritage Listings

No. 29 Moore Road, Freshwater:

- <u>Is</u> listed as an item of local heritage significance by Schedule 5 Part 1 of *Warringah LEP 2011.*
- Is <u>not</u> located within a Conservation Area as defined by Schedule 5 Part 2 of the *Warringah LEP 2011*.
- Is <u>not</u> listed as a heritage item on the State Heritage Register under the auspices of the *NSW Heritage Act* 1977.

The State Heritage Inventory Listing Sheet provides the following statement of significance for the subject property known as Harbord Beach Hotel, 29 Moore Street, Freshwater:

A rare example of an inter-war hotel building which shows influences of the Californian bungalow style. Historically provides evidence of the early development of social & recreational facilities to serve the growing population. Local landmark.<sup>9</sup>

This statement is adopted for the purposes of this report.

#### 4.2 Heritage Items in the Vicinity of the Site

For the following 'in the vicinity' is determined by the distance between the site and heritage items, the nature of the proposed works, the character of the area and existing and potential view corridors. In Figure 43, a detail from the *Warringah LEP 2011* heritage plan, heritage items are coloured brown and numbered. Conservation Areas are hatched in red. The site is indicated by the blue arrow.

<sup>&</sup>lt;sup>9</sup> Harbord Beach Hotel, 29 Moore Road, Freshwater. Heritage Act, SHI Database No. 2610063



**Figure 43 Detail from the Heritage Plan, Warringah Local Environmental Plan 2011** Heritage Map - Sheet HER\_010.

The subject site is located within the vicinity of the locally listed 'Freshwater' Restaurant, 80 Undercliff Road, Freshwater (176).

#### 4.2.1 'Freshwater' Restaurant, 80 Undercliff Road, Freshwater (176).

'Freshwater' Restaurant is located to the east of the subject property on the neighbouring Undercliff Road. The Restaurant addresses Freshwater Beach and is located to the eastern end of the Freshwater Beach car park, formerly the Moore Street tram terminal. The restaurant is note visible from the subject property nor does not share any significant view corridors with the subject property.

The State Heritage Inventory Listing Sheet provides the following statement of significance for this item:

A building with great social & historical significance as an early meeting place & recreation venue for the first settlers in Freshwater. Representative of the federation style, with high integrity. Prominent local landmark located above Freshwater Beach.<sup>10</sup>



**Figure 44:** No. 80 Undercliff Road, Freshwater.

<sup>10</sup> '*Freshwater' Restaurant*, 80 Undercliff Road, Freshwater. Heritage Act, SHI Database No. 2610064.



**Figure 45:** The Harbord beach Hotel is not visible from No. 80 Undercliff Road, Freshwater

Figure 46, provided below, demonstrates the location of the No. 80 Undercliff Road, indicated by the yellow arrow, and the location of the subject property, indicated by the blue arrow. This figure clearly demonstrates that there no visual links between the neighbouring heritage item and the subject property due to their location and the intervening neighbouring properties.

No historical links between the neighbouring restaurant and the subject property have been determined during the preparation of this report.



**Figure 46:** There are no visual links between No. 80 Undercliff Road, indicated by the **yellow arrow, and the subject property, indicated by the blue arrow.** Six Viewer Annotated by Weir Phillips Heritage and Planning

#### 5.0 SCOPE OF WORKS

The following should be read in conjunction with the plans prepared by Alexander & Co that accompanies this Application.

The current proposal seeks to:

- Install an entry door to the Charles Street elevation.
- Replace the metal framed doors to the principal elevation with sliding doors.
- Reconfigure the entry foyer to provide access to the bar area and new entry to the restaurant.

- Remove panelling to the hallway revealing the original configuration of the stair.
- Remove and upgrade internal bar and sanitary facilities.
- Internal alterations to the TAB area.

#### 6.0 METHOD OF ASSESSMENT

The following considers heritage related issues only. It does not consider compliance or otherwise with numerical controls unless non-compliance will result in an adverse heritage impact. Refer to the Statement of Environmental Effects (SEE) that accompanies this application.

The proposal is assessed with a full understanding of the requirements for Heritage Impact Statements provided by the Heritage NSW's publication *Statements of Heritage Impact* (2002 update).

The potential impact of the proposed works to the identified heritage values of the subject property and neighbouring heritage item is assessed against the relevant clauses of the *Warringah Development Control Plan* (WDCP), refer to section 7.0 of this report.

#### 7.0 EFFECT OF WORK

The *Warringah Development Control Plan 2011* supplements the provisions and controls of the *Warringah LEP 2011*. The WDCP **does not** contain any objectives and controls for the development and conservation of buildings within Heritage Conservation Areas and Heritage Items.

#### 7.1 Assessment of heritage Impact

In the absence of any local controls, the proposed development is assessed in accordance with guidance provided in the Heritage NSW publication *Statements of Heritage Impact* (2002 update). The following questions relate to 'Minor Partial demolition (including internal elements)', 'Minor Addition' and 'New development adjacent to a heritage item (including additional buildings and dual occupancies)':

#### **Minor partial demolition**

• Is the demolition essential for the heritage item to function?

The proposed demolition is limited to the removal of non-original fabric. The majority of which dates from the 1970s/1980s and 2002 development phases. The removal of this fabric will facilitate the ongoing use of the place as a hotel.

• Are important feature of the item affected by the demolition (e.g fireplaces in buildings)?

No. As noted above, the proposed demolition is restricted to the removal of non-original fabric. The proposed work will reinstate the original staircase as a visually prominent element within the ground floor of the hotel.

• Is the resolution to partially demolish sympathetic to the heritage significance of the item?

Yes. The removal of the non-original fabric will not impact the building as an item of historic, aesthetic and social significance.

• If the partial demolition is a result of the condition of the fabric, is it certain that the fabric cannot be repaired?

No. The condition of the fabric has been not a determining factor, refer to Appendix A for further detail.

#### **Minor additions**

• How is the impact of the addition on the heritage significance of the item to be minimised?

The proposed additions are limited to the insertion of a door to the Charles Street (western) elevation and internal modifications to previously altered spaces. As detailed in section 2.3 of this report, the original layout of the hotel included access from Charles Street which was removed after 1982. The reinstatement of an entrance from Charles Street is sympathetic to the heritage values of the place. The proposed internal works are considered to be acceptable and will remove fabric added during the previous owners' occupation of the site.

• Can the additional area be located within an existing structure? If no, why not?

The proposed works are largely internal. The exception being the proposed door to the Charles Street elevation which is considered to be acceptable due to the evidence that this space has previously undergone alteration including the removal of an entry door.

Will the additions visually dominate the heritage item?

No. The proposed works are minor and will not visually dominate the heritage item.

• Is the addition sited on any known, or potentially significance archaeological deposits? If so, have alternative positions for the additions been considered?

The *LEP* has not identified the site as having archaeological potential.

Furthermore, the proposed alterations are located to a previously modified building and do not include significant excavation.

• Are the additions sympathetic to the heritage item? In what way (e.g. form proportion, design)?

The proposed additions seek to replace previous alteration to the interior of the property and an external door to the Charles Street elevation. The proposed works are considered to be minor and are sympathetic to the highly modified building.

## 'New development adjacent to a heritage item (including additional buildings and dual occupancies)'

• How is the impact of the new development on the heritage significance of the item or area to be minimised?

As noted above the proposed works is relatively minor and will not be visible from the neighbouring heritage item. There is no impact to the heritage significance of the neighbouring heritage item arising from the proposed development.

Why is the new development required to be adjacent to a heritage item?

The proposed works are located to a neighbouring separately owned property. The proposed works seek to modernise and update the hotel

• How does the curtilage allowed around the heritage item contribute to the retention of its heritage significance?

There are no proposed changes to the curtilage of the neighbouring heritage item as part of this proposal.

• How does the new development affect views to, and from, s the heritage item? What has been done to minimise negative effects?

The proposed development to the interior and western elevation of the hotel will not be visible from the neighbouring heritage item and will not impact any views to or from the neighbouring item.

• Is the development sited on any known, or potentially significant archaeological deposits? If so, have alternative sites been considered? Why were they rejected?

The *LEP* has not identified the site as having archaeological potential.

• Is the new development sympathetic to the heritage item? In what way (e.g. form, siting, proportions, design)?

The proposed work is relatively minor. The proposed work will not visible from the neighbouring heritage listed restaurant and will not impact the identified heritage significance of 'Freshwater' restaurant.

• Will the additions visually dominate the heritage item? How has this been minimised?

For the reasons identified above, the addition will not visually dominate the neighbouring heritage items.

• Will the public, and users of the item, still be able to view and appreciate its significance?

The public and users of the 'Freshwater' Restaurant will continue to be able to view and appreciate the identified significance of the place.

In addition to the above questions, the guidelines also require consideration of the following aspects of the proposed works:

• Aspects of the proposal which respect or enhance heritage significance

The proposed works are considered to respect and enhance the heritage significance of the place by means of the removal of the circa 1980s entry door and reinsertion of a door to the Charles Street entry. The proposed internal works remove non-original fabric and will encourage and facilitate the ongoing use of the site as a hotel which its traditional and best use.

• Aspects of the proposal which could have detrimental impact on heritage significance

Given the above, it is submitted that the proposal will not have a detrimental impact on the heritage significance of the Harbord Beach Hotel or neighbouring heritage listed restaurant.

• Sympathetic alternative solutions which have been considered and discounted

The proposed work is minor in nature and no alternative sympathetic solutions have been considered and discounted.

#### 7.2 Effect of work on the subject property

In summary, the proposed works will have a minimal and acceptable impact on the significance of the Harbord Beach Hotel. The proposed works will have no impact on the historic, aesthetic, social significance of the building and its landmark because:

- The external alterations are limited to the enlargement of a window opening to create entry from Charles Street (western elevation). The current window has a modern metal frame and early images indicate that this elevation has previously undergone change with the removal of doors. The reinstatement of an entry from Charles Street is considered to be acceptable and will not affect the predominate architectural language of the existing hotel.
- The proposed internal works seeks to remove non-original fabric and reveal the original stair detailing.
- The heritage inventory sheet does not contain any information pertaining to the internal fabric suggesting that it is not considered to contribute to the heritage significance of the place.
- The proposed works assist in the continuation of the use of the item as a hotel which is its original and best use.

#### 7.3 Effect of Work on Heritage Items Within the Vicinity

The proposed works will have a minimal and acceptable impact on the significance of the 'Freshwater' Restaurant for the following reasons:

- The proposed works, include an addition of a door to the west elevation and internal works, will not be visible from the neighbouring heritage item. Accordingly, the proposed works will not impact the ability to view and understand the neighbouring heritage item.
- Views to and from the neighbouring item will not be affected by the proposed works.

#### 8.0 CONCLUSIONS

This Heritage Impact Statement has been prepared in conjunction with a DA for alterations and additions to No. 29 Moore Road, Freshwater. The existing building on the subject site is a two storey Inter-War era hotel. The building is a locally listed heritage item.

The proposed works are minor in nature and will have no impact on the significance of the nearby heritage listed Freshwater Restaurant.

The proposed works fulfil the objectives for alterations and additions to a heritage listed item, in the vicinity of heritage items set out by the *Warringah LEP 2011* and the *Warringah DCP 2011*.

### Appendix A

**Building Fabric Survey** 

# **BUILDING FABRIC SURVEY**



## Harbord Beach Hotel

*No 29 Moore Road, Freshwater NSW 2096* April 2020 |



Level 19, 100 William Street, Woolloomooloo NSW 2011 Phone: (02) 8076 5317

#### **1 INTRODUCTION**

#### 1.1 Preamble

This building fabric survey of the ground floor of the Harbord Beach Hotel located at No 29 Moore Road, Freshwater NSW 2096 found very little original building fabric other than the underlying structural masonry.

#### 1.2 Authorship

This building fabric survey has been prepared by Edward Alder, Building and Remedial Works Specialist, and James Phillips, B.Sc.(Arch), B.Arch, M.Herit.Cons.(Hons), of Weir Phillips Heritage.

#### 1.3 Limitations

This building fabric survey is limited to the ground floor, the Moore Road entry and the entry foyer and the internal stair case to the first floor.

The visual inspections from which assessments and this survey were made, where from ground level and from within the building only. The inspections were neither invasive or exhaustive.

#### 1.4 The Site

The site is located at 29 Moore Road, Freshwater on the southern side of Moore Road. The western boundary of the side addresses Charles Street and Undercliff Road is located to the rear.




**Figure 1: The site.** Google Maps; annotations by Weir Phillips Heritage, 2020.

#### 2 OVERVIEW

#### 2.1 Location of the Site:

No. 29 Moore Road, Freshwater is located on the southern side of Moore Road. The western boundary of the side addresses Charles Street and Undercliff Road is located to the rear. The site is identified as Lots 1-5 Section 1 of D.P. 7022. (Fig. 2).

The site is located within the Northern Beaches Council Local Government Area (formerly Manly, Warringah and Pittwater Councils). The principal planning control for the site is the Warringah Local Environmental Plan 2011 (LEP 2011). The site is listed as a heritage item by Schedule 5 the LEP 2011. Under Part 5.10 of the LEP 2011:



#### Figure 2: Site Location.

Google Maps; annotations by Weir Phillips Heritage, 2020.

#### 3 SURVEY

Phillips

and Planning

Heritage

Weir

#### Building Fabric Survey Harbord Beach Hotel 29 Moore Road, Freshwater NSW 2096

External masonry at Moore Road Entry



**LOCATION:** Street Frontage.

**OBSERVATION:** The historical photo of the 1929 building shows the extent of the construction.

LOCATION: Street Frontage.

#### **OBSERVATION:**

The Moore Road Street frontage has been extended and the central entry from Moore Road has been extensively modified from the original 1929 building pictured above.



**LOCATION:** Central entry from Moore Road.


#### **OBSERVATION:**


There is visual evidence of where a masonry wall has been removed to facilitate the installation of the existing entry. Weir Phillips Heritage and Planning

Building Fabric Survey Harbord Beach Hotel Moore Road, Freshwater NSW 2096

External masonry at Moore Road Entry










Building Fabric Survey Harbord Beach Hotel Moore Road, Freshwater NSW 2096

**Moore Road Entry Foyer** 



Weir Phillips Heritage and Planning

Building Fabric Survey Harbord Beach Hotel Moore Road, Freshwater NSW 2096

#### Moore Road Entry Foyer and Stair to 1st Floor



#### LOCATION:

The Moore Road entry foyer.

#### **OBSERVATION:**

The timber panelling and light timber wall framing are a late 1980s addition. The end of the stair balustrade is original building fabric which has been incorporated into the panelling.

### LOCATION:

Stairway from ground floor to 1<sup>st</sup> floor adjacent to the Moore Road entry foyer.

#### **OBSERVATION:**

The original stair balustrade is engulfed by the addition of plasterboard and light timber wall.



#### Building Fabric Survey Harbord Beach Hotel Moore Road, Freshwater NSW 2096

Stair to 1<sup>st</sup> Floor



#### **LOCATION:** Internal stairs from ground to 1<sup>st</sup> floor.

#### **OBSERVATION:**

The stair and stair balustrade are original building fabric.


#### **LOCATION:** Internal stairs from ground to 1<sup>st</sup> floor.


#### **OBSERVATION:**

The stair and stair balustrade are original building fabric.

The masonry wall on the right of the picture beginning at the bottom step up to the rear of the mid-level landing is also original building fabric, though the timber panelling is a late 1980s addition as is the wall on the left of the picture that engulfs the top of the timber and metal balustrade at the bottom step.

The panelled wall the bottom of the stairs and doorway on the right are both late 1980s additions.





#### LOCATION:

Plan of the ground floor Moore Road entry and stairs to the 1<sup>st</sup> floor.

#### **OBSERVATION:**

The light timber framing installed in the late 1980s is shown on this plan dotted in red. The masonry building fabric shown as solid black.

Both the masonry elements "1" and "2" (circled in blue) are original building fabric.

Masonry elements "3" and "5" (*circled in blue*) may have original building fabric that has been altered. Masonry elements "4", and "6" (*circled in blue*) appear to be late 1980s additions as masonry element "6" would have been a very odd location in relationship to the original stair which suggests that the masonry element "4" is also not original building fabric.

Masonry elements "7" (outlined in blue) are a late 1980s additions.