NO	CONTENTIONS TO BE ADDRESSED	RESPONSES BY ARCHIRDOME	REFERENCED PLANS BY
no.	UNITERIORS IN DE AUDRESSED		ILI LIENGED FLAND DT
1	The provisions of P21 DCP require shared driveway crossings to Lorikeet Drive and Warriewood Road in order to maximise on-street parking. This can readily be accommodated in the proposed development.	Torrent tille dat about Lorited Dire and Warrenood Road new have Stand diverse cospelag in order to maximize on street galaria	A03
_			
2	Lot 3 is very tight and is awkward due to the angled front boundary – please provide an indicative floor plan.	Lat bounderes have now been adjusted and areas have been ra-distributed. Lot 1 is now larger that before and can accomodate a deeting controlatory. Site pine and other raised drawings updeted with now tot areas.	A03, Subdivision plan by SUMMIT GEOMATIC
3	Subdivision plan prescribes that dwellings fronting Warriewood Road are to be satback 9m from the rear boundary – how is this to be restricted?	Indument BBE and Subdivision plan updatedRESTIRCTION ON THE USE OF LAND JPRI added on LOTS 1-SRESTRCTION ON THE USE OF LAND JPRI added on LOTS 5-11	Instrument 88B and Subdivision plan by SUMMIT GEOMATIC
4	Fencing forward of the front building line of dwellings is not supported.	Fencing Forward to the building line has been removed. Fencing Plan has been updated.	A03.a
5	Can the external wall of the ground floor living rooms be setback to increase the area of the covered POS and decrease the depth of the living space (which exceeds 8m)?	The ground floor have units with cross through floor plans that accross related light from both ends of the floor plans. This the firm estiction is not applicable here, as the layout are open plan at the ground level with galaxies on both sides.	
6	Covered POS required for upper floor units at each end. This should be achieved within the existing internal floor space without extending the roof, particularly as there has been very little change to the massing of the buildings as a whole.	Unit in the upper foor have been further underst is accorrectioned POD within floor pilotes. A their anables area of 224 500M has been medicical in the upper floor in batk in order to medice the messing of the buildings as a whone. Flow, Elevations, Viewa and Elabote analyzais underst	A07,A09.3, A10.3
7	Integrated planter at ends of upper floor should wrap around the perimeter of the balcony to prevent downward overlooking of neighbouring properties and POS of units below.	Updated Farm share juliation wasping amount the perimeter	A07,A09.3, A10.3
8	A formalised pathway is not required for maintenance along the western bids of Block C. Alos, is in unclear why this is to be elevated above the ground level of the melphoburing pits and the proposed POS of Block C (Bes Section as and bb on AR23 and EB), resulting in finences exceeding 12m in height. The internal finences the POS for Block C could be lowered to 15m, as there shouldn't be an ongoing privacy issue associated with maintenance of the landscaping.	Pliner and advision attained will knot have been induced is accordance with metabolines allo and anovaed FDS of Block C. Additionally findes allow here beind Block Cover have a reduced heads of 1500m. Bit allow. Fencine plan and Defaulted Sections are undered in the labera set offer	A03, A03.1, A12.3
•	Trees proposed to the east of Block D are too close to the		Defeat and some
9	proposed retaining wall for the easement.	CF8 b Respond	Refer Landscape Drawings
10	Proposed elevated internal fencing is not shown on shadow diagrams.	Ervahol fensing is new selected is shadow dagwars. Shadow analysis shado undeked	A13.1-A13.15
n	Proposed internal front fencing is not shown on perspective images.	Verse updated brahow internal* fencing behind landscape blanterbores	A16.1
12	Solar access diagrams need to highlight impact to dwellings along Bubalo Street associated with height non- compliance.	Additional abeets added in Disadow analyze focusing on theilings allow Judato St	A13.1-13.15
13	Consider operable roofs to POS of balconies that get no sun to increase daylight to these units.	Skright added to cost of balances that gat no sun. Plans and shadow analysis updated.	A07, A08
14	Units D11, D12, C16 and C17 (110m ² minimum area) should be considered 3 bedroom units, ndt 2 bedroom as suggested. The proposal does not provide any of the required 4 x studia, 4 x 1 bedroom or 4 x 2 bedroom apartments required by clause C6.8 of P21 DCP.		A07,A09.3, A10.3
15	One ground floor unit next to recessed planters at lift core could borrow amenity from the proposed landscaping with a semi-transparent/open style fence (there is no need for solid fences to both sides).	Geen Spie skilled fronce incorporated in post on one sold main each ift core. Fercore pairs and directings updated.	A03.a
16	Further detail is required re-planting in lift recesses and whether there is suitable soil depth and area provided. The perspectives confirm that it not reading as a landscaped ago between buildings. The design of the basement should be reconsidered where it clashes with these deep soil areas.	Beennert under planting in It rocess is now mixed and algebred to the It will be ensure full of depth, thereby eliminating mased planters. Beannert Plan and Bulk and Scale analysis Pert 3 Steels, showing section of the area in new updated. TRAVIER BOX HAS BEEN REMOVED	A12.7
17	Flip location of kitchen and living room in Unit C13.		A07, A09.3
		Location of Livino nom and lithen fitopod as reouvated	
18	The retention of Lot 13 in separate ownership is not supported and should form part of Lot 12.	This will be addressed in the SEE. (1, of 13 and Dresilitie contiders conversible and management is not above on any updated drawings).	