

Platform Architects 503/39 East Esplanade Manly NSW 2095

Site: 14 Wyatt Avenue Belrose NSW 2085 Statement regarding minor design changes to driveway for section 4.55 application

Dear Platform Architects,

I have reviewed the following plans in relation to proposed driveway modifications for approved DA2018/0401 as part of a section 4.55 application:

- A02 Site Plan 4.55 issue Rev 1
- A03 Plan Basement 4.55 issue Rev 1
- A04 Plan Ground Level 4.55 Issue Rev 1
- A05A Plan Level 1 4.55 Issue Rev 1
- A05B Plan Level 2 4.55 Issue Rev 1
- A06 Plan Roof 4.55 Issue Rev 1
- A10 Elevation 4.55 issue Rev 1
- A13 Elevation 4.55 issue Rev 1
- A14 Elevation 4.55 issue Rev 1
- A15 Elevation 4.55 issue Rev 1

It is noted that the approved plans through the Land and Environment Court (LEC) are Revision M dated August 2020, with the initial Arborist report completed using drawings done under Revision L dated Feb 2020. Changes between the two revisions include increased fill along the length of the driveway to support finished driveway level. This required a small retaining wall on the eastern side of the driveway to support the driveway.

I note the following changes within the plans:

- The driveway is to be widened by up to 400mm in 3 separate locations to accommodate better access for emergency vehicles. The widening will occur within the Tree Protection Zones and Structural Root Zones of the following trees: 30, 31, and 32
- Increased fill is required to level the gradient along the length of the driveway for emergency vehicle access.

The amended incursions due to the increase of the driveway width are as follows:

Tree #	Tree Name	Original incursion	New incursion	Change %
30	Casuarina glauca	28.8%	30.89%	2.09%
31	Eucalyptus spp	28.39%	39.94%	1.55%
32	Casuarina glauca	34.58%	35.69%	1.11%

As noted in table 1 and the supplied snapshot plan showing the incursion, the increased incursion due to the widening of the driveway is a minor addition to the already approved major incursion into the Tree Protection Zones and Structural Root Zones of trees numbered 30, 31 and 32. This slight increase in incursion is predicted to have a negligible impact on tree health in addition to what has been previously approved.

LOUIS PUTNAM GRAY 0401 135 436 TREE SURGEON I CONSULTING ARBORIST

e∣axiomarbor@gmail.com | w∣axiomarbor.com.au 301/39 Mclaren Street North Sydney 2060

ABN 80 364 422 932

16/11/2021



Supervision by the project arborist will be required for the excavation required for the installation of the retaining wall used to house the elevated driveway. All roots are to be severed cleanly with a sharp cutting tool.

Kind regards

Louis Putnam Gray AQF5 Arborist



ABN 80 364 422 932



