

MANLY COUNCIL

6<sup>th</sup> August 2010

0 9 AUG 2010

RECEIVED BY RECORDS

Building Certifiers Strata Plan Certifiers Building Regulations Consultants Fire Safety Consultants

The General Manager Manly Council PO Box 82 Manly NSW 1655

Attention: Planning Department

Dear Sir/Madam,

### RE: DA NO: 17/09 S96 15-17 THE CORSO, MANLY NSW 2095

Please find attached a copy of the Interim Occupation Certificate for the above development that has been granted by the Principal Certifying Authority, Lyall Dix.

The certificate relates to the alterations and additions to the existing building at the above address for additional retail use and office refurbishment, including external facade work.

Together with the Certificate, we have enclosed the following for Council's record:

- 1. Interim Occupation Certificate Application Form
- 2. Final Fire Safety Certificate
- 3. Revised Fire Safety Schedule
- 4. Other documents relied upon.

We have attached a cheque for the registration of this certificate. In forwarding the receipt for this cheque it is requested that reference be made to the address of the premises.

If you have any queries regarding the above please do not hesitate to contact the undersigned on 9279 3657 during business hours.

Yours faithfully,

Carl Parkinson Dix Gardner Pty Ltd

CC:- Hilrok Properties Pty Ltd.

709625 9/0/0012

Job 09/0333 Page 1 of 1 Level 2, 25 Watt Street P.O. Box 1809 Newcastle NSW 2300 Tel: 02 4927 1822 Fax: 02 4927 1844



Building Certifiers Strata Plan Certifiers Building Regulations Consultants Fire Safety Consultants

### **Occupation Certificate**

Issued under the Environmental Planning and Assessment Act 1979 Sections 109C (1) (c) and 109H

Certificate No.:

205/10

Interim

Approved

06/08/2010

Subject land: Lot and DP:

Applicant: Address: Hilrok Properties Pty Ltd. 27 The Corso, Manly NSW 2095

Other certificates relied upon
 Final Fire Safety Certificate

Whole, excluding minor works to one office

Hilrok Properties Pty Ltd.

15-17 The Corso, Manly NSW 2095

Lot 1, DP 5777268; Lot 1, DP 64558 & Lot B, DP 373583

**Owner:** 

**Type of Certificate:** 

Determination: Date of Determination:

Attachments:

Whole/Part of building works: Description of part (if applicable): BCA Classification:

DA No.: Issued by: 17/09 S96 Manly Council

Class 5 & 6

Construction Certificate No.: Date:

Accreditation Level:

Registration No.: Accreditation Body: 003/10 27/01/2010

N/A

A1 - Accredited Certifier - Building Surveyor Grade 1 BPB0092 Building Professionals Board

I certify that:

- the health and safety of the occupants of the building have been taken into consideration where an interim occupation certificate is being issued, and
- a current development consent or complying development certificate is in force for the building, and
- if any building work has been carried out, a current construction certificate (or complying development certificate) has been issued with respect to the plans and specifications for the building, and
- the building is suitable for occupation or use in accordance with its classification under the Building Code of Australia, and
- a fire safety certificate has been issued for the building, and
- a report from the Fire Commissioner has been considered (if required).

Signed:

Date: 06/08/2010

Lyall Dix Principal Certifying Authority

# COUNCIL COPY



Building Certifiers Strats Plan Certifiers Building Regulations Consultants Fire Safety Consultants

	Interim K Final
Name	HILROCK PROPERTIES PTY 40
Address	27 THE CORSO
	Marky 2095.
Signature & Date	
OWNER	
Name	HIL ROCK PROPERTIES PTY LTD
Address	AS Above
SUBJECT LAND	
Address	15, 15 A, 17 THE CORSO MANUY
Lot & DP	LOTI, PP597268; LOTI, PP64558 \$ LOTB, DP 373583
PROPOSAL	
Description	THE PRUPPISHA COMPRISES RESTORATION & CONSERVATION OF
	THE WHOLE OF THE PROPERTIES INTERNALLY AND
Part or Whole	EXTERNALLY. THERE IS NO PROPOSED CHIANGE IN
of Building	USINGE OF THE BUILDINGS.
DEVELOPMENT CO	
DA No.	$\frac{applications for CDC}{\frac{17}{09}}$ Date of Determination 11 08 09 \$\nothermodel{eq}\$ 2 06
CONSTRUCTION/C	OMPLYING DEVELOPMENT CERTIFICATE
Construction or	
Complying	
Development	al. tak
Certificate No	00310 Date 27/01/2010

Level 4, 155 Castlereagh Street Sydney NSW 2000 Tel: 02 9279 3657 Fax: 02 9279 3666 Level 2, 25 Wat: Street P.O. Box 1809 Newcestle NSW 2300 Tel: 02 4927 1822 Fax: 02 4927 1844



**Building Certifiers** Strata Plan Certifiers **Building Regulations** Consultants Fire Safety Consultants

### **INSPECTION RECORD**

Address:	15-17 The Corso, Manly NSW 2095		
DA No.:	17/09	CC/CDC No.:	003/10
AC/PCA:	Lyall Dix - BPB0092	DG Project No:	09/0333
Inspection Type:	Pre / Stormwater / Final / BCA Compliance	Inspections By:	Carl Parkinson (Building Surveyor) Lyall Dix (PCA)

CRITICAL STAGE INSPECTIONS	S	ection 109E (	3) (d) of the Ac	t & Clause 162A of t	he Reg's
In the case of a class 5, 6, 7, 8 or 9 building,	Critical Stage In	nspection Satis	factory	Inspection Date	Officer
(a) Prior to issuing the Construction Certificate	Yes 🖾	Missed 🔲	N/A 🗖	15/06/2009 18/01/2010	LD/CP
(b) prior to covering any stormwater drainage connections, and	Yes 🛛	Missed 🛛	N/A 🗖	29/06/2010	LD/CP
(c) after the building work has been completed and prior to any occupation certificate.	Yes 🛛	Missed 🗖	N/A 🗖	29/06/2010 23/07/2010 03/08/2010	LD/CP

Fire Safety Certificate Issued under the Environmental Planning and Assessment Regulation 2000, Clauses 170 to 174

Type of Certificate	🗌 Interim 🗸 Final	
Owner / Agent	I, James Crawford	
Address	of Quasar Constructions Pty Ltd Unit 3 & 4, 23 Brookhollow Ave NSW 2153	
	Certify that:	
	each of the essential fire safety measures specified in the current fire safety schedule for the building to which the certificate relates:	
	<ul> <li>has been assessed by a properly qualified person, and</li> </ul>	
	b) was found, when it was assessed, to be capable of performing to at least the standard required by the current fire safety schedule for the building for which the certificate is issued.	
Identification of Building		
Location: Manly NSW 2095		
Street: 15 - 17 The Corso, Manly NSW 2	2095	
Nearest Cross Street: Market Lane		
House/unit no or name: Retail / Comme	rical Building, Number 15 - 17	
Particulars of Building		
Scope	🗹 Whole 🔲 Part	
Description of Part (where applicable)		
House/unit no or name: Retail/Commerical Building, Number 15 - 17		
Date of Assessment: 22/07/2010		
Owner's Details		
Name: Hilrok Properties Pty Ltd		

Address: 17 The Corso, Manly NSW 2095

Essential Fire and other Safety Measures	Standard of Performance
Automatic fire detection and alarm system	BCA Spec. E2.2a and AS 1670-2004
Emergency Lighting	BCA Clauses E4.2/E4.4 & AS/NZS 2293 1-1995/ 2005
Exit Signs	BCA Clauses E4.5/NSW E4.6 /E4.8 and AS/NZS 2293.1-1995/ 2005
Fire hydrant systems (street hydrant)	BCA Clause E1.3 & AS 2419.1-2005
Fire doors (Electrical switch board cupboard)	BCA Clause C2.13 & AS1905.1-2005
Hose reel system	BCA Clause E1.4 & AS 2441-2005
Mechanical air handling systems including auto-shutdown of the air handling system	BCA Clauses E2.2/NSW F4.5(b) & AS/NZS 1668.1-1998
PORTATILE FIRE EXTINGUISHERS ISCA CLAUSE EISE & A	

Date of Cordificate	dated this day of 22/07/2010	
Signature	Ownersegent	an i and an and a summer

A copy of this certificate together with the relevant fire safety schedule must be forwarded to the Council and the Commissioner of the New South Wales Brigades.

A copy of this certificate together with the relevant fire safety schedule must be prominently displayed in the building.

### Notes for completing the Fire Safety Certificate

### Note 1

An interim fire safety contificate or a final fire safety certificate is required before:

- an interim occupation certificate can be issued to allow a partially completed new building (including and altered portion of, or an extension to, a new building) to be occupied or used, or
- an interim occupation certification can be issued to allow a change of building use for part of an existing building.

A final fire safety certificate is required:

- before a final occupation certificate can be issued to allow a new building (including an altered portion of, or extension to, a new building) to be occupied or used, or
- before a final occupation certificate can be issued to allow a change of building use for an existing building, or
- in accordance with a fire safety order given by a council.

An interim fire safety certificate is issued for part of the building and may deal only with those essential fire safety measures appearing on the most recent fire safety schedule (see note 3) relevant to the part of the building for which interim occupation certificate will be sought.

A final fire safety certificate must deal with all essential fire safety measures appearing on the most recent fire safety schedule (see note 3), subject to the following.

An interim fire safety certificate or a final fire safety certificate need not deal with those essential fire safety measures which have been the subject of some other final fire safety certificate or annual fire safety statement within the previous 6 months, unless the person or authority responsible for determining the relovant development consent, complying development certificate, construction certificate or fire safety order, has specified otherwise in the schedule. See also note 3.

### Note 2

The person who carries out the assessment:

- must inspect and verify the performance of each fire safety measure being assessed; and
- in the case of a (interim or final) fire safety certificate for a new building (not an alteration to, or enlargement or extension of an existing building) must test the operation of each item of fire safety equipment installed in the building.

#### Note 3

The relevant assential fire safety measures are those specified in the most recent fire safety schedule, attached to one of the following:

- development consent for a change of building use; or
- complying development certificate for the erection of a building or a change of building use; or
- construction certificate for proposed building work, including building work associated with a change of building use; or
- a fire safety order.

The fire safety schedule will also identify standard of performance for each essential fire safety measure



Building Certifiers COUNCIL COPY Strata Plan Certifiers Building Regulations Consultants Fire Safety Consultants

# Fire Safety Schedule

(Clause 168 of the Environmental Planning and Assessment Regulation 2000)

Premises:	15-17 The Corso, Manly NSW 2095
Development Consent No.:	17/09
Construction Certificate No.:	003/10

The following essential fire safety measures shall be implemented in the whole of the building premises and each of the fire safety measures must satisfy the standard of performance listed in the schedule which, for the purposes of Clause 168 of the Environmental Planning and Assessment Regulation 2000, is deemed to be the current fire safety schedule for the building.

### **SCHEDULE**

Essential Fire and other Safety Measures	Standard of Performance	Existing	Proposed
Automatic fire detection and alarm system	BCA Spec. E2.2a and AS 1670-2004		✓
Automatic fire suppression system (sprinklers)	BCA Spec. E1.5 and AS 2118.1-1995	✓	
Emergency Lighting	BCA Clauses E4.2/E4.4 & AS/NZS 2293.1-1995/ 2005	~	✓
Exit Signs	BCA Clauses E4.5/NSW E4.6 /E4.8 and AS/NZS 2293.1-1995/ 2005	~	4
Fire hydrant systems (street hydrant)	BCA Clause E1.3 & AS 2419.1-2005		√
Fire Doors (Electrical switch board cupboard)	BCA Clause C2.13 & AS1905.1-2005		1
Hose reel system	BCA Clause E1.4 & AS 2441-2005		√
Mechanical air handling systems including auto-shutdown of the air handling system	BCA Clauses E2.2/NSW F4.5(b) & AS/NZS 1668.1-1998		4
Portable fire extinguishers	BCA Clause E1.6 and AS 2444-2001	1	1

090043

Statement of Available Pressure and Flow Sydney

Hybrid Consulting Services PO Box 7660 Baulkham Hills, 2153

WMS No:	34924
Contact No:	8849-3531
Fax No:	8849-3111

**Attention: Scott Harris** 

Date:

07/09/2009

### Pressure & Flow Application Number: 2656443 Your Pressure Inquiry Dated: Fri August 28 2009 Property Address: 17 The Corso Manly 2095

The expected maximum and minimum pressures available in the water main given below relate to modelled existing demand conditions, either with or without extra flows for emergency fire fighting, and are not to be construed as availability for normal domestic supply for any proposed development.

### ASSUMED CONNECTION DETAILS

Street Name: The Corso	Side of Street: North	
Distance & Direction from Nearest Cross Street	50 metres East from Darley Road	
Approximate Ground Level (AHD):	6 metres	
Nominal Size of Water Main (DN):	450 mm	

### EXPECTED WATER MAIN PRESSURES AT CONNECTION POINT

Normal Supply Conditions	
Maximum Pressure	104 metre head
Minimum Pressure	56 metre head
	Go mod noda

WITH PROPERTY FIRE PREVENTION SYSTEM DEMANDS	Flow /s	Pressure head m
Fire Hose Reel Installations (Two hose reels simultaneously)	0.66	55
Fire Hydrant / Sprinkler Installations (Pressure expected to be maintained for 95% of the time)	5 10 15 20 30 35 40	73 72 71 71 69 68 68
Fire Installations based on peak demand (Pressure expected to be maintained with flows combined with peak demand in the watermain)	5 10 15 20 30 35 40	55 54 53 52 50 49 48
Maximum Permissible Flow	48	46

(Please refer to reverse side for Notes)

Robert Wickham

Team Leader Asset Planning

Sydney Water Corporation ABN 49 776 225 038 1 Smith St Parramatta 2150 | PO Box 399 Parramatta 2124 | DX 14 Sydney | T 13 20 92 | www.sydneywater.com.au Delivering essential and sustainable water services for the benefit of the community



Unit 3 & 4, 23 Brookholiow Drive Bauikham Hills NSW 2153 PO Box 7918 Baulkham Hills NSW 2153 T: 02 8853 5600 F: 02 9680 9340 E: enquines@quasargroup.com.au

W. quasargroup.com.au

ACN 069 663 403 ABN 86 069 663 403 Company Licence No. 76988C

28th July 2010

NBRS+Partners Level 3, 4 Glen Street MILSONS POINT NSW 2061

Attention: Whom it may concern

RE: CERTIFICATE OF COMPLIANCE - 15-17 The Corso, Manly NSW 2061

Quasar Constructions Pty Ltd wishes to confirm that the works under taken to the development mentioned above complies with all design documentation.

For any queries don't hesitate to contact the under signed.

Yours faithfully Quasar Constructions Pty Ltd

Graeme Shaw Operations Manager



Unit 3 & 4, 23 Brookholiow Drive Baulkham Hills NSW 2153 PO Box 7918 Baulkham Hills NSW 2153 T: 02 8953 5600 F: 02 9680 9340 E: enquiries@quasargroup.com.au W, quasargroup.com.au

ACIN 069 663 403 ABN 86 069 663 403 Company Licence No. 76988C

28th July 2010

NBRS+Partners Level 3, 4 Glen Street MILSONS POINT NSW 2061

Attention: Whom it may concern

### RE: CERTIFICATE OF COMPLIANCE - 15-17 The Corso, Manly NSW 2061

Quasar Constructions Pty Ltd wishes to confirm that the Garbage Room located at 15-17 The Corso, Manly premises complies and satisfies Development Consent Condition DA215 – 219.

For any queries don't hesitate to contact the under signed.

Yours faithfully Quasar Constructions Pty Ltd

Graeme Shaw Operations Manager



### STORMWATER

All work is done is accordance to the AS3500 Work is done to architectural drawings Material used is PVC



P 02 9540 2311 F 02 9540 4311 EMAIL admin@eastcoastgroup.net.au ABN 61 001 377 886 12/23 Bay Road, Taren Point NSW 2229 P.O. Box 2020, Taren Point NSW 2229

# CERTIFICATION

### To Whom It May Concern

### Project: 15-17 The Corso Manly Retail Shops base building only G.01, G03, & G.04. Office space areas 1.01, 1.02, 1.07, 1.08, 1.09, & 1.10. House and common areas

The Electrical project mentioned above including Emergency lighting and Exit signs for whole/part of building:

Retail Shops base building only G.01, G03, & G.04. Office space 1.01, 1.02, 1.07, 1.08, 1.09, & 1.10. House and common areas, of this facility is as per and in accordance with the following; The electrical design is as per documentation, drawings and specifications provided by Knox Advanced Engineering Consultants.

- 1. AS3000:2008 and Section J of BCA.
- 2. AS2293,1:2005
- 3. BCA Clauses E4.2, E4.4, E4.5/NSW, E4.6, E4.7 and E4.8
- 4. Design Meetings to date.
- 5. Knox Advanced Engineering Consultants relevant drawings and specifications.

Manuel Bonnici

July 13, 2010



### Waddington Consulting Pty Ltd

ACN 130 522 851 Structural and Civil Engineering Suite 506, Level 5 22 Central Ave, Manly NSW P.O. Box 1044 Manly NSW 1655

> P (02) 9976 0070 F (02) 9976 0095

22 July 2010

Hilrok Properties Pty Ltd 17 The Corso Manly NSW

c/o NBRS & Partners Level 3, 4 Glen St Milsons Point NSW 2061

Attention: Mr Graham Nicholas

Dear Graham,

### Subject: Alterations and Additions at 15-17 The Corso, Manly ENGINEERS CERTIFICATE FOR INSPECTIONS

I certify that our firm carried out the structural engineering inspections of the structural work listed below for the alterations and additions at the above address and that at the time of the inspection the structure appeared to be in accordance with the design intent of the structural details shown on drawings 9053-S0.00, S1.00, S2.00, S3.00, S3.01.

During construction, we carried out the following engineering inspections. The date of the inspection is given in brackets.

- Steel reinforcement for the reinforced concrete ground floor level slabs and external paving slabs (22/04/2010, 03/06/2010, 18/069/2010, 21/06/2010)
- Structural steel and timber framing for first floor, new awnings and new wall openings (17/02/2010,23/02/2010, 21/06/2010)

This certificate assumes the construction was carried out by a licensed builder who has experience in this type of work. The above inspections do not, in any way whatsoever, relieve the builder of his responsibility.

The above inspections do not include inspections for contract administration purposes (e.g. progress payments), cosmetic matters and work that, once the competence of the builder has been established, is reasonable for the builder to supervise.

Yours sincerely,

Since liberting

Simon Waddington MIEAust CPEng NPER (Structural) Director Waddington Consulting Pty Ltd



P 02 9540 2311 F 02 9540 4311 EMAIL admin@eastcoastgroup.net.au ABN 61 001 377 886 12/23 Bay Road, Taren Point NSW 2229 P.O. Box 2020, Taren Point NSW 2229

### Fire Safety Certificate for Emergency and Exit Lighting

Issued under the Environmental Planning and Assessment Regulation 2000,

Clauses 170 to 174 Type of Certificate Interim E Final Owner / Agent I, Manuel Bonnici Address of 12/23 Bay Rd, Taren Point NSW 2229 **Certify that:** each of the essential fire safety measures specified in the current fire safety schedule for the building to which the certificate relates: a) has been assessed by a properly qualified person, and b) was found, when it was assessed, to be capable of performing to at least the standard required by the current fire safety schedule for the building for which the certificate is issued. C) All of the electrical design is as per Knox Advanced Engineering documentation, drawings and specifications issued for this project. Identification of Building Street The Corso Manly 2095 House/Unit No. or Building Name 15 - 17 Side of Street West Nearest Cross Street Market Lane Particulars of Building 🖾 Whole Scope X Part Description of Part (where applicable) Retail Shops base building only G.01, G03, & G.04. Office areas 1.01, 1.02, 1.07, 1.08, 1.09, & 1.10. House and common areas. House/Unit No. or Building Name Date of Assessment 13/07/2010 **Owner's Details** Name Hilrok Properties PTY LTD Address 27 The Corso Manly 2095

Essential Fire and Other Safety Measures	Standard of Performance
Emergency Lighting	BCA Clause E4.4 & AS 2293.1-2005 BCA Clause E4.2
Exit Signs	BCA Clause E4.5, E4.6 & E4.8 and AS 2293.1 - 2005

Date of Certificate dated this thirteenth day of July 2010

Signature

owner/agent

A copy of this certificate together with the relevant fire safety schedule must be forwarded to the Council and the Commissioner of the New South Wales Brigades. A copy of this certificate together with the relevant fire safety schedule must be prominently displayed in the building.

### Notes for completing the Fire Safety Certificate

### Note 1

An interim fire safety certificate or a final fire safety certificate is required before:

- an interim occupation certificate can be issued to allow a partially completed new building (including and altered portion of, or an extension to, a new building) to be occupied or used, or
- an interim occupation certification can be issued to allow a change of building use for part of an existing building.

A final fire safety certificate is required:

- before a final occupation certificate can be issued to allow a new building (including an altered portion of, or extension to, a new building) to be occupied or used, or
- before a final occupation certificate can be issued to allow a change of building use for an existing building, or
- in accordance with a fire safety order given by a council.

An interim fire safety certificate is issued for part of the building and may deal only with those essential fire safety measures appearing on the most recent fire safety schedule (see note 3) relevant to the part of the building for which interim occupation certificate will be sought.

A final fire safety certificate must deal with all essential fire safety measures appearing on the most recent fire safety schedule (see note 3), subject to the following.

An interim fire safety certificate or a final fire safety certificate need not deal with those essential fire safety measures which have been the subject of some other final fire safety certificate or annual fire safety statement within the previous 6 months, unless the person or authority responsible for determining the relevant development consent, complying development certificate, construction certificate or fire safety order, has specified otherwise in the schedule. See also note 3.

### Note 2

The person who carries out the assessment:

- must inspect and verify the performance of each fire safety measure being assessed; and
- in the case of a (interim or final) fire safety certificate for a new building (not an alteration to, or enlargement or extension of an existing building) must test the operation of each item of fire safety equipment installed in the building.

### Note 3

The relevant essential fire safety measures are those specified in the most recent fire safety schedule, attached to one of the following:

- development consent for a change of building use; or
- complying development certificate for the erection of a building or a change of building use; or
- construction certificate for proposed building work, including building work associated with a change of building use; or
- a fire safety order.

The fire safety schedule will also identify standard of performance for each essential fire safety measure.

	1994-Clauses 8		
the stinter to	Certificato =	<u>)</u> .	/
type of certificate			
	interim		🗸 final
certificate	E		
name owner/agent		er Slonne	
address		r Fire Sys 7 Hoyle Av	tems NSW re Castle Hill NSW 2154
	certify that	7 noyie 25	e Cashe ilin 11517 2159
	(a) each of t	he essential	fire measures listed below:
			a person (chosen by me) who was
	<ul> <li>property</li> <li>was foun</li> </ul>	qualified to d, when it w	up so, and as assessed, to have been properly
	impleme	nted and to 1	be capable of performing to a standard nired by the most recent fire safety
	schedule	(copy attack	red) for the building for which the
		e is issued.	ined in this certificate is, to the best of my
	knowledg	ge and belief	, true and accurate.
identification of building			
Ŭ	Location	•	Manly NSW 2095
	Street: nearest cross s	treet.	The Corso Market Lane
	house/unit no		Retail/Commercial Building, Number 15-17
	<b>11</b>		
particulars of building	whole/part		Part
	description of	part	all areas excluding Retails G.02 and 1.14 (Bar
			Tenancy)
date of assessment	l		
date of assessment			13/7/2010
owner's defails			
anic			Hilrok Properties Pty Ltd
ldress			27 The Corso Manly NSW 2095
	<u>A</u>		
essential fire safety measures			
measure			standard of performance
Fire Detection System			AS1670.1-2004, BCA Spec E2.2a
Occupant Warning System		1	AS1670.1-2004, BCA Spec E2.2a
te of certificate	dated this	14 <sup>th</sup>	day of July 2010
signatura		nA	· · · · · · · · · · · · · · · · · · ·
signature		1 <u>11 (</u>	
			owner/agent/installer



Advanced Metal Door Frames P/L A.B.N 42 076 510 060 UNIT 1A 42 BEAUMONT RD MT KURING-GAI NSW 2080 PH: 9457 7901 FAX: 9457 7902

### FIRE SAFETY CERTIFICATE

Name owner/agent:	I,	Terry Frendo
Address:	of,	Advanced Metal Door Frames P/L
		la 42 Beaumont Road, Mt Kuring-Gai, NSW 2080

### Certify that:

- (a) Each of the essential fire measures listed below:
  - Has been assessed by a person (chosen by me) who was properly qualified to do so, and was found, when assessed, to have properly implemented and to be capable of performing to a standard not less than that required by the most recent fire safety schedule for the building for which the certificate is issued
- (b) The information contained in this certificate is, to the best of my knowledge and belief, true and accurate.

### Identification of Building

Location:	Manly	
House No. Unit No. or Name:	15-17	
)reet:	The Corso	
Side of Street:	n/a	
Nearest Cross Street:	n/a	

Date of Assessment by the Properly Qualified Person

13<sup>th</sup> July, 2010

**Owner's Details** 

Name:

Quasar Constructions

Address:

Unit 3 & 4, 23 Brookhollow Avenue, Baulkham Hills

### Essential/Critical Fire Safety Measures:

Measure	Standard of Performance		
FIRE DOOR ASSEMBLY	AS 1905.1-2005 AS & NZS 1905 : 1 – 1997 BCA CLAUSE C3.4		
FIRE SEALS	BCA C3.12, C3.15 & Spec C3.15		
SMOKE DOORS	BCA Spec C3.4		
SOLID CORE DOORS	BCA C3.11		

Date of Statement

dated this Tuesday 13th July 2010

Signature

)

.....

A copy of the certificate together with the relevant fire safety schedule must be forwarded to the Council and Commissioner of the New South Wales Fire Brigades.

A copy of this certificate together with the relevant fire safety schedule must be prominently displayed in the building.

# FINAL/INTERIM FIRE SAFETY CERTIFICATE

--- (Form 15).....

Issued under the Environmental Planning and Assessment Regulations 1994. clauses 80E and 60F

Type of Certificate I FINAL □ INTERIM sea note 1 (overleaf) I Geoffrey Beeche, CPEng. of Crest Air Conditioning certify that: certificate see note 1 (overleaf) (a) each of the essential fire measures listed below: \* has been assessed by a person who was see note 2 (overleaf) assessment properly qualified to do so, and requirements. \* was found, when it was assessed, to have been properly implemented and to be capable of performing to a standard not less than that required by the most recent fire safety schedule see note 3 (overleaf) relevant fire-(copy attached) for the building for which the certiticate is safety schedule. issued. \* (b) the information contained in this certificate is, to the best of my knowledge and belief, true and accurate. MANLY Location 15-17 THE CORSO Identification of Building Street NORTHERN Side of Street location DARLEY ROAD Nearest cross street **RETAIL/OFFICE DEVELOPMENT** Name Whole/Part: Part Particulars of Building Upstairs only (downstairs awaiting fitout) **Description of Part** Monday 19th July 2010 **Date of Assessment Hilrok Properties Pty Ltd Owners** Details Name 17 The Corso Manly NSW 2095 Address Standard of Performance **Essential Fire Safety** Measure Measures **Electrical Installation** AS3000 see note 3 AS4254 Ductwork AS1668,1 & AS1668.2 Mechanical air handling **BCA Section J5 Energy efficiency** AS1668.1 **Fire Dampers** Warringah Shire Council Municipality Signature Aaen

\* A copy of this certificate together with the relevant fire safety schedule must be forwarded to the council and the Commissioner of the New South Wales Fire Brigade.

\* A copy of this certificate together with the relevant fire safety schedule must be prominently displayed in the building.

# solveit Plumbing

ABN. 82004517552 LIC NO. 1824250 Specialising in - Drainage - Gas Fitting & 24Hr Emergency Work 8 Crown Street, Harris Park, NSW 2150 Mobile. 0419600737 Fax. 98970201

12 July 2010

To: Quasar Constructions

Job Address: 15, 17, 17A The Corso Manly

**Description: Certificate** 

To Whom It May Concern:

This is to state that all work done at the above property complies with the AS3500 and BCA part J7.

Thank You

Arthur Romanous

# solveit Plumbing

ABN• 82004517552 LIC NO• 1824250

SPECIALISING IN - DRAINAGE - GAS FITTING & 24HR EMERGENCY WORK 8 CROWN STREET HARRIS PARK NSW 2150 Mobile 0419600787 Fax- 98970201

### 12 July 2010

To: Quasar Constructions

Job Address: 15, 17, 17A The Corso Manly

Description: Fire Hose Reel certificate

To Whom It May Concern:

This is to state that the fire hose reels at the above address have been installed to manufactures instructions and in accordance to BCA Clauses E1.4 & AS 2441-2005

Thank You

Arthur Romanous

# creating effective height safety solutions



QUASAR CONSTRUCTIONS

2 1 JUL 2010

RECEIVED

## HEIGHT SAFETY SYSTEM WARRANTY

- 1. Roofsafe Industrial Safety Pty Limited guarantees the height safety system and installation against defects caused by faulty workmanship and materials for twelve (12) months from the date of purchase.
- 2. During this Guarantee period Roofsafe Industrial Safety will replace any defective parts and provide labour to install. However if the product includes a number of accessories only the defective product or accessory will be replaced.
- 3. In addition the parts and accessories making up the system are guaranteed for structural integrity for a period of 12 months from date of purchase.
- 4. It is a condition of this warranty and a requirement of the Australian Standard AS/NZS 1891 Part 4 that this system be inspected and recertified every twelve months by Roofsafe.
- 5. Roofsafe Industrial Safety reserves the right to make minor adjustments instead of replacing the product or accessory.
- 6. In the event of a part, product, accessory or system being replaced during this guarantee, the guarantee on the replacement will expire at the original date i.e. 12 months from the original purchase date.
- 7. This guarantee excludes defects caused by the product or system not being used in accordance with instructions, accidental damage, misuse or being tampered with by unauthorised persons.
- 8. If failure or fault occurs, notification should immediately be given in writing to Roofsafe Industrial Safety at 130 Gilba Road, Girraween N.S.W. 2145.
- 9. If any product or part is forwarded to Roofsafe Industrial Safety a label should be attached stating your full name, address and nature of fault or complaint. The Guarantee and copy of the Purchase Receipt should also accompany any claims.
- 10. This guarantee is additional to the Conditions and Guarantee which are mandatory and as implied by the Trade Practices Act 1974 and other legislation.

PRODUCT: W	ALKWAY, LADDER/STAIR, PLATFORM
MODEL: W	W, RIS, PLF
DATE OF PURCH	ASE / INSTALLATION: 19.07.2010
PURCHASED BY:	QUASAR CONSTRUCTIONS
LOCATION:	17 THE CORSO, MANLY
AUTHORISED BY	:
	ROOFSAFE INDUSTRIAL SAFETY

### **Roofsafe-T-Systems**

ABN 46 008 445 458

 Head Office:
 130 Gilba Rd, Girraween NSW 2145 Australia
 Mollourne
 Adelaida

 PO Box 260, Pendle Hill NSW 2145
 Ph: (03) 9545 3177
 (08) 8241 0690
 Ph: (03) 9545 3177
 (08) 8241 0690

 T: +61 2 9898 8644, F: +61 2 9896 8650, E: salus@routsale.com.au
 Fx: (03) 9545 3455
 (00) 8241 0122

www.roofsafe.com.au

(02) 6280 7200 (02) 6239 1666 1308 663 255

(07) 3216 6413 (07) 3216 7745 (08) 9417 9337 (08) 9417 9337



# creating effective height safety solutions

Certificate of Inspection

Installed System

Certificate No : 02-02-8880 Site Barcode :

CLIENT				17 The Cors	i0				
ADDRESS	P.O. Box 791	8				Manly			
Baulkham F	lills		POSTCODE	2153, N	SW				
PHONE	88535631		FAX		·		······		
ASSET TYI	PE	BAR COL	E COM	ISSION E	NEXT SERVICE	RATING	*COMPLYING STANDARDS	MANUFACTURED & INSTALLED BY	COMMENTS
Aluminium	Walkway	ww	19.07	2010	N/A	150kg	1657-1992	RIS/RIS	5m x 600mm Wide Walkway Installed, 19m x 1m Wide Walkway Installed, visually inspected pass
Aluminium	Ladder/Stair	RIS	19.07	2010	N/A	150kg	1657-1992	RIS/RIS	1 x Access Ladder/Stair Installed with Handrail, visually inspected pass
Aluminium	Platform	PLF	19.07	2010	N/A	150kg	1657-1992	RIS/RIS	1 x 2m Platform Installedail, visually inspected pass

Supply & Install: Walkway, Ladder/Stair, Platform

\*Design and location of Height Safety System is in accordance with AS/NZS 1891-4 - AS1657-1992 and local Regulatory Authorities.

AUTHORISED BY:	Dean Harrison	DATE: 19.07.2010	SIGNATURE:	O.M.
SYDNEY:	BRISBANE:	CANBERRA:	MELBOURNE:	ADELAIDE:
Tel: (02) 9896 8644	Tel: (07) 3216 6413	Tel: (02) 6280 7200	Tel: (03) 9545 3177	Tel: (08) 8241 0090
Fax: (02) 9896 8650	Fax: (07) 3216 7745	Fax: (02) 6239 1066	Fax: (03) 9545 3455	Fax: (08) 8241 0122

19 Jul 10 06:45a

Vista Glass Aust

02 4722 2463

Nista Glass Australia P/L ABN 69 133 088 356 PO Box 7030 Penrith Sth LPO NSW 2750 Ph - 0433 045 897 - Fax - 02 4729 0750 Email - vistaglass2@blgpond.com

**Glazing Certificate** 

Project: 15-17 The Corso Manly

Date; 14<sup>th</sup> July 2010

Quasar Constructions Units 3 & 4 Brookhollow Ave Baulkham Hills NSW 2153

Attn Mr Serge Younan

This is to Certify that the glass installed to all windows and doors installed by <u>Vista Glass Australia P/L</u> A Grade Safety Glass and complies to AS1288-2006 Human Impact codes

The windows and doors have been installed into a builder prepared opening, the certification only covers the integrity of the installation of window frames and glass and does not take into account the suitability of the linings surrounding the window or the integrity of the opening.

Yours Sincerely

C

Jordan Bencic

21 JUL 10 07:22a

Vista Glass Aust

UZ 47ZZ Z463

PO Box 7030 Penrith Sth LPO NSW 2750 Ph - 0433 045 897 - Fax - 02 4729 0750 Email - <u>vistaclass2@bigpond.com</u>

Project: 15-17 The Corso Manly

Date; 14<sup>th</sup> July 2010

Quasar Constructions Units 3 & 4 Brookhollow Ave Baulkham Hills NSW 2153

Attn Mr Eric Katafano

All materials used to all windows and doors installed by Vista Glass Australia P/L conform to all required BCA codes and specifications.

All work was carried out as per specification other than where changes were made at the builders request or in situe issues would not allow for specified materials to be used.

Materials that could not be sourced or were not able to be used in the appropriate method were substituted with equal quality or better upon approval of the builder's site representative,

**Yours Sincerely** 

Much

Jordan Bencic

# **LUMINARY 40 & 48**

### \*OBSIDIAN 900

	Product Specifications		Product Specifications
Product: Date: Description: Be Fibre; Ble Fibre; Fibre Quality: Fibre Quality: Pauge: Stitch Rate: Viel Mass: Be Height: Selourdion: Vimary Backing: Secondary Backin	Luminary 46 January 2007 Fine Gauge, High Density Level Loop Healhär 100% Pure New Selected Carpet Wools Semi Worsted, multi-ply, twisted and non-set 92% Wool, 8% BCF Nyton Semi Worsted plus Solution Dyed Nyton Accent 3.175 mm (1/6") 54.7 per 100mm 1627 gm/m² (3.8 oz/yd²) 4.8mm Stock Dyed 114 g/m² (3.8 oz/yd²) Woven Polypropytene 237 gm² (7 oz/yd²) Synthetic Latex 10.7 kg/LM (86.6oz/yd²) 3.66 metres 93037 Residential Extra Heavy Duty (Stairs) - 6 Star Contract Extra Heavy Duty (Stairs) - 7 Star Contract Extra Heavy Duty (Stairs) - 7 Star Contract Extra Heavy Duty (Stairs) - 7 Star Contract Extra Heavy Duty (Stairs) - 8 Star Contract Extra Heavy	Produot: Date: Description: Pile Fibre: Fibre Quality: Pile Pibre: Fibre Quality: Gauge: Sitch Rate: Pile Height: Colouration: Primary Backing: Secondary Backing: Laminate: Total Weight: Width: A.C.C.S. Reg. No.: A.C.C.S. Grade: Critical Radiant Flux: (Burning Behaviour) AS/ISO 9239-1:2003 Part 1 - Test Product Features:	Luminary 40 January:2007 Fine Gauge. High Density Level Loop Heather. 100% Pure New Selected Carpet Wools. Semi Worsted, multi-ply, twisted and non set 92% Woot, 8% BCF Nion Semi Worsted pkrs, Solution Dyed Nyloh Accent 3.175 mm (1/8″) 38.5 per 100mm 1356 gm/m2 (40 oz/yd2) 4.4mm Stock Dyed 114.g/m2 (3.3 oz/yd2) Woven Polypropylene. 237.g/m2 (7 oz/yd2) Woven Jule 956 g/m2 (28.2 oz/yd2) Synthetic Latex 9.7 kg/LM (66.8oz/yd2) 3.66 metres 93038 Residential Extra Heavy Duty (Stairs) - 6 Star Contract Extra Heavy Duty (Stairs) - 3 Star CHF Mean Hesuit 7.8 kw/m2 (Conventionally) Stocke Value 132 % nin (Conventionally) Passes requirements of BCA spec C1.10a Class 9a; 9b; 9c Buildings (Conventional) • Increased thermal and acoustic confort. • Superior apparance retention when correctly maintained. • Available in 6 standard colours. • The use of chafr pads is mandatory when used in commercial application. • Must be laid in accordance with AS 2456.1995. • Subject to Tuifumaster's Terms of Tracing.
Cei Dui A n Pai	carpel installations are to be in accordance with AS2455. I: 1995 unless otherwise rpal is a taxile that is subjected to extreme variations in temperature and tension in ring this process variances may occur in both the width and length of this patterne easonable pattern match may be obtained when installing carpet conventionally on thermaliciting cannot be guaranteed when installed by the direct tick or dual to an entropy of the patternet to be guaranteed when installed by the direct tick or dual to the matching cannot be guaranteed when installed by the direct tick or dual to an entropy of the patternet by the direct tick or dual to the patternet by the direct to be guaranteed when installed by the direct tick or dual to be an entropy of the patternet by the direct to the patternet by the patternet by the direct by the direct by the direct by the direct by the direct by the direct by the direct by the direct by	n the mariulacturing process. Id carpet and as a result an exi- rer an underlay and whan insta- rd method as this only alows fo	act pattern match cannol be guaranteed. lied by trained, experienced and professional carpet layers. Ir minor stretching and adjustments of the pattern during installation.
inst paļ	en installing pallemed carpels on open floors it is a requirement that the carpet lag tatalion is the most critical and ensures that the project is set out occurately prior t lem match can be guaranteed it the carpet layers are only provided part floors at a	o jolning, to ensure the best po a time.	ssible pallem match over the entile lloor area is achieved. No acceptable
be.;	Initister Carpals specify that when laying conventionally or dual bond that at out ex given sufficient time to oure property prior to heat taping (time is dependent on site of when installing carpat by both methods.	dges to be joined must be tipp e conditions and tempereture),	ed with an edge saaling blex adhesive (mhimum 00% component) and It is the installers responsibility to ensure that the correct heat lapes are
e variation: Sha be	ade or pallem variations may occur from sample and between dye lots and within within recognized lexitle industry standards.	production runs due to the ma	ny variances in the manufacturing of carpet, however these variations will
aning: Car	pet should be cleaned and mainteined in accordance with AS 3733:1995.1.		
nelling: Par	nelling may be seen in some loop ple corpets. The effects of the stippled yarn can formance of the corpet.	appear as panalling down the	length of the carpet. This is not a manufacturing defect and will not effect

N,S,W.

S.A. tolozinteichn

### HEAD OFFICE TUFTMASTER CARPETS PTY. LTD. A.C.N. 004 802 564

Cope Street, Preston, Victoria 3072, Telephone: 61 3 9791 1388 Fraginila GU3/8480/2060 Email Graticumate.comati

Interstate Offices W.A. 0402 119 545 (02) 9555 2177 Queensland 0402 119 538 1800 062 076 Tasmanian Agent (03) 6234 9855

LIVERE CONFICTION CONTRACTOR A TANA DE CONTRACTORIA







T???



m/s Tuftmaster Carpets Pty Ltd, 8 Cope St, Preston, Vic 3072



TEST REPORT No. 000935

LABORATORY REF: P060935

### CUSTOMER REFERENCE LUMINARY 40

Sample description as provided by customer Mass/unit area 40 oz/yd² 1356 g/m² Pile Fibre Content 100% WOOL Construction Details Tufted Secondary Backing Jute Sivie Level Loop

Order No. 31341

Colour Black/Grey Pile Height 4.4 mm

TEST METHOD AS/ISO 9239.1 2003 Reaction To Fire Tests For Floorings Part 1 Determination of the Burning Behaviour Using a Radiant Heat Source. As required by specification C1.10a of the Building Code of Australia.

Tested in accordance with the Carpet Institute Code of Practice for AS/ISO 9239 Testing Version 10 / 0805.

The test results relate to the behaviour of the test specimens of a product under the particular conditions of the test, they are not intended to be the sole criterion for assessing the patential fire hazard of the product in use. Clause 9 of AS/ISO 9239 Part 1

Conditioning as specified in BS EN 13238.2001 Sample submitted Date November 2006 Test Date 7/12/2008

## ASSEMBLY SYSTEM DIRECT STICK details below.

• • • The floor covering was directly stuck to the substrate using ROBERTS 95 SF achesive.

lble Substrate : Non-combustible.

Substrate - 6mm Fibre Reinforced Cement Board to simulate a Non-Combustible Flooring. Sample Cleaned as Specified in ISO 11379.1997

Initiai Test		Length Direction Width Direction
	Full tests and	and out to the

Full tests carried out in the

Critical Radiant Flux 8.2 kW/m<sup>2</sup> Critical Radiant Flux 10.0 kW/m<sup>2</sup> Length Direction

÷., ,

SPECIMEN	Length #1	Length #2	Length #3	Mean
Critical Radlant Flux (kW/m²)	8.2	10.1	9.9	9.4
Smoke Development Rate (%.min)	29	39	31	33

The values quoted below are as required by Specification C1.10a Fire Hazard Properties (Floors) of the Building Code of Australia. The Critical Radiant Flux quoted is the value at Flame-Out.

# MEAN CRITICAL RADIANT FLUX 9.4 kW/m<sup>2</sup> **MEAN SMOKE DEVELOPMENT RATE 33 %.min**

**OBSERVATIONS The samples singed then ignited** 



PAGE 1 of 2

Page 2 only shows the time required in seconds for the flame front to reach each time marker, the total test time and the CHF value at 30 minutes (if applicable). The laboratory allows the use of this page of the report without the use of page 2.

1001 01 06

APL Australia Ply Ltd 5 Carloish Rd, Oakleigh South Victoria 3167 Australia

Telephone: 03 9543 1618 Facsimile: 03 9562 1818 Mobile: 0411 039 088

Email: api@apiaustralia.com.au Web: www.aplaustralia.com.au ARN 69 468 849 319



Att Mr Don Considine m/s Tuftmaster Carpets Pty Ltd, 8 Cope St, Preston, Vic 3072 TEST REPORT No. 000934

LABORATORY REF: P060934

# CUSTOMER REFERENCE

Sample description as provided by customer Mass/unit area 40 oz/yd<sup>2</sup> 1356 g/m<sup>2</sup> Pile Fibre Content 100% WOOL Construction Details Tufted Secondary Backing Jute Style Level Loop Order No. 31341

Colour Black/Grey Pile Height 4.4 mm

TEST METHOD AS/ISO 9239.1 2003 Reaction To Fire Tests For Fleorings Part 1 Determination of the Burning Behaviour Using a Radiant Heat Source. As required by specification C1.10a of the Building Code of Australia.

Tested in accordance with the Carpet Institute Code of Practice for AS/ISO 9239 Testing Version 10 / 0805.

The test results relate to the behaviour of the test specimens of a product under the particular conditions of the test, they are not intended to be the sole criterion for assessing the potential fire hazard of the product in use. Clause 9 of AS/ISO 9239 Part 1

Conditioning as specified in BS EN 13238.2001

Sample submitted Date November 2006

Test Date 6/12/2006

# ASSEMBLY SYSTEM DOUBLE BOND (DOUBLE STICK) details below.

The underlay used was SENSI SLAB it was achieved to the substrate using ROBERTS 656 adhesive. The floor covering was adhered to the underlay using ROBERTS 95 SF adhesive.

Substrate : Non-combustible

Substrate - 6mm Fibre Reinforced Coment Board to simulate a Non-Combustible Floering. Sample Cleaned as Specified in ISO 11379.1997

Initial	Test
Imilial	Teef
ILING	IGSI

Specimen 1 Length Direction Specimen 1 Width Direction Full tests carried out in the Critical Radiant Flux 8.2 kW/m<sup>2</sup> Critical Radiant Flux 10.1 kW/m<sup>2</sup> Length Direction

SPECIMEN	Length #1	Length #2	Length #3	Меал
Critical Radiant Flux (KW/m²)	8.2	8.4	8.2	8,3
Smoke Development Rate (%.min)	61	62	90	71

The values quoted below are as required by Specification C1.10a Fire Hazard Properties (Floors) of the Building Code of Australia. The Critical Radiant Flux quoted is the value at Flame-Out.

# MEAN CRITICAL RADIANT FLUX 8.3 kW/m<sup>2</sup> MEAN SMOKE DEVELOPMENT RATE 71 %.min

**OBSERVATIONS The samples singed then ignited** 



Authorised Signatory M. B. Webb Date 6/12/2006

NATA Reg. No. 15393 Heat and temperature measurement.

APL Australia Pty Ltd 5 Carlnish Rd, Oakleigh South Victoria 3167 Australia Telephone: 03 9543 1618 Facsimile: 03 9562 1818 Mobile: 0411 039 088

### PAGE 1 of 2

Page 2 only shows the time required in seconds for the flame front to reach each time marker, the total test time and the CHF value at 30 minutes (if applicable). The laboratory allows the use of this page of the report without the use of page 2.

1001 01 06

Email: apl@aplaustralia.com.au Web: www.aplaustralia.com.au ABN 69 468 849 319

	₩VTA 7	EXTILE	e <b>T</b> est	ING		
Au	stralian Wool Testing Aut	hority Ltd - tradii 3.N. 43 006 014 1		ile Testing	<b>NEORM</b>	
	1st Floor, 191 Raceco P.O. Box 240, N		nington, Victoria , Victoria 3051	3031	⑦ ⑦ ⑦ ⑦ ⑦ ⑦ ⑦ ⑦ ⑦ ⑦ ⑦ ⑦ ⑦ ⑦ ⑦ ⑦ ⑦ ⑦ ⑦	•
		ST REPO	•		DANDY	_
		• • • •	· :			
1 BENNET ST			DATE		: 7-542086-AV : 19/12/2005	
DANDENONG V	10 3119		. ORDE	R NUMBER	: 20857	
	· ·			•		• •
SAMPLE DESCRIPTION C	lients Ref: Lumi	nary 40				
	evel loop pile t clour: dark grey pproximate pile	ufted carpo /black stri	ipe			
Material Specificat Nominal Composition Nominal Total pile Nominal backing: Pr	1: 100% wool mass: 1356g/m2	ypropylene				
ASISO 9239.1-2003 Part 1	- Reaction Determin	to Fire Te ation of th Radiant Hea	ie Burning	oorings Behaviour		•
Date of sample arri Date tested: Results:	15/12/20 CHF (Crit	)05 lical Heat 1	7lux / Crit		ant Flux)	
Length	1 8.5	2	3	Mean	kW/m2	
Width	8.1	6.8	8.5	7.8	kw/m2	
Length	<u>1</u> · 92	2	oke Value 3	Méan	n	•
Width	113	192	191	132	8 min 8 min	
Observations: Melti Blist	ng ering					· · . ·
Note: Sample was co temperature of 23+/ 48 hours prior to t	-2degC and Relat	ordance wit ive Humidit	ch BSEN 132 Ly of 50+/-	38-2001 a 5% for a	it a minimum of	
Each specimen was t reconstituted fibre mass of 900 +/-50g/ reinforced cement b	underlay of nom m2 and clamped t	iinal thick	1ess 9.0 +/	–0.8mm ha	wing a bre	\$
		· · ·	*			*
149736 1		. ; ((	CONTINUED N	ext page)	PAGE 1	•
	• •			· . · · ·		
· · · · · · · · · · · · · · · · · · ·						
Australian Wook Texting Authority Ltd Copyright - All Rights Resorved	MATA - Chemical Testing of	iccredited by the Nationa of Textiles & Ralated Proj g of Textiles & Related Pr re Measurement	iucis :	Authonitics, Australia Accreditation No Accreditation No Accreditation No	983	
	The tests reported herein have to their identifying descriptions have warranty, implied or otherwise, as sample or somolas tasted. This docur and an intervel, This docur adventising providing the content Managing Director of AWTA Ltd.	a been provided by the o to the source of the tests ocument shall not be rep ment, the names AWTA	dient unless otherwise of samples. The above woduced exceptin fully A Textile Testing and A	stated. AWTA Ltd m test resulta relate on and shall be rendere WTA Ltd may be	akes no AVA (A ly to tho LIMITED d void k used in	
			All.	neli	Maar	
0204/5/05			APPROVED SIG		KCHAELA, JACKSON B.Sc.(Hons) MANAGING DIFFECTOR	

•



Australian Wool Testing Authority Ltd - trading as AWTA Textile Testing A.B.N. 43 006 014 106 1st Floor, 191 Racecourse Road, Flemington, Victoria 3031 RO. Box 240, North Melbourne, Victoria 3051 Phone (03) 9371 2400 Fax (03) 9371 2499

## TEST REPORT

TUFTMASTER CARPETS PTY LTD 1 BENNET STREET DANDENONG VIC 3175 CLIENT

1

TEST NUMBER 7-542086-AV 2 19/12/2005 20857 DATE 2 ORDER NUMBER :

JE. 22 DEC ...

DAND\

The test results relate to the behaviour of the test specimens of a product under the particular conditions of the test, they are not intended to be the sole criterion for assessing the potential fire hazard of the product in use

Aretralian Wool Tasting Author Copylight - All Pights Reserved wity Ltc



This Laboratory is accredited by the National Association of T 1574 Chemical Testing of Textiles & Related Products Mochanical Testing of Textiles & Related Products Accreditation No. Accruditation No. - Heat & Temperature Measurement Accreditation No. 1356



JACKSON B.Sc.(Hons)

MARAGING DIRECTOR

983

985

The tests reparted therein have been performed in accordance with its terms of accreditation. Remples, and their identifying descriptions have been performed in accordance with its terms of accreditation. Bemples, and their identifying descriptions have been provided by the dient unless otherwise stated, AWA Ltd maker no warrantly, implied or otherwise, as to the source of the tested samples. The above test results relate only to the sample or asmples tested. This document shall not be reproduced except in full end shall be rendered void it and analytic or alkored. This document, the names AWTA Taxile Testing and AWTA Ltd makers to used in adventising providing the content and format of the adventisement have been approved in advance by the Managing Director efAWTALtd.

APPROVED SIGNATORY

0204/5/05



Environmental Sertification Scheme

1018

93038

26/11/2008

. Licence Number

**Carpet Names** 

Licensee

LUMINARY 40. WENTWORTH 40

TUFTMASTER CARPETS PTY LTD



Label Number Environmental Certification Approved

ACCS Contract Grading ACCS Residential Grading Suitable for Stairs CHD \*\*\* REHD2 \*\*\*\*\*

Office Number

Certificate printed

26 November 2008

Allow Firth



Allan Firth Secretary ACCS

01071

Administered by the Carpet Institute of Australia Limited ABN 11 006 829 303 PO Box 7172, St Kilda Road, Melbourne Victoria 8004 Tel: (03) 9804 5559 • Fax: (03) 9804 5560 Email: info@carpetoz.com.au • www.carpetinstitute.com.au



Tony Lee Tile Pty Ltd	

# **Tiling Certificate of Compliance**

Subcontractor: Tony Lee Tile Pty Ltd ABN: 86 134 330 519 QUASAR CONSTRUCTIONS

2 0 JUL 2010

RECEIVED

Client: Company Name: Qua Sar Construction ABN: 86069663403

Project:

Name: The Corso manby

Site Address: 15. 15a - 17 The corso manly NSW 2095

Subcontract works or products

Area	Product		
wet Area wall	SKhemp 2310 K (300/00)		
4 Iloov	Skheme stoll ritoxiso)		
External Wall	«Kheme 23351 1 (00 × 600)		
Walk way and starr	SKheme po 503 ( 500×500)		

Warranty period is 5 years from the date of issue indicated on this certificate.

The subcontractor warrants that all work performed and materials supplied comply with the specifications and Australian Standards and the Building code of Australia; BS 6431, AS 2358, AS 3972, AS CA27.

The subcontractor promises to replace or make good to the reasonable satisfaction of the client, any of the works or products which, within the warranty period, are found to be of lower standard or quality.

Signed

Tony Lee Lic. No. 163150C

Date of Issue of 7 /2010

 Tony Lee Tile PTY LTD
 ABN 86 134 330 519

 P.O. BOX 308 Pymble, NSW, 2073

 Ph: 0419 488 460
 Fax: 02 9687 5274

 Email: tonylectiling@gmail.com



# Waterproofing Certificate of Compliance

Subcontractor: Tony Lee Tile Pty Ltd ABN: 86 134 330 519 QUASAR CONSTRUCTIONS

2 0 JUL 2010

RECEIVED

Client:

Company Name: Octa Sar

АВИ: <u>86069663403</u>

Project:

Name: The Corso manly

Site Address:

Waterproofing works and products:

Date	Area	Membrane	Recommended glue
15 16/2010	wat Atea	Themeo	Coment Base

Warranty period is twelve (12) years from the actual completion date of the whole of the works.

The subcontractor warrants that all waterproofing performed and materials used on the aforementioned projects on the specified dates conforms to the Australian Standards 3740.

The subcontractor promises to make good to the reasonable satisfaction of the client, any of the waterproofing which, within the warranty period, are found to be of lower standard or quality.

Signed

Tony Lee Lic. No. 163150C

Date 15 (7 /2010

Tony Lee Tile PTY LTD · ABN 86 134 330 519 P.O. BOX 308 Pymble, NSW, 2073 Ph: 0419 488 460 · Fax: 02 9687 5274 Email: tonyleetiling@gmail.com

# TREMCO **Vulkem Non-Exposed** Membrane

# 02/05 2 Pages PRØDUCT DATA SHEET

### ONE PART URETHANE WATERPROOFING

MEMBRANE

### Key Benefits Summary

- Permanently flexible 600%
- Meets requirements of AS3740-2004
- Compatible with TREMIX ceramic tile adhesive ۵
- Π. Primerless single pack product
- đ Fast curing
- Compatible with Metz C26 tile adhesive
- High strength and puncture resistant
- Ľ Vertical and horizontal applicationsd
- Easy to apply
- Resistant to range of chemicals and pollutants

### **PRODUCT INFORMATION**

#### DESCRIPTION

Vulkem Non-Exposed Membrane le a single pack elastemeric, moliture curing high tensile strength and tough curing polyurethane membrane. It auras to form a rubbar membrane surface that provides waterlight substrates.

Vulkem Non-Exposed Membrane may be used to apply a seamless monolithic waterproof membrane to concrete substrates, AC sheeting compressed, timber decks which are well anchored and primed. Simple, easy to follow procedures and use of conventional equipment and tools or spray equipment permit fast, sure and secure application,

#### **BASIC USES**

For :

- Wet Areas
- Ľ **Roof Terraces**
- Dacks Belconies
- D Laundries Kitchens
- D
- Concrete Substrate Plazas Shower Receases Þ

### **USAGE GUIDELINES**

One part urethane, Vulkem Non-Exposed Membrane bonds firmly to clean, dry concrete and well anchored wood substrates. It retains its integrity even if substrate movement causes bairline cracks of up to 1.5mm, if out or damaged, Vulkem Non-Exposed Membrane will prevent water migration between it and its substrate. Vulkem Non-Exposed Membrane can be finished after a 48-72 hours cure at temperatures over 15.8°C. A Quick Cure Catelyst can be utilized for a fast track application procedures,

### SUBSTRATE PREPARATION

Concrete should be cured for 21-28 days Ľ

 Remove all dirt, dust, plaster, cement droppings, protructors, of and other cantaminants. Fillscrew holes
 To the wait/floor junctions and the floor/hob, hob/ wall joints within the shower tray, apply filtet bead of Tremco PU1 Polyurelbane Sealantas a bond breaker. Apply sealant around floor penetrations, tep and shower rose and other discontinuities. Floor wastes in concrete shall be cut level with the floor. For sheet flooring, leak control flanges shall be fitted and fully sealed.

Cracks: non movement and helding cracks may be filled with a brush cost of Vulkem Non-Exposed Membrane. Movement cracks to be routed out, cleaned and filled with Tremco PU1 Polyurethene Sealant.

#### PRIMING

Vulkem Non-Exposed Membrane is generally a primeriess membrane on most clean substrates

All wood surfaces are to be primed using Vulkem Primer 171

All metal surfaces are to be primed using Vulkem. Primer 181

C Existing urethane membrane surfaces are to be primed using Vulkem Primer 191.

#### METHOD OF APPLICATION

Mix the Vulkem Non-Exposed Membrane to ensure no cellement of the material is in the boltom of the pail and the colour of the material is consistent with no streaks or strictions

CI All internal wet areas should be weterproofed to meetAS 3740-2004 requirements

Apply one coat of Vulkem Non-Exposed Membrane at specified coverage rates using both brush, roller or SQUEED68

Ensure the membrane is turned down into the floer waste or well sealed around the leak centrol flange and other penetrations. Ensure flashing angles are properly sealed across doorways. Check for cracks in the membrane when dry and rectify

Tremco TREMfix Tile Adhesive should be used to adhere tiles directly to membrane

Exposed Membrane may be Introduced when adhering directly to the membrane

#### COVERAGE

 Approximately 1.2L/m² at a dry film thickness of 1.0mm (approximately 16m² por 18.9L pail) to achieve the waterproof requirements as stated in AS 3740-2004

Ci Approximately 0.6L/m<sup>2</sup> at a dry film thickness of 0.5mm (approximately 32m\*per 1.89L pail) to achieve water resistant requirements as stated in AS 3740-2004 (vertical applications),

# *TREMCO* Vulkem Non-Exposed Membrane

### **TECHNICAL INFORMATION**

TYPICAL PHYS	ICAL PROPER	TIES
Property	<b>Test Method</b>	Result
Tensile	ASTM D-412	2MPa
Elongition	ASTM D-412	800%
\$100	ASTM D-412	414kPe
Herdness (Shore A)	ASTM C-601	20
Poel Strength concrete	ASTM C-794	30/bs,100% cah an

0.12matrie perms

UL 790 CLASS A FIRE RATING CAN/ULC - \$102.2 - M88 GLASS A RATING

E-96

### Wet Material Properties

Non Valatile Conte	nt ASTM D-1353	78% min
Viscosity, cps	Brookfield HBT	8-10.000
Cure Time	ASTM D-1840	48 Houra mex,
@ 25°C - 50% R.H Flash point	Scialiash	44.4 <b>-</b> G

### AVAILABILITY

Permeability

Vulkem Non-Exposed Membrane is available through your nearest Tranco office.

### HEALTH AND SAFETY PRECAUTIONS

Material Safety Data Sheet must be read and understood before use.

### **TECHNICAL SERVICE**

TREMCO has a team of qualified Technical Sales Representatives who provide assistance in the selection and specifications of produce. For more detailed information or service and advice call Customer Service on (02) 9838 2765 or fax (02) 9838 2955.

### GUARANTEE/WARRANTY

We warrant our products to be free of defacts and menufactured to meet published physical properties when tested according to applicable specifications and TREMCO standards.

Linder this warranty we will provide at no charge, product to replace any product proven to be defactive when applied in accordance with our written instructions and in applications recommended by TREMCO as being suitable for this product.

All claims concerning product defacts must be made within 12 months of shipment. Absence of such claims in writing during this period will contribute a weiver of all claims with respect to such product. This warranty is in lieu of any and all other warranties expressed or implied.

 TREMCO PTY LTD
 ABN 25 809 024 084

 Unit 1, 2 Park Rd, RYDALMERE NSW 2118 Australia
 Tei: (02) 9638 2755

 Tei: (02) 9638 2755
 Fax: (02) 9638 2955

 tremco@tremco.com.au
 Fax: (02) 9638 2955
alating pathylicity constru-ances (1 G in Construction

To:	Quasar Construction
Att:	Eric
Date:	Tuesday, July 20, 2010
Pages:	2 (including the cover page)

#### **RE: TECHNICAL SPECIFICATIONS / SLIP RATINGS**

Dear Eric,

We refer to your email seeking technical specifications in relation to the SKM-80503-80483 series. Please find attached the test results providing slip ratings in relation to the tiles.

We note that we are providing this technical information without any information being provided by you as to the ultimate environment in which these tiles are to be placed. The suitability of these tiles for the environment in which they are to be placed is your responsibility.

While these tiles may achieve an acceptable rating in a laboratory test, it is quite probably that the performance in-situ will be less than expected due to grouting, wear and tear, build up of residue or unforeseen circumstances. These results are there fore to be seen as a relative guide to estimate the ments of one tile versus another. Please read the following carefully, and also refer to the Australian Standards (table 3), which indicates locations that correspond to the relevant Pendulum and/or Ramp ratings.

We note even if these results have a value which may appear acceptable, these results must not be viewed to mean that Skheme Pty Ltd is providing any sort of warranty against the damages for slipping on tiles when wet.

You should at all times provide your client with notification that all ceramics tiles can be slippery, especially when wet. Variables such as floor levels, water, fat, oil and other contaminants affecting the tiles are beyond the control of the supplier. Many tiles, which can be slippery when wet, are commonly used in wet areas, such as bathrooms. Customers should be aware of the potential danger of wet ceramic tiles and seek advice from the relevant consultants as to the level of slip-resistance of any particular tile, and its suitability for the intended application, as no liability can be accepted for personal injury or accidents arising from slipping or falling etc, under any circumstances.

Should you have any further enquiries please do not hesitate to contact the undersigned.

Kind regards, Skheme Pty Ltd

Kim Lindsey Commercial Sales Support



Manufacturing & Materials Technology, Graham Road (PO Box 56), Highett, Victoria, Australia 3190 Telephone: 61 3 9252 6000 Facsimile: 61 3 9252 6244 Email: tiles@csiro.au Web: http://www.cmmt.csiro.au

**Registered Testing Authority - Building Code of Australia** 

26 March 2007

Our Ref. EN13 / 52 03/0212

### **TEST REPORT No. 3841.2s**

Requested by: on (date): Manufacturer: Product Desc.:	Pamesa Ceramics S.L. 22 March 2007 Pamesa Buxi Serles, Dust-Pressed Ceramic Tiles, Bush Hammered Finish 500x500mm
Sampling details: Where:	Deliveredi
Date:	22 March 2007
By whom: How (methods):	Courier N/A

The results reported relate only to the sample(s) tested and the information received. No responsibility is taken for the accuracy of the sampling unless it is done under our own supervision. CSIRO cannot accept responsibility for deviations in the manufactured quality and performance of the product. While CSIRO takes care in preparing the reports it provides to clients, it does not warrant that the information in this particular report will be free of errors or omissions or that it will be suitable for the client's purposes. CSIRO will not be responsible for the results of any actions taken by the client or any other person on the basis of the information contained in the report or any opinions expressed in it. The reproduction of this test report is only authorised in the form of a complete photographic facsimile. Our written approval is necessary for any partiel reproduction.

This test report consists of 4 pages

	SUMMARY OF SLIP RESISTANCE TESTS PERFORMED:	Result	Class
AS/NZS 4586:2004	Slip resistance classification of new pedestrian surface materials Appendix A: WET Pendulum (Four S slider): Mean BPN:	60	v
AS/NZS 4586:2004	Slip resistance classification of new pedestrian surface materials, Appendix D: OIL-WET Ramp Mean overall acceptance angle:	34.1°	R 12

In order to interpret the classifications, please refer to Standards Australia Handbook 197, An Introductory Guide to the Slip Resistance of Pedestrian Surface Materials, which recommends minimum classifications for a wide variety of locations.

It is important to realise that test results obtained on unused factory-fresh samples may not be directly applicable in service, where proprietary surface coatings, contamination, wear and subsequent cleaning all influence the behaviour of the pedestrian surface.



Manufacturing & Materials Technology, Graham Road (PO Box 56), Highett, Victoria, Australia 3190 Telephone: 61 3 9252 6000, Facsimile: 61 3 9252 6244 Email: tiles@csiro.au Web: http://www.cmmt.csiro.au

REPORT NO:3841.2sPage 2 of 4ISSUE DATE:26 March 2007MANUFACTURER:PamesaPRODUCT DESC:Buxi Series, Dust-Pressed Ceramic Tiles, Bush Hammered Finish<br/>500x500mm

### SLIP RESISTANCE CLASSIFICATION OF NEW PEDESTRIAN SURFACE MATERIALS

#### WET PENDULUM TEST METHOD

TEST CARRIED OUT IN ACCORDANCE WITH AS/NZS 4586:2004 (Appendix A)

Test Date: 26 March 2007

RESULTS:	Location:	Slip Resistance Laboratory	Rubber slider used: Four S Conditioned with grade P400 paper, dry
	Sample: Cleaning: Temperature:	Unfixed Acetone 23°C	

Pendulum Friction Tester: Stanley (S/N: 9234, calibated 13/6/05) Test conducted by: David Weeks

	Specimen 1	2	3	4	5
Last 3 swings	61	59	62	60	61
······	60	59	62	60	59
	60	59	61	60	59
Averages	60	59	62	60	60

Mean BPN : 60

CLASS:





Manufacturing & Materials Technology, Graham Road (PO Box 56), Highett, Victoria, Australia 3190 Telephone: 61 3 9252 6000 Facsimile: 61 3 9252 6244 Email: tiles@csiro.au Web: http://www.cmmt.csiro.au

REPORT NO:3841.2sPage 3 of 4ISSUE DATE:26 March 2007MANUFACTURER:PamesaPRODUCT DESC:Buxi Series, Dust-Pressed Ceramic Tiles, Bush Hammered Finish<br/>500x500mm

### SLIP RESISTANCE CLASSIFICATION OF NEW PEDESTRIAN SURFACE MATERIALS

#### OIL-WET RAMP TEST METHOD

TEST CARRIED OUT IN ACCORDANCE WITH AS/NZS 4586:2004 (Appendix D)

Test Date: 26 March 2007

Location: Slip Resistance Laboratory

Sample Fixed

Joint width: mm

Surface structure:

] Smooth X ] Profiled ] Structured

not tested

RESULTS

Mean overall acceptance angle: 34.1 °

Displacement space:

**CLASSIFICATION:** 

Slip Resistance Assessment Group:

R 12	
,	

**Displacement Space Assessment Group:** 

	Ĺ
-	



Manufacturing & Materials Technology, Graham Road (PO Box 56), Highett, Victoria, Australia 3190 Telephone: 61 3 9252 6000 Facsimile: 61 3 9252 6244 Email: tiles@csiro.au Web: http://www.cmmt.csiro.au

REPORT NO:3841.2sPage 4 of 4ISSUE DATE:26 March 2007MANUFACTURER:PamesaTILE DESC:Buxi Series, Dust-Pressed Ceramic Tiles, Bush Hammered Finish<br/>500x500mm

Date and Place

j

26 March 2007,

Highett, Vic

Name, Title and Digital Signature:

Ku

DAVID WEEKS Technical Officer

Tel: 61 3 92526064 Fax: 61 3 92526011 Email: David.Weeks@csiro.au

Consulting services are available if further detailed analysis of the test results are required.

PR:W260307-12:43:45



Manufacturing & Materials Technology, Graham Road (PO Box 56), Highett, Victoria, Australia 3190 Telephone: 61 3 9252 6000 Facsimile: 61 3 9252 6244 Email: tiles@csiro.au Web: http://www.cmmt.csiro.au

REPORT NO:3841.2sJSSUE DATE:26 MarcMANUFACTURER:PamesaTILE DESC:Buxi Ser

3841.2sPage 4 of 426 March 2007PamesaBuxi Series, Dust-Pressed Ceramic Tiles, Bush Hammered Finish500x500mm

Date and Place

26 March 2007,

Highett, Vic

Name, Title and Digital Signature:

Mh

DAVID WEEKS Technical Officer

Tel: 61 3 92526064 Fax: 61 3 92526011 Email: David.Weeks@csiro.au

Consulting services are available if further detailed analysis of the test results are required.

PR:W260307-12:43:45



Manufacturing & Materials Technology, Graham Road (PO Box 56), Highett, Victoria, Australia 3190 Telephone: 61 3 9252 6000 Facsimile: 61 3 9252 6244 Email: tiles@csire.au Web: http://www.cmmt.csire.au

Addendum 3841.2s **REPORT NO:** 26 March 2007 ISSUE DATE: MANUFACTURER: Pamesa Buxi Series, Dust-Pressed Ceramic Tiles, Bush Hammered Finish **PRODUCT DESC:** 500x500mm

### DETERMINATION OF Rz SURFACE ROUGHNESS

(Using a Taylor-Hobson Surtronic Duo roughness meter using a 0.8mm cut off length)

Test Date: 26 March 2007

#### RESULTS

Slip Resistance Laboratory Location:

Rz values

60 F
52.5
37.5
39.0
47.3
53. <b>6</b>
51.9
48.9
68.1
52. <b>9</b>
57.6

### Surface Roughness (Rz) mean = 50.9 microns

BS 7976:2002, Pendulum Testers, requires a different test foot preparation (lapping paper) for pedestrian surfaces that have a Rz roughness of less than 15 microns. This lapping paper tends to reduce the pendulum result, sometimes appreciably. CSIRO recommends the use of this procedure (CSIRO COF1) as an adjunct to AS/NZS 4586. It helps to discriminate among products that have marginal wet slip resistance and to identify those that may be dangerous if wet.

The measurement of the various aspects of surface roughness is complex given the number of potential roughness parameters. While there is still some uncertainty as to exactly what type of roughness needs to be measured, peak-to-trough roughness (Rz) gives a useful guide to the likely slip resistance in wet conditions. Research has suggested that hard floors need to have a slightly higher Rz roughness than polymeric floors for the same degree of safety in wet conditions, but whatever flooring material is used an Rz roughness value of at least 10 microns is required where wet slip resistance may be required. In circumstances where wetness is normal or expected, this figure should be increased by a factor of 2 or more.

Greater peak surface roughnesses are likely to be required where floors slope or where the floor is likely to become contaminated with high viscosity liquids.



Manufacturing & Materials Technology, Graham Road (PO Box 56), Highett, Victoria, Australia 3190 Telephone: 61 3 9252 6000 Facsimile: 61 3 9252 6244 Email: tiles@csiro.au Web: http://www.cmmt.csiro.au

REPORT NO:3841.2sPage 2 of 4ISSUE DATE:26 March 2007MANUFACTURER:PamesaPRODUCT DESC:Buxi Series, Dust-Pressed Ceramic Tiles, Bush Hammered Finish<br/>500x500mm

### SLIP RESISTANCE CLASSIFICATION OF NEW PEDESTRIAN SURFACE MATERIALS

#### WET PENDULUM TEST METHOD

TEST CARRIED OUT IN ACCORDANCE WITH AS/NZS 4586:2004 (Appendix A)

Test Date: 26 March 2007

RESULTS:	Location:	Slip Resistance Laboratory	 Rubber slider used: Four S Conditioned with grade P400 paper, dry
	Sample: Cleaning: Temperature:	Unfixed Acetone 23°C	 

Pendulum Friction Tester: Stanley (S/N: 9234, calibated 13/6/05) Test conducted by: David Weeks

	Specimen 1	2	3	4	5
Last 3 swings	61 60 60	59 59 59	62 62 61	60 60 60	61 59 59
Averages	60	59	62	60	60

Mean BPN: 60

**CLASS:** 

V



Manufacturing & Materials Technology, Graham Road (PO Box 56), Highett, Victoria, Australia 3190 Telephone: 61 3 9252 6000. Facsimile: 61 3 9252 6244 Email: tiles@csiro.au Web: http://www.cmmt.csiro.au

REPORT NO:	3841.2s	2	1 (1) 1	Page 3 of	4
ISSUE DATE:	26 March 2007		÷		۰.
MANUFACTURER:	Pamesa				
PRODUCT DESC:	Buxi Series, Dust-Pressed Ceran	nic Tiles, Bush Han	nmered Fi	inish.	
	500x500mm			1 - A	

SLIP RESISTANCE CLASSIFICATION OF NEW PEDESTRIAN SURFACE MATERIALS

#### **OIL-WET RAMP TEST METHOD**

TEST CARRIED OUT IN ACCORDANCE WITH AS/NZS 4586:2004 (Appendix D)

Test Date: 26 March 2007

Location: Slip Resistance Laboratory

Sample Fixed

Joint width: mm

Surface structure:	[ ]	Smooth
	[X]	Profiled
	ĨĨ	Structured

RESULTS

Mean overall acceptance angle:

Displacement space:

34.1 °

not tested

**CLASSIFICATION:** 

Slip Resistance Assessment Group:

R 12

**Displacement Space Assessment Group:** 



Manufacturing & Materials Technology, Graham Road (PO Box 56), Highett, Victoria, Australia 3190 Telephone: 61 3 9252 6000 Facsimile: 61 3 9252 6244 Email: tiles@csiro.au Web: http://www.cmmt.csiro.au

REPORT NO: ISSUE DATE: MANUFACTURER: TILE DESC: 3841.2s Page 4 of 4 26 March 2007 Pamesa Buxi Series, Dust-Pressed Ceramic Tiles, Bush Hammered Finish 500x500mm

Date and Place

26 March 2007,

Highett, Vic

Name, Title and Digital Signature:

M

DAVID WEEKS Technical Officer

Tel: 61 3 92526064 Fax: 61 3 92526011 Email: David.Weeks@csiro.au

Consulting services are available if further detailed analysis of the test results are required.

PR:W260307-12:43:45



Manufacturing & Materials Technology, Graham Road (PO Box 56), Highett, Victoria, Australia 3190 Telephone: 61 3 9252 6000 Facsimile: 61 3 9252 6244 Email: tiles@csiro.au Web: http://www.cmmt.csiro.au

REPORT NO: 3841.2s ISSUE DATE: 26 March 2007 MANUFACTURER: Pamesa PRODUCT DESC: Buxi Series, Dust-Pressed Ceramic Tiles, Bush Hammered Finish 500x500mm

### DETERMINATION OF Rz SURFACE ROUGHNESS

(Using a Taylor-Hobson Surtronic Duo roughness meter using a 0.8mm cut off length)

Test Date: 26 March 2007

Addendum

#### RESULTS

Location: Slip Resistance Laboratory

Rz values

1	52. <b>5</b>
2	37.5
3	39.0
4	47. <b>3</b>
5	53. <b>6</b>
6	51. <b>9</b>
7	48. <b>9</b>
8	68.1
9	52. <b>9</b>
10	57. <b>6</b>

### Surface Roughness (Rz) mean = 50.9 microns

BS 7976:2002, Pendulum Testers, requires a different test foot preparation (lapping paper) for pedestrian surfaces that have a Rz roughness of less than 15 microns. This lapping paper tends to reduce the pendulum result, sometimes appreciably. CSIRO recommends the use of this procedure (CSIRO COF1) as an adjunct to AS/NZS 4586. It helps to discriminate among products that have marginal wet slip resistance and to identify those that may be dangerous if wet.

The measurement of the various aspects of surface roughness is complex given the number of potential roughness parameters. While there is still some uncertainty as to exactly what type of roughness needs to be measured, peak-to-trough roughness (Rz) gives a useful guide to the likely slip resistance in wet conditions. Research has suggested that hard floors need to have a slightly higher Rz roughness than polymeric floors for the same degree of safety in wet conditions, but whatever flooring material is used an Rz roughness value of at least 10 microns is required where wet slip resistance may be required. In circumstances where wetness is normal or expected, this figure should be increased by a factor of 2 or more.

Greater peak surface roughnesses are likely to be required where floors slope or where the floor is likely to become contaminated with high viscosity liquids.



27 Beverley Crescent Marsfield NSW 2122 Phone 0416 224 460 Fax 02 9889 3004

19 November 2007

Slip Check Ref C81-R215

# **Test Report No. R215**

Slip resistance classification of new pedestrian surface materials AS/NZS 4586:2004 Appendix A (Wet Pendulum Test)

Requested by:	Skheme Pty Ltd
Product Manufacturer:	Studio Italia
Description:	Uptown Series – Matt Finish (dark chocolate)
-	Dust pressed vitrified ceramic tile, 300 x 300mm

Note: Please refer to Standards Australia Handbook 197:1999, An introductory guide to the slip resistance of pedestrian surface materials for guidance on the interpretation of these results. This report relies on the samples and information provided by the client. Slip Check Pty Ltd cannot accept responsibility for the actions taken due to the information provided within this report. The slip resistance of new surfaces can change significantly by processes including but not limited to; installation, surface treatments, maintenance, wear and contamination. Regular monitoring is recommended to assess changes in slip resistance.

#### **Results:**

Results: Test conducted according to: Location: Pendulum Friction Tester: Conducted by:	Slip Che Stanley l	AS/NZS 4586:2004 Appendix A Slip Check Pty Ltd Test Facilities, Marsfield. Stanley London (SN 0601; Calibrated 24 Jan 2006) Carl Strautins						
Date: Sample: Rubber slider used:	19 November 2007 Unfixed Four S			Temperature: Cleaning: Conditioned:		24°C Water Grade P 400 paper dry		
Specimen	1	2	3	4	5			
Mean BPN of last 3 swings	39	39	38	40	36			
Mean BPN of Sample:	39							
Class:	X							

4 9

Carl Strautins Principal Materials Scientist

Project One Corporation Pty Ltd trading as PROJECT ONE CONTRACTING 798 Parramatta Rd Lewisham, NSW 2049

Date: 22/07/2010

NBRS+Partners Level 3, 4 Glen Street Milsons Point, Sydney 2061 QUASAR CONSTRUCTIONS

2 2 JUL 2010

RECEIVED

### 15-17 The Corso, Manly Roofing, Sarking/Insulation & Access Roof Hatch Installation Certification

ATTENTION:

Dear

ROSECT ORSE <u>Connectors</u> hereby certify that the Roof Sheeting, have been installed in accordance with the manufacturer's have been installed in accordance with the manufacturer's have been installed in accordance with the manufacturer's of Sarking & Insulation for the MANUA Corso instructions, drawings, specifications and conform to Australian Standards and BCA Requirements. Installation of the access hatch and stair ladder conforms to AS1657. Refer to attached manufacturer's documentation for Fire Hazard Testing.

The information contained in this statement is true and accurante to the best of my knowlege

JAY Fox

Regards,

Name of Contractor:

Company:

Address:

PLOJEN ONE CONTRACTINE
798 PAREAMATTA LOND
LEWISHAM
02-9560 6274
02 9560 688

Date

Phone Number: Fax Number:

Signature



27<sup>th</sup> October 2009

Email; cp@dixgardner.com.au

Att; Mr C Parkinson

Dear Carl,

#### RE; BCA COMPLIANCE STATEMENT 15-17 THE CORSO MANLY DA No: 17/09

We have reviewed the construction documents issued for construction certificate approval and confirm their general compliance with the relevant sections of the BCA.

Included in this documentation is the provision for compliant disabled access to the retail tenancies and section J roof fabric and glazing.

Also note the windows have not been increased in area and no increase in fire load occurring. We have received no conditions or request from the council indicating any variance to this requirement.

Your independent detail inspection of the documentation should be undertaken to verify these statements prior to your certification.

Yours Sincerely NBRS+ Partners

**GRAHAM NICHOLAS** General Manager Reg; Architect 3159

2 McManus-Street McMahons Point, North Sydney NSW 2060 Australia T: 61 2 9922 2344: F: 61 2 9922 1308 Etarchitects@nbrsep.com.au W: www.nbrsep.com.au DEECTORS Ridey Smith reg. No 2268 + Graham Thorburn reg. No 5706 + Robert Stazs + Geoffrey Deane reg. No 3766 + Gany Holdinett reg. No 5286 + Andrew Duffin reg. No 5602 GENERAL MANAGER Graham Nicholas SENIOR ASSOCIATES John Baker + Barry Flack ASSOCIATES Vicki Van Dijk + Robert Gred + Jon West + Charles Vela NOEL BELL RIDLEY SMITH & PARTNERS PTY LIMITED ABN 16 002 247565