FITZGERALD BUILDING CERTIFIERS PTY. LTD.

ABN 63 119 997. 3/2A Pioneer Ave Thomleigh NeW 2120 ph 9980 2155 fax 9980 2166 ⊟

FINAL OCCUPATION CERTIFICATE

Occupation Certificate Number

oc

2008/370

Approval Date

27 05 08

Issued in accordance with the provisions of the Environmental & Assessment Act 1979 under Sections 109C(1)(b) and 109F Construction Certificate Number CC

2007/338

Approval Date

10 07 07

Council

Pittwater

DEVELOPMENT CONSENT NO

Name of Certifying Authority Name of Accredited Certifier

Accreditation Body

N0619/06

APPROVAL DATE

18 01 07

Fitzgerald Building Certifiers Pty Ltd

Paul Fitzgerald - No BPB0119 DIPNR, 20 Lee Street, Sydney 2000

Applicant

Mr John Paterson

Address

20 Cabarıta Rd Avalon NSW 2107

Owner

Address

As Applicant As Applicant

Subject Land Lot

7

DΡ

17704

No

20

Cabanta Rd Avalon

Description of Development -

Alterations & additions to existing dwelling

Building Code of Australia - Classification

1a

Value Of Work

\$

201,400 00

The building is suitable for occupation

Attachments

Pest certificate, Waterproofing certificate, Smoke alarm certificate, Engineers certificate

Record of Inspections,

1)	Commencement of Building Work	Satisfactory
2)	Piers prior to pour	Satisfactory
3)	Footings prior to pouring of reinforced concrete	Satisfactory
4)	Timber frame prior to lining	Not Required
5)	Waterproofing of wet areas	Not Required
6)	Stormwater pipes prior to backfilling	Not Required
7)	Pool Steel prior to pouring of reinforced concrete	Not Required
8)	Pool Fence prior to water in the pool	Not Required
9)	Final Inspection - issue of Occupation Certificate	Satisfactory

CERTIFICATION

! Paul Fitzgerald as the certifying authority am satisfied that

the building will not constitute a hazard to the health or safety of the occupants of the building a current development application is in force for the building a current complying development consent construction certificate has been issued for the building in respect to the plans and specifications for the building the building is suitable for its use under the Building Code of Australia and, all the pre-conditions of development consent have been satisfied

PCA Accreditation No BPB 0119
Accreditation Body Building Professionals Board

SIGNATURE OF PCA

DATE

27 05 08

Bayer Environmental Science





Warranty No

2007-10-1704

This Warranty covers damage by Subterranean Termites Termites) only

Bayer warrants that Kordon shall restrict the entry of Termites into the Building through the Kordon barrier for a period of ten (10) years from the date of installation

("Warranty Period")
This Warranty covers damage by Termites to structural timbers and internal timbers BUT DOES NOT INCLUDE damage by Termites to

(a) chattels of any nature whatsoever including (but without limiting the foregoing) antiques heirlooms paintings artwork and paintings and (b) any pergolas wiring extensions to the Building and

outhouses

If Termite infestation of the Building occurs as a result of the failure of the Kordon and damage by Termites is caused to structural timbers and/or internal timbers fixtures and fittings during the Warranty Period Bayer will without charge to the Owner

(a) repair the Kordon barrier where practicable ànd/or

(b) cause the repair or replacement of structural timbers and/or internal timbers so damaged

To the extent permitted by the Law of the State or Territory in which the premises are located

(a) the liability of Bayer under this Warranty is limited to a maximum of \$100 000 00 in respect of any one (1) warranty claim

(b) All répresentations and other warranties express or implied and whether arising by virtue of Statute or otherwise are excluded or limited as stated in this Warrantv

This Warranty shall only have effect if the Kordon is installed by an Accredited Bayer Installer

OWNERS RESPONSIBILITIES

The Owner of the Building during the Warranty Period (Owner'), at the Owner's expense arrange for thorough and regular inspection of the Building for the presence of Termites at intervals not exceeding 12 months by an accredited/licenced Timber Pest Inspector Where the Termite risk is high or the Building type is susceptible to Termite attack (e.g. North of the 26th parallel) more frequent inspections (3-6 months) should be undertaken

These inspection recommendations comply with those outlined in AS 3660 Termite Management Series and AS 4349 1-1995, Inspection of buildings

If Termites are detected or are found to have breached the Kordon barrier the Owner must, within 7 days of such detection notify Bayer

EXCLUSIONS
This Warranty shall be void and have no effect in any of the following circumstances

The Kordon barrier is damaged modified bridged or otherwise interfered with by any person or any act, fact, matter or thing beyond the reasonable control of Bayer The Building is structurally modified, altered or otherwise changed in any way which would or may diminish the effectiveness of the Kordon as a Termite barrier If at any

time during the Warranty Period, the Owner
(a) allows or fails to prevent accumulation of

(í) wood rubbish or timber against the Building AND (ii) finished ground level around the Building to a height which does not comply with the terms of the Installation Manual

(b) allows the barrier dividing the soil surface and the structure of the Building formed by the Kordon to be bridged or broken by any other material or matter through which Termites may by-pass the Kordon and

infest the Building
Termites shall enter the Building through any manner other than by a breach of the Kordon barrier If the Kordon is installed other than by an Accredited Bayer Installer



Date of Installation 14/09/2007 Installation Address 20 Cabarita Road Avalon NSW, 2107

Company Contact Company Name

Barry Slattery Orange Protector Pty Ltd

Address

PO Box 90 MacArthur Square NSW, 2560

Phone Number

1300 888 638

Accreditation Number N119


THIS WARRANTY SHALL BE VOID UNLESS THE KORDON HAS BEEN INSTALLED BY A BAYER ACCREDITED INSTALLER

Bayer will grant additional specific warranty conditions where required to accommodate high density commercial constructions government buildings etc on documented request

Bayer Environmental Science 391-393 Tooronga Rd Hawthorn East, VIC 3123

Bayer Environmental Science





NOTE This documen	t is to be attached to Warranty Docur	ment Number	2007-10-1704	
Date of Installation	14/09/2007	Job Type	Large Job - Miscellaned	ous
Installation Address	20 Cabarita Road			
	Avalon NSW, 2107	Product used		
			Product Width (mm)	Total SQM
		48	1000	4 80_
Builder	Mr John Paterson			
Phone number	02 99184646	-		
Owner	Mr John Paterson			
Phone number Local Council	02 99184646 Pittwater Council	Service Penetration		0.00
Phone number	02 99701111	<u>Kordon Kollars</u> Manual Collars		0 00 0 00
Company Contact	Barry Slattery	Maridal Collars	Total Kordon Installed	
Installer's Name	Andy Juggiah			·
Company Name	Orange Protector Pty Ltd			
Address	PO Box 90			
Addioso	MacArthur Square			
	NSW, 2560			
Phone Number	1300 888 638			
Fax Number	1300 888 639			
Accreditation Number	N119			
	A.			
Audi usad Cometo	Lynns	5 .	45/40/0005	
Authorised Signature		Date	15/10/2007	
Regular termite inches	ıll only protect(areas where the produ ctions as per the Australian Standard	ICT IS INSTAILED		
Extention to front of ex	xisitna dwellina 48 X TMB full under	treatment installed		

BARRENJOEY WATERPROOFING SERVICES

Office, 02 99400147 Mobile, 0401 032 084

DA No CC No

WA-1 COMPONENT CERTIFICATE FOR COMPLETION OF WET AREAS

Property DA No

20 Cabarita Road Avalon 2107

I Christopher Hopkins of Barrenjoey Waterproofing Services Being a qualified waterproofer, my qualifications being License No 128851c, hereby certify that the works have been inspected and have been completed in accordance with the appropriate standards and conditions of Development Consent. Australian Standards 3740-2004

Further, I am appropriately qualified and experienced to provide the certification for this project.

March 5 2008

One external wet area. Deck. Three internal wet areas. Bathrooms.					
Council use only	•••••••••••••••••••••••••••••••••••••••				
Records Officer: Received by	Date				

ABN 21 379040926 Lic No 128851c e-mail barrenjoeywp@optusnet com au



Attn Craig Formosa Fitzgerald Building Certifiers 22/05/08 Re 20 Cabarita Rd Avalon

To Whom It May Concern,

Smoke alarms complying with Australian Standards 3786-1993 have been installed at the above address

Yours Sincerely

Todd Richardson



Jack Hodgson Consultants Pty Limited Consulting Civil GEOTECHNICAL AND STRUCTURAL ENGINEERS

ABN 94 053 405 011

VS 24260 20th June, 2007 Page 1

The General Manager Pittwater Council PO Box 882 MONA VALE NSW 1660

Dear Sur,

20 CABARITA ROAD, AVALON Development Application No · N0619/06

On the 13th June, 2007 we inspected the pier holes for the proposed extension at the subject

The 6 pier holes inspected for extension had been taken to material of suitable bearing

At the time of the inspection some of the holes were filled with water at the base. We are of the understanding the water will be pumped from the holes and they will be cleaned out before concrete is poured

JACK HODGSON CONSULTANTS PTY LIMITED

J. D Hodgson M Eng.Sc., F.I.E.Aust., CP ENG

Civil & Structural Engineer Nper3, Struct Civil. No 149788

Director



Bruce Delprado B Sc., B E, M Eng Sc., MIEAust, NPER Structural Consulting Engineer ABN 17 658 258 654 3 Maytone Avenue, Kıllara 2071

9418 1373 TeL 9418 1135 Fax 0428 181 373 bdelprado@optusnet.com.au

2 March 2008

S Crosby Stephen Crosby & Associates Pty Ltd PO Box 23 Church Point 2105

0299996272

Dear Steve.

Alterations & Additions at 20 Cabarita Road, Clareville

Structural Engineering Inspection Certificate

A. Framing to the Main Residence

On 20 December 2007 I inspected the framing for the main residence (except for Bedroom 3 which was previously inspected by others) Most of the framing had been satisfactorily installed but a few items needed to be completed I was subsequently provided with photos of the finalisation of these outstanding items and they showed that they had all been satisfactorily completed with one exception. This related to the upper weld of TR1 to C2 as shown on Section 11 I was able to inspect this item on 29 February 2008 and it had been satisfactorily completed

Based on the above, I certify that the framing to the main residence (except Bedroom 3) has been satisfactorily completed structurally

B Reinforcement to the Carport Slab

On 29 February 2008 I inspected the reinforcement for the new carport slab. I certify that the work was structurally satisfactory with the following comment. A reinspection was not required

The top reinforcement needed to be cut back in places to maintain the required side cover Also the bottom fabric reinforcement needed to be cut back to maintain clearance from the drip grooves

Yours faithfully

Bruce Delprado

GEOTECHNICAL RISK MANAGEMENT PÓLICY FOR PITTWATER FORM NO 3 - Post Construction Geotschricel Certificate

	TOWN PATTERSON			
	Development Application for JOHN PATTERSON Name of Applicant			
	Address of site 20 CABARITA RD, CLAREVILLE			
Deciaratio	made by geotechnical engmeer on completion of the Development			
i DR L	OANIEL MACTENS & ASSOCIATES (Insert Name) (Trading or Company Name)			
	(Insert Name) (Trading or Company Name)			
on this the certify that	I am a geometrical engineer as defined by the Geotochnical Risk Management Policy for Pittwater I am authorised by the above			
organisado least \$2mil	in/company to issue this document and to certify that the organisation/company has a current professional indemnity policy of at life in prepared and/or verified the Geotechnical Report as per Form 1 dated referred to below			
Geolecim	Report Date: Report Date: Report Date: JANVARY 2006			
	Author J FUSTON the original structural design and where applicable the subsequently amended structural details (below listed) which have been ad into the completed project.			
I have inspected and/or am satisfied that the foundation materials upon which the structural elements (as detailed in the original and amended structural documents) of the development have been erected, comply with the requirements specified in the Geotechnical Report.				
I have inspected the site during construction and to the best of my knowledge. I am satisfied that the development referred to in the development consent D.A. No. 19/07 dated 18/01/07 dated 18/01/07 (D.A.No) (Date consent given)				
has been constructed in accordance with the intent of the Geotechnical Report, and the requirements of the conditions of Development Consent relating to the geotechnical issues (including any treatment and/or maintenance plan that may be required to remove risk where reasonable and practical).				
I am aware that Pittwater Council require this certificate prior to issuing an occupancy certificate for the development identified above and will rely on this certificate in regard to the development having achieved the Acceptable Risk Management* criterion defined in the Policy and that reasonable and practical measures have been taken to remove forespeable tak				
List of all	work as executed drawings and Ongoing Maintenance plans relevant to geotechnical risk management.			
Inclus	star Rail Details 24260-1A			
	Signature			
	Name DA DANIEL MARTENS			
	Chartered Professional Status CPERS - NPER, MIEAUS+ Membership No. 218 5379			
	Membership No 2/8 53/9			
	Company MARTENS & ASSUCIATES			



Jack Hodgson Consultants Pty Limited CONSULTING CIVIL, GEOTECHNICAL AND STRUCTURAL ENGINEERS

ABN 94 053 405 011

VS 24260A 7th June 2007 Page 1

The General Manager Pittwater Council PO Box 882 MONA VALE NSW 1660

Dear Sir,

20 CABARITA ROAD, AVALON Development Application No N0619/06

On the 1st June, 2007 we inspected the foundation material for the proposed inclinator at the subject address

At the time of our inspection the piers had been taken to material of adequate hearing capacity and stability for the loads likely to be imposed on it

JACK HODGSON CONSULTANTS PTY LIMITED

J D Hodgson M Eng Sc., F.LE Aust., CP ENG

Civil & Structural Engineer

Nper3, Struct. Civil. No. 149788.

Durector