

17 August 2023

Lisa Keighery
c/- TJ York Constructions
66 Ellery Parade
Seaforth, NSW, 2092

By e-mail: thomas@tjorkconstructions.com

**Removal of tree
at
888 Barrenjoey Road, Palm Beach
Job N° 201099**

To whom it may concern,

We refer to the defective and unsafe stone flagged retaining wall that requires demolition and reconstruction. The wall is located below and close to a large tree that sits within the zone of influence of the wall.

A report provided by Alliance Geotechnical (report number: 16815-GR-1-1) on the 2nd of August 2023 states that a safe batter cannot be achieved for the construction of the proposed new boundary wall without destabilising the tree and recommends that the tree is to be removed.

We endorse this evaluation and recommend that the tree is removed to provide safe soil batters on site.

Yours faithfully,

NORTHERN BEACHES CONSULTING ENGINEERS P/L



Stewart McGeady

BE (Civil), MIEAust., PDP, PRE, DEP.
(Director NB Consulting Engineers)

\\Nbads\nbc company\NBC PROJECTS\201099 888 BARRENJOEY ROAD, PALM BEACH (181128)\ENG Design\L002.docx