

Heritage Referral Response

Application Number:	DA2024/0077	
Proposed Development:	Alterations and additions to a semi-detached dwelling including swimming pool	
Date:	28/03/2024	
То:	Anaiis Sarkissian	
Land to be developed (Address):	Lot 1 DP 512753, 85 Griffiths Street BALGOWLAH NSW 2093	

Officer comments

HERITA	GF	COM	JEN	TS.

Discussion of reason for referral

The proposal has been referred as it is in the vicinity of State Heritage item listed in schedule 5 Manly LEP 2013:

Item I13 Street trees Griffiths Street (from Condamine Street to Boyle Street) Item I14 -Electricity substation - 81 Griffiths Street

Details of heritage items affected

Detail of heritage item affected by the proposal as listed in the Heritage Inventory:

Item I13 Street trees Griffiths Street (from Condamine Street to Boyle Street)
Statement of Significance

Listed for its aesthetic importance to the streetscape.

Physical Description

Note: There is no inventory sheet for this item. The listing is believed to cover the large established trees within the carriageway on the northern side of the street, closer to the Condamine Street intersection.

<u>Item I14 -Electricity substation - 81 Griffiths Street</u>

Statement of significance

Listed as an impressive Inter-War Georgian style substation, important landmark example of a utilities structure in this style.

Physical Description

1928 on the building. Two storey polychrome brick Inter-War Georgian revival substation. Features arched multipaned windows and shallow blind brick arches, corbelled parapet.

Other relevant heritage listings			
SEPP (Biodiversity and Conservation) 2021	No		
Australian Heritage Register	No		
NSW State Heritage Register	No		
National Trust of Aust (NSW) Register	No		

DA2024/0077 Page 1 of 2



RAIA Register of 20th Century	No	
Other	No	

Consideration of Application

The proposed development seeks consent for alterations to the ground floor, addition of a new first floor and a new pool, including refurbishment of existing carport.

The existing semi-detached dwelling is located in a highly prominent corner location that the first floor extension is going to be visible from a number of view points. The proposal retains portions of the existing semi-detached dwelling on the which is an intact Inter-war style semi, retaining its original built form, roof form, chimney, face brick walls, original fenestration, and internal features. Therefore, it is recommended that the integrity and character of the existing semi-detached building and the adjoining semi and the the impact of the proposed changes upon the character and heritage values of the semis should be carefully considered. The proposed bulk and scale is considered excessive (the proposed upper level floor to ceiling height is 2810mm) and the relation with the adjoining semi is considered unacceptable. The overall height can be reduced by using a 2.1m springing height for a gabled roof shape and using the roof volume for spatial generosity that will achieve a lowering of at least 710mm. This will reduce the dominance and impact of the proposed extension and show respect to the adjoining semi.

The current proposal is considered to not impact the significance of the heritage listed street trees, however the proposed bulk and scale is considered to be overwhelming in relation with the adjacent semi and to impact the existing heritage context of Griffiths Street and Boyle Street. Therefore, it is required to amend the proposal having regard to the controls and guidelines of Manly DCP: "3.2.1.1 Development in the vicinity of heritage items, or conservation areas," and "4.1.7 First Floor and Roof Additions"

Therefore, Heritage require amendments to the proposal.

Consider against the provisions of CL5.10 of Manly LEP2013
Is a Conservation Management Plan (CMP) Required? No
Has a CMP been provided? No
Is a Heritage Impact Statement required? No
Has a Heritage Impact Statement been provided? No

The proposal is therefore unsupported.

Note: Should you have any concerns with the referral comments above, please discuss these with the Responsible Officer.

Recommended Heritage Advisor Conditions:

Nil.

DA2024/0077 Page 2 of 2