

Water Management Referral Response

|--|

| То: | Adam Urbancic |
|---------|---|
| . ` ` , | Lot 32 DP 5464 , 41 Warriewood Road WARRIEWOOD NSW 2102 |

Reasons for referral

Council's Water Management Officers are required to consider the likely impacts.

Officer comments

This application has been assessed for compliance with the Water Management Report Rev 7 for 41 Warriewood Road and the Warriewood Valley Water Management Specification. The lot is limited to 65% impervious area.

Water management has largely been dealt with under the subdivision application.

The sediment controls are adequate, and they have the appropriately sized rainwater tank for the subdivision.

Sediment and erosion controls must be installed prior to any work on site and maintained until work is complete and groundcover re-established. Due to there being an online bio-retention water treatment basin, particular care should be taken to ensure sediment does not wash into the gutter, as the residents will be responsible for cleaning sediment out of the basin in future.

Referral Body Recommendation

Recommended for approval, subject to conditions

Refusal comments

Recommended Water Management Conditions:

CONDITIONS TO BE COMPLIED WITH DURING DEMOLITION AND BUILDING WORK

Installation and Maintenance of Sediment and Erosion Control

Sediment and erosion controls must be installed in accordance with Landcom's 'Managing Urban Stormwater: Soils and Construction' (2004) and the Erosion and Sediment Control Plan prepared by New South Homes with detail by SDS Engineering.

Erosion and sediment controls are to be adequately maintained and monitored at all times, particularly after periods of rain, and shall remain in proper operation until all development activities have been completed and the site is sufficiently stabilised with vegetation.

Reason: To protect the surrounding environment from the effects of sedimentation and erosion from the site.

DA2019/0770 Page 1 of 1