BPB Accredited Certifier No: BPB0043
Level 2, 41 Rawson Street Epping NSW 2121
Email: info@boycecorp.com.au

Ph: 9868 2855

Ref: N0690/07 CC #:BP10037

28 May 2012

The General Manager Pittwater Council PO Box 882 Mona Vale NSW 1660

Dear Sir,

Submission of Occupation Certificate 20 Palm Beach Road Palm Beach

Please find enclosed:

- 1. Occupation Certificate
- 2. Final Inspection Certificate
- 3. Critical Stage Inspection Certificate
- 4. Stormwater as executed plan
- 5. Certification Basix requirements
- 6. Photographs x 4, kerbing and landscaping
- 7. Engineers Certificate x 2
- 8. Geo-Technical Certificate Form 3
- 9. Final Fire Safety Certificate
- 10. Waterproofing Certificate
- 11. Structural Certificate and Inspection Certificates x 10
- 12. Termite Certificate
- 13. Basix Completion Receipt

Should any of the above documents not be received please advise me immediately.

Many thanks.

Peter Boyce

\$36 REC: 322386 29/5/12

Final occupation certificate (SF15) | 15 September 2011

7 |

BPB Accredited Certifier No: BPB0043
Level 2, 41 Rawson Street Epping NSW 2121
Email: info@boycecorp.com.au

Ph: 9868 2855

Your Ref: N0690/07

Fax: 9868 2655

28 May 2012

The General Manager Pittwater Council PO Box 882 Mona ValeNSW 1660

Dear Sir,

Final Inspection & Final Occupation Certificates 20 Palm Beach Road Palm Beach

Please find enclosed copy of Final Inspection Certificate and Final Occupation Certificate for the above property issued under N0690/07.

Enclosed please find a cheque for \$36.00 for registration of the Final Occupation Certificate.

Yours faithfully

Peter Boyce

BPB Accredited Certifier No: BPB0043 Level 2, 41 Rawson Street Epping NSW 2121 Email: info@boycecorp.com.au

Ph: 9868 2855

Fax: 9868 2655

Final Occupation Certificate

Certificate no. BP10037 SECTION A. The Application 1. Details of the applicant Mr Ms Mrs Dr Dr Other: First name Family name/Name of company and ABN Grainne Meehan Unit/Street no. Street name c/- Michael 64 Goodhope Street Robilliard Suburb or town State Postcode Paddington NSW 2021 2. Details of the property Unit/Street no. Street name 20 Palm Beach Road Suburb or town Postcode Palm Beach 2108 Lot no. Section A DP / SP no. Volume/folio DP 342891 3. Description of the building or part of the building Demolition of existing dwelling and construction of a new two storey timber and brick dwelling with a vaulted copper roof. 4. Development Consent N0690/07 4. Class of building Class* of the proposed building under the Building Code of Australia. *Note: If parts of the building will have different classes, include all classes. 1a

5. Date of the application		
23 May 2012		
6. Date application received by the	certifying authority	
17 May 2012		
SECTION B. Certifying authority		
Peter Boyce		Accreditation no. BPB 0043
Address Level 2, 41 Rawson S	St	
Epping NSW 2121		
SECTION C. Attachments (tick box/s	as applicable)	
Fire safety schedule	Fire link conversion schedule	Fire safety certificate
SECTION D. Certification		
the building is suitable for occupation a fire safety certificate has been issue	sued with a respect to the plans and specification or use in accordance with its classification unde	
(Must only be signed by the	e PCA)	
SECTION E. Date		
Date of this certificate	3 MAY 2012	
SECTION F. Attachments (tick as app	licable)	
Fire safety certificate	Fire safety schedul	le

BPB Accredited Certifier No: BPB0043
Level 2, 41 Rawson Street Epping NSW 2121
Email: info@boycecorp.com.au

Fax: 9868 2655

Ph: 9868 2855 Ref: BP10037

23 May 2012

Inspection Certificate

Development Consent No.	N0690/07
Construction Certificate No.	BP10037
Council Area:	Pittwater Council
Property Address:	20 Palm Beach Road Palm Beach
Owners Name:	Grainne Meehan
Address:	c/- Michael Robilliard Architect 64 Goodhope Street Paddington

<u>Final Inspection:</u> A final inspection of the building work at the above property has revealed that the work has been completed generally in accordance with the approved plans, conditions of the Development Approval, and the requirements of the Building Code of Australia.

Certifier

Date: 23 May 2012

BPB Accredited Certifier No: BPB0043
Level 2, 41 Rawson Street Epping NSW 2121
Email: info@boycecorp.com.au

Fax: 9868 2655

Ref: BP10037

23 May 2012

Ph: 9868 2855

Critical Stage Inspection Certificate

Development Consent No.	N0690/07
Construction Certificate No.	BP10037
Council Area:	Pittwater Council
Property Address:	20 Palm Beach Road Palm Beach
Owners Name:	Grainne Meehan
Address:	c/- Michael Robilliard Architect 64 Goodhope Street Paddington

Critical Stage Inspections:


Commencement	Satisfactory
Slab	Satisfactory
Frame	Satisfactory
Waterproofing	Satisfactory
Stormwater	Satisfactory
Final	Satisfactory

Certifier

Date: 23 May 2012



Stormwater As-Installed drawing supplied by Karl King for 20 Palm Beach Rd, Palm Beach.



MICHAEL ROBILLIARD AND ASSOCIATES PTY LTD

64 Goodhope street

Paddington 2021 tel 02 9331 2232 mob 0431 295512

16th May 2012 Peter Boyce and Associates Level 2 41 Rawson street Epping 2121

Dear Peter and Lyn 20 Palm Beach road, Palm Beach: Meehan House DA 690/07

Peter Boyce No 2: Condition B10 The requirements of Basix Certificate 168618S_02 have been met.

Peter Boyce No 3: Condition B12, Screen planting has been planted along the road verge in accordance with this condition.

Peter Boyce No 4: Condition B18: the redundant garage has been replaced with landscaping in accordance with the approved landscape plans.


Peter Boyce No 8: Condition E9 a photographic record of the condition of the street is attached

Peter Boyce No 9: No lift has been installed on this property


Yours faithfully


Michael Robilliard and Associates Pty Limited

principal











Jack Hodgson Consultants Pty Limited CONSULTING CIVIL, GEOTECHNICAL AND STRUCTUAL ENGINEERS

ABN: 94 053 405 011

VS 24761 28th March, 2012 Page 1.

The General Manager Pittwater Council PO Box 882 MONA VALE NSW 1660

Dear Sir,

20 PALM BEACH ROAD, PALM BEACH **Development Application No: N0690/07**

No part of the development referred to in the "Risk Analysis & Management for Proposed Additions & Alterations at 20 Palm Beach Road, Palm Beach dated 12th October, 2007 requires frequent or regular Geotechnical inspections.

The maintenance conditions in section 10.8 of the report refer to general good maintenance and construction on slopes and are not specific to the property. They are not included in the report with the intent of being added to the title by a Positive Covenant.

JACK HODGSON CONSULTANTS PTY. LIMITED.

Ben White M.Sc. Geol., AusIMM., CP GEOL.

No. 222757

Engineering Geologist.



GEOTECHNICAL RISK MANAGEMENT POLICY FOR PITTWATER FORM NO. 3 – Post Construction Geotechnical Certificate to be submitted with Occupation Certificate or Subdivision Certificate

	Development Applica	eation for	
		Name of Applicant	
	Address of site2	20 PALM BEACH ROAD, PALM BEACH	
Declaration	on made by geotechni	nical engineer on completion of the Development	
I,	BEN WHITE	on behalf of Jack Hodgson Consultants Pty Ltd_	
	(Insert Name)	(Trading or Company Name)	
on this the	28TH MARCH, 201	112	
Policy for F a current p referred to	Pittwater • 2009. I am aut rofessional indemnity pol below.	ngineer, Engineering Geologist and/or Coastal Engineer as defined by the Geotechnical Risk Manager uthorised by the above organisation/company to issue this document and to certify the organisation/co olicy of at least \$2million. ; I prepared and/or verified the Geotechnical Report as per Form 1 dated	ment impany
Geotechn	ical Report Details:	NALYSIS AND MANAGEMENT FOR PROPOSED ALTERATIONS AND ADDITIONS AT 20	
	PALM BEACH ROAD,		
	Report Date: 12-10-20	2007	
	Author: BEN WHITE	:	
	Author's Company/O	Organisation: JACK HODGSON CONSULTANTS PTY LTD	
Report an	d the Construction Cert	ents) of the development have been erected, comply with the requirements specified in the Geo rtificate approved Structural Plans. site during construction and to the best of my knowledge, I am satisfied that the development re d	
D.A. No.	N0690/07	Date consent given16-6-2008	
Onsent arplan that m	nd the Construction Certi	in accordance with the intent of the Geotechnical Report, and the requirements of the conditions of Di dificate approved Structural Plans relating to the geotechnical issues (including any treatment and/or rave risk where reasonable and practical).	evelopment maintenance
⊠ will rely on reasonable	this certificate in regard	ster Council require this certificate prior to issuing an occupancy certificate for the development identifi d to the development having achieved the "Acceptable Risk Management" criterion defined in the Polic is have been taken to remove foreseeable risk.	ied above ar cy and that
List of all	work as executed draw	wings and Ongoing Maintenance plans relevant to geotechnical risk management.	
10.8.1	The property is t	to be maintained in good order and in accordance with the guideling	es set
out in	CSIRO BIF 18	8 "Foundation Maintenance and Footing Performance: A Homeowalian Geomechanics Article "Landslide Risk Management Concept	s and
	nes" May 2002.		3 and
	-	itenance is required	- 1
10.0.2	140 special manie	Monanio 15 Foquirod	
		Signature Bulliule	
		Name BEN. WHITE	
		Chartered Professional Status MScGEOLAusIMM	
		Membership No. 222757	
		Company Jack Hodgson Consultants Pty Ltd	

Page 1

El Covenant Not recessary to Sahsty his DH Conditions





Jack Hodgson Consultants Pty Limited

CONSULTING CIVIL, GEOTECHNICAL AND STRUCTUAL ENGINEERS

ABN: 94 053 405 011

VS 24761 28th March, 2012 Page 1.

The General Manager
Pittwater Council
P O Box 882
MONA VALE NSW 1660

Dear Sir,

20 PALM BEACH ROAD, PALM BEACH Development Application No: N0690/07

No part of the development referred to in the "Risk Analysis & Management for Proposed Additions & Alterations at 20 Palm Beach Road, Palm Beach dated 12th October, 2007 requires frequent or regular Geotechnical inspections.

The maintenance conditions in section 10.8 of the report refer to general good maintenance and construction on slopes and are not specific to the property. They are not included in the report with the intent of being added to the title by a Positive Covenant.

JACK HODGSON CONSULTANTS PTY. LIMITED.

Ben White M.Sc. Geol., AusIMM., CP GEOL.

No. 222757

Engineering Geologist.



FINAL / INTERM FIRE SAFETY CERTIFICATE (FORM 15)



Under the Environmental Planning & Assessment Regulation, 1994


Type of Certificate	☑ Final □	Interim (tick one)		
Identification of Building	Lot No., DP or SP:			
Identification of Building	Street:	Palm Beach Road		
	Side of street:	East		
	Nearest cross street:	Sunrise Road		
	House / unit no. or nat	me: 20		
Owners details	Name:	Meehan Residence		
	Address: 20 Palm Beach Road, Palm Beach 2108			
Date of assessment	2/12/2011			
Certificate Name / agent	I, Malcolm Custer of MSC Electrical Services Pty Ltd Certify that;			
See Note 2 Assessment	assessed by a pers qualified to do so, a have been properl performing to a sta	ial fire measures listed below has been son (chosen by me) who was properly and was found, when it was assessed, to y implemented and to be capable of andard not less than that required by the fety schedule for the building for which		
See Note 3 Relevant Fire Safety	the certificate is issue			
Schedule	b) The information contained in this certificate is, to the best of my knowledge and belief, true and accurate.			
Date of Certificate				
	Dated this 2nd day of D	ecember, 2011		
Particulars	Whole / Part – Description of Smoke De	on of part (where applicable). etectors.		

Essential / critical fire safety measures	Standard of performance
Smoke detectors for domestic premises,	AS 3786-1993 & Part 3.7.2 of BCA

Malcolm S. Custer - MSC Electrical Services Pty Ltd

Agent signature





WATERPROOFING SERVICES waterproofing with care

WATERPROOFING CERTIFICATION CERTIFICATE OF COMPLIANCE

16 April 2012

The Construction Connection
Attn: Tim Rooney
PO Box 334
AVALON BEACH NSW 2107

Phone:

9973 2070

Fax:

9918 3059

RE: 20 PALM BEACH ROAD, PALM BEACH

This letter is to certify that all wet areas at the above mentioned address have been waterproofed using a liquid membrane system in accordance with manufacturers' recommendations and complies with Australian standards (AS 3740).

Regards,

David Brown

DAVID BROWN

FO Box 445, Mirando NSW 2228 ABN 24 002 792 305 E superiorypt hotmail.com T 9525 7075 F 9525 6466 M 0419 466 466



Consulting Structural + Civil Engineers

ACN 003 797 911 ABN 99 003 797 911

583 Darling Street, Rozelle NSW 2039 Telephone: 9555 7230 Facsimile: 9555 7239 Email: office@birzulisassociates.com

23 March 2012

Principal Certifying Authority c/- Michael Robilliard & Associates Pty Ltd 64 Goodhope Street PADDINGTON NSW 2021

Dear Sir,

STRUCTURAL CERTIFICATE

NEW DWELLING AT 20 PALM BEACH ROAD, PALM BEACH

This is to certify that we prepared structural engineering drawings No. 4311 -S01 to S06 of the structural details for the above project. The structural engineering design and detailing was carried out in accordance with the relevant Australian Standards and the Building Code of Australia.

We have also carried out visits of inspection of the building works in progress. The works as inspected where found to be in accordance with our drawings and thus structurally adequate.

Yours faithfully

for Birzulis Associates Pty Ltd



BIRZULIS ASSOCIATES PTY LTD 2 SITE INSPECTION REPORT

583 Darling Street, Rozella NSW 2039 (A.c.N. ogs 797 911) Telephone (02) 9555 7230 Facsimile (02) 9555 7239
PROJECT: 20 VALM BESCH NO FALM GEACH DATE: 20 10 10 PROJECT NUMBER: 431
ITEMS INSPECTED: STANCAULO TULI DESTINIA
WITHOUTH DETT JANETOUTE SHIT I
EDANATIONALI MILANEMEN ES OF LASINA
TO 112 THE STANCENEL BOTTONS
COMBINIO COMBINIO DE COMBINIO
CARONAL STUMM BE RODAD
6010 DIZ 4 CI67 056
EGLEPET SHS. 24 DUSD BUCK WALLS TO BATHMON
ANER TO BE RHONED TO SLADS
TOP ABJUL & BE 220 BRICKWORK
P2 DISCOUSED ON WLEY
3 AWHING DETAILS TO FILLOW.
le Lau Cut Fon
E-20 10 10
NB: If the above involves a variation to the contract; the builder shall obtain approval from the Contract Administrator before proceeding with the work, otherwise no claim may be accepted.
Distribution ☐ Client
SP5:2/Form Ins01 Rev0/April 1996

BIRZULIS ASSOCIATES PTY LTD. SITE INSPECTION REPORT

PROJECT:	20	PALM BY	He. K	20 1	Im Ber	k //	i i
DATE:	7/1		PROJE	CT NUMI	3ER:	3//	
		Rein					
							25
addira interaction	ಪರ-ಮ್ಲಿಷಣ ಹಿನಿಮಿ.	t her	Chryslatin car	45 <u>(19</u> 16) 4 (1977)			
Acce	PTABLE	= Exc	EPT	oek.			
- 1	e u Nesc	AROUND	, PEr	JETRAT	od, i.e.	211	Z
1	T. 0.1	BOHOM	600	0,0-	Mag die	12 /N	En
				498. J. 138 11 18	CLET		
URECTI	τ ω .				/ i:		را او در اور در اور
6	XTCA	, N16 C	, (10 0	(ENTR	Es Hy	JACEN 7]
o Ner	leve	TRATION	1/3	Viscus	sep.		
1							
	1						
)/		(
	ψ						
							egi. J
							i vi g veg

Contractor

Rev0/April 1996

Distribution.

SP5.2/Form Ins01

BIRZULIS ASSOCIATES PTYLETD

ROJECT: <u>Mee</u> hni	J Hous€			
ATE: 27/8	in hat sind of a finding 54	DJECT NUMB	er: 43	
EMS INSPECTED:		かたまり さんしょ デニア とうりがんしょく	in the second of	
FRAME GON	ermlly	//3 /E	N SHEL	, V.C.
ACCEPT &	KCEPT			
-70	BEAMS	(HANIA	ED 16	
그 그 그들은 학생들은 사람들은 사람들이 되는 것이 없는 것이 없는데 없는데 없었다.	大型投資的人,有關自己不可以 人名德		and the first transfer of the second	
100 UC - 7.	o Be (HECK E	DY	
ONFIRMED S	n RUCTUA	11249		
Ω				
$M-H_{-}$				
All				

Rev0/April 1996

BIRZULIS ASSOCIATES PTY LTD SITE INSPECTION REPORT

A STATE OF THE STA	SW 2039 (A.C.N. 003 797 911) Telephone (02) 9555 7230 Facsimile (02) 9555 7239
	PACIN BEACH RO. PACM BEACH
	19 PROJECT NÜMBER: 4311
ITEMS INSPECTED:	CF GAMAGE SUAS
ME HY	ent coundstill en
	ement thutur for
THE AS	anos enally eve
TWU 70	BE IN ACCOMANACE
	E CTNUCTORUSE DOFAILS
trues, s	LOT MORSETZINA
CONCURATION	
	Pan Mancustono
	$rac{1}{2}$ $rac{1}{2}$ $rac{1}{2}$

NB: If the above involves a variation with the work, otherwise no cleim m	to the contract, the builder shall obtain approval from the Contract Administrator before proceeding	ġ.
with the work, outerwise no clean m	ay de accepted.	
Distribution	□ Client □ Architect □ Contractor □	
SP5,2/Form Ins01	Rev0/April 1996	<u> </u>
		100

BIRZULIS ASSOCIATES PTY LTD. SITE INSPECTION REPORT

583 Darling Street, Rozelle NSW 2039 (A.C.N. 003 797 911) Telephone (02) 9555 7230 Facsimile (02) 9555 7239
PROJECT 20 Prim Brenzis ND Paun Goach
DATE: 2 8 10 PROJECT NUMBER: 4311
ITEMS INSPECTED: FINST FLOOR CLAC
WE HOUS INFO ESTED TWO
4名年90年,但中国各种的制造的主动的,可以可以是实际中的工程的影响中的最后上现金的"导展"等的影响。对于,只知识为中央工作等等的企业中。
LENARONCEMENT LAW-UP FON
The Anous & Haus Found
TWU TO BE COMMONAUM IN
TO CO
ACROMANCE WITH THE STWOTING
JOHN PUBLICH POL
1) HEATING COILS BUT TO BUT PLACED
MANAUL 106 VOIMENT
Charlet Colonial Academic Company
2 ADDITION 2 BANK NAQUINOD AT
하는 경기 사람들이 가득하는 것이 있다고 하는데, 이미를 바꾸게 되었다는 것이 나를 다고 있다.
CAMORIOR BALCOUN
3 ADDITIONAL LAUGH DR (500 TIED)
2 ADDITIONAL LANGER OF STARTERS FOUR NIC WAY - ENCIR ROLL
race race
CARROL OF THE CONTRACT OF THE
C-1/R/C
NB: If the above involves a variation (a the contract, the bullier shall obtain approval from the Contract Administrator before proceeding with the work; otherwise no claim may be accepted.
Distribution
The state of the s

SP5:2/Form Ins01

BIRZULIS ASSOCIATES PTY LTD SITE INSPECTION REPORT

	35 Y 1795 1 178	tas-talianentii Ni	er e	risery in all	QA, P.P.L	5 7230 Facsimile (
Pi	ROJECT: "	10 /A	<u> </u>	B&∧⊂	14 UV	- VALUE	BEACH
D,	ے؟ . :ATE	$\parallel \neg : 1$.(PROJECT	NUMBER:	4-3	
第四日的 相同的现在分词		1990 Trush Village	1 263 fg 1 1 33			us e	
			YWF.A				
\$47	و پور پ	so in	\dot{x} .	45772	10 TECN	1 J	
and the first of t		1.11 (1 5 1.15 1)	10.00	Annual Control of the	The second second second		
					و و ال	~ M- CUT	M CT (A)
1.4		-wex	70 rw		ع√-تا–فا	SICE.	
74	(S)	-\-\-\-\-\-\\					
			co a	- 1) c	3-CN	~ <u> </u>	F-Nowla
	0 m.n			#11	News 1	2/7	5106-
							3016
					1		
A		e					
\mathcal{T}							
		\ _ = ₁ -					
	1016	2 4 o	> c/c				
	e∰art i i i i i i i i i i i i i i i i i i i	ے 40 ہے۔ م					
	1,01	2 Nis	11112	~			
) To	CILIC	¥ -	Sc	7- ,-	- 4	- & C9	-1
k-0.6.	- C	C 5 4	TIST N	V 10 W			
		7,0					
S S HO	the above involves	a variation to the co	ontract, the build	ONS ler shall obtain app	roval from the Contre	act Administrator befor	e proceeding
· with th	e work, olherwise i	no claim <i>may</i> be ac	cepted.	10-	aln	(1)	
Distri	bution	" □ Clie	ent ا	Architect	Contractor		
SP5.4	2/Form Ins01					Rev0/April 1	996
		A Section 1		是一个"	1886年(1915年)		等的线, 是198

E MULL TO TO SITE INSPECTION REPORT

583 Darling Street, Rozelle NSW 2039 (A.C.N. 003 797 911) Telephone (02) 9555 7230 Facsimile (02) 9555 7	7239
PROJECT: 20 PLUS BEACL NO PAUN DO	ACV
DATE: 7314 10 PROJECT NUMBER: 4311	agantiga.
items inspected: Vichi Postiuc Obance	
tont dependent and the solvi	
Delikencemian Lan-or ron	
THE ROOVE & HAVE FOUND	
THIS TO BE 114 ACLOMANCE	
Make a service was maken	S
TIME SATIFICATION TOWN	
OWENDEND WO	
Par May Clipfond	
22/4/10	

NB: If the above involves a variation to the contract, the builder shall obtain approval from the Contract Administrator before proceeding with the work, otherwise no claim may be accepted.

tricker to be the firm that the term is particulable to the contract of		The second of th	<u> </u>
tera dia bandaran dari di Lara da di Araba di A		CALLS TO COLUMN TO A COLUMN TO THE TAX OF THE COLUMN TWO	and the second of the second o
istribution	Cliont DA	robitant Di Contractor	in in bord of the transfer of the day of
isitipution			and the second of the second o
NO 672 (1077 11 12 A. H. H. L. L. L. 1988 11 C		見い 走る かいしょく あわいてのあげる アルディー・コンプ	- (2) カー(2017年) - ディー 二、カール コンディン 特定

SP5.2/Form Ins01

Revo/April 1996

E MILA TCO

Distribution

SP5.2/Form InsO1

□ Client

BIRZULIS ASSOCIATES PTY LTD SITE INSPECTION REPORT

	583 Darling	Street, Rozelle	NSW 2039 (A.C.	N. 003 797 911) Tel	ephone (02) 95	55.7230 Facsim	ila (02) 9555,7239
	PROJECT	: 1.0	امس	يالجعة	a No.	. Paun	L'ISBLEV
	医前的 医洛勒森氏征动脉管	图形 110 电阻量数数 中華	240 year, 240 year	PROJEC1	·罗铁成新译的	: <u>'</u>	Z V 1
	ITEMS IN	SPECTED	Pic	-n.s.,			
	We-	MA	UG	11416	ع ھع	سا √ 0ر	+0
D	عالم	ولتار	5 (%)	Prent	IL I	مهومد	e C J
	1400		Rouw	τ	W _8	M477	=p.vAc
Ŋ		_U_U_V	1 1/2	-	- 25	CO.	07 [11
1.3	giff the spirit of the PMS 1	Takin entertie 6 in	องเสียงที่ รูเสรียงกับ	りし	Bartar Balandari	ur i da Williama.	
٦	ry.	さんご	σr	NG-	821	KFA	CTONY
				まる」。		医抗疫肺 禁犯的 医皮肤	Miller Miller State
	الريخ (ب	2 15-0 V	Je'M	13.HZ	- 65	$g = \sigma r$	5
٩v	عاعدات	-O -	مت∵ ا	ia cant	<u> </u>	6,20	un.
S	e Pe	ジ ハ む (ρ,				
			/	AU (Leri	9 N)	
			III AN LYBOL S	14-		海影,不由于"大"。	

☑ Contractor

Rey0/April 1996

E. M. L. T. BIRZULIS ASSOCIATES PTYLITD STEINSPECTION REPORT

	583 Darling Street, Rozelle NSW 2039 (A.C.N. 003 797 911) Telephone (02) 9555 7230 Facsimile (02) 9555 7239
	PROJECT 20 PACK BEACH M. PACK BEACH
	DATE: 31/3/10 PROJECT NUMBER: 4-3.1
	ITEMS INSPECTED: FOULD ATION EXCRURTION
	1) - 1-18 mar 01 mars 11 - 11 - 11
	MULDERSON TO BUTH BY CAURATION
	THERE IS HO BED ROLL APPARED
	OUT THE SITE & BONTILON EXCHUNTING
	발표를 통해 통해 한다고 하는 다른 사람들이 다양하는데 하는데 하는데 하는데 하는데 보고 있다. 그는 사람들은 사람들이 다른 사람들이 되었다. 그는 사람들은 사람들이 다른 사람들이 되었다. 그는 사람들이 다른 사람들이 되었다. 그는 사람들이 되었다면 하는데 보고 있다면 하는데 되었다면 되었다면 하는데 되었다면 되었다면 하는데 되었다면 되었다면 되었다면 되었다면 되었다면 되었다면 되었다면 되었다면
	1408 HOL EORHO VOCIT
*	WE USCOMMEND THAT A PIT BE BOO
	IN THE MIDDLE DE THE SITE TO
	S Javan noch Level ?
	SHOOLD BE CALLED UPDA TO VERSIEU
	THO FOUNDATION CONDITIONS
4	DALLO RESO WIFORMS US TRACT THERE
	12 100 min OF TOPPING SUAD PURHUUD
	For AU FLOOMS? PLEASE COMPILIN
	1 20 AOJ 17 BLOZA-BU HALM SILV TANT O?
	NB. If the above hydron a variation to the contract, the builder shall obtain approval from the Contract Administrator before proceeding with the work, otherwise no claim may be accepted.
	Distribution Client Granchifect Grantractor Distribution D
	Distribution
罐 "好"。	

12

Bayer Environmental Science





Certificate of Compliance

This document is to certify that the Kordon TMB / TB system was installed by a Bayer Accredited Installer and has been completed in accordance with the Manufacturer's specifications. Kordon TMB / TB complies with AS 3660.1 - 2000, the primary referenced standard of the Building Code of Australia. Kordon TB is only part of a termite management system for a new property. The slab must be constructed in accordance with the Standard; Residential Slabs and Footings Construction, AS 2870-1996

NOTE: This documer	nt is to be attached to Warranty Docu	ment Number:	2010-12-1097	
Date of Installation:	30/09/2010	Job Type:	Large Job - Full Perimeter	<u>Protection</u>
Installation Address:	20 Palm Beach Road Palm Beach NSW, 2108	54	300	otal SQM 16.20
Builder: Phone number: Owner:	The Construction Connection 02 99732070 Unknown	26	150	3.90
Phone number: Local Council: Phone number: Company Contact: Installer's Name: Company Name:	Pittwater Council 02 99701111 Peter Sakley Peter Sakley Precision Pest Control Pty Ltd	Service Penetration Kordon Kollars Manual Collars	ons 25 0 Total Kordon Installed:	2.50 0.00 22.6
Address:	Unit 26/75 Corish Circle Eastgardens NSW, 2035			
Phone Number: Fax Number: Accreditation Number	02 9666 8477 02 9666 8577 :n121			
perimeter. Kordon will only prote Regular termite inspe Kordon is installed to	er has been advised to maintain a 75 ct areas where the product is installe ctions as per the Australian Standard the service penetrations and perimet r d12 monthly termite inspections red	d. I are recommended. er as per the manufacture		

No pre installation site inspection report as recommended by AS3660.1 was carried out.

Bayer Environmental Science





This warranty is granted by Bayer Environmental Science ("Bayer") (ACN 000 226 022) of 391-393 Tooronga Road, Hawthorn East, Victoria in respect of the installation of Kordon Termite Barrier ("Kordon") in the Building.

Warranty No:

2010-12-1097

This Warranty covers damage by Subterranean Termites

("Termites") only.
Bayer warrants that Kordon shall restrict the entry of Termites into the Building through the Kordon barrier for a period of ten (10) years from the date of installation ("Warranty Period").

This Warranty covers damage by Termites to structural timbers and internal timbers BUT DOES NOT INCLUDE

damage by Termites to:

(a) chattels of any nature whatsoever including (but without limiting the foregoing) antiques, heirlooms, paintings, artwork and paintings; and (b) any pergolas, wiring, extensions to the Building and outbeares.

oulhouses.

If Termite infestation of the Building occurs as a result of the failure of the Kordon and damage by Termites is caused to structural timbers and/or internal timbers fixtures and fittings during the Warranty Period, Bayer will without charge to the

(a) repair the Kordon barrier where practicable;

and/or

(b) cause the repair or replacement of structural timbers and/or internal timbers so damaged.

To the extent permitted by the Law of the State or Territory

in which the premises are located:
(a) the liability of Bayer under this Warranty is limited to a maximum of \$100,000.00 in respect of any one (1) warranty claim.

(b) All representations and other warranties express or implied and whether arising by virtue of Statute or otherwise are excluded or limited as stated in this Warranty.

This Warranty shall only have effect if the Kordon is installed by an Accredited Bayer Installer.

OWNERS RESPONSIBILITIES
The Owner of the Building during the Warranty Period
("Owner"), at the Owner's expense, arrange for thorough
and regular inspection of the Building for the presence of
Termites at intervals not exceeding 12 months by an accredited/licenced Timber Pest Inspector.

Where the Termite risk is high or the Building type is susceptible to Termite attack (e.g. North of the 26th parallel) more frequent inspections (3-6 months) should be undertaken.

These inspection recommendations comply with those outlined in AS 3660 Termite Management Series and AS 4349.1-1995, Inspection of buildings.

If Termites are detected or are found to have breached the Kordon barrier, the Owner must, within 7 days of such detection, notify Bayer

EXCLUSIONS
This Warranty shall be void and have no effect in any of the

following circumstances: The Kordon barrier is damaged, modified, bridged or The Kordon barrier is damaged, modified, bridged or otherwise interfered with by any person or any act, fact, matter or thing beyond the reasonable control of Bayer. The Building is structurally modified, altered or otherwise changed in any way which would or may diminish the effectiveness of the Kordon as a Termite barrier. If at any time during the Warranty Period, the Owner

(a) allows or fails to prevent accumulation of:
(i) wood, rubbish or timber against the Building; AND
(ii) finished ground level around the Building to a height which does not comply with the terms of the Installation Manual.

Installation Manual.

Installation Manual.
(b) allows the barrier dividing the soil surface and the structure of the Building formed by the Kordon to be bridged or broken by any other material or matter through which Termites may by-pass the Kordon and infest the Building.

Termites shall enter the Building through any manner other than by a breach of the Kordon barrier.

If the Kordon is installed other than by an Accredited Bayer Installer.

Bayer Installer.



Date of Installation:

30/09/2010

Installation Address:

20 Palm Beach Road Palm Beach NSW, 2108

Company Contact: Company Name:

Peter Sakley
Precision Pest Control Pty Ltd

Address:

Unit 26/75 Corish Circle Eastgardens NSW, 2035

Phone Number:

02 9666 8477

Accreditation Number: N121

th 3 hyarraty samel be no duraess the ropcon his electristatled by a bingraccedited installer

Bayer will grant additional specific warranty conditions where required to accommodate high density, commercial constructions, government buildings, etc on documented request.

Bayer Environmental Science, 391-393 Tooronga Rd, Hawthorn East, VIC, 3123

Go to Alterations and Additions Administra

Search by: Previous Completion Receipts

Get: New Completion Receipt

Previously certified projects for New Dwellings

View Completion Receipt View BASIX Certificate Suburb Postco

Postcode LGA

1686185

Palm Beach 2108

Pittwater Council

Terms and Conditions: Disclaimer: Copyright: Privacy: Terms of Use for Registered Users: Contact us