

Arboricultural Impact Assessment For Proposed development at 24 Wyatt Ave Belrose NSW

Prepared for McDonald Jones Homes

By
Michael Shaw
Diploma Horticulture (Arboriculture) AQF5

17 October 2023



Contents

1.	Brief		3							
2.	Scop	oe	3							
3.	The	proposed development	3							
4.	Site description									
5.	Site visit details									
6.	Main	documents utilised	4							
7.	Meth	odology	5							
	7.1.	All tree assessments were carried out utilising the following methods	5							
	7.2.	Measurements and observations were taken using	5							
	7.3.	Data collection and encroachment calculation	5							
8.	Tree	s potentially affected by the proposed development	6							
9.	Gene	eral Tree Protection Instructions	9							
10.	Tree	protection zone information	10							
10.	1. /	Activities prohibited within the Tree Protection Zone	11							
Ref	erenc	es	11							
Qu	alifica	tions and experience (Michael Shaw)	12							
Apı	endix	x 1 Tree AZ	13							
Арј	pendix	x 2 Landscape significance and tree retention determination	14							
Арі	pendix	x 3 Tree survey data table	15							
		x 4 Images (Tree protection plan / Google Earth image with plans and tree overlaid)	18							



1. Brief

1.1. I am requested by McDonald Jones Homes, on behalf of the property owners to identify and assess all trees at or near 24 Wyatt Ave Belrose that will be potentially affected by the proposed development, and to provide an arboricultural impact assessment which discusses relevant aspects of the proposed development's impact on existing trees.

2. Scope

2.1. This report focuses on trees within and close to the subject site that may be affected by the proposed development.

All trees were assessed visually from ground level in accordance with Mattheck and Breloer's Visual Tree Assessment methodology.

No excavation or invasive testing was conducted as a part of the visual tree assessment.

3. The proposed development

3.1. The proposed development is for the demolition of an existing residential structure and garage and the construction of a replacement residential structure, garage/granny flat and associated landscaping.

The proposed development is located within the residential suburb of Belrose in the Northern Beaches local government area.

Several existing trees at or near the site will be affected if the proposed development occurs as planned.

4. Site description

4.1. The subject site (24 Wyatt Ave Belrose) is a residential property.

Potentially affected trees at the site are located mainly around existing structures and trees consist of a mixture of native and non-native, planted and self-sown mature and immature trees.

The site is within a NSW Rural Fire Service (RFS) 10/50 Clearing entitlement area and is therefore subject to the vegetation clearing exemptions that apply.

Site visit details


5.1. One unaccompanied site visit was made by the author on 31 May 2023 for the purposes of data collection and tree assessment for this document.

During this visit, tree location and other data was collected and assessments undertaken for the subject trees in relation to the proposed development.

The weather at the time of the site visit was fine and the effect of wind was negligible.



Site location (Google maps)



6. Main documents utilised

The following documents were provided for the author's information by McDonald Jones_ Homes,

- Design drawing number 606935 Revision "9" (29 sheets), by McDonald Jones Homes, dated 13/09/2023
- Survey by Aspect Development and Survey dated 11/05/2023
- Stormwater layout plan by ALW Design dated 28/08/2023

Other documents and information may have been provided, however the main ones used to assist the author with this assessment are listed above.

These documents were provided to the author in electronic format via email.



7. Methodology

7.1. All tree assessments were carried out utilising the following methods

- Visual Tree Assessment Method (VTA) (Mattheck and Breloer,)
- Tree AZ (Barrell)
- Significance and retention value were assessed using STARS (IACA 2010)
- No aerial inspections, root excavations or soil sampling were conducted as part of this assessment
- Tree identification was based on visual inspection of features available at the time of inspection. A complete taxonomical process of identification was not conducted; therefore, the identification of trees in this document represents the probable identity of the species.

7.2. Measurements and observations were taken using

- Positioning and data recording conducted using a GPS PDA device.
- Binoculars and naked eye
- DBH (Diameter at Breast Height) was measured with a diameter tape or estimated at approx. 1.4 metres above existing levels
- Tree height and canopy spread was estimated or measured using a laser range finder and an inclinometer and/or based on surveyor's estimates

7.3. Data collection and encroachment calculation

All assessed and recorded trees have been identified with a number which corresponds with the number on the tree survey data table at Appendix 3 and its location at the subject site may be viewed on the aerial image at Appendix 4 Images.

The author attempted to locate the trees as accurately as possible by using Google Earth in conjunction with plan drawings and provided professional survey images, which were overlaid using the tools available in the Google Earth application. These images were placed manually, as accurately as possible and cross referenced with the location point data collected by the author and displayed on the Google Earth interface screen.

Measurements to the nearest TPZ/SRZ disturbance was measured using tools available in the Google Earth application and encroachment percentages were calculated using the "Proofdocs" TPZ Incursion Calculator which is available online.



8. Trees potentially affected by the proposed development

Discussion

8.1. Tree 1

Is a mature grey gum which is located around 4 metres to the east of the existing garage structure on the subject property.

This tree will experience a significant tree protection zone (TPZ) encroachment of over 25% from soil disturbance and level changes necessary for the installation of the proposed new garage and granny flat structure.

The health and vigour of this tree is likely to be adversely affected if the development proceeds as planned.

If the proposed soil disturbance and level changes in the TPZ are reduced to about 10% or less of the TPZ area, this tree may be protected and retained without being adversely affected.

In accordance with guidance provided in AS4970-2009 (Protection of Trees on Development Sites) the calculated encroachment is unsustainable and the tree requires removal if the development proceeds as currently planned.

8.2. Tree 2

Is a mature Alexander palm which is located several metres to the east of the existing garage structure on the subject property.

This species of palm is exempt from protection and may be removed without consent.

This tree is proposed to be removed to facilitate the development and related landscaping.



8.3. Tree 3

Is a mature grey gum which is located several metres to the east of the existing garage structure on the subject property.

At the time of the site visit in May 2023, this tree displayed very poor health and was in advanced decline.

Observations of recent photos of the tree's current condition suggest that the health and vigour of this tree has not improved and it's expected lifespan is short.

This tree will experience a 9% encroachment into its total tree protection zone (TPZ) area from soil disturbance and level changes necessary to install the proposed new garage structure.

This is acceptable in accordance with AS4970 however, as the health and vigour of this tree is compromised, the effect of the calculated encroachment on this tree is likely to be more pronounced and the tree's ability to withstand and adapt to the encroachment compromised due to its poor health.

If the development proceeds as is currently planned, this tree is likely to be adversely affected and may die, however, the structural root zone is not affected by any obvious features of the proposed design and it will not be structurally compromised.

This tree is proposed to be removed as part of the development.

8.4. Tree 4

Is a juvenile Southern magnolia which is located in a garden bed near the north western corner of the existing garage structure on the subject property.

This tree is exempt from protection and may be removed or retained at the discretion of the property owner.

This tree will not be affected by any obvious proposed works and may be protected and retained or removed as desired by the owner.



8.5. Trees 5

Are all small mature camellias which are located within a garden bed which follows the southern face of the existing residential structure

These trees are all exempt from protection due to their small dimensions and their proximity to the existing structure and may be removed without council consent.

These trees are all located in very close proximity to the proposed construction footprint and will require removal if the development proceeds as planned due to direct conflict with aspects of the construction process combined with an unsustainable encroachment.

Relevant general notes relating to this site

I am advised that the existing VAC at the south western corner of the property will remain unaltered and that the VAC shown on the plans is indicative only, therefore, no nearby trees will be affected.

All other trees not listed specifically here are either insignificant and unprotected, or will not be affected by the proposed development if protected in accordance with AS4970-2009.



9. General Tree Protection Instructions

All other trees not listed specifically here will not be affected by the proposed development if protected in accordance with AS4970-2009.

Basic tree protection measures have been recommended in this document however, more comprehensive and detailed tree protection specifications may be mandated by the consenting authority in the form of a tree protection management plan which is to be provided by an AQF5 arborist in cooperation with the project manager.

All tree protection measures must be installed before any phase of development related activity occurs (including demolition).

Tree protection measures must be assessed and certified in writing by an AQF5 consulting arborist with a sufficient time allowance to make physical adjustments to protection measures in order to ensure efficacy of tree protection before any works commence.

Any soil disturbance in the form of trenching or fill placement or tunnelling for the installation of infrastructure including but not limited to pipes for communications, electrical, drainage, water or sewer must be considered in relation to retained trees and advice shall be sought from an AQF5 consulting arborist if any infrastructure as described above is proposed to be installed within the TPZ radius for any tree to be retained.

Ground protection to protect the soil within the TPZ may be utilised as an alternative to erecting a fenced exclusion zone if the practicalities of the development process necessitates it.

If ground protection is used as an alternative to protective fencing, the ground surface within the TPZ is to be protected in accordance with Section 4.5.3 of AS4970 and a thick (200-300mm) layer of wood chip mulch is to be placed on the ground within the TPZ and load spreading plates, rumble boards or heavy timber planking is to be placed on top of the mulch and strapped together to prevent movement so as to spread the load and to prevent compaction of the soil.

The level of soil protection and materials to be used within the TPZ will vary depending on the plant proposed to be utilised and specific protection measures will need to be discussed and agreed upon in writing by the project manager and an AQF5 qualified arborist before works commence.



10. Tree protection zone information

- TPZ- (Tree protection zone) the tree protection zone (TPZ) is the principal means of
 protecting trees on development sites. The TPZ is a combination of the root area and
 crown area requiring protection. It is an area isolated from construction disturbance, so
 that the tree remains viable.
- SRZ- (Structural root zone) The SRZ is the area required for tree stability. A larger area is required to maintain a viable tree.
- Any trees recorded within the scope of this assessment that are to be retained shall be
 protected by a physical TPZ exclusion zone to the radius from the trunk calculated in
 accordance with section 4 of AS 4970-2009 Protection of Trees on Development Sites
 (Provided at Appendix 3) Tree survey data table) and in consultation with the project
 arborist.
- It is strongly recommended that a copy of this standard is obtained by the project manager as a reference before any work commences on site.
- Tree protection zones shall be established in accordance with Section 4 of AS 4970-2009 before commencement of any other demolition or construction work. This will include trunk, branch and ground protection if considered necessary by the project arborist and also placement of appropriate and compliant TPZ signage to the physical TPZ fence.
- The TPZ shall remain until the completion of all demolition and construction related activity.
- Any pruning and tree works recommended are to be conducted by a certificate 3
 (minimum) qualified and experienced arborist and work is to be conducted according to
 AS4373: Pruning of Amenity Trees.
- Consent to prune trees may be required from the tree owners and Council.
- Establishment and erection of tree protection zone and signage should be inspected and certified by the project arborist to ensure compliance with the standard.
- Unless approved by the project arborist beforehand, no activity as detailed in section 4.2 of AS 4970-2009 Protection of Trees on Development Sites and Section 10 of this document is to occur within the TPZ.



10.1. Activities prohibited within the Tree Protection Zone

- Modification of existing soil levels
- · Excavations and trenching
- Cultivation of the soil
- Mechanical removal of vegetation
- Soil disturbance
- Movement of natural rock
- Storage of materials, plant or equipment
- Erection of site sheds
- Affixing of signage or hoarding to the trees
- · Preparation of building materials
- Disposal of waste materials and chemicals
- Lighting fires
- Refuelling
- Movement of pedestrian or vehicular traffic
- Temporary or permanent location of services, or the works required for their installation
- Any other activities that may cause damage to the tree.

References

- NSW Rural Fire Service 10/50 Vegetation Clearing Code of Practice
- Northern Beaches Council DCP Section E1 Preservation of Trees or Bushland Vegetation
- Standards Australia (2009) "AS4970: Protection of trees on development sites"
- Standards Australia (2007) "AS4373: Pruning of Amenity Trees"
- http://www.treetec.net.au/TPZ SRZ DBH calculator.php
- http://www.proofdocs.com/arborist report template/tpz incursion calculator/
- Mattheck, C., Breloer, H (1994) The Body Language of Trees- A handbook for failure analysis
 HMSO. London.



Qualifications and experience (Michael Shaw)

Practising AQF level 5 consulting arborist from 2009 - present

AQF level 5 Diploma of Horticulture (Arboriculture)

Licensed QTRA practitioner (quantitative tree risk assessment)

Licensed VALID Tree Risk assessment practitioner April 2021

ISA Tree risk assessment qualification (TRAQ) October 2013

Senior Tree Risk Assessment Officer (Central Coast Council) Sep 2015- Dec 2017

Part time contractor as a Tree Management Officer at Lane Cove, Strathfield and Hornsby Councils between 2013-2015

Tree Assessment and Vegetation Management Officer Port Stephens Council from September 2009 - Dec 2011

ISA conference Canberra 2017

VTA (visual tree assessment) workshop March 2011 and March 2013

ISA 87th annual Conference delegate, Parramatta NSW July 2011.

Matheny & Clark "Arboriculture" Seminar. Melbourne November 2009

Specialising in arboriculture and tree assessment from Feb 2008

Certificate 3 Horticulture (Parks and gardens)

Working in horticultural industry from April 2004



Appendix 1 Tree AZ

Category Z: Unimportant trees not worthy of being a material constraint

Local policy exemptions: Trees that are unsuitable for legal protection for local policy reasons including size, proximity and species

Young or insignificant small trees, i.e. below the local size threshold for legal protection, etc

Too close to a building, i.e. exempt from legal protection because of proximity, etc

Species that cannot be protected for other reasons, i.e. scheduled noxious weeds, out of character in a setting of acknowledged importance, etc

High risk of death or failure: Trees that are likely to be removed within 10 years because of acute health issues or severe structural failure

- Z4 Dead, dying, diseased or declining

 Severe damage and/or structural defects where a high risk of failure cannot be satisfactorily reduced by reasonable remedial care, i.e. cavities, decay, included bark, wounds, excessive imbalance, overgrown and vulnerable to adverse weather conditions, etc
- Z6 Instability, i.e. poor anchorage, increased exposure, etc
 Excessive nuisance: Trees that are likely to be removed within 10 years because of unacceptable impact on people
- Excessive, severe and intolerable inconvenience to the extent that a locally recognised court or tribunal would be likely to authorise removal, i.e. dominance, debris, interference, etc

 Excessive, severe and intolerable damage to property to the extent that a locally recognised court or tribunal would be likely to authorise removal, i.e. severe structural damage to surfacing and buildings, etc

Good management: Trees that are likely to be removed within 10 years through responsible management of the tree population

- Severe damage and/or structural defects where a high risk of failure can be temporarily reduced by reasonable remedial care, i.e. cavities, decay, included bark, wounds, excessive imbalance, vulnerable to adverse weather conditions, etc
- Poor condition or location with a low potential for recovery or improvement, i.e. dominated by adjacent trees or buildings, poor architectural framework, etc
- Z11 Removal would benefit better adjacent trees, i.e. relieve physical interference, suppression, etc
- Z12 Unacceptably expensive to retain, i.e. severe defects requiring excessive levels of maintenance, etc

NOTE: Z trees with a high risk of death/failure (Z4, Z5 & Z6) or causing severe inconvenience (Z7 & Z8) at the time of assessment and need an urgent risk assessment can be designated as ZZ. ZZ trees are likely to be unsuitable for retention and at the bottom of the categorisation hierarchy. In contrast, although Z trees are not worthy of influencing new designs, urgent removal is not essential and they could be retained in the short term, if appropriate.

Category A: Important trees suitable for retention for more than 10 years and worthy of being a material constraint

	A1	No significant defects and could be retained with minimal remedial care									
	A2	Minor defects that could be addressed by remedial care and/or work to adjacent trees									
	A3	Special significance for historical, cultural, commemorative or rarity reasons that would warrant extraordinary efforts to retain for more than 10 years									
	A4	Trees that may be worthy of legal protection for ecological reasons (Advisory requiring specialist assessment)									
Г											

NOTE: Category A1 trees that are already large and exceptional or have the potential to become so with minimal maintenance, can be designated as AA at the discretion of the assessor. Although all A and AA trees are sufficiently important to be material constraints, AA trees are at the top of the categorisation hierarchy and should be given the most weight in any selection process.

Barrell Tree Consultancy



Α

Appendix 2 Landscape significance and tree retention determination

Tree Significance - Assessment Criteria

INSTITUTE OF AUSTRALIAN CONSULTING ARBORICALITARISTS O

1. High Significance in landscape

- The tree is in good condition and good vigour;
- The tree has a form typical for the species;
- The tree is a remnant or is a planted locally indigenous specimen and/or is rare or uncommon in the local area or of botanical interest or of substantial age;
- The tree is listed as a Heritage Item, Threatened Species or part of an Endangered ecological community or listed on Councils significant Tree Register;
- The tree is visually prominent and visible from a considerable distance when viewed from most directions within the landscape due to its size and scale and makes a positive contribution to the local amenity;
- The tree supports social and cultural sentiments or spiritual associations, reflected by the broader population or community group or has commemorative values;
- The tree's growth is unrestricted by above and below ground influences, supporting its ability to reach dimensions typical for the taxa in situ - tree is appropriate to the site conditions.

2. Medium Significance in landscape

- The tree is in fair-good condition and good or low vigour;
- The tree has form typical or atypical of the species;
- The tree is a planted locally indigenous or a common species with its taxa commonly planted in the local area
- The tree is visible from surrounding properties, although not visually prominent as partially obstructed by other vegetation or buildings when viewed from the street,
- The tree provides a fair contribution to the visual character and amenity of the local area,
- The tree's growth is moderately restricted by above or below ground influences, reducing its ability to reach dimensions typical for the taxa in situ.

3. Low Significance in landscape

- The tree is in fair-poor condition and good or low vigour;
- The tree has form atypical of the species;
- The tree is not visible or is partly visible from surrounding properties as obstructed by other vegetation or buildings,
- The tree provides a minor contribution or has a negative impact on the visual character and amenity of the local area,
- The tree is a young specimen which may or may not have reached dimension to be protected by local Tree Preservation orders or similar protection mechanisms and can easily be replaced with a suitable specimen,
- The tree's growth is severely restricted by above or below ground influences, unlikely to reach dimensions typical for the taxa in situ tree is inappropriate to the site conditions,
- The tree is listed as exempt under the provisions of the local Council Tree Preservation Order or similar protection mechanisms,
- The tree has a wound or defect that has potential to become structurally unsound.

Environmental Pest / Noxious Weed Species

- The tree is an Environmental Pest Species due to its invasiveness or poisonous/ allergenic properties,
- The tree is a declared noxious weed by legislation.


Hazardous/Irreversible Decline

- The tree is structurally unsound and/or unstable and is considered potentially dangerous,
- The tree is dead, or is in irreversible decline, or has the potential to fail or collapse in full or part in the immediate to short term.

The tree is to have a minimum of three (3) criteria in a category to be classified in that group.

Note: The assessment criteria are for individual trees only, however, can be applied to a monocultural stand in its entirety e.g. hedge.

Table 1.0 Tree Retention Value - Priority Matrix.





Appendix 3 Tree survey data table

Significantly affected trees requiring removal or trees proposed for removal in red text

Tree ID	Botanical and common name	DBH cm / TPZ m / SRZ m	Height x radial canopy spread m	Age	Estimated life expectancy	Landscape significance (STARS)	Retention value (STARS)	Vigour and health (% of live canopy)	Tree AZ	Features/Comments
1	Eucalyptus punctata (Grey gum)	60cm _7.2m_2.8m	10x12	Mature	Medium 15-40 years	Medium	Medium	Good(80-100% live foliage)	A1 No significant defects and could be retained with minimal remedial care	
2	Archontophoenix alexandrae (Alexander palm)	30cm_7m_2m	8x6	Mature	Medium 15-40 years	Medium	Medium	Good(80-100% live foliage)	A1 No significant defects and could be retained with minimal remedial care	Exempt palm species. May be retained or removed at the discretion of the property owner.
3	Eucalyptus punctata (Grey gum)	60cm _7.2m_2.8m	10×10	Mature	Short 5- 15 years	Medium	Low	Fair(30-50% live foliage)	"Z4 Dead, dying, diseased or declining"	Tree is in advanced decline.
4	Magnolia grandiflora (Southern magnolia)	10cm_2.0m_2.0m	3x1.5	Young	Long >40 years	Low	Medium	Good(80-100% live foliage)	"Z1 Young or insignificant small trees, i.e. below the local size threshold for legal protection, etc"	Exempt dimensions. May be retained or removed at the discretion of the property owner.



Tree ID	Botanical and common name	DBH cm / TPZ m / SRZ m	Height x radial canopy spread m	Age	Estimated life expectancy	Landscape significance (STARS)	Retention value (STARS)	Vigour and health (% of live canopy)	Tree AZ	Features/Comments
5	Camellia sp x 9 individuals	Multiple leaders from base, estimated diameter at base,10cm_2m_2m	2x2	Young mature (mature but still young)	Medium 15-40 years	Low	Low	Good(80-100% live foliage)	"Z1 Young or insignificant small trees, i.e. below the local size threshold for legal protection, etc"	Exempt dimensions. May be removed at the discretion of the property owner.
6	Persea americana (avocado)	20 30cm_4.2m_2.3m	4x3	Mature	Medium 15-40 years	Low	Low	Good(80-100% live foliage)	"Z10 Poor condition or location with a low potential for recovery or improvement, i.e. dominated by adjacent trees or buildings, poor architectural framework, etc"	Not recorded on provided survey. Lopped at 3m. May be retained or removed at the discretion of the property owner.
7	Persea americana (avocado)	25cm_3.0m_2.0m	4x3	Mature	Medium 15-40 years	Low	Low	Good(80-100% live foliage)	"Z10 Poor condition or location with a low potential for recovery or improvement, i.e. dominated by adjacent trees or buildings, poor architectural framework, etc"	Not recorded on provided survey. Lopped at 3m. Exempt species. May be retained or removed at the discretion of the property owner.



Tre		DBH cm / TPZ m / SRZ m	Height x radial canopy spread m	Age	Estimated life expectancy	Landscape significance (STARS)	Retention value (STARS)	Vigour and health (% of live canopy)	Tree AZ	Features/Comments
8	Mangifera indica (mango)	20cm_2.4m_2.0m	4x3	Mature	Medium 15-40 years	Low	Low	Good(80-100% live foliage)	"Z3 Species that cannot be protected for other reasons, i.e. scheduled noxious weeds, out of character in a setting of acknowledged importance, etc"	Not recorded on provided survey. Exempt proximity to structure. Exempt species. May be retained or removed at the discretion of the property owner.
9	Cyathea cooperi (Australian tree fern)	10cm_5m_2m	4x4	Mature	Medium 15-40 years	Low	Low	Good(80-100% live foliage)	"Z1 Young or insignificant small trees, i.e. below the local size threshold for legal protection, etc"	Not recorded on provided survey. Exempt dimensions. May be retained or removed at the discretion of the property owner.



Appendix 4 Images (Tree protection plan / Google Earth image with plans and tree locations overlaid)



This page intentionally left blank