

Heritage Referral Response

Application Number:	DA2021/0497

Date:	17/06/2021
То:	Adam Croft
Land to be developed (Address):	Lot CP SP 5403, 87 - 88 North Steyne MANLY NSW 2095

Officer comments

HERITAGE COMMENTS

Discussion of reason for referral

The proposal has been referred to Heritage as the subject property contains a heritage item

12 - All stone kerbs - (former) Manly municipal area

Details of heritage items affected

Details of the item as contained within the Manly inventory is as follows:

Statement of significance:

Stone kerbs are heritage listed.

Physical description

Sandstone kerbing to streets relating to paving and kerbing of streets in the nineteenth century. Mostly located within Manly Village area and adjacent lower slopes of Eastern Hill and Fairlight.

Other relevant heritage listings		
Sydney Regional	No	
Environmental Plan (Sydney		
Harbour Catchment) 2005		
Australian Heritage Register	No	
NSW State Heritage Register	No	
National Trust of Aust (NSW)	No	
Register		
RAIA Register of 20th	No	
Century Buildings of		
Significance		
Other	N/A	

Consideration of Application

The proposal seeks consent for changing the balustrades on the balconies of the existing residential flat building from a solid wall to glass. The mapping of the stone kerb heritage item run through the North Steyne frontage of this property, however there is no stone kerb present within the property grounds. The listing also runs along the rear boundary of the site however the kerbing here has been replaced with concrete. Thus the proposal is considered to not impact upon this heritage item.

Therefore Heritage raises no objections and requires no conditions.

Consider against the provisions of CL5.10 of MLEP.

DA2021/0497 Page 1 of 2



Is a Conservation Management Plan (CMP) Required? No Has a CMP been provided? No Is a Heritage Impact Statement required? No Has a Heritage Impact Statement been provided? No

Further Comments

COMPLETED BY: Brendan Gavin, Principal Planner

DATE: 17 June 2021

The proposal is therefore supported.

Note: Should you have any concerns with the referral comments above, please discuss these with the Responsible Officer.

Recommended Heritage Advisor Conditions:

Nil.

DA2021/0497 Page 2 of 2