

Heritage Referral Response

Application Number:		DA2021/0001
Date:		20/01/2021
Го:		Adam Urbancic
Land to be developed (Addres	ss):	Lot 100 DP 1047405, 1 Park Street MONA VALE NSW 210
Officer comments		
HERITAGE COMMENTS		
Discussion of reason for referra	al	
The proposal has been referred	d to Her	itage as one of sites are within the vicinity of a heritage item
Victory Tree Holly Oak (Quero	us llex)	- 1785 Pittwater Road, Mona Vale
Details of heritage items affected	ed	
Details of the item as contained	d within	the Pittwater inventory is as follows:
CBD. Two smaller trees growin	ıg under	olly Oak) growing beside Pittwater Road in the Mona Vale its canopy should be removed to enhance the aesthetic
A mature specimen of Quercus CBD. Two smaller trees growin values of the Victory Tree and	ig under to maxir	. ,
A mature specimen of Quercus CBD. Two smaller trees growin values of the Victory Tree and Other relevant heritage listings	ig under to maxir	its canopy should be removed to enhance the aesthetic
A mature specimen of Quercus CBD. Two smaller trees growin values of the Victory Tree and Other relevant heritage listings Sydney Regional	ig under to maxir	its canopy should be removed to enhance the aesthetic
A mature specimen of Quercus CBD. Two smaller trees growin values of the Victory Tree and Other relevant heritage listings	ig under to maxir	its canopy should be removed to enhance the aesthetic
A mature specimen of Quercus CBD. Two smaller trees growin values of the Victory Tree and Other relevant heritage listings Sydney Regional Environmental Plan (Sydney	ig under to maxir	its canopy should be removed to enhance the aesthetic
A mature specimen of Quercus CBD. Two smaller trees growin values of the Victory Tree and Other relevant heritage listings Sydney Regional Environmental Plan (Sydney Harbour Catchment) 2005	ng under to maxir No	its canopy should be removed to enhance the aesthetic
A mature specimen of Quercus CBD. Two smaller trees growin values of the Victory Tree and Other relevant heritage listings Sydney Regional Environmental Plan (Sydney Harbour Catchment) 2005 Australian Heritage Register	ng under to maxir No No	tis canopy should be removed to enhance the aesthetic nise its growth potential and safe and useful life expectancy.
A mature specimen of Quercus CBD. Two smaller trees growin values of the Victory Tree and Other relevant heritage listings Sydney Regional Environmental Plan (Sydney Harbour Catchment) 2005 Australian Heritage Register NSW State Heritage Register NSW State Heritage Register National Trust of Aust (NSW) Register RAIA Register of 20th Century Buildings of Significance	ng under to maxir No No No	tis canopy should be removed to enhance the aesthetic nise its growth potential and safe and useful life expectancy.
A mature specimen of Quercus CBD. Two smaller trees growin values of the Victory Tree and Other relevant heritage listings Sydney Regional Environmental Plan (Sydney Harbour Catchment) 2005 Australian Heritage Register NSW State Heritage Register NSW State Heritage Register National Trust of Aust (NSW) Register RAIA Register of 20th Century Buildings of	ng under to maxir No No No	tis canopy should be removed to enhance the aesthetic nise its growth potential and safe and useful life expectancy.
A mature specimen of Quercus CBD. Two smaller trees growin values of the Victory Tree and Other relevant heritage listings Sydney Regional Environmental Plan (Sydney Harbour Catchment) 2005 Australian Heritage Register NSW State Heritage Register NSW State Heritage Register National Trust of Aust (NSW) Register RAIA Register of 20th Century Buildings of Significance Other	ng under to maxir No No No No	tis canopy should be removed to enhance the aesthetic nise its growth potential and safe and useful life expectancy.

second is located near to the car park at 1 Park Street Mona Vale, but on the Pittwater Road frontage. No heritage items are located within the immediately vicinity of the site at Park Street, while the Victory Tree is located to the north of the Bungan Street site. However there is sufficient separation between this kiosk and the heritage item, as well as a four storey development in between and no impact to the item or its significance is expected.



Therefore Heritage raises no objections and requires no conditions.

Consider against the provisions of CL5.10 of PLEP.

Is a Conservation Management Plan (CMP) Required? No Has a CMP been provided? No Is a Heritage Impact Statement required? No Has a Heritage Impact Statement been provided? No Further Comments

COMPLETED BY: Brendan Gavin, Principal Planner

DATE: 20 January 2021

The proposal is therefore supported.

Note: Should you have any concerns with the referral comments above, please discuss these with the Responsible Officer.

Recommended Heritage Advisor Conditions:

Nil.