FIRE SUPPORT NSW

ABN: 83 923 328 329

Bushfire Attack Level Assessment Statement

Type of Statement Development Application - Bush Fire Attack Level (BAL) Assessment 15-16 Mulawa Place Fenchs Forest NSW 2086 Identification of Site Owner Address As Above Details of Person/s making Company Name: Fire Support NSW Statement Address: 8 Lolita Lane Ermington NSW 2115 Phone: 0413 229 347 Statement I, Christopher Edwin Wainwright of the above-mentioned company

state that:

- a) Each bush fire threat assessment factor, and category specified, in this statement has been assessed by a properly qualified person.
- b) A properly qualified person (whether the person referred to in paragraph (a) or another person) has inspected the site & has assessed that, as at the date of inspection, the category of bush fire attack risk is

BAL LOW

- c) The proposed development is to comply with AS3959,
 - BAL: LOW, to all sides of development.
- d) Compliant development together with existing development on the site and any occupants will be reasonably protected from the impact of bush fire hazard in accordance with the requirements specified by the State Government through relevant legislation and advisory documents.
- e) Compliant development would be expected to survive the passage of a wildfire.
- f) The information contained in this statement is, to the best of my knowledge and belief, true and accurate.

Signature:	CE.Wainwright	Signature:	TWain
Position/Title:	Chief Fire Officer	Position/Title:	Director – Fire Safety & Training
Qualification:	Urban Station Officer and Country Fire Officer Rtd.	Qualification:	Diploma in Firefighting Management
Date:	07/11/19	Date:	07/11/19



Fire Support NSW P: 0413 229 347 E: info@firesupport.com.au W: www.firesupport.com.au Page 1 of 3

FIRE SUPPORT NSW

ABN: 83 923 328 329

Property Location



Fire Support NSW P: 0413 229 347 E: info@firesupport.com.au W: www.firesupport.com.au Page 2 of 3

FIRE SUPPORT NSW

ABN: 83 923 328 329

Site Observations			
Factor	Observations		
Vegetation Assessment	Hazardous vegetation 30m to North Dry Sclerophyll Open Woodland		
2. Slope	Offsite: < 5° - Flat to hazardous vegetation to North		
·	Onsite: Flat		
	Cardinal Points:		
	North: Flat		
	South: > 10° down-slope		
	East: > 10° down-slope		
	West: Flat		
3. Fuel Type	Offsite: Dry Sclerophyll Open Woodland		
	Onsite: Managed curtilage		
4. Fuel Loading	Offsite: NSW Rural Fire Service document: "Planning for Bushfire Protection" indicates: >5 tons per hectare – Hazardous Vegetation to West.		
	Onsite: <5 tons per hectare - Managed curtilage		
5. Access	Offsite: Good via 2 lane sealed road.		
	Onsite: Good via paved driveway.		
6. Water	Offsite: Reticulated water mains with fire hydrants.		
	Onsite: Domestic supply		
7. Aspect	Site looks out to: Main Hazardous Vegetation to North		
8. Exposures	Hazardous vegetation to: North		
	Houses and managed curtilage to: West and South		
9. Wind	Predominant bushfire winds are from the: North West.		
10. Environmental Sensitivity	This development will have NO impact on environmental sustainability or sensitivity of known threatened species, population or ecological community.		
	This development will have NO impact on any known Aboriginal site or relic.		
11. Asset Protection	East: N/A		
Zone (APZ)	South N/A		
	West N/A		
	North N/A		
12. Compliance with Planning for Bushfire Protection	Dwelling will need to comply with BAL LOW		

Fire Support NSW P: 0413 229 347 E: info@firesupport.com.au W: www.firesupport.com.au Page 3 of 3