



## Professional Consulting Arborists

---

**Date:** 10/01/2023

**Re:** 23 Wakehurst Parkway, Seaforth 2092

**DP:**13750

### To Whom It May Concern

At the request of the property owners Complete Arborcare were engaged to conduct an assessment of vegetation at the above stated address.

A site visit was conducted on the 1<sup>st</sup> January 2023. Weather conditions were fine.

Upon inspection it was found that all trees on the subject site were either exempt (non-protected *species*) or did not meet dimensions as to be classed as being prescribed (under the current Northern Beaches Council Tree Management Plan<sup>1</sup>).

A minor acceptable (<10%) encroachment into the TPZ<sup>2</sup> of one (1) x Bottle Brush (*Callistemon viminalis*) will occur from the proposed widening of the existing driveway crossover, therefore protection fencing will be required to be installed in accordance with the Australian Standard (AS) 4970-2009, Protection of Trees on Development Sites (see image as an example).

Best Regards

Colin Curtis

Level 5 Consulting Arborist

Member of Arboriculture Australia #2332

Tree Risk Assessment Qualification (TRAQ)

Member of the International Society of Arboriculture # 228182

---

<sup>1</sup> Council, W., 2015. Trees & Developments. [Online]

Available at: <http://www.warringah.nsw.gov.au/planning-and-development/trees-and-development>

<sup>2</sup> Tree Protection Zone (TPZ) - is a "No Go Zone" surrounding a tree to aid in its ability to cope with disturbances associated with construction works.



Tree protection fencing must be secured with locking clamps in between each panel.

Minimum 1.8m

Tree protection fencing must be secured with concrete feet in between each panel.