

Heritage Referral Response

Application Number:	DA2021/0008
---------------------	-------------

Date:	11/03/2021
То:	Rebecca Englund
. , , ,	Lot 22 DP 7577 , 14 Ponsonby Parade SEAFORTH NSW 2092 Lot 21 DP 7577 , 12 Ponsonby Parade SEAFORTH NSW 2092

Officer comments

HERITAGE COMMENTS

Discussion of reason for referral

The proposal has been referred to Heritage as the subject property is within the vicinity of a heritage item, listed in Schedule 5 of Manly LEP 2013:

Item I278 - House - 14 Ross Street (corner Panorama Parade)

Details of heritage items affected

Details of the item as contained within the Northern Beaches heritage inventory is as follows:

Item I278 - House

Statement of significance:

Consideration of Application

Small brick cottage unique in age, style and social association for the area; unique to context of local area architecturally. Major significance historically.

Physical description:

Small brick cottage possibly mid to late 19th century. Iron roof, timber verandah with brick piers. Symmetrical plan, hipped roof, stone foundation. Painted bricks are hand made. Fibro and corrugated iron lean-to to rear. Over looks Spit with views to Middle Head.

Other relevant heritage listings		
Sydney Regional	No	
Environmental Plan (Sydney		
Harbour Catchment) 2005		
Australian Heritage Register	No	
NSW State Heritage Register	No	
National Trust of Aust (NSW)	No	
Register		
RAIA Register of 20th	No	
Century Buildings of		
Significance		
Other	N/A	

The proposal seeks consent for the demolition of the existing properties on the subject site and the construction of a seniors housing development incorporating 9 apartments.

DA2021/0008 Page 1 of 2



The bulk and scale and the unarticulated facade treatment of the proposal is considered to adversely impact the existing streetscape and the character of the locality. Heritage conservation requires retention of an appropriate visual setting that contributes to the existing character of the place. Section 3.2 - Heritage Considerations - Objective 3 of the Manly Development Control Plan 2013, notes that:

"To ensure that development in the vicinity of heritage items, potential heritage item and/ or conservation areas, is of an appropriate form and design so as not to detract from the significance of those items."

Section 3.2.1.1 Development in the vicinity of heritage items, or conservation areas.

- b) Proposed development in the vicinity of a heritage item or conservation area must ensure that:
- i) it does not detract or significantly alter the heritage significance of any heritage items, conservation area or place;
 - ii) the heritage values or character of the locality are retained or enhanced; and
- iii) any contemporary response may not necessarily seek to replicate heritage details or character of heritage buildings in the vicinity, but must preserve heritage significance and integrity with complementary and respectful building form, proportions, scale, style, materials, colours and finishes and building/street alignments.

Additionally Section 3.2.1.2 Potential Heritage Significance of the Manly DCP 2013 notes that: "If the property is assessed as having merit as a potential heritage item, the heritage controls and considerations in this plan will apply."

Additionally, Heritage recommended in the PLM notes that, a Heritage Report, investigating the potential significance of the property at 12 Ponsonby Parade, be produced by the applicant and included with any future development application.

For all the above reasons, Heritage recommends amendments to the application to address the heritage impact of the proposal.

Consider against the provisions of CL5.10 of Manly LEP2013.

Is a Conservation Management Plan (CMP) Required? No

Has a CMP been provided? No

Is a Heritage Impact Statement required? Yes

Has a Heritage Impact Statement been provided? No

Further Comments

COMPLETED BY: Oya Guner, Heritage Advisor

DATE: 11 March 2021

The proposal is therefore unsupported.

Note: Should you have any concerns with the referral comments above, please discuss these with the Responsible Officer.

Recommended Heritage Advisor Conditions:

Nil.

DA2021/0008 Page 2 of 2