

10 October 2007

The General Manager Pittwater Council PO Box 882 MONA VALE NSW 1660

Dear Sir/Madam.

HOUSE 4, 1148-1152 BARRENJOEY ROAD, PALM BEACH DEVELOPMENT APPLICATION NO. N 1233/00 & S96 FINAL OCCUPATION CERTIFICATE NO. 24655

City Plan Services have issued a Final Occupation Certificate for the above-mentioned project under Section 109H of the Environmental Planning and Assessment Act 1979.

Please find enclosed the following documentation:

- Final Occupation Certificate No. OC 24655
- Documentation used to determine the occupancy certificate
- A cheque for Council's registration fee

Should you need to discuss any issues, please do not hesitate to contact the Project Building Surveyor Brendan Bennett on 8270-3500.

Yours faithfully,

Brendan Bennett Managing Director

Encl

R#226585 17/10/07

PLANNING BUILDING HERITAGE LANDSCAPE UPBANDESIGN

PLAN SERVICES



House 4, 1148-1152 Barrenjoey Road, Palm Beach Final Occupation Certificate No. 24655



FINAL OCCUPATION CERTIFICATE NO. 24655

Issued under Part 4A of the Environmental Planning and Assessment Act 1979 Sections 109C(1)(C) and 109H (Occupation/Use of a New Building)

APPLICANT

Name of person having benefit of the development consent:

Address:

Contact Details:

Darren Leete - Raypond P/L PO Box 1346 Dee Why 2099

Phone: 0412 226 044 Fax: 9944 0316

OWNER

Name: Address:

Contact Details:

Darren Leete - Raypond P/L PO Box 1346 Dee Why 2099

Phone: 0412 226 044 Fax: 9944 0316

RELEVANT CONSENTS

Consent Authority/Local Government Area:

Development Consent No: Date of Development Consent: Construction Certificate No:

Date of Construction Certificate:

Pittwater Council N 1233/00 & S96

24.01.02

CC 24655 & CC 24655/1 22.10.04 & 20.01.05

PROPOSAL

Address of Development:

House 4, 1148-1152 Barrenjoey Road, Palm

Beach, AKA 62 Palm Beach Road, Palm

Building Classification:

Type of Construction:

Scope of building works covered by this Notice:

Attachments:

Fire Safety Schedule:

Exclusions:

Beach

Class 1a N/A

Residential home

Schedule 1

N/A

PRINCIPAL CERTIFYING AUTHORITY

Brendan Bennett for and on behalf of

City Plan Services Pty Ltd

ACCREDITATION NUMBER

BPB 0027

That I, Brendan Bennett, as the certifying authority, certify that:

- I have been appointed as the Principal Certifying Authority under s109E;
- A current Development Consent or Complying Development Certificate is in force with respect to the building;
- A Construction Certificate has been issued with respect to the plans and specifications for the building;
- The building is suitable for occupation or use in accordance with its Classification under the Building Code of Australia;
- Where required, a final Fire Safety Certificate has been issued for the building;
- Where required, a report from the Commissioner of Fire Brigades has been considered.

DETERMINATION

Approval dated this 10th

day

of October

2007

Brendan Bennett

Managing Director

Right of Appeal: Under s109K where the Certifying Authority is Council an applicant may appeal to the land & Environment Court against the refusal to issue an Occupation Certificate within 12 months from the date of the decision.

M:\Projects\CP2004\24-655\FOC\Final Occupation Certificate.doc

TELEPHONE 8270 3500 FACSIMILE 8270 3501

LEVEL 1 364 KENT STREET SYDNEY NSW 2000

WWW.CITYPLAN.COM.AU ABN 30 075 223 353



SCHEDULE 1

1. Attachments to the Occupation Certificate

Title	Prepared By	Reference	Date
Final Occupation Certificate Application Form	Darren Leete – Raypond	City Plan Services	08.10.07
Inspection Report – Footings	City Plan Services – Brendan Bennett		09.12.04
Inspection Report – Ground Floor Slab	City Plan Services – Brendan Bennett		01.02.05
Inspection Report – First Floor Slab	City Plan Services – Brendan Bennett		18.03.05
Inspection Report – Timber Framing	City Plan Services – Adam De Looze		11.12.06
Inspection Report – Part Timber Framing	City Plan Services – Adam De Looze		27.10.06
Inspection Report – Progress & Part Timber Framing	City Plan Services – Brendan Bennett		15.09.06
Inspection Report - Wetarea	City Plan Services – Brendan Bennett		14.02.07
Inspection Report – Stormwater Connection	City Plan Services – Brendan Bennett		14.02.07
Inspection Report – Final	City Plan Services – Brendan Bennett		04.10.07
Termite Protection Notice	Kordon Termite Barrier		20.09.06
Warranty – Subterranean Termites	Kordon Termite Barrier		20.09.06
Certificate of Compliance – Full Perimeter Protection	Kordon Termite Barrier		07.06.07
Component Certificate – Piers, Footings	Pittwater Council	-	05.10.07
Component Certificate – Ground Floor Levels	Pittwater Council		03.08.07
Component Certificate – Footings, Slabs, Piers, Retaining walls	Pittwater Council		08.10.07
Certificate of Waterproofing	R.L. Butler		26.07.07
	Waterproofing Service		
Component Certificate – Masonry Construction, Accessories & Weatherproofing	Pittwater Council		20.09.07
Component Certificate – Floor Levels	Pittwater Council		03.08.07
Certificate of Compliance – Balustrades	Stainless Timber Glass		
nstallation – Windows & Sliding loors	Vision 3 Window Systems Pty Ltd		03.09.07
Component Certificate – Roof Cladding	Pittwater Council		07.08.07
Component Certificate – Roof Ridge evels	Pittwater Council		27.07.07
Component Certificate – Smoke clarms	Pittwater Council		18.07.07
Component Certificate – Onsite stormwater Detention	Pittwater Council		08.10.07
component Certificate – Driveway	Pittwater Construction		03.08.07



Construction		
Component Certificate – Excavation and/ or Filling	Pittwater Council	27.07.07
Component Certificate – Site Landscaping	Selena Hannan Design	05.10.07
Component Certificate – Bushland Management Strategy	Pittwater Council	28.09.07
Component Certificate – Native Vegetation Planting	Pittwater Council	28.09.07
Inspection Report	Urban Forestry Australia	19.07.07
Component Certificate – Structural Certification Class 2-9	Pittwater Council	08.10.07
Plan Registration Advice	Department of Lands	10.08.07



OCCUPATION CERTIFICATE APPLICATION

Made under the Environmental Planning and Assessment Act 1979 Sections 109C(1)(c) & 109H

TYPE OF APPLICATION	☐ Interim Certificate ☐ Final Certificate
Tick Appropriate Boxes	☐ Change of Building Use of an Existing Building
	Occupation/Use of a New Building
	The second CARCONN ST ED DAM SOREM
IDENTIFICATION OF BUILDING	ALL PRINCES POR
IDENTIFICATION OF BUILDING	Address 62 14LM LEACHT TO
	Address 62 Park Braces RD PARM BEACH Lot, DP/MPS etc
	Suburb or town Parm BEACH Post Code
DESCRIPTION OF DEVELOPMENT	RESIDENTIAL HOME
Detailed Description:	KEDILLEY (IZ
REVELEVANT CONSENTS	
Development Consent:	DA No. 1/232/00 15/6 Date 14/01/32
O. I. Was On Wanter	DA No. 1/232/00 1596 Date 24/01/02 CC No. 24655 7 21655/1 Date 20/01/05
Construction Certificate:	CC NO. 21635 1260271
APPLICANT	
Name of person having benefit of the	Name DAREH LEETE COMPANY KATHENDALL
development consent:	1 80 R 13/11
	Address C TO LOC COURT
	Name Dager LEETE Company RATIONS D/L Address C/- P.O. Box 1344 Suburb or town DEE WHT Post Code 2899
	Phone B/HFax No
	Phone B/H Fax No Fax No Email derical esta Co
	email com a
As the applicant, I/we hereby;	ion under the Environmental Planning & Assessment Act 1979, for
determination by the Principal Certifying At	rthority.
Certify that the works have been completed	I in accordance with the relevant Development Consent.
Attach a Fire Safety Certificate, where relevant	vant, for the subject building work in accordance with the Fire Safety
Schedule.	
Signature of applicant:	Sign
-	



DA No: N1232/00

CC No: 24655/1

Site Address: Lot 4, 1148 Barrenjoey Road, Palm Beach

Site Contact Name: Darren

Phone No: 0412 226044

Type of Inspection: Footings Inspection Date: 09.12.04

Result of Inspection

Pad footings bearing on rock - Satisfactory

Inspected by: Brendan Bennett

Accreditation Body: PIA Results conveyed to: Darren

Date: 09.12.04

Signed:



DA No: N1232/00

CC No: 24655/1

Site Address: Lot 4, 1148 Barrenjoey Road, Palm Beach

Site Contact Name: Darren

Phone No: 0412 226044

Type of Inspection: Ground Floor Slab

Inspection Date: 01.02.05

Result of Inspection

Steel placed as per engineers details - Satisfactory

Inspected by: Brendan Bennett

Accreditation Body: PIA Results conveyed to: Darren

Date: 01.02.05



DA No: N1232/00

CC No: 24655/1

Site Address: Lot 4, 1148 Barrenjoey Road, Palm Beach

Site Contact Name: Darren

Phone No: 0412 226044

Type of Inspection: First Floor Slab

Inspection Date: 18.03.05

Result of Inspection

Steel placed as per engineers details - Satisfactory

Inspected by: Brendan Bennett

Accreditation Body: PIA Results conveyed to: Darren

Date: 18.03.05



DA No: DA-N1232/00 CC No: 24655/1 Site Address: Lot 4, 1148 Barrenjoey Road, Palm Beach

Site Contact Name: Darren Phone No: 0412 226044

Type of Inspection: Timber Framing

Inspection Date: 11.12.06

Result of Inspection

DA CONDITIONS

Condition A6 - Protection of public places - Satisfied

Condition A7 – Site signage – Installed. Condition A8 – Toilet facilities – Provided.

Condition B29 – Sediment control – Adequate at the time of the inspection.


Condition D20 & D21 - Sediment control - Adequate at the time of the inspection.

Condition D196 – Tree fencing erected – Refer to arborist reports.

Condition D201 - Tree exclusion warning signs - Erected.

ADDITIONAL APPROVAL

The masonry erected under the natural rock outcrops adjacent to the garage, would not comply with the intent of conditions D107, D144, D145 & D190. Additional approval must be obtained from Council and the NSW National Parks and Wildlife.





MANDATORY INSPECTION

Timber/steel framing inspected prior to covering. Structural engineer certification must be submitted certifying the structural component of framing, with specific reference to roof and wall framing tie downs, wall bracing, compliance with the certified plans and relevant Australian Standards applicable to the works.

Works in progress are consistent with the CC approved plans.

Inspected by: Adam DeLooze

Accreditation Body: BSAP

Results conveyed to: Darren

Date: 11.12.06

Signed:



DA No: DA-N1232/00 CC No: 24655/1 Site Address: Lot 4, 1148 Barrenjoey Road, Palm Beach

Site Contact Name: Darren Phone No: 0412 226044

Type of Inspection: Part Timber Framing

Inspection Date: 27.10.06

Result of Inspection

DA CONDITIONS

Condition A6 - Protection of public places - Satisfied

Condition A7 – Site signage – Installed. Condition A8 – Toilet facilities – Provided.

Condition B29 - Sediment control - Adequate at the time of the inspection.


Condition D20 & D21 - Sediment control - Adequate at the time of the inspection.

Condition D196 - Tree fencing erected - Refer to arborist reports.

Condition D201 - Tree exclusion warning signs - Erected.

ADDITIONAL APPROVAL

The masonry erected under the natural rock outcrops adjacent to the garage, would not comply with the intent of conditions D107, D144, D145 & D190. Additional approval must be obtained from Council and the NSW National Parks and Wildlife.





MANDATORY INSPECTION

Timber/steel framing inspected prior to covering. Structural engineer certification must be submitted certifying the structural component of framing, with specific reference to roof and wall framing tie downs, wall bracing, compliance with the certified plans and relevant Australian Standards applicable to the works.

Works in progress are consistent with the CC approved plans.

lns	nected	by: Ad	dam Del	0078
1113	Decrea	DV. A	Jan Dei	UUZE

Signed: ___

Accreditation Body: BSAP

Accreditation No.: P0118

Results conveyed to: Darren

Date: 08.11.06

M:\Projects\CP2004\24-655\IR261027 Part Timber Framing.doc



DA No: DA-N1232/00 CC No: 24655/1 Site Address: Lot 4, 1148 Barrenjoey Road, Palm Beach

Site Contact Name: Darren Phone No: 0412 226044

Type of Inspection: Progress and Part Timber Framing

Inspection Date: 15.09.06

Result of Inspection

DA CONDITIONS

Condition A6 - Protection of public places - Satisfied

Condition A7 - Site signage - An unauthorised entry sign and a sign with the name of the person in charge of the works and a telephone number at which that person can be contacted outside working hours must be erected. Confirmation of installation must be submitted.

Condition A8 - Toilet facilities - Provided.


Condition B29 - Sediment control - Adequate at the time of the inspection. Condition D20 & D21 - Sediment control - Adequate at the time of the inspection.

Condition D196 - Tree fencing erected - Refer to arborist reports.

Condition D201 - Tree exclusion warning signs - Confirmation of erection must be submitted.

ADDITIONAL APPROVAL

The masonry erected under the natural rock outcrops adjacent to the garage, would not comply with the intent of conditions D107, D144, D145 & D190. Additional approval must be obtained from Council and the NSW National Parks and Wildlife.



M:\Projects\CP2004\24-655\IR260915 Part Timber Framing.doc



GENERAL

Works proceeding in accordance with the CC approved plans and condition B62.

Inspected by: Adam DeLooze

Signed: ____

Accreditation Body: BSAP

Accreditation No.: P0118

Results conveyed to: Darren

Date: 20.06.06

M:\Projects\CP2004\24-655\IR260915 Part Timber Framing.doc

TELEPHONE 8270 3500 FACSiMILE 8270 3501 LEVEL 1 364 KENT STREET SYDNEY NSW 2000

WW.CITYPLAN.COM.AU ABN 30 075 223 353



DA No: N1232/00

CC No: 24655/1

Site Address: Lot 4, 1148 Barrenjoey Road, Palm Beach

Phone No: 0412 226044

Site Contact Name: Darren Type of Inspection: Wetarea

Inspection Date: 14.02.07

Result of Inspection

Works proceeding in accordance with the CC approved plans.

Wetareas inspected prior to covering. Certification of installation in accordance with AS3740 must be submitted to City Plan Services prior to the issue of an Occupation Certificate.

Inspected by: Brendan Bennett

Signed:

Accreditation Body: PIA

Accreditation No.: 3004

Results conveyed to: Darren

Date: 14.02.07



DA No: N1232/00

CC No: 24655/1

Site Address: Lot 4, 1148 Barrenjoey Road, Palm Beach

Site Contact Name: Darren

Phone No: 0412 226044

Type of Inspection: Stormwater Connection

Inspection Date: 14.02.07

Result of Inspection

Stormwater connection to retention tank

Satisfactory

Inspected by: Brendan Bennett

Accreditation Body: PIA Results conveyed to: Darren

Date: 14.02.07

Signed:



DA No: DA-N1232/00

CC No: 24655/1

Site Address: Lot 4, 1148 Barrenjoey Road, Palm Beach

Site Contact Name: Darren

Phone No: 0412 226044

Type of Inspection: Final

Inspection Date: 04.10.07

Result of Inspection

Works generally completed in accordance with the development consent.

Inspected by: Brendan Bennett

Accreditation Body: BPB

Signed:

Accreditation No.: 00027

Results conveyed to: Darren

Date: 04 10 07

AFFIX TO KITCHEN CUPBOARD

		Follow up inspections are to be completed by		
AFFIX TO ELECTRICAL METER BOX		Full Perimeter Service Penetrations Popper Colon C	nstallation:	
			_	

15 other (2/01/01/07 TS)	an accre	dited/lice	nsed timb	er pest in	pector.
Date of Installation: 20 9 06					
Installation Address: HOUSE 4					
Sto Palm Beach Road					
Valu beach 2108	ਜ	8	m	4	Ŋ
Accredited Kordon Potector Phild					
WARNING: Refer to the Bayer Kordon Warranty & Reference-Manual for the full terms of the Warranty and Conditions for the use of Kordon					
Termite Barrier. Bayer CropScience 391.393 Tooronga Rd East Hawthom Vic 3123	9	7	8	9	10

						_
	o o		IJ		¢	?
	ect ect				T-	•
E JOSEPH	Follow up inspections are to be completed by an accredited/licensed timber pest inspector					_
	급		4		୍ ପ)
	co					
	함					
	유		~	<u> </u>	~	7
	ම් ' ‡		(,)		_ α	1
	sed sed					
	ion					4
	ect Si	,	S		7	٠
	S S			ĺ.,	•	
	눈꽃					ı
a L	i e	·	_1			1
Commence of the second	800		77		9	1
	<u> </u>					1
and the second						╛
		1	4 1			
			1	7	c 5	
* * * * * * * * * * * * * * * * * * *		- 1 19	134	1	of Kordon Bekoose/HAT	
The state of the s	Ì	767	10	7	- 돌 호	
————————————————————————————————————	5	1/1-5		Potecho A	75 5 E	5
→ 一 二 三 三 三 三 三 三 三 三 三 三 三 三 三 三 三 三 三 三	3	ـ الم	$ \mathcal{O} $, ~	ren t us	7
	tra	ジだ	1		the	5
一个一种 主义	e l	$\mathcal{A}_{\mathcal{M}}^{\mathcal{M}}$		اھ	% <u>o</u>	
三 重量差量	s.∖	はてに		-	Arc Tr	Ē
- 3.3425	o , [-]	91 JU	1	୍ୟ	dition 4	Ē
n = 2 =	žζ	YU.	K	꿧	¥8	5
	neter D Service	HI.	\mathbb{N}	\sim	함	2
出に思る語)	<u> </u>	$Q \supset Z$	12	7	X X 4 X 4	5
	= =	ع! ا (βŢ	rant	3
	<u>7</u> të	/ <u>: ::</u>	\mathbf{d}	IJλ		2
→ 写 语音音	<u> </u>	ation 2	Ź	Sorden Coden	F 5	ï
	₽ 3	B B 7		20	5.5 S	2
	区 Full Id Perimeter Id Service Penetrations ID Other (こ) (こ) (こ) (こ)	Date of Installation:_ Installation Address:_		Accredited Kordon Installer:	WARNING: Refer to the Baser Kordon Warranty & Reference-Manual for the full terms of the Warranty and Conditions for the use of Kordon Elemite Baserier, Reserved Conscience 301 303 Transfer and East University of East University Conscience 301 303 Transfer and East University of East University o	Dayor Ciphodicine agrego lookalka na cast namuotu vic 3173
5 m 2 = 2	<u> </u>	in in it	-	ba :	Frie Frie	3
全人工工程	= =	o te O		ē ë	Z E B	5
	Z Other Z	ə <u>E</u> √		Accredited Installer: (WARNING: Re for the full tern Termite Barrier,	, ,
ニントー・カンス はんしん シストル マスメ かきてぬ	~~ ~~	A (A)		- n		

Bayer Environmental Science





Warranty

This warranty is granted by Bayer Environmental Science "Bayer") (ACN 000 226 022) of 391-393 Tooronga Road, Hawthorn East, Victoria in respect of the installation of Kordon Termite Barrier ("Kordon") in the Building.

Warranty No:

2007-6-1321

This Warranty covers damage by Subterranean Termites "Termites") only.

Bayer warrants that Kordon shall restrict the entry of Termites into the Building through the Kordon barrier for a eriod of ten (10) years from the date of installation "Warranty Pèriod").

This Warranty covers damage by Termites to structural ambers and internal timbers BUT DOES NOT INCLUDE

damage by Termites to:

(a) chattels of any nature whatsoever including (but without limiting the foregoing) antiques, heirlooms, paintings, artwork and paintings; and

(b) any pergolas, wiring, extensions to the Building and outhouses.

Termite infestation of the Building occurs as a result of the failure of the Kordon and damage by Termites is caused to tructural timbers and/or internal timbers fixtures and fittings Juring the Warranty Period, Bayer will without charge to the Owner:

- (a) repair the Kordon barrier where practicable; and/or
- (b) cause the repair or replacement of structural timbers and/or internal timbers so damaged.

To the extent permitted by the Law of the State or Territory which the premises are located:

- (a) the liability of Bayer under this Warranty is limited to a maximum of \$100,000.00 in respect of any one (1) warranty claim.
- (b) All répresentations and other warranties express or implied and whether arising by virtue of Statute or otherwise are excluded or limited as stated in this Warranty.

his Warranty shall only have effect if the Kordon is installed by an Accredited Bayer Installer.

OWNERS RESPONSIBILITIES

The Owner of the Building during the Warranty Period Owner"), at the Owner's expense, arrange for thorough and regular inspection of the Building for the presence of ermites at intervals not exceeding 12 months by an accredited/licenced Timber Pest Inspector.

'Mhere the Termite risk is high or the Building type is susceptible to Termite attack (e.g. North of the 26th parallel) more frequent inspections (3-6 months) should be ndertaken.

These inspection recommendations comply with those utlined in AS 3660 Termite Management Series and AS +349.1-1995, Inspection of buildings.

If Termites are detected or are found to have breached the ordon barrier, the Owner must, within 7 days of such detection, notify Bayer

EXCLUSIONS

This Warranty shall be void and have no effect in any of the following circumstances:

The Kordon barrier is damaged, modified, bridged or otherwise interfered with by any person or any act, fact, matter or thing beyond the reasonable control of Bayer. The Building is structurally modified, altered or otherwise changed in any way which would or may diminish the effectiveness of the Kordon as a Termite barrier.If at any time during the Warranty Period, the Owner

(a) allows or fails to prevent accumulation of:

(i) wood, rubbish or timber against the Building; AND

(ii) finished ground level around the Building to a height which does not comply with the terms of the Installation Manual.

(b) allows the barrier dividing the soil surface and the structure of the Building formed by the Kordon to be bridged or broken by any other material or matter through which Termites may by-pass the Kordon and infest the Building.

Termites shall enter the Building through any manner other than by a breach of the Kordon barrier. If the Kordon is installed other than by an Accredited Bayer Installer.



Date of Installation: 20/09/2006

Installation Address: 56 Palm Beach Road

Palm Beach NSW, 2108

Company Contact: Company Name:

Barry Slattery

Orange Protector Pty Ltd

Address: PO Box 90

MacArthur Square NSW, 2560

Phone Number: 1300 888 638

Accreditation Number: N119

THIS WARRANTY SHALL RE VOID UNLESS THE KORDON HAS BEEN INSTALLED BY A BAYER ACCREDITED INSTALLER,

Bayer will grant additional specific warranty conditions where required to accommodate high density, commercial constructions, government buildings, etc on documented request.

ayer Environmental Science





NOTE: This document is to be attached to Warranty Document Number:

Certificate of Compliance

This document is to certify that the Kordon TMB / TB system was installed by a Bayer Accredited Installer and has been completed in accordance with the Manufacturer's specifications. Kordon TMB / TB complies with AS 3660.1 - 2000, the primary referenced standard of the Building Gode of Australia. Kordon TB is only part of a termite management system for a new property. The slab must be constructed in accordance with the Standard, Residential Slabs and Footings Construction, AS 2870-1996.

NOTE: This documen	it is to be attached to Warranty Docume	ent Number:	2007-6-1321	
Date of Installation:	20/09/2006	Job Type:	Large Job - Full Perimet	er Protection
Installation Address:	56 Palm Beach Road Palm Beach NSW, 2108	Product used:	Dec dood Middle (com)	Tatal SOM
		Linear Wetres (m) 426	Product Width (mm) 1000	Total SQM 426.00
		81	220	17.82
Builder:	Raypond Pty Ltd	7	450	3.15
Phone number:	0422 373904	7	750	5.25
Owner:	Unknown	73	300	21.90
Phone number:		Service Penetration		
Local Council:	Pitt Water Council	Kordon Kollars	23	2.30
Phone number:	02 99701111	Manual Collars	0	0.00
Company Contact:	Barry Slattery		Total Kordon Installed:	476.42
Installer's Name: Company Name: Address:	Warren m/ Andy H/ Andy J Orange Protector Pty Ltd PO Box 90 MacArthur Square			
	NSW, 2560			
Phone Number:	<u>1300 888 638</u>			
Fax Number: Accreditation Number	1300 888 639 :N119			
Authorised Signature:	Lycius ermite inspections as por the Australian	Date:	7/6/2007	<u></u>
4 x New dwellings. Co full TMB vertical walls.	n inspections as per the Australian production slab on ground & bearers ar 23 x penetrations, 81 x K220 perimeter K750 perimeter installed.	nd joist. Perimeter retain	ing walls & penetrations t	reated. 426 x



Pittwater Council

Component Certificate

DA No:

N1232 00

CC No:

Property: 1148 BARRENJOEY ROAD PALM BEACH NSW 2108

Geotechnical Requirements

1. John Braybrooke of Douglas Partners P/L

(Name) (Business)

at 96 Hermitage Rd, West Ryde, 2114 (Mailing Address)

being a practising geotechnical-engineer with corporate membership of the institute of Engineers Australia (MIE), or eligible to become a Corporate member and having appropriate experience and competence in the related field, my qualifications being: BSc CHONS), MSc, DIC hereby certify that the picrs/slabs/footings/retaining walls/other have been constructed in accordance with the recommendations contained in the geotechnical report referred to in the Development Consent/Construction Certificate, and the relevant conditions of Development Consent. Further, I am appropriately qualified and experienced to provide the certification for this component of the project. Signature Assuprosler Date 5/10/07

PITTWATER COUNCIL

Component Certificate

DA No:	N1232/ 00
CC No:	

Property:

Ground Floor Levels

1148 BARRENJOEY ROAD PALM BEACH NSW 2108

1	Greg Gearin	of	Bowdens Group
At	PO Box 387, Parramat	tta NSW 2124 (Mailing Addres	
Being a regis	tered surveyor, my quali	fications being:	
Bachelor Sur	veying UNSW 1982		
Registered S	urveyor 1985		
	y that the ground floor ved plans or by any cond		ly comply with the levels nominated opment Consent.
Further, I am component of		and experience	d to provide the certification for this

28-OCT-2007 29:56 FROM NBCONSULTING

TD 99491544

Lim 4



Pittwater Council Component Certificate

DA No:

N1229/00

N 12:32/00

CC No:

Property: 1148 BARRENJOEY ROAD PALM BEACH NSW 2108

Footings/Slabs/Piers/Retaining Walls at (Mailing Address) being an: accredited certifier practising structural engineer with corporate membership of the institute of Engineers Australia (MIE), or eligible to become a Corporate member and having appropriate experience and competence in the related field, my qualifications being: SE Chang MIE (Aust) NPER. hereby certify that the footings/slabs/piers/retaining walls/other have been constructed in accordance with the engineers details nominated on the Construction Certificate or where not nominated, Part 3.2 "Footings and Slabs" of the Building Code of Australia Housing Provisions, AS 2870-1996 "Residential Slabs and Footings", AS 3600-1994 "Concrete Structures" and the relevant conditions of Development Consent. Further, I am appropriately qualified and experienced to provide the certification for this component of the project. Signature .

MD (Gm

RLBUTLER WATERPROOFING SERVICE

49 CHRISTINE CR, LALOR PARK 2147 TELEPHONE: (02)9624 8404 MOBILE: 0418 291 737 iic No 4248C

Certificate Of Waterproofing

This is to certify that this company has supplied and applied waterproofing membrane's to the project specified on this document as per AS3740 and manufacturers specifications.

Project. Ba PALLY BEACH ROS
TALLY BEACH

Material DAMPELS MEMERAME
TO LUET BREES BLOS
SPECIALIED DETRINING

Ray Butler.

MANAGER



Pittwater Council

Component Certificate

DA No:

N1229/00 N1232(00

CC No:

Property: 1148 BARRENJOEY ROAD PALM BEACH NSW 2108

Masonry Construction, Accessories & Weatherproofing MC-1

MICHAEL MOSS OF MOSBUILD (Business)
(Name) (Business) at fa DoodCourt RD, Deraw RA Helahits (Mailing Address)
being an:
□ accredited certifier
licensed builder
my qualifications being:
hereby certify that the masonry construction (including articulation joints), masonry accessories (including wall ties, tie down systems and lintels) and weatherproofing of masonry (including damp proof courses, flashings and ventilation), have been designed and constructed in accordance with Part 3.3 "Masonry", Part 3.3.3 "Masonry Accessories" and Part 3.3.4 "Weatherproofing of Masonry" of the Building Code of Australia Housing Provisions, AS 3700-1998 "Masonry structures", and the relevant conditions of Development Consent.
Further, I am appropriately qualified and experienced to provide the certification for this component of the project.
Signature Mushal Mon Date 20/9/07

PITTWATER COUNCIL

Component Certificate

DA No:

N1232/00

CC No:	
Property:	1148 BARRENJOEY ROAD PALM BEACH NSW 2108
	Floor Levels
I	Greg Gearin of Bowdens Group
At	PO Box 387, Parramatta NSW 2124 (Mailing Address)
Being a regist	ered surveyor, my qualifications being:
Bachelor Sun	veying UNSW 1982
Registered Su	urveyor 1985
approved plar	that the floor levels generally comply with the levels nominated on the as or by any conditions of Development Consent. appropriately qualified and experienced to provide the certification for this the project.
Signature	4 5003 Date 03/08/07

Stainless Timber Glass

102 Walkumatta Rd Newport 2106 Phone: 0404 063 335 / 0420 314 941

Fax: 9997 5640

CERTIFICATE OF COMPLIANCE

I hereby certify that the balustrades for job: 62 Palm Beach Road, Palm Beach have been installed to resist loads in accordance with AS 1170.1-1989.

Yours Faithfully

JAKE WILSON

Jew Cut



VISION 3 WINDOW SYSTEMS PTY LTD

P.O. Box 387, Brookvale N.S.W. Australia 2100 Ph: 02 9905 9700 Fax: 02 9905 9755 Email: jo@vision3windows.com.au ABN: 89 119 367 494

3rd September, 2007

House 4, 56 Palm Beach Rd, Palm Beach

All Vision 3 Windows and Sliding Doors are manufactured to meet the wind loading/structural and water performance requirements specified at the time of ordering. The products are labeled to indicate the AS2047 performance ratings which they meet. This conforms to the requirements of the Australian Building Code Amendment No.13 for Class 1 Buildings. This amendment requires window manufacturers to label windows and sliding doors with the wind loading/structural and water performance ratings of the window/door.

AS1288 is specified within AS2047, therefore products which are labeled as meeting AS2047 must also be glazed to meet AS1288.

All Vision 3 products are glazed to meet the requirements of AS1288 based on information supplied at the time the windows/doors are ordered.

In some instances the positioning of a window will determine the type of glazing required for the glazing to meet AS1288. Thus it is important that windows are installed in the locations specified at the time of ordering. Windows which are broken at site must be re-glazed to meet AS1288 for the location and the Class of Building in which they are installed.

Based on the above details it is not necessary for Vision 3 to issue a glazing certificate. Vision 3 is unable to issue a glazing certificate without carrying out a detailed inspection and an associated charge for that inspection to very that windows have not been replaced, exchanged, installed in incorrect locations or re-glazed incorrectly.

Vision 3 Window Systems Pty Ltd

OMAR RUTHERFORD



Pittwater Council

Component Certificate

DA No:

N1229/00 N1232/00

CC No:

Property: 1148 BARRENJOEY ROAD PALM BEACH NSW 2108

Poof Cladding

ROOI Clauding RC-1
at One Warraba RS, Narrabeen (Mailing Address)
being an:
□ accredited certifier
□ licensed builder
licensed roofer
my qualifications being: Roof Pleember.
hereby certify that the roof cladding has been installed, fixed and flashed in accordance with Part 3.5.1 "Roof cladding" of the Building Code of Australia Housing Provisions, relevant Australian Standards and the relevant conditions of Development Consent.
Further, I am appropriately qualified and experienced to provide the certification for this component of the project.
Signature Date $7 - 8 - \infty$

PITTWATER COUNCIL

Component Certificate

DA No:	N1232/ 00
--------	-----------

CC No:

Property:

1148 BARRENJOEY ROAD PALM BEACH NSW 2108

Roof Ridge Levels

l	Greg Gearin	of	Bowdens Group
At	PO Box 387, Parramatt		
	(Mailing Addres	s)
Being a regi	stered surveyor, my qualif	ications being:	
Bachelor Su	rveying UNSW 1982		
Registered S	Surveyor 1985		
	ify that the roof ridge lev d plans or by any condition		comply with the levels nominated on nent Consent.
	m appropriately qualified a of the project.	ind experience	d to provide the certification for this
Signature	- Glaces	Date	27 July 2007



N 1232/00 Pittwater Council Component Certificate

DA No:

N1230/00

CC No:

Property: 1148 BARRENJOEY ROAD PALM BEACH NSW 2108

Smoke Alarms

SA-1

1 Mark Rysn (Name)	of Mick Kyan Electrican Services P
at	
	(Mailing Address)
being a qualified electrician, my qual	lifications being:
Lie Electricis	
hereby certify that the smoke alarms mains electrical supply in accordance of Australia Housing Provisions, AS 3 conditions of Development Consent.	s have been located, installed and connected to the with Part 3.7.2 "Smoke Alarms" of the Building Code 3786-1993 "Smoke Alarms", and the relevant
Further, I am appropriately qualified a component of the project.	and experienced to provide the certification for this
Signature //	Date 18 -7 - 07 -

08-OCT-2007 09:56 FROM NBCONSULTING

TO 99491544

1007 4



Pittwater Council Component Certificate

DA No:

N1229/00

N 1232 W

CC No:

Property: 1148 BARRENJOEY ROAD PALM BEACH NSW 2108

Onsite Stormwater Detention OSD-1 RICHARD (Name) of NB GASUCTIAL EAC. PL (Name) (Mailing Address) being a practising civil engineer with corporate membership of the institute of Engineers Australia (MIE), or eligible to become a Corporate member and having appropriate experience and competence in the related field, my qualifications being: CPANS MIE (Aust) NPER hereby certify that the onsite stormwater detention has been constructed in accordance with the plans nominated on the Development Consent and/or Construction Certificate, and the relevant conditions of Development Consent. Further, I am appropriately qualified and experienced to provide the certification for this component of the project. Signature Date

PITTWATER COUNCIL

Component Certificate

N1232/00

DA No:

CC No:	
Property:	1148 BARRENJOEY ROAD PALM BEACH NSW 2108
	Driveway Construction DW-1
Į.	Greg Gearin of Bowdens Group
At	PO Box 387, Parramatta NSW 2124 (Mailing Address)
Being a regist	tered surveyor, my qualifications being:
Bachelor Sun	veying UNSW 1982
Registered St	urveyor 1985
approved pla relevant cond	that the driveway has been constructed generally in accordance with the ans and/ or Council's policy DCP-E3 and/ or AS2890.1-1993 and the itions of Development Consent appropriately qualified and experienced to provide the certification for this the project.
Signature	

PITTWATER COUNCIL

Component Certificate

DA No: N1232/ 00

CC No:	
Property:	1148 BARRENJOEY ROAD PALM BEACH NSW 2108
	Excavation and/ or Filling
1	Greg Gearin of Bowdens Group
At	PO Box 387, Parramatta_NSW_2124 (Mailing Address)
Being a regist	ered surveyor, my qualifications being:
Bachelor Surv	eying UNSW 1982
Registered Su	rveyor 1985
nominated or accordance v	that the site excavation and / or filling (including around the trees the approved plan as being retained) has been carried out generally in with the levels shown on the approved plans or as nominated by and Development Consent.
Further, I am component of	appropriately qualified and experienced to provide the certification for this the project.
Signature	Date 27 July 2007



05 October 2007

To: Pittwater Council, Component Certificate

DA: N1232/00

Property: 1148 Barrenjoey Road, Palm Beach, NSW, 2108 ('House 4')

I, Selena Hannan, of Selena Hannan Landscape Design, at PO Box 549 Avalon Beach NSW 2107, being a qualified horticulturist, my qualifications being Associate Diploma of Applied Science (Landscape) and Advanced Certificate of Urban Horticulture, hereby certify that the site landscaping has been completed generally in accordance with the details shown on the approved plans or as required by any Condition of Development Consent.

The Conditions of Consent refer to works (shown on the Landscape Plan) that were to be carried out and certified by other consultants, being an Arborist and a Bushland Management Consultant. Site landscaping, certified here as being complete, does not include these other consultants' scope of work.

I am appropriately qualified and experienced to provide the certification for the landscaping component of the project.

Yours sincerely,

Hawan

Selena Hannan

DA No:

N1229/00 N1 |232 CO

CC No:

Property: 1148 BARRENJOEY ROAD PALM BEACH NSW 2108

Bushland Management Strategy

1 Stephen Toakley of total Earth Carl (Name) Of total Earth Carl
at 37 Irrawong Rd, NM Narmbeen 2101 (Mailing Address)
being a qualified and appropriately experienced bushland management consultant, my qualifications being: Centian in bush Regeneration Padstow TATE 21995
hereby certify that the bushland management strategy or plan has been completed in accordance with the details shown on the bushland management strategy or plan and the relevant conditions of Development Consent.
Further, I am appropriately qualified and experienced to provide the certification for this component of the project.
Signature 5 12 Date 28/9/07



DA No:

N1229/00

N1232/00

CC No:

Property: 1148 BARRENJOEY ROAD PALM BEACH NSW 2108

Native Vegetation Planting

(Name) of Total Earth Care (Business)
at 37 (Mailing Address)
being a qualified and appropriately experienced bushland management consultant, m qualifications being:
Cetiticate in Bush Regeneration
Palstow TAFE 1995
hereby certify that local native vegetation only has been planted within the creekline corridor or riparian zone consistent with:
Species listed in the Warriewood Valley Landscape Masterplan
2. Warriewood Valley Water Management Strategy and Specifications
and the relevant conditions of Development Consent.
Further, I am appropriately qualified and experienced to provide the certification for this component of the project.
Signature S Tab. Date $28/9/07$

Mr. Darren Leete C/O Raypond P/L PO Box 1364 DEE WHY NSW 2099

19 July 2007

Dear Mr. Leete

RE: Tree Inspection at 'Observation Point', 1148 – 1152 Barrenjoey Rd., Palm Beach.

URBAN FORESTRY

TREE MANAGEMENT
CONSULTING ARBORICULTURISTS
HORTICULTURISTS
LANDSCAPE DESIGNERS

At your request I visited the above site on 10th July 2007, to carry out a limited visual inspection of trees to be retained as identified in the conditions of development approvals DA N012281/00, N01229/00, N01230/00, N01233/00 and N01232/00.

During my inspection of the site, I noted there are trees that exhibit an increase in health and vigour which is most likely attributable to recent good rainfalls in the area, and additional water required during establishment of site landscaping. I did note that the large tree in the site (Tree 23 as identified in the Pre-construction Tree/Vegetation Report by Pittendrigh Shinkfield Bruce (PSB) Pty Ltd. April 2003), has deteriorated since my last inspection, but point out this tree was identified as in decline in the PSB report. The tree has not sustained physical damage as a result of the approved site works

The health and condition of the Port Jackson Figs remains unchanged from that noted in the PSB report.

Hand digging was carried out adjacent to the trees identified as T25 (Cheese Tree), and Trees 461 and 463, where walls or decking was proposed within the tree root zones. The driveway near Tree 23 has been elevated to reduce impacts on the tree root zone.

URBAN FORESTRY AUSTRALIA Consulting Arboriculturists ABN 90 639 906 218

PO Box 151 Newport Beach NSW 2106 Email:cat@urbanforestryaustralia.com.au

Telephone: (02) 9918 9833 Facsimile: (02) 9918 9844

Mobile: 0414 997 417

There are some damaged branches to trees where the recent storms may have caused branch failures and tearing. General pruning should be carried out on these trees to improve their growth, and reduce the potential for insect or pest attack.

Any pruning must be carried out by a qualified tree worker, of at least an AQF3 level of training, and in accordance with Australian Standard 4373-2007 Pruning of Amenity Trees.

I am satisfied that the trees to be retained have been appropriately protected during the course of site development. The majority of those trees do not show a decline in health or condition directly attributable to any works, and in some cases, the health and vigour of trees has improved as a result of associated works.

Should you require further assistance with this matter, or require my liaison with Council officers, please do not hesitate to contact me.

Yours sincerely,

Catriona Mackenzie

Consulting arboriculturist and landscape designer. Certificate of Horticulture Honours

Diploma of Horticulture (Arboriculture) Distinction

Associate Diploma of Applied Science (Landscape) Distinction

Member of the Australian Institute of Horticulture

Member of the International Society of Arboriculture

Member of the Institute of Australian Consulting Arboriculturists

P. 04/04



Pittwater Council Component Certificate

DA No:

N1252 60

CC No:

Property: 1148 BARRENJOEY ROAD FALM BEACH NSW 2108

Structural Certification Class 2-9

at (Mailing Address)


being a qualified structural engineer with corporate membership of the institute of Engineers Australia (MIE), or eligible to become a Corporate member and having appropriate experience and competence in the related field, my qualifications being:

Cleng ME(two) NPER

hereby certify that the development has been inspected and was found to be atructurally sound and in accordance with section B "Structure" and Specification C1.1 "Fire Resisting Construction" of the Building Code of Australia, any standards adopted by reference within the Building Code of Australia, approved Development Consent plans and any conditions of Development Consent.

Further, I am appropriately qualified and experienced to provide the certification for this component of the project.

Signature ...



1 Prince Albert Rd Sydney NSW 2000 Ph 1300 OLANDS Fax (02) 9233 4357 www.lands.nsw.gov.au

RAYPOND PTY LIMITED P.O. BOX 1364 DEE WHY 2099

Date: 10/8/2007

PLAN REGISTRATION ADVICE

PLAN NUMBER: DP1115251

THE ABOVE PLAN WAS REGISTERED ON 10/8/2007

FOR READY IDENTIFICATION OF DOCUMENTS REFERRED TO IN DEPARTMENTAL CORRESPONDENCE, PLEASE SHOW YOUR REFERENCE IN THE AREA PROVIDED ON THE LODGMENT FORM

ANY INQUIRIES REGARDING DELIVERY OF TITLE DOCUMENTS LODGED

WITH THE PLAN OR NEW CERTIFICATE(S) OF TITLE THAT HAVE ISSUED

MAY BE DIRECTED TO PLAN INQUIRIES ON (02) 9228 6798

WARWICK WATKINS REGISTRAR GENERAL

