

Engineering Referral Response

Application Number:	Mod2022/0450
Date:	07/09/2022
То:	Stephanie Gelder
Land to be developed (Address):	Lot 13 DP 1275411, 1180 Barrenjoey Road PALM BEACH

Reasons for referral

This application seeks consent for the following:

- New Dwellings or
- Applications that require OSD where additional impervious area exceeds 50m2 or

NSW 2108

- Alterations to existing or new driveways or
- Where proposals affect or are adjacent to Council drainage infrastructure incl. watercourses and drainage channels or
- Torrens, Stratum and Community Title Subdivisions or
- All new Commercial and Industrial and RFB Development with the exception of signage or
- Works/uses in flood affected areas

And as such, Council's development engineers are required to consider the likely impacts on drainage regimes.

Officer comments

07/09/2022:

Proposal is for alterations and additions to previously approved development under application number N0379/16 and subsequent modifications MOD2018/0272, MOD2019/0048 and MOD2021/0725. Proposal includes internal alterations and additions including;

- · construction of new playroom/cellar,
- reducing parking space in basement for only one car by increasing livable area and
- re-construction of recently dilapidated retaining wall (due to heavy rainfall) on the southern boundary.

Stormwater

The submitted SEE report states that the new hardstand area is between 50 -70 sqm hence there is provision of an OSD tank but no plans have been submitted in this context.

Geotech:

Site is mapped as H1 on Council's Geotechnical Hazard map and proposal is to excavate for new cellar under existing dwelling hence an updated Geotech Report with form 1 and 1a is required.

Wall

The survey plan summited with this application does not show any retaining wall at southern boundary. However based on the survey plan submitted at DA (N0379/16) shows a retaining wall along southern boundary located within next door property no. 1178 Barrenjoey Road. Clarification and survey details are required.

MOD2022/0450 Page 1 of 2



The proposal is therefore unsupported.

Note: Should you have any concerns with the referral comments above, please discuss these with the Responsible Officer.

Recommended Engineering Conditions:

Nil.

MOD2022/0450 Page 2 of 2