Bushfire Planning Services Pty Limited



Matthew Willis (Grad Dip Design for Bushfire Prone Areas.) 15 Parkcrest Place Kenthurst 2156 Tel: 02 96543228 Mob: 0428 408 577 Email: mattw@bushfireconsultants.com.au

Thursday, 27 February 2020

Bushfire Attack Level (BAL) Assessment

In relation to proposed development at:

23 Reynolds Cres Beacon Hill.

Bushfire Planning Services Pty Limited has undertaken a Bushfire Attack Level [[BAL] risk assessment in accordance with the requirements of AS3959-2009, Table 2.4.2 *'Determination of Bushfire Attack Level [BAL] - FDI 100 1090K]* for the above-mentioned property.

THIS REPORT IS NOT SUITABLE FOR DA SUBMISSION.

Based on the site assessment contained in Table 1 of this document, this is to certify that the subject site on lot 20, DP218395, number 23, Reynolds Cres Beacon Hill has been assessed as not being BAL FZ or BAL 40 and is likely to have an anticipated radiant heat level of less than 12.5kw/m² and the subsequent BAL level is AS3959, 2009 BAL-12.5.


Direction	Distance of APZ	Vegetation Classification	Assessment of Effective Slope	Bushfire Attack Level (BAL)
North	>100m	Managed land	N/A	BAL-LOW
East	72m	Managed land/forest	0-5 degrees downslope	BAL-12.5
South	>100m	Managed land	N/A	BAL-LOW
West	>100m	Managed land	N/A	BAL-LOW

Table 1: Reference AS3959, 2009 Table 2.4.2

Determination of category of bushfire attack for the site and subsequent required building standards. <u>This table is not to be used as construction advice</u>. The BAL level is only shown for the aspect considered to be at the highest risk from bushfire attack.

Notes:

- 1. This Certificate is valid for 12 months from the date of issue.
- 2. This certificate does not constitute construction advice. Its purpose is to satisfy the requirements of section 3.4(2)(a) of the Exempt and Complying Development SEPP.
- 3. A level described as BAL-LOW in table 1 does not necessarily reflect the construction level UNLESS ALL ASPECTS are BAL-LOW.
- 4. Further consideration by other persons will need to be given regarding the proposals compliance with the other aspects of section 3.4 of the SEPP and specific requirements of AS 3959 2009 and the Rural Fire Service that are not included in this certificate.
- 5. The BAL level for this proposal has been calculated based on the plans supplied by, Studio ML dated 25/9/2019. (Attached)



Map 1. The above is an extract of the local councils bushfire prone land map. The subject lot is indicated by the black arrow.



Photo 1. The yellow dashed circle on the aerial photograph above indicates the 100m study area for this proposal.

COMPLYING DEVELOPMENT CERTIFICATE

23 Reynolds Crescent BEACON HILL

Alterations and additions to an existing two (2) storey dwelling.



design : STUDIO ML

residential : mutli - unit dwellings : alterations & additions : commercial

