

Heritage Referral Response

Application Number:	DA2023/0849
Proposed Development:	Alterations and additions to a commercial premise
Date:	05/10/2023
То:	Kye Miles
Land to be developed (Address):	Lot 1 SP 67337 , 1 / 63 - 67 The Corso MANLY NSW 2095

Officer comments

HERITAGE COMMENTS

Discussion of reason for referral

The proposal has been referred to heritage as the subject property is a heritage item, being a part of a group listed **Item I106 - Group of commercial buildings -** All numbers, The Corso and sits within the **C2 - Manly Town Centre Conservation Area**. It is also within the vicinity of a number of heritage items:

Item I110 - New Brighton Hotel - 69-71 The Corso

Item I233 - Commercial and residential building - 12 Sydney Road

Item I104 - Street trees - The Corso (from Whistler Street to Sydney Road)

Details of heritage items affected

Details of the heritage items as contained within the Manly Heritage inventory are as follows:

Item I106 - Group of commercial buildings

Statement of significance

The streetscape and its special qualities are of major significance to the state. The Corso has important historical links to the development of tourism and recreation which is still present and likely to continue. It's role as the pedestrian link between harbour and ocean, city and sea - for the tourist, is fundamental to Manly's status as a resort.

Physical description

The Corso acts as a low scale horizontal corridor which steps down from the harbour to the ocean. The atmosphere of The Corso is of a 19th century place. Its special qualities include the contrasts of horizontal (low scale architecture) and vertical (planting) dimensions, and urban and natural elements.

C2 - Manly Town Centre Conservation Area

Statement of significance

The Manly Town Centre Conservation Area (TCCA) is of local heritage significance as a reflection of the early development of Manly as a peripheral harbor and beachside village in the fledgling colony of New South Wales. This significance is enhanced by its role as a day-trip and holiday destination during those early years, continuing up to the present time, and its association with H G Smith, the original designer and developer of the TCCA as it is today. The physical elements of the TCCA reflect this early development and its continued use for recreational purposes, most notably the intact promenade quality of The Corso and its turn of the century streetscape, as well as key built elements such as hotels, and remaining original commercial and small scale residential buildings.

DA2023/0849 Page 1 of 4



Item I110 - New Brighton Hotel

Statement of significance

This building is an example of exotic Egyptian-like motifs and Inter-war Free Classical style. The hotel is of major significance due to its contribution to the streetscape, its visual/textural interest and its association with early 20th century development of the resort. An unusual design utilising exotic Egyptian-like motifs appropriate to the resort location such as columns faintly reminiscent of the Brighton Pavilion. The building is an important feature on the corner of Sydney Rd and the Corso and its eclectic design contributes to the rich collection of architectural styles in the streetscape of the Corso.

Item I233 - Commercial and residential building

Statement of significance

The building reflects its former use as a fire station. It has a strong presence in the Sydney Road streetscape and contributes to the overall cultural heritage significance and character of the Town Centre Conservation Area.

Physical description

Two storey, brick rendered building with parapet. The former Fire Station was designed in Federation Free style. The building, although now redeveloped, retains its picturesque facade that features a curved parapet, heavily moulded entablature and group of three arch headed, elongated windows. The words 'Metropolitan Fire Brigade 1897' are embossed on the parapet with 'Manly' below. The windows are timber framed double hung with round headed highlight and multiple small sashes. The face brickwork is now painted but highly contrasted with render, especially the detail such as voussoirs. The adjoining wing to the south-east appears to have been a later addition of face brickwork with similar style windows and entablature but without a high parapet.

Item I104 - Street trees

Statement of significance

Part of earliest planting on The Corso c.1850's by H.G. Smith. Historic and aesthetic importance to the streetscape.

Physical description

Centre planting of Ficus Macrophylla (Moreton Bay Fig) Remnant Palm planting (Phoenix Canariensis) of 1928.

Other relevant heritage listings		
SEPP (Biodiversity and	No	
Conservation) 2021		
Australian Heritage Register	No	
NSW State Heritage Register	No	
National Trust of Aust (NSW)	No	
Register		
RAIA Register of 20th	No	
Century Buildings of		
Significance		
Other	No	

Consideration of Application

The proposal is seeking consent for alterations and additions to the existing building to facilitate a change the use of the existing ground floor retail at Unit 1 / 63-67 The Corso, Manly into three commercial tenancies requiring replacement shopfronts and internal works. The existing shopfront is proposed to be replaced with slim metal-framed glazed storefronts with a small section of wall

DA2023/0849 Page 2 of 4



above the shopfronts. Heritage supports the following statement from the HIS, submitted with this application: "As an alternative to reconstruction, a shopfront design interpretive of the original interwar version could be proposed. This occurred with an earlier scheme reviewed by the author of this report when only two tenancies were proposed. It included recessed entrances and low-tiled stall boards. From a heritage impact perspective, it was preferable."

The proposal should revise the shopfront treatment to comply with the controls of the related parts of Manly DCP 2013 including the following controls:

- Manly DCP 2013 Schedule 6 The Corso: Site Specific Controls require the following for 63-67 The Corso:
 - re-paint façade to highlight the Art Deco detailing.
 - reconstruct ground floor shops as opportunity arises.
- Manly DCP 2013 5 Special Character Areas and Sites 5.1.2 The Corso require specific controls for developments located within The Corso including the following:

5.1.2.13 Shop-fronts are to be Reinstated

- a) Where shop-fronts have been removed and replaced with shuttered openings, the reinstatement of shop-fronts is supported for aesthetic and historic reasons. New Shuttered openings will not be permitted.
- b)New shop-fronts should comprise a 'frame' established by masonry ends read as vertical continuations of the façade above, and by a solid horizontal plinth between the ground and the window sill. The design of the space within this frame can reflect the use of the premises, and utilise contemporary design. See Figure 51 Shop-fronts within a masonry frame.

The proposed external colours should also be revised to remove the proposed awning colour "Dulux Monument" from the external finishes schedule as colours should be selected with an emphasis on light and neutral colours that are based on historical evidence and harmonise. Dark colours, such as black and grey, are not considered appropriate within The Corso.

Revised comments - 05 October 2023

Amended drawings, received on 20 September 2023, have resolved the main concern that Heritage had with the proposal, by providing recessed entrances and low-tiled stall boards to the proposed shopfront. The amended colour scheme is also considered to not have an adverse impact within the heritage context.

Therefore, no objections are raised on heritage grounds and no conditions required.

Consider against the provisions of CL5.10 of Manly LEP 2013. Is a Conservation Management Plan (CMP) Required? No Has a CMP been provided? No Is a Heritage Impact Statement required? Yes Has a Heritage Impact Statement been provided? Yes

DA2023/0849 Page 3 of 4



The proposal is therefore supported.

Note: Should you have any concerns with the referral comments above, please discuss these with the Responsible Officer.

Recommended Heritage Advisor Conditions:

Nil.

DA2023/0849 Page 4 of 4