





### FINAL OCCUPATION CERTIFICATE

Date Application Received	22-04-2015			
Council	Pittwater Council			
Occupation Certificate No.	2015-066-FOC	Date Approved	21-10-2015	
CDC No.	2015-066	Date Approved	13-05-2015	
Certifying Authority	Craig Formosa			
Accredited Certifier	Craig Formosa	Accreditation No.	BPB0124	
Accreditation Body	Building Professionals Board			
APPLICANT DETAILS	ar productive knows disk in the second subsites			
Name	Michael Butler	Contact Number	0402 067 988	
Address	14 Elaine Avenue, Avalon Beach NSW 2107	The second secon	A Comment of the Section of the Sect	
OWNER DETAILS				
Name	Michael & Kelly Butler			
Address	14 Elaine Avenue, Avalon Beach NSW 2107			
DEVELOPMENT DETAIL	S			
Subject Land	14 Elaine Avenue, Avalon Beach NSW 2107	Lot No. 32	DP 16153	
Description of Development	Alterations & additions to an existing dwelling			
Class of Building	1a Value of Work \$77,000.0			
	THE BUILDING IS SUITABLE FOR OCCUPAT	TION		
Certificates Attached	Mandatory Inspection Reports, Builders Basix Co Basix Completion Receipt, Fire Rated Wall, Term Waterproofing.			
RECORD OF INSPECTI	ons			
Site Inspection prior to issue of Complying Development Certificate 11-03				
Timber Frame – prior to linir	g		29-05-15	
Waterproofing			19-06-15	
Final Inspection – Issue of C	Occupation Certificate		17-09-15	

### CERTIFICATION

- I, Craig Formosa, as the certifying authority am satisfied that;
  - (a) the building will not constitute a hazard to the health or safety of the occupants,
  - (b) a current Complying Development Certificate has been issued for the building in respect to the plans and specifications for the building,
  - (c) the building is suitable for its use under the Building Code of Australia, and
  - (d) all the prescribed conditions of the SEPP have been satisfied.

Signed:

Date: 21-10-2015

PCA Accreditation No. BPB0124

Opmor

Accreditation Body: Building Professionals Board

a Rac: 38/915 28/10/15.

Form Building Certifiers Pty Ltd PO Box 1824, DEE WHY NSW 2099 Phone: 8021 9313 Fax: 8021 9313

### **BUILDING INSPECTION** RESULT SHEET

BPB2185

Number

Date of Inspection



Site Inspection v	PRE COC	
APPLICATION DETAILS		7
Date App. Received:	6-3-15.	
Property Address:	14 Elaine Ave, Walan.	
Development Type:	ALTERATIONS TO EXISTING	
Company Name:	RAPOPLANS	
Owners Name & No.:	BUTLER	
DA No. (If Applicable):	NIA	
OBSERVATIONS FROM	SITE VISIT:	
Application Type	Possibly CD CC only	
Site Access	1	
Stormwater Drainage	TO STREET- EXISTING	
Kerb & Gutter		
Overhead Power Lines		
Easements	CHECK CERT OF TITLE - REQUEST	
Tree Removal	nia .	
Bushfire Hazard		
Flooding	-Likely or not likely	
Slope of Block	FLAT	
Retaining Walls	I NIA	
Set Backs	GARAGE O. HM TO BOUNDARY	
Sewer Mains		
Fire Safety Measures	Fire Hydrant □ Fire Hose Reels □ Exit Signs □	
(Class 2-9 Only)	Portable Fire Extinguishers ☐ Emergency Lighting ☐	
( 2 0 0111)/	Other □ ∩ L/T	
* Do the plans and speci and/or existing buildings	ifications adequately & accurately depict existing site conditions?	N.
	of the site or buildings that would mean the development	
cannot be CD or comply	with the BCA? Yes \( \triangle \) No \( \triangle \)	V
If Yes, give details: /	with the BCA? Yes ☐ / No ☐ DILL NEED TO BE FIRE RATED	
	ommenced? Yes 🗆 / No 🕽	
	Jimmencedr Tes El 7 No C	Post-
To giro doudio.	OF MERS, SOUTH STORN SERVICE STORN S	J
Comments:		
10a 5 muchur	e changing to Ia	
CONDOT BE	155UED WIDER PART H, MUST BE PA	ART =
FIRE RATING	TO ISSUES TO BE ADDRESSED.	11 5 " hand
	property sertock over 900mm + no	10:00
neighbour ing	rigidity between over 40mm + 10	WIND
MACHICA BOUR	UITKY.	7
	Craig Formosa	
Št.	BPB0124	
Accreditation	Trish Gray 1910	



# **INSPECTION REPORT** 6264

Owner	☐ Applicant	Builder	Other
Name Four	e Hammers		Tel/Email
PROPERTY	NATIONAL DESCRIPTION OF THE PROPERTY OF THE PR		is used to and a supplication of the supplicat
14 EA.	INE AVE, AV.	ALON	
INSPECTIO	N TYPE		
FRAMING	Commence of the Commence of th		
	N OUTCOME		
Certifier Opini			Action Required (read with NOTES below)
☐ Inspection s	stage is Satisfactory		☑ NO re-inspection required
☑ Inspection s	tage is Satisfactory subj	ect to Action Required	☐ Re-inspection required
	stage is Not Satisfactory		☐ Tick if result has also been given verbally
NOTES			
MODAK L	VALL LINING	TO EXT.	WALL TO ACHEIVE
FRL 60/	160/60		
KORDON	WHITE AT	NT PROTECT	ION IN PLACET PEST
PONTROZI	ER TO 155	UE CERTIFI	CATE OF COMPLIANCE
Exs. Su	43 APPEAR	s 70 HAV	(E HAD) A WATERPROOFER
WEMBRAS	ME APACIE	D TO PREVI	ENT RISING DAMP.
BOILDER	78 n_550€	CERTIFICATE	E OF CONPUANCE
WAZE &	2007 x Fre	SOR FRAMIN	4 ALL GENERALS
	SATISTACTO		
_			
1			29 15 120 15
Accredited Cer	rtifier - BPB	1714	Date



## **INSPECTION REPORT** 6456

□ Owner	☐ Applicant	Builder	Other
Name For	R Hannet	KS	Tel/Email
PROPERTY	A. T.		
14 EN	AINE AV.	AVAZON	
INSPECTION	TYPE		
VATERI	ROOTING		
INSPECTION	OUTCOME		
Certifier Opinio	on		Action Required (read with NOTES below)
☐ Inspection st	age is Satisfactory		TNO re-inspection required
Inspection st	age is Satisfactory sub	oject to Action Required	☐ Re-inspection required
☐ Inspection st	tage is Not Satisfactory	1	☐ Tick if result has also been given verbally
NOTES			
WATERPI	ROOTING C	7 WET AK	EA DONE SATISTACTOR
91- P	At rox	PANK-1RAT	ion LS IN WAI
INING	10000	>C AIFT	VATTILL CFAITA
_	MUST		John Jan Jan F
0 48		TER ENTER!	
DVIRAC	TUR 70 /	issuf CERT	17-12-17 OF COMPLIANCE
			10 /
		>	19 16 120 15
Accredited Cert	tifier - BPB	1714	Date



# **INSPECTION REPORT** 6129

□ Owner □ Applicant □ Builder	Other
Name Butler / Four nammers	Tel/Email
PROPERTY ADDRESS	
14 Elaine Ave, Avalon	
INSPECTION TYPE	
Final	
INSPECTION OUTCOME	
Certifier Opinion	Action Required (read with NOTES below)
Inspection stage is Satisfactory	☐ NO re-inspection required
☐ Inspection stage is Satisfactory subject to Action Required	☐ Re-inspection required
☐ Inspection stage is Not Satisfactory	☐ Tick if result has also been given verbally
NOTES	
Prounds the following certifical	tes - waterproofing
	- termite protetrar (if app)
	-Smoke alarmi
- Builders	compliance statement for Ba.
	cooling of existing Slaby
<b>a</b>	ire rated wall,
Modale f	
- Wazer	ig certificate
Once above untificates are	received oc ax to be rel
mbutter@ Kordomenty	a. com
manyether a Kordonen a	7.*
invige posterior streets	
Chermore	17 1 09 120 15
Accredited Certifier - BPB 0124	Date

# **BASIX Completion Receipt**

Receipt no.: CR-1445398682756-A210774

This receipt is confirmation that the certifying authority identified below has satisfied the requirements of clause 154C of the Environmental Planning and Assessment Regulation 2000 for the development described in the 'BASIX Certificate details' section below.

Director-General Date of issue: Wednesday, 21/10/2015



### Principal certifying authority

Name: Craig

Accreditation scheme: BPB


Accreditation number: 0124

### Final Inspection

Date of final inspection: Thursday, 17/09/2015

### **BASIX Certificate details**

BASIX Certificate no.	A210774
Project name	Butler
Street address	14 Elaine Avenue
Suburb	Avalon
Postcode	2107
Local Government Area	Pittwater Council



# Four Hammers Building and Carpentry

### BASIX COMPLIANCE LETTER

22/09/2015

14 Elaine Av Avalon

Basix Certificate number: A210774

To whom it may concern,

We Troy Tester and Kristian Gray Builder/Director of Four Hammers Pty. Ltd state that the components that Four Hammers Pty Ltd was contracted to complete, meet the requirements set by the BASIX A210774

R2.0 insulation in external walls.

R2.5 insulation to ceiling.

75 mm existing foil back roofing insulation.

Sewer connection to Ensuite is to the existing sewer.

Lighting is a minimum of 40% LED.

Taps, toilets and shower heads are 3 star or above water rating (supplied by client)

The doors and windows were installed as per manufactures specification and to meet Australian standards

Kordon termite barrier was installed to the garage conversion only.

The existing garage floor has 2 coats of Ardex WPM300 water based epoxy membrane applied.

Kristian Gray

Builder/Director Four Hammers Ptv. Ltd.

Phone: 9972 4950

Fax: 9944 0131

Email: builders@fourhammers.com.au WEB: www.fourhammers.com.au

32 Albert Ross (North Avaron NSW 2)37 P (02) 9918 6030 P (02) 9918 0894 IM 0414 918 088 email: rwabuild@optusnet.com.au Burong Lt No 16865C ABN 743814 6664

29/05/2014

Project: 14 Elaine Avenue Avalon Beach

### BCA COMPLIANCE Fire Safety Measures

This is to certify that the external wall lining of attached garage have been installed to achieve a 60/60/60 fire rating as required. The systems used was Modak board, certified (CMA-CM40007) and tested for timber framing. The soffit and fascia boards are constructed of non-combustible materials.

Relevant BCA Codes include.

AS3837, AS1648.

Yours Sincerely

Robert Adema

Lic No 41165

MBA Member 1861435





# PRODUCT WARRANTY



Warranty Number: NK20150900204231

Expiry Date: 04/06/2016

Property Address: 14 Elaine Avenue

AVALON BEACH

NSW 2107

### Warranty Scope

This warranty is given by Bayer CropScience Pty Ltd (Bayer) (ACN 000 226 022) of 391-393 Tooronga Road, Hawthorn East, Victoria 3123 (Phone number 1800 804 479) in respect of the Kordon Barrier products (as defined below).

Your rights under this warranty are in addition to and are not intended to in any way detract from or limit any rights you have under the Australian Consumer Law or any other applicable laws.

Kordon has been extensively tested by the CSIRO and has been evaluated to have a durability and design life in excess of fifty (50) years. This represents the life expectancy of a building as deemed by Australian Building Codes Board (ABCB). This warranty document represents twelve (12) months coverage for the insured events and is renewable for the life of the building upon inspection by a qualified timber pest inspector, approved and authorised by Bayer.

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure.

### 1. Definitions

In this warranty document:

- Accredited Installer means any person appointed by Bayer to be an accredited installer of the Kordon Barrier
- b. Australian Consumer Law means the Australian Consumer Law set out in Schedule Two of the Competition and Consumer Act 2010 (Cth) and in any applicable state and territory acts.
- Building means the original structure in which the Kordon Barrier is installed (as specified in the Certificate of Compliance).
- d. Certificate of Compliance means a certificate issued by an Accredited Installer certifying that installation of the Kordon Barrier complied (amongst other things) with Bayer's recommended installation procedures.
- e. Installation Date means the date of installation of the Kordon Barrier, as specified in the Certificate of Compliance.
- Kordon Barrier means the Kordon termite barrier manufactured by Bayer.
- g. Owner means the owner of the Building.
- Warranty Period 1 year from the installation date or anniversary of the installation date in the case of

a policy renewal. Refer to Warranty Scope above. **Life of Building** deemed to be 50 years as deemed by the Australian Building Codes Board (ABCB).

### 2. Warranty

2.1 Bayer warrants to the Owner that (subject to the exclusions in paragraph 3 below) for the duration of the Warranty Period, the Kordon Barrier will restrict the entry of subterranean termites into the Building THROUGH THE KORDON BARRIER.

### 3. Circumstances where warranty does not apply

- 3.1 The warranty in paragraph 2 does not apply where (in Bayer's reasonable opinion) termites are able to obtain entry into the Building as a result of:
  - a. damage, modifications, bridging or other interference with the Kordon Barrier by any person;
  - the Kordon Barrier being installed other than by an Accredited Installer in accordance with Bayer's recommended installation procedures;
  - alteration, structural modification, or any other changes to the Building which would or may diminish the effectiveness of the Kordon Barrier as a termite barrier;

- d. the Owner or any other person (including any occupier of the Building) allowing the Kordon Barrier to be bridged or broken by any material or matter through which termites may by-pass the Kordon Barrier and enter the Building;
- e. the finished ground level around the Building being higher than the maximum height specified in Bayer's installation manual for the Kordon Barrier; or
- f. any circumstances beyond the reasonable control of Bayer.
- 3.2 The warranty in paragraph 2 will also not apply where:
  - a. a Certificate of Compliance is not issued in respect of the installation of the Kordon Products;
  - b. damage is caused by termites other than subterranean termites; or
  - c. termites enter the Building in any way other than by a breach of the Kordon Barrier.

### 4. Warranty claim procedure

4.1 If termites are detected in the Building and have found to have gone **THROUGH THE KORDON BARRIER** by a qualified Timber Pest Inspector during the Warranty Period and the Owner wishes to make a claim under this warranty, the Owner must within seven days contact the Bayer Kordon Claims Centre as per below.

### BAYER KORDON CLAIMS CENTRE 1800 634 913

- 4.2 Any expenses incurred by the Owner in claiming under this warranty (including without limitation postal expenses, telephone calls and time incurred) will be the responsibility of the Owner.
- 4.3 If a claim is made under this warranty the Owner must provide Bayer or its representatives with access to the Building at any times nominated by Bayer (acting reasonably) to enable Bayer or its representatives to inspect the installed Kordon Barrier and any termite damage or activity.
- 4.4 A claim under the warranty in paragraph 2 can only be accepted by Bayer giving notice in writing to the Owner. Any discussion, regardless of content, with Bayer staff or representatives cannot be construed or interpreted as acceptance of a warranty claim.
- 4.5 If Bayer rejects a claim made under the warranty in paragraph 2, Bayer may (but is under no obligation to) provide reasons for the rejection.
- 4.6 For the avoidance of doubt, claims under the warranty in paragraph 2 can only be made during the Warranty Period.

### 5. Remedies

- 5.1 For the avoidance of doubt, the remedies and limitations in this paragraph are in addition to and do not limit any remedies the Owner or any other person may have against Bayer under the Australian Consumer Law or any other applicable laws.
- 5.2 If the Kordon Barrier fails to comply with the warranty in paragraph 2 and the Owner makes a claim under that warranty within the Warranty Period which is accepted by Bayer, Bayer will (subject to paragraphs 5.3 and 5.4) without charge to the Owner:
  - a. eradicate the termite infestation, repair the Kordon Barrier where practicable; and/or
  - b. cause the repair or replacement of structural timbers and/or internal timbers damaged by termites.
- 5.3 Bayer will not repair, replace or reimburse the Owner under this warranty for any damage caused by termites to:
  - a. chattels of any nature whatsoever, including (but not limited to) antiques, heirlooms, paintings, and artwork; or
  - b. any pergolas, wiring, extensions to the Building and outhouses.
- 5.4 Bayer's liability for repair and replacement under paragraph 2 of this warranty is limited to a maximum of \$250,000.00 in respect of any one warranty claim.



Date of Installation: 04/06/2015

Installation Address: 14 Elaine Avenue

**AVALON BEACH** 

NSW 2107

Company Contact:

Accounts

Company Name:

Design Pest Solutions

Address:

5, 93-99 South Creek Road

DEE WHY

NSW 2099

Phone Number:

02 8404 0619

Accreditation Number:

N134

Bayer will grant additional specific warranty conditions where required to accommodate high density, commercial constructions, government buildings, etc on documented request.



NOTE: THE ANNUAL RENEWAL OF THIS WARRANTY IS CONDITIONAL TO ANNUAL INSPECTIONS.

Visit www.kordontmb.com.au/kordon/aboutKordon/Warranty\_tmp.asp





This document is to certify that the Kordon TM8 / TB system was installed by a Bayer Accredited Installer and has been completed in accordance with the Manufacturer's specifications.

Kordon TM8 / TB complies with AS 3660,1 - 2000, the primary referenced standard of the Building Code of Australia. Kordon TB is only part of a termite management system for a new property. The slab must be constructed in accordance with the Standard; Residential Slabs and Footings Construction, AS 2870-1996.

NOTE: This document is to	be attached to Warranty Document Number:	r: NK20150900204231					
Date of Installation:	04/06/2015	Job Type: Miscellaneous job					
Installation Address:	14 Elaine Avenue	Product used:					
	AVALON BEACH	Type	Linear	Product	Total SQM		
	NSW 2107		Metres (m)	Width (mm)	solicate and the		
Builder's Name:	Four Hammers	Other	25.00	300	7.5		
Builder's Address:							
Builder's Email	troy@fourhammers.com.au						
Phone Number:	0418 609 027						
Owner's Name:	Four Hammers						
Phone Number:	0418 609 027						
Local Council:	Pittwater Council			Grand Total:	7.5		
Phone Number:	0299701111	Service Penetrations	To	otal:	0		
Company Contact:	Accounts	Kordon Kollars			0		
Installer's Name:	Fergus Bermingham	Manual Collars			0		
Company Name:	Design Pest Solutions	Wraps			0		
Address:	5, 93-99 South Creek Road	Others			0		
	DEE WHY	Total Kordon Installed:			7.50		
	NSW 2099						
Phone Number:	02 8404 0619						
Fax Number:		Date: 23/09/2015					
Accreditation Number:	N134						
Authorised Signature:	harz Barin Janes						

- The builder has been advised to maintain a 75mm hard surface inspection zone around the building perimeter.
- · Annual Termite inspections as per Australian standards are a condition of the warranty.
- Kordon is installed as per the manufacturer's specifications. Refer to the site installation drawing for details.
- · Warranty and compliance only applies to the areas where Kordon has been installed.
- Where Kordon has been installed to an extension of a building no warranty applies if termites gain entry from the existing structure.
- · No pre-installation site inspection report as recommended by AS3660.1 was carried out.
- Kordon has been installed to service penetrations and perimeter to manufacturer's specifications.







This document is to certify that the Kordon TMB / TB system was installed by a Bayer Accredited Installer and has been completed in accordance with the Manufacturer's specifications.

Kordon TMB / TB complies with AS 3660.1 - 2000, the primary referenced standard of the Building Code of Australia. Kordon TB is only part of a termite management system for a new property. The slab must be constructed in accordance with the Standard; Residential Slabs and Footings Construction, AS 2870-1996.

NOTE: This document is to be attached to Warranty			Product used:						
		Miscellaneous job 04/06/2015			Type	Linear Product Tot Metres (m) Width (mm)			Total SQM
					1,100				Total out
Date of Installation:	Other				25.00		300	7.5	
Installa	ition Address:		14 Elaine Avenue						
		AVALON BEACH							
		NSW 2107							
	e Penetration	s Total	:	0]					
	n Kollars			0					
	al Collars			0					
Wraps				0					
Others		Total Kordon Installed		7.50					
Legen	id.	lotal kordon installed	- Contraction of the Contraction	7.00				Grand Total:	7.5
K	= Kollar		000	= Step Down		-	- Dotaining wa	Ills/Wall sheeting	
XXX	= Cold Joint			= Perimeter			= Full Under	the wan enectally	
W	= Wrap		X	= Piers			= Other		
Parameter Control	- mah		L.A.,	~ LIQ12			= 00161	na a sera en grand Christian (n'a sera esta participa de la constanta de la constanta de la constanta de la co	and free day pages of the commence and execution and
		****************************							
					* * * * * * * * * * * * * * * * * * * *				
		111111111111111111111111111111111111111							
		**********			* * * * * * * * * * * * * * * * * * * *				
		************************************							
					110000000000000000000000000000000000000				
		1::::::::::::::::::::::::::::::::::::::							
1									
					*****************				
		* * * * * * * * * * * * * * * * * * * *							
1									
		* * * * * * * * * * * * * * * * * * * *							
		******************************							
			* * * * * *						
		************************							
		* * * * * * * * * * * * * * * * * * * *							
		*****							
1:::::									
		* * * * * * * * * * * * * * * * * * * *							

Application traffic Ruching

Address:

Unit 8/10 Eustace Street

MANLY NSW 2095

Tel: Email: 0405 611 756

Web: www.abetterseal.com.au

### **INSTALLATION CERTIFICATE**

Signature:

PROJECT ADDRESS; # 14 Elaine Ave, Avalon
Pursuant to the provisions of Part 4A of the Environmental Planning and Assessment Act 1979 and Section 145 of the Environmental Planning and Assessment Regulation 2000.
Pursuant to the provisions of Part A1.3 and Spec. A1.3 of the Building Code of Australia Volume 1 I JADE MICKLEY of ABETTERSEAL WATERPROOFING of 8/10 EUSTACE STREET, MANLY, NSW 2095
Hereby certify:-
That the waterproofing and wet areas installed in the building (Building work/element) project comply with:-
a) The relevant clauses of the Building Code of Australia F1.7
b) The architectural/services/structural plans and specifications approved by the Accredited Certifier and released for construction
c) The relevant Australian Standards listed in the Building Code of Australia (specification A1.3)
d) The following Australian Standards: AS3740
e) Other practices or standards relied upon for this certification :
f) Exclusions: YES/NO
Full Name of Certifier :Jade Mickley
Qualifications and Experience:Certificate III Construction Waterproofing/ 5 / 0 7 7 C
Address of Certifier:8/10 Eustace Street, MANLY NSW 2095
Phone Numbers :
Bus Fax Mob 0405611756