

BY:

FINAL



TREVOR R HOWSE & ASSOCIATES PTY LTD

ACN 003 753 839

OCCUPATION CERTIFICATE

ABN 24 003 753 839

Building Regulations Consultants

PRELIMINARIES				
CERTIFICATE NO. :	CP 22020 – 3 AD			
PROPERTY :	Manly Wharf East Esplanade, Manly			
APPLICANT :	St. Hilliers Interiors Pty. Ltd			
APPROVAL DATE :	30 th April 2003			

DEVELOPMENT C	ONSENT / COMPLYING DEVELOPMENT CERTIFICATE
REFERENCE NO. :	DA 185/01 & Section 96(1A) DA 185/01
DATE OF ISSUE :	23 July 2001, 3 rd June 2002
ISSUING AUTHORITY :	Manly Council

	CONSTRUCTION CERTIFICATE
REFERENCE NO. :	CP 22015 - 1,2,3 & 4
DATE OF ISSUE :	1 February 2002, 18 February 2002, 8 April 2002 & 12 August 2002
ISSUING AUTHORITY :	Trevor R Howse

	AREA OF OCCUPANCY
DATE OF INSPECTION :	30 th April 2003
AREA OF OCCUPANCY :	Basement & Ground Floor Redevelopment – excluding those areas not approved by the aforementioned Development Approval.

CENTRED.	CERTIFYING AUTHORITY			
CERTIFIER :	Trevor R. Howse – accreditation no. 5671			
ACCREDITED BY :	Planning NSW			
STATEMENT :	 A current Development Consent / CDC is in force; 			
	 A current Construction / CDC has been issued with respect to the building plans & specifications; 			
	 The building is suitable for occupation or use in accordance with its classification under the Building Code of Australia; 			
	 A Fire Safety Certificate has been issued for the building; 			
• · ·	• The health & safety of the occupants has been considered;			
	• A Fire Commissioner report has been considered (as applicable)			
SIGNED :				
	1 Heave			

FIRE SAFETY BUILDING AUDIT DESIGN ASSESSMENT CERTIFICATION Level 8, 210 George St Sydney, NSW, 2000 PO Box N694 Grosvenor Place, NSW 1220 Telephone (02) 9251 4500 Facsimile (02) 9252 9822 Email trh@trh.com.au

115

Fire Safety System	Existing	ETY SCHEDULE Performance Standard	Proposed	Performance
Fire rated access panels & doors				Standard BCA C3.13
Automatic fail safe devices				DCA C3.13
Automatic fire detection & alarm			Yes	101(70/170
Automatic fire suppression systems	Yes	AS 2118.1	Yes	AS 1670 / AS 3786
Emergency lifts			165	AS 2118.1, *
Emergency lighting	Yes	AS/NZS 2293.1	Yes	BCA C3.4
EWIS		101120 2275.1	ies	AS/NZS 2293.1
Exit signs	Yes	AS/NZS 2293.1	Yes	AS 2220
Fire control centers & rooms		1 100002293.1	1 05	AS/NZS 2293.1
Fire dampers	Yes	AS/NZS 1668.1, 2	Yes	BCA E1.8
Fire doors	Yes	AS 1905.1	Yes	AS/NZS 1668.1, 2
Fire hydrant systems	Yes	AS 2419.1		AS 1905.1
Fire seals		A5 2419.1	Yes	AS 2419.1
Fire shutters	Yes	AS 1905.1	Yes	BCA C3.15, C3.16,
Fire windows	103	AS 1903.1		AS 1905.1
Hose reel systems	Yes	AS 2441		BCA Spec. C3.4
Lightweight construction	Yes	BCA C1.8	Yes	AS 2441
Mechanical air handling systems	Yes	AS/NZS 1668.1, 2	Yes	BCA C1.8
Perimeter emergency vehicle access		AS/1423 1008.1, 2	Yes	AS/NZS 1668.1, 2
Portable fire extinguishers	Yes	AS 2444		BCA C2.4
Safety curtain in proscenium opening	103		Yes	AS 2444
Smoke & heat vents				BCA H101.10
Smoke dampers				BCA Spec. E2.2c
Smoke detectors & heat detectors	Yes	AS 1670	Yes	AS/NZS 1668.1, 2
Smoke doors	105	A5 1070	······	AS 1670
Solid core doors		·		BCA Spec, C3.4
standby power systems				BCA Spec. C3.4
Vall-wetting sprinkler / drenchers				
Warning & operational signs	Yes	PCA DO 22 ROO		BCA C3.2
G F m. Buo	103	BCA D2.23, E3.3,	Yes	BCA C3.6, D2.23,
DTHER				E3.3, H101.8
	ļ		Yes	SSL Report
	1			Version v04
				Dated 5/11/2001

NUMBER	OCCUPATION CERTIFICATE DOCUMENTATION	DATED
I	Application Form	undated
2	Final fire safety certificate	16.10.02
3	Passive fire protection certificate by Bowsers	14.8.02
4	Passive fire protection certificate by Bowsers	15.8.02
5	Glazing certificate by Shorecode Pty Ltd	29.8.02
6	Thermo block fire resistance certification by Hebel	16.8.02
7	Hebel Test Certificate by CSIRO	13.10.93
8	Mechanical ventilation certificate by Quitstar Pty Ltd	19.8.02
9	Emergency/exit lighting certificate's by Galpern Electrics	17.8.02 (3 of)
10	Emergency/exit lighting certificate by Galpern Electrics	12.8.02
11	Fire sprinkler, detection, occupant warning system, & fire extinguisher certificate by Precision Fire Protection Services P/L	17.8.02
12	Fire hydrant, hydrant booster, & fire hose reel certificate by Grateholt Pty Ltd	16.8.02
13	Structural certification of lift loadings by Taylor Thomson Whiting	16.8.02

	OCCUPATION CERTIFICATE DOCUMENTATION	l .
14	Slip resistance test report by CSIRO	17.7.02
15	Glazing certificate by Central Coast Shopfronts	27.8.02
16	Electrical wiring installation certificate by Galpern Electrics	27.8.02
17	Artificial lighting certificate by Galpern Electrics	29.8.02
18	Plumbing & drainage certificate of compliance by TWF Hooper	Undated
19	Structural design certificate inclusive of balustrading by Taylor Thomson Whiting	28.8.2002
20	Structural inspection certificate by Taylor Thomson Whiting	28.8.02
21	Emergency lighting certificate by Galpern Electrics	18.10.02
22	Lft motor room fire door certificate	18.10.02
23	Automatic fire sprinkler, fire detection & alarm, portable fire extinguisher, & wall wetting drencher systems certificate by Precision Fire protection Services Pty Ltd	4.10.02
24	Glazing certificate by Central Coast Shopfronts	3.10.02
25	Exit sign certificate by Galpern Electrics	4.10.02
25	Emergency/exit lighting certificate by Galpern Electrics	24.9.02
26	Emergency/exit lighting certificate by Galpern Electrics	9.9.02
27	Emergency/exit lighting certificate by Galpern Electrics	17.8.02 (3 of)
28	Emergency/exit lighting certificate by Galpern Electrics	12.8.02
29	Mechanical ventilation certificate by Quitstar Pty Ltd	19.8.02
30	Mechanical ventilation certificate (inclusive of DJ's tennancy smoke exhaust system) by Quitstar Pty Ltd	3.10.02
31	Plumbing & drainage certificate of compliance by TWF Hooper	1.9.2002
32	Passive fire protection certificate by Bowsers	9.9.02
33	Passive fire protection certificate by Bowsers	23.9.02
34	Warning & Operational signs certificate by A & W Industries	17.10.02
35	Landscaping maintenance agreement by Profile Landscapes	12.3.03
36	Glazing certificate by Central Coast Shopfronts	4.2.03
37	Structural certificate for restaurant & main bar areas by George Clarke & Associates	7.2.03
38	Fire Safety Engineering Assessment Report – Fire rating of roof slab	3.6.02