
Sent: 8/06/2020 12:23:04 PM
Subject: Online Submission

08/06/2020

MR David Raffles
1 Bungan Head RD
Newport NSW 2106
dkraffles@optusnet.com.au

RE: DA2020/0486 - 1 E Bungan Head Road NEWPORT NSW 2106

Further to my submission for the original application, the issues relating to the cutting of the rocky outcrop do not seem to have been addressed.

DA1.01 shows a large section of the rock outcrop as a 'cut zone' whilst subsequent drawings (DA1.06) exclude this section from the 'cut zone'.

If the cutting to the rock is as designated on DA1.01, reinforcement of the remaining rock needs to be addressed so as to ensure the stability of the rear and south-west corner of the property at 1 Bungan Head Road (which is incorrectly labelled on DA1.00 as 1C).