green field Accredited Certifiers

27 March, 2012

RECEIVED
2 9 MAR 2012
PITTWATER COUNCIL

The General Manager
Pittwater Council
PO BOX 882
MONA VALE NSW 2103

Dear Sır/Madam,

Re Occupation Certificate No 2011/14368 Property 34 Whale Beach Road, Avalon

The attached copy of the Occupation Certificate & \$36 00 Council submission cheque is forwarded for your record in accordance with Regulation 151 of the Environmental Planning & Assessment Regulation 2000

Yours faithfully

Stephen Murray
Accredited Certifier

Accidance Certifici

\$36 PEC 319897 29/3/12

Telephone 1300 663 215 Facsimile (02) 9836 3000 PO Box 6160 Baulkham Hills BC NSW 2153

STREET, STREET



R Moy & Associates Pty Ltd T/as Greenfield Accredited Certifiers ACN 100 924 605 ABN 23 100 924 605

Final Occupation Certificate

Issued in accordance with section 109C(1)(c) of the Environmental Planning & Assessment Act 1979

Subject Site Address

Lot No DP

Council Area

Development Consent No

CC or CDC No

Description of Building Work

Applicant Name Applicant Address

Applicant Address

Owner Name Owner Address

Determination

34 Whale Beach Road, AVALON 2107

90 17189

PITTWATER COUNCIL

NO069/11 CC2011-14368

Single Storey Secondary Dwelling

Brendan Hackett

PO Box 81, NEWPORT BEACH 2106

Hackett, Brendan

14/40-44 Foamcrest Avenue, NEWPORT

Approval granted

List of documents relied upon by the PCA in making the determination

\$36 00 Council Submission Cheque
Occupation Certificate Application Form
Engineers Certificates - Piers & Slab
Engineers Certificates - Driveway
Part A & B Pest Certificate
Wet Area Certificate
Smoke Detector Certificate
Basix Compliance Certificate
Insulation Certificate
Glazing Certificate
Engineers Certificate - Stormwater
Tipping Dockets
Council Letter - Road Reserve

Arborist Certificate

Set Out Survey Report Photo's of Street Area

Inspection of stages carried out during construction

The following stages of construction were inspected in accordance with Environmental Planning and Assessment Act 1979 and Environmental Planning and Assessment Regulation 2000

Date	Inspection Stage	Inspected By
19/05/11	Pre Certification	Stephen Murray
29/07/11	Piers/Footings	Rick Moy
11/08/11	Slab Ground Floor	Rick Moy
28/09/11	Framework	Rick Moy
16/12/11	Wet Areas	Rick Moy
16/12/11	Storm Water	Rick Moy
20/03/12	Completion	Stephen Murray

(Continued on Page 2)

eliko krajan 18. jan 1

Statement by Certifying Authority

I, the Certifying Authority for building works as described in this certificate, am of the opinion that the following matters have been complied with

- A current development consent or complying development certificate is in force for the building
- For building works, a current construction certificate (or complying development certificate) has been issued with respect to the plans and specifications for the building
- The building is suitable for occupation or use in accordance with its classification under the Building Code of Australia
- A fire safety certificate has been issued for the building where required under the Act
- A report from the Fire Commissioner has been considered where required under the Act

Signed

Certifying Authority Accreditation Number

Date of this Certificate

Accreditation Body

Stephen Murray

BPB0282

Building Professionals Board

27/03/2012

Christian (Christian Christian Christian Christian) Christian (Christian Christian) (Christian Christian)



green field Accredited Certifiers

OCCUPATION CERTIFICATE APPLICATION FORM

CHECKLIST		
prohibits Greenfield from accepting	per "OC Checklist" provided at CC stage of project	
SECTION 1 PARTICULARS		
Applicant Name	Brendan Hackett	
Applicant Address (This is the address all correspondence will be delivered)	PO Box 81 Newport Beach NSW 2 Tel/Fax/Email 0408 080 790	2106
Applicant Contact Details	bhackett@bigpond com	
SITE Address of the Proposed Building Works	34 Whale Beach Rd Avalon NSW21	٥7
Local Government (Council) Area		•
Development Consent No	Pittwater	
	N0069/11	
Detailed description of completed building works	Secondary Dwelling	
Application Type (Please select one) NB It is recommended you contact our	X Final Occupation Certificate (recommended)	
office before selecting the "Interim" option	Interim Occupation Certificate	

SECTION 2 TERMS OF APPLICATION

Scope

The scope of works covered under this application is restricted to those building works as described in the PARTICULARS section of the form

Terms and Conditions

All information provided by the Applicant on this form will be taken to be accurate and correct Greenfield does not accept any responsibility for any intentional or unintentional error or omission made by the Applicant on this form

Fees

Failure to pay the quoted fee for services will generally result in a refusal to release the Occupation Certificate Should an Occupation Certificate be released and payment not honoured the Applicant will be hable in addition to any associated debt recovery costs plus interest incurred from the time of the application. Greenfield may suspend where fees have not been paid in accordance with the provisions of the Building and Construction Industry Security of Payment Act 1999.

SECTION 3 DECLARATIONS BY THE APPLICANT

I the aforementioned person or authorised representative of a legal entity as described as the Applicant in the PARTICULARS section hereby declare the following

- I to the best of my knowledge have completed all details in the PARTICULARS section in a correct
 and accurate manner and hereby indemnify Greenfield against any damages losses or suffering as a
 result of incorrect information provided under that section
- I have read, understood and hereby accept the terms and conditions outlined in Section 2 of this form
- I understand that the Application for Occupation Certificate is not complete until all required documentation has been received by Greenfield

SECTION 4 CONSENT TO SUPPLY BUILDER WITH COPY OF OCCUPATION CERTIFICATE

Make a selection

I/we consent for Greenfield to forward a copy of the Occupation Certificate to our builder
 I/we do not wish for Greenfield to forward a copy of the Occupation Certificate to our builder

APPLICANT SIGNATURE

Signature of Applicant	x B Huss
Full Name of Applicant	Brendan Hackett
Dated	19312

Page 2 of 2 Greenfield Accredited Certifiers 'OC Application Form'
Postal Address PO Box 6160 Baulkham Hills BC NSW 2153 (Ph 1300 663 215)
Form version 1 Jun 09

Initial







ABN 35 079 047 466

Level 2 103 Vanessa St Kingsgrove NSW 2208

Telephone (02) 9554 9311 Facsimile (02) 9554 9764

DATE

Thursday, 28 July 2011

OUR REFERENCE

47661PC

YOUR REFERENCE BRENDAN HACKETT

JOB LOCATION

34 WHALE BEACH ROAD AVALON

STRUCTURAL CERTIFICATE

This is to certify that an inspection of the pier holes was undertaken at the above mentioned site prior to the placement of any concrete


The piers have generally been placed based on the current engineers details and to our approval

Yours Faithfully

John Rafeletos

BE MIE Aust CPEng NPER3 Structural and Civil

RAFELETOS





ABN 35 079 047 466

Level 2 103 Vanessa St Kingsgrove NSW 2208

Telephone (02) 9554 9311 Facsimile (02) 9554 9764

DATE

Thursday, 11 August 2011

OUR REFERENCE

47661PC

YOUR REFERENCE BRENDAN HACKETT

JOB LOCATION

34 WHALE BEACH ROAD AVALON

STRUCTURAL CERTIFICATE

This is to certify that an inspection of the slab reinforcement was undertaken at the above mentioned site prior to the placement of any concrete

The slab has been constructed and the reinforcement placed based on the current engineers details and to our approval

Yours Faithfully

John Rafeletos

BE MIE Aust CPEng NPER3 Structural and Civil

RAFELETOS





ABN 35 079 047 466

Level 2 103 Vanessa St Kingsgrove NSW 2208

Telephone (02) 9554 9311 Facsimile (02) 9554 9764

DATE

Wednesday 26 October 2011

OUR REFERENCE

47661PC

YOUR REFERENCE BRENDAN HACKETT

JOB LOCATION

34 WHALE BEACH ROAD AVALON

STRUCTURAL CERTIFICATE

This is to certify that an inspection of the piers under the driveway were undertaken at the above mentioned site during construction prior to the placement of any concrete

The piers under the driveway have been constructed and the reinforcement placed, generally in accordance with the current engineers details

In our opinion the piers under the driveway will support the proposed loads to be expected

Yours Faithfully

John Rafeletos

BE MIE Aust CPEng NPER3 Structural and Civil

RAFELETOS



/AUIIT

ABN 35 079 047 466

Level 2 103 Vanessa St Kingsgrove NSW 2208

Telephone (02) 9554 9311 Facsimile (02) 9554 9764

DATE

Wednesday, 26 October 2011

OUR REFERENCE

47661PC

YOUR REFERENCE BRENDAN HACKETT

JOB LOCATION

34 WHALE BEACH ROAD AVALON

STRUCTURAL CERTIFICATE

This is to certify that an inspection of the suspended driveway slab were undertaken at the above mentioned site during construction prior to the placement of any concrete

The suspended driveway slab have been constructed and the reinforcement placed, generally in accordance with the current engineers details

In our opinion the suspended driveway slab will support the proposed loads to be expected

Yours Faithfully

John Rafeletos

BE MIE Aust CP Eng NPER3 Structural and Civil

Bayer Environmental Science





This warranty is granted by Bayer Environmental Science ("Bayer") (ACN 000 226 022) of 391-393 Tooronga Road Hawthorn East Victoria in respect of the installation of Kordon Termite Barner ("Kordon") in the Building

Warranty No

2011-10-1349

This Warranty covers damage by Subterranean Termites

('Termites") only Bayer warrants that Kordon shall restrict the entry of Termites into the Building through the Kordon barner for a period of ten (10) years from the date of installation (Warranty Period")

This Warranty Course I

This Warranty covers damage by Termites to structural timbers and internal timbers BUT DOES NOT INCLUDE damage by Termites to

(a) chattels of any nature whatsoever including (but without limiting the foregoing) antiques heirlooms paintings artwork and paintings and

(b) any pergolas wiring extensions to the Building and outhouses

If Termite infestation of the Building occurs as a result of the failure of the Kordon and damage by Termites is caused to structural timbers and/or internal timbers fixtures and fittings during the Warranty Period Bayer will without charge to the

- (a) repair the Kordon barrier where practicable
- and/or
- (b) cause the repair or replacement of structural timbers and/or internal timbers so damaged

To the extent permitted by the Law of the State or Territory

- in which the premises are located
 (a) the liability of Bayer under this Warranty is limited to a
 maximum of \$100 000 00 in respect of any one (1) warranty claim
 - (b) All representations and other warranties express or implied and whether arising by virtue of Statute or otherwise are excluded or limited as stated in this Warranty

This Warranty shall only have effect if the Kordon is installed by an Accredited Bayer Installer

OWNERS RESPONSIBILITIES

The Owner of the Building during the Warranty Period (Owner") at the Owner's expense arrange for thorough and regular inspection of the Building for the presence of Termites at intervals not exceeding 12 months by an accredited/licenced Timber Pest Inspector

Where the Termite risk is high or the Building type is susceptible to Termite attack (e.g. North of the 26th parallel) more frequent inspections (3.6 months) should be undertaken

These inspection recommendations comply with those outlined in AS 3660 Termite Management Series and AS 4349 1-1995 Inspection of buildings

If Termites are detected or are found to have breached the Kordon barrier the Owner must within 7 days of such detection notify Bayer

EXCLUSIONS
This Warranty shall be void and have no effect in any of the

following circumstances

The Kordon barrier is damaged modified bridged or otherwise interfered with by any person or any act fact otherwise interfered with by any person or any act fact matter or thing beyond the reasonable control of Bayer. The Building is structurally modified altered or otherwise changed in any way which would or may diminish the effectiveness of the Kordon as a Termite barrier If at any time during the Warranty Penod the Owner.

(a) allows or fails to prevent accumulation of (i) wood rubbish or timber against the Building AND (ii) finished ground level around the Building to a

(ii) finished ground level around the Building to height which does not comply with the terms of the Installation Manual

(b) allows the barrier dividing the soil surface and the structure of the Building formed by the Kordon to be bridged or broken by any other material or matter through which Termites may by-pass the Kordon and infest the Building
Termites shall enter the Building through any manner

other than by a breach of the Kordon barrier If the Kordon is installed other than by an Accredited Bayer Installer



Date of Installation 11/09/2011

Installation Address No 34 Whale Beach Road

Company Contact Company Name

Fergus Bermingham Design Pest Solutions

Address

PO Box 1157 Dee Why NSW, 2099

Phone Number

02 9970 5560

Accreditation Number N134

Bayer will grant additional specific warranty conditions where required to accommodate high density commercial constructions government buildings etc on documented request

Bayer Environmental Science 391 393 Tooronga Rd Hawthorn East VIC 3123

Bayer Environmental Science





Certificate of Compliance

This document is to certify that the Kordon TMB / TB system was installed by a Bayer Accredited Installer and has been completed in accordance with the Manufacturer's specifications (Kordon TMB / TB complies with AS 3660 1 2000) the primary referenced standard of the Building Code of Australia Kordon TB is only part of a termite management system for a new property The slab must be constructed in accordance with the Standard Residential Slabs and Footings Construction, AS 2870-1996

NOTE This document is to be attached to Warranty Document Number			2011-10-1349	
Date of Installation 11/09/2011		Job Type	Large Job - Miscellaneous	
Installation Address	No 34 Whale Beach Road Avalon NSW, 2107	Product used Linear Metres (m) 38	Product Width (mm)	Total SQM 11 40
Builder	Brendan Hackett			
Phone number Owner	0408 080790 Unknown			
Phone number		Service Penetration	กร	. — —
Local Council	Pittwater	Kordon Kollars		0 70
Phone number Company Contact	02 99705560 Fergus Bermingham	Manual Collars	Total Kordon Installed	0 00 12 1
Installer's Name	Fergus Bermingham		TOTAL	
Company Name	Design Pest Solutions			
Address	PO Box 1157 Dee Why NSW, 2099			
Phone Number	02 9970 5560			
Fax Number	02 9970 5542			
Accreditation Number	n134			
Authorised Signature Comments The builds perimeter	er has been advised to maintain a 75mm	Date or hard surface inspe	11/10/2011 ction zone around the buil	ding
Kordon will only protect Regular termite inspect Kordon is installed to t installation drawing for	ct areas where the product is installed ctions as per the Australian Standard are the service penetrations and perimeter as details inspection report as recommended by A	per the manufacture		the site

Bayer Environmental Science





Site Installation Report

This document is to certify that the Kordon TMB / TB system was installed by a Bayer Accredited Installer and has been completed in accordance with the Manufacturer's specifications. Kordon TMB/ TB comples with AS 3660 1 2000 the primary referenced standard of the Building Code of Australia Kordon TB is only part of a termite management system for a new property. The slab must be constructed in accordance with the Standard Residential Slabs and Footings Construction AS 2870-1996.

NOTE This docume	nt is to be attached to Warranty Docum	ent Number	2011 10-1349	
Date of Installation Installation Address	11/09/2011 No 34 Whale Beach Road	Job Type	Large Job Miscellaneo	ous
Installation Address	Avalon NSW, 2107	Product used Linear Metres (m) 38	Product Width (mm)	Total SQM 11 40
Legend		Service Penetration	one	
		Kordon Kollars Manual Collars	7 0 Total Kordon Installed	0 70 0 00 12 1

AISam's Tiling

Email:foxtile@optusnet.com.au

Mob 0416613306

Fax 88127057

LIC 94568C

waterproofing certificate

22/12/2011

This certificate is been given to Brendan hackett for waterproofing carried out at 34 whale beach rd Avalon NSW

Work done included all wet areas of bathroom and laundry

3 good coats of waterproofing k10 davco have been applied

All work to be guaranteed for 5 years

Soly

WILKOM ELECTRICAL SERVICES PTY. LTD

LIC No 189642C ABN 33 092 679 395 Mobile 0417 450 879 wilkom@bigpond net au

SMOKE ALARM

Installation and Test Report Building Code of Australia – Part 3 7 2 Ref AS3786-93 (Smoke Alarms)

Date 15/02/2012

Job Address 34 Whale Beach Road Avalon NSW 2107 Owner/Builder Brendan Hackett

Type of System

Alarm Details

New

Product/Model No Clipsal 755FM Aust. Elec Authority No CS/96262V

Location of Detector (wired to mains power with battery backup and interlinked)

Hallway x 1

Total of 1 detector installed

Installers Details

Name Address

Wilkom Electrical Services Pty Ltd 9 Julian Close Kellyville NSW 2155

Date of installation and testing 15/02/2012

Tony Wilkinson Electrical Licence No 189642C

BASIX COMPLIANCE STATEMENT - owners

SITE ADDRESS
34 Whale Beach Rd Avalon NSW 2107
Basix Certificate No 3627655 02
Declaration
I/we, the owner/s of the "Site Address" stated above
Owner Name Brendan James Hackett
Owner 2 Name
sincerely and solemnly do swear that the following declaration is true, to the best of my knowledge
Declaration 1 I declare that all relevant basix commitments within my scope of responsibility, as advised by my builder (per Basix Compliance Certificate Schedule) and indicated in the "Certifier check" column within the "Schedule of BASIX Commitments", of the Basix Certificate number specified above, have been complied with and to specification as stated in the said BASIX Certificate. I have taken all reasonable steps to satisfy myself that this declaration is true and fair and acknowledge that the relevant compliance certificates recommended in the Basix Compliance Certificate Schedule under my responsibility have been verified to be accurate and correct.
Signed $\frac{X}{9 3 2}$

Bradford™ for smartel environmen's



Bradford Home Insulation LIFETIME WARRANTY

This is to certify that Bradford™ Insulation product has been installed at

Address	34 Whale Beach Road, Avalon	the Premises

Date of Installation

Ceiling/Roof 17 November 2011

Walls 17 November 2011

Floor

	Material R Value			
Product Installed	Ceiling/Roof	Wall	Floor	
Bradford Gold Insulation	R4 1	R2 0		
Bradford Gold HP Insulation			Į	
Bradford SoundScreen™				
Bradford Optimo™ Sub-Floor Insulation		Market State		
Bradford EnviroSeal™** [Yes/No]			100000000000000000000000000000000000000	

CSR Building Products Limited ACN 008631356 (**Bradford**) warrants that Bradford™ Gold Bradford™ Gold HP Bradford SoundScreen™ and Bradford Optimo™ Sub-Rioor Insulation installed at the Premises will meet the following standards for the life of your home* provided they are not disturbed after installation

- 1 Achieve optimum fire resistance performance of four zeros when tested in accordance with Australian Standard 1530 part 3 of 1999
- 2 Be electrically non-conductive allergy free will not pack down rot support mould or deteriorate
- 3 Achieve the stated thermal resistances (R Values) in accordance with AS/NZS4859 1
- **Bradford EnviroSeal $^{\mathbf{M}}$ is warranted by Bradford for 10 years from the date of installation

Other than as set out above the Lifetime Warranty is in substitution for and to the exclusion of all other rights and remedies (if any) including liability for personal injury property damage loss of profits savings or opportunity or special or consequential loss however caused or ansing

Certain legislation including the Trade Practices Act 1974 (Cth) may imply warranties or conditions or impose obligations upon Bradford that cannot be excluded restricted or modified or cannot be excluded restricted or modified except to a limited extent. This warranty must be read subject to those statutory provisions.

- If these statutory provisions apply to the extent to which Bradford is able to do so its liability under those provisions will be limited at its option to
- (a) the replacement of the goods resupply of the services or supply of equivalent goods or services
- (b) the payment of the cost of replacing the goods or supplying the services again or acquiring equivalent good or services
- (c) the repair of the goods or
- (d) the payment of the cost of having the goods repaired


HEALTH and SAFETY INFORMATION

Information on health risks and safe handling of our products is displayed on the packaging and/ or the documentation accompanying them Additional information is listed in product Material Safety Data Sheets available from your regional Bradford Insulation office or on our website www bradfordinsulation com au

*The life of the home is taken by Bradford to be 70 years from the date of product installation for the purpose of this warranty

Ray Thompson

Group Marketing Manager
Bradford Insulation Group



23 B Curtis Road Mulgrave NSW 2756 PH (02) 4577 8371 FAX (02) 4577 5839

INVOICE TO

Brendan Hackett

34 Whale Beach Rd

WHALE BEACH NSW

Company Business Number

INVOICE NO

19017

PRECISION POLY

23B CURTIS ROAD MULGRAUE NSW 2756

TERMINAL ID 08292002601

0044 PUR

18 069 524 161

AUD

\$1125 00

Visa Debit AID A0000000031010 APSN 000 C0000Z ATC 0004

APPROVED

PU NU

A668209

27/01/12 14 13 \$004455

THANK YOU FOR YOUR CUSTOM PLEASE RETAIN FOR YOUR RECORD

IP DATE SHIP VIA

			27/01/2012	
DESCRIPTION	QTY	RATE	TAX AMT	AMOUNT
Delivery Charge 3000 Litre slim line Shale Grey Hose & Brass Tap		80 00 1 000 00 45 00	7 27 90 91 4 09	80 00 1 000 00 45 00

ANZ BSB 012129 AC 350042622 bank details for prompt payment

Subtotal	A\$1 022 73
Tax	A\$102 27
Total	A\$1 125 00
Balance Due	A\$1 125 00



BORAL WINDOW SYSTEMS LTD ABN 78 004 069 523 312 Woodpark Road
Smithfield NSW 2164
Telephone (02) 9757 0555
Facsimile (02) 9604 9440

GLAZING CERTIFICATE

14/09/2011

BRENDAN HACKETT 4 URSULA ST WINSTON HILLS NSW

Dear Customer

RE

WHALE BEACH RD 34 AVALON

Sales Order No

88599

Rep No Mark

Customer Order No.

We Confirm that the Dowell Aluminium Windows and doors supplied to the above project were manufactured to conform with the requirements of an N2 rating and glazed and assembled in accordance with the requirements of the following Australian Standards

AS2047-1999 Windows in Buildings

AS1288-2006 Glass in buildings

AS4055-2006 Wind Loads for Housing

Note based on the 2006 revision to AS1288 and AS4055 'ultimate limit state design pressure', the following applies,

N1 - 700paUWP N2 - 1000pa UWP N3 - 1500paUWP N4 - 2200paUWP

N5 - 3300paUWP N6 - 4400paUWP

Note Windows have been supplied to meet the requirements of AS3959-2009. In cases where Dowell Windows have not supplied screens, it is the builder's responsibility to ensure that the screens have been supplied and certified to comply with the requirements of AS3959-2009. The responsibility for installing windows in the correct manner and position within the structure lies with the purchaser. Further, if the windows have been supplied to comply with a window schedule and not from a take off from a plan, Dowell A Boral Company will not accept responsibility for the accuracy of the 'Human Impact' requirements encompassed in AS1288.

Yours Faithfully

Andrew Vassel Branch Manager

Credit Officer



15 March 2012 Our Ref DMS dp 14011

General Manager Pittwater Council PO Box 882 MONA VALE NSW 1660

Dear Sır

Re Stormwater Drainage System – 34 Whale Beach Road Avalon

This is to certify that an inspection was undertaken on the stormwater drainage system 15 March 2012 following the completion of construction. The drainage system was generally in accordance with the approved drainage plans and nothing significant was observed during the course of the inspection to suggest that the intent of the design had not been followed.

This construction appeared to meet accepted standards of engineering practice and Council's requirements

This certification shall not be construed as relieving any other party of their responsibilities or contractual obligations

Yours faithfully TAYLOR CONSULTING

D M SCHAEFER - Director BE (Civil) MIEAust

C12/14C11 Drainage Cert





2 metre 3 metre 4 metre 5 metre 8 metre 10 metre 15 metre 20 metre Skips Supp	ABN 97 086 458 488 PO Box 39 Avalon 2107 Fax Our Flusiness is Picking Up!	one 9918 2483 bile 0418 476 625 2 9999 6477 2 7669
	Thoras /	
DATE	DESCRIPTION	TOTAL DUE
14/11/11	p/ 253	240
	Pd ec.	
	5353 16/3/372 7218 Lyp 06/14	The second secon
	with your remittance or direct deposit BSB 062 205 Account 10212956 Please quote the bin delivery address or invoice number All prices include GST	

PLEASE NOTE Terms are strictly nett 7 days only

PITTWATER

ABN61340837871

02 9970 111¹ 02 9970 7150

PO Box 882 Mona Vale NSW 1660 DX 9018 Mona Vale

Ross McWhirter Project Leader – Road Reserve Management 8am to 4 30pm Mon - Fri Phone 9970 1207 Mobile 0419 629 007

27 February 2012

Brendan Hackett PO Box 81 NEWPORT BEACH NSW 2106

Dear Sir,

Re Final Inspection of Works in Road Reserve at 34 Whale Beach Road, Avalon

DA No N0069/11 - Compliance

A final inspection of the approved works in the road reserve at the above address was carried out on 27 February 2012 at 2pm

The work has been completed in accordance with the approved application to Council's satisfaction

Should you wish to discuss the matter further, please contact the abovementioned Officer

Yours faithfully

Ross McWhirter

R McWhinter

PROJECT LEADER - ROAD RESERVE MANAGEMENT

ALL ARBOR SERVICES

Professional Tree Solutions

www.allarborservices.com.au

Nick Lloyd Mobile 0422 741 886 Email <u>nick@allarborservices.com</u>.au ABN 4699 0458 085

14th March 2012

I, Nicolas Lloyd, have inspected the site at 34 Whale Beach Rd, Avalon, NSW, 2107, after the completion of construction works and have found the existing trees have not been damaged and are considered to be in a healthy condition at the time of this inspection.

Regards

Nicolas Lloyd Arborist Level II


Stephen Murray

Brendan Hackett [bhackett@bigpond.com] Tuesday, 20 March 2012 11:13 AM Stephen Murray 34 Whale Beach Rd-Street Area Photos

From: Sent: To: Subject:



IMG_8632



IMG_8633




IMG_8642




IMG_8647




IMG_8648



IMG_8659




IMG_8662




IMG_8667



IMG_8673



IMG_8678





IMG_8689

Regards Brendan Hackett Ozicomm Pty Ltd 0408 080 790

