

# MORTHERN BEACHES 1 3 OCT 2017 MONA VALE CUSTON CERTIFICATE FINAL OCCUPATION CERTIFICATE

Date Application Recei	ived	27.02.17						
Council	Northern Beaches Council - Pittwater			DA Numb	ər	NO525	5/16	
Occupation Certificate	No.	FOC2017-048	Date Appr	oved	29.09.1	17		
CC No.		CC2017-048		Date Appr	oved	06.03.1	17	
Certifying Authority Craig Formosa								
Accredited Certifier		Craig Formosa		ŀ	ccredit	tation No	). I	BPB0124
Accreditation Body		Building Professionals Board						
APPLICANT DETAILS	S							
Name	Multidwe	II Group Pty Ltd		Email	paul	@multidv	vell.c	om.au
Address	PO Box	1245, Dee Why NSW 2099		Ph No	1300	0 801 090	D	
OWNER DETAILS								
Name	Richard	Geeves & Rina Chhoeun	Email	geeves	viafilm@	@gmail.co	om	
Address	2 Old Ba	rrenjoey Road, Avalon Beach NS	SW 2107	Ph No	0449	9 895 493	3	
DEVELOPMENT DETAI	ILS							
Subject Land	2 Old Ba	rrenjoey Road, Avalon Beach N	SW 2107	Lot No	15		DP	27698
Description of Development	New deta	ached secondary dwelling						
Class of Building	ilding 1a Value of Work \$193,018.00							
endee er Bananig	la		Value	JI WOIK	\$130	5,010.00		
Certificates attached at		THE BUILDING IS SUITAB Mandatory Inspection Reports Glazing, Builders Basix Comp Geotech, Council letter re pub certification	LE FOR OCO	CUPATION fing, Structu	ral Eng	gineers, S ipt, Storn	nwate	er, Form 3
Certificates attached at upon for this decision RECORD OF INSPEC	nd relied	Mandatory Inspection Reports Glazing, Builders Basix Comp Geotech, Council letter re pub certification,	LE FOR OCO	CUPATION fing, Structu	ral Eng	gineers, S ipt, Storn	nwate	er, Form 3 le design
Certificates attached au upon for this decision RECORD OF INSPEC Site Inspection prior to	nd relied TIONS issue of C	Mandatory Inspection Reports Glazing, Builders Basix Comp Geotech, Council letter re pub certification,	LE FOR OCO	CUPATION fing, Structu	ral Eng	gineers, S ipt, Storn	nwate	er, Form 3 le design 02.03.17
Certificates attached an upon for this decision RECORD OF INSPEC Site Inspection prior to Footings – prior to pour	nd relied TIONS issue of C	Mandatory Inspection Reports Glazing, Builders Basix Comp Geotech, Council letter re pub certification,	LE FOR OCO	CUPATION fing, Structu	ral Eng	gineers, S ipt, Storn	nwate	er, Form 3 le design 02.03.17 22.03.17
Certificates attached an upon for this decision RECORD OF INSPEC Site Inspection prior to Footings – prior to pour Timber Frame – prior to	nd relied TIONS issue of C	Mandatory Inspection Reports Glazing, Builders Basix Comp Geotech, Council letter re pub certification,	LE FOR OCO	CUPATION fing, Structu	ral Eng	gineers, S ipt, Storn	nwate	er, Form 3 le design 02.03.17 22.03.17 26.05.17
Certificates attached au upon for this decision RECORD OF INSPEC Site Inspection prior to Footings – prior to pour Timber Frame – prior to Waterproofing	nd relied TIONS issue of C	Mandatory Inspection Reports Glazing, Builders Basix Comp Geotech, Council letter re pub certification,	LE FOR OCO	CUPATION fing, Structu	ral Eng	gineers, S ipt, Storn	nwate	er, Form 3 le design 02.03.17 22.03.17
Certificates attached an upon for this decision RECORD OF INSPEC Site Inspection prior to Footings – prior to pour Timber Frame – prior to Waterproofing Stormwater	nd relied TIONS issue of C	Mandatory Inspection Reports Glazing, Builders Basix Comp Geotech, Council letter re pub certification,	LE FOR OCO	CUPATION fing, Structu	ral Eng	gineers, S ipt, Storn	nwate	er, Form 3 le design 02.03.17 22.03.17 26.05.17 08.06.17
Certificates attached an upon for this decision RECORD OF INSPEC Site Inspection prior to Footings – prior to pour Timber Frame – prior to Waterproofing Stormwater Final Inspection	nd relied TIONS issue of C r o lining	Mandatory Inspection Reports Glazing, Builders Basix Comp Geotech, Council letter re put certification,	LE FOR OCO	CUPATION fing, Structu	ral Eng	gineers, S ipt, Storn	nwate	er, Form 3 le design 02.03.17 22.03.17 26.05.17 08.06.17 26.07.17 26.07.17
Certificates attached an upon for this decision <b>RECORD OF INSPEC</b> Site Inspection prior to Footings – prior to pour Timber Frame – prior to Waterproofing Stormwater Final Inspection Final Re-Inspection – is <b>CERTIFICATION</b>	nd relied TIONS issue of C r o lining ssue of Oc	Mandatory Inspection Reports Glazing, Builders Basix Comp Geotech, Council letter reput certification, construction Certificate	LE FOR OCO	CUPATION fing, Structu	ral Eng	gineers, S ipt, Storn	nwate	er, Form 3 le design 02.03.17 22.03.17 26.05.17 08.06.17 26.07.17
Certificates attached at upon for this decision <b>RECORD OF INSPEC</b> Site Inspection prior to Footings – prior to pour Timber Frame – prior to Waterproofing Stormwater Final Inspection Final Re-Inspection – is <b>CERTIFICATION</b> I, Craig Formosa, as th (a) the building v (b) a current Dev (c) a current Con the building, (d) the building i	nd relied TIONS issue of C r o lining ssue of Oc ne certifyin will not cor velopment instruction is suitable	Mandatory Inspection Reports Glazing, Builders Basix Comp Geotech, Council letter re put certification,	LE FOR OCC s, Waterproo pliance, Basix plic infrastruc	CUPATION fing, Structu Completio ture, Builde	ral Eng n Recei rs wall/n	jineers, S ipt, Storn roof/balu		er, Form 3 le design 02.03.17 22.03.17 26.05.17 08.06.17 26.07.17 26.07.17 28.08.17
Certificates attached at upon for this decision <b>RECORD OF INSPEC</b> Site Inspection prior to Footings – prior to pour Timber Frame – prior to Waterproofing Stormwater Final Inspection Final Re-Inspection – is <b>CERTIFICATION</b> I, Craig Formosa, as th (a) the building v (b) a current Dev (c) a current Con the building, (d) the building i (e) all the prescr	nd relied TIONS issue of C r o lining ssue of Oc ne certifyin will not cor velopment instruction is suitable ribed cond	Mandatory Inspection Reports Glazing, Builders Basix Comp Geotech, Council letter reput certification, construction Certificate compation Certificate g authority am satisfied that; institute a hazard to the health of Application is in force for the to Certificate has been ssued for for its use under the Building C	LE FOR OCC s, Waterproo pliance, Basix plic infrastruc	CUPATION fing, Structu Completio ture, Builde	ral Eng n Recei rs wall/n	jineers, S ipt, Storn roof/balu		er, Form 3 le design 02.03.17 22.03.17 26.05.17 08.06.17 26.07.17 26.07.17 28.08.17
Certificates attached at upon for this decision <b>RECORD OF INSPEC</b> Site Inspection prior to Footings – prior to pour Timber Frame – prior to Waterproofing Stormwater Final Inspection Final Re-Inspection – is <b>CERTIFICATION</b> I, Craig Formosa, as th (a) the building v (b) a current Dev (c) a current Con the building, (d) the building i	nd relied TIONS issue of C r o lining ssue of Oc ne certifyin will not cor velopment instruction is suitable ribed cond	Mandatory Inspection Reports Glazing, Builders Basix Comp Geotech, Council letter reput certification, construction Certificate compation Certificate g authority am satisfied that; institute a hazard to the health of Application is in force for the to Certificate has been ssued for for its use under the Building C	LE FOR OCC s, Waterproo pliance, Basix plic infrastruc	CUPATION fing, Structu a Completion ture, Builde	ral Eng n Recei rs wall/n	jineers, S ipt, Storn roof/balu		er, Form 3 le design 02.03.17 22.03.17 26.05.17 08.06.17 26.07.17 26.07.17 28.08.17



# FINAL INSPECTION REPORT

Sheet 1 of

ADD	RESS 2 Old Barrenjoey Road, Avalon			
CON	TACT Multidwell		MAILED TO APPLIC	CANT/BUILDER
cc/c	CDC No CC2017-048	DA No		
Req'd	CERTIFICATES/ITEMS REQUIRED TO ISSUE	OC (indicated	by ticks 🖄 )	Rec'd
	Wet Area Certification for	+ 2 0 1 of the N		D
	from an appropriately qualified person, in accordance with AS3740 and Par Structural Engineers Certification for		otech Engineer	
	Smoke Alarm Certification from a licensed Electrician, in accordance with			
	Glazing Certification in accordance with AS1288, AS2047 and (if applicab	le) AS3959 BAL	level	
	for windows doors balustrades pool barrier other			
	Termite Control Certification from a licensed Pest Controller, in accordan			
	BASIX Compliance Certification from Builder, confirming all requirement Stormwater Certification from an appropriately qualified DPER Civil Er			
	Survey Certification from a Registered Surveyor confirming the set-out of	f building & finis	shed ridge height	
	Pool Plumbing Certification in accordance with AS1926.3			Ū
	Non-slip Stair Tread/Nose Finish Certification from Applicator, in accord	dance with AS4	586	
	Childsafe Locks on bedrooms Continuous Handrail to stain	s 🗋	Non-slip Finish ap	oplied to stairs
OTH	ER		1	
	All previous issues of non compliance now complete	9		
	ok to issue Occupation Certificate			
0				
0				
INSP NOT				
NOT	<ul> <li>NO DRIP FEEDING OF DOCUMENTS - PLEASE PROVIDE THE ABOVE IN (</li> <li>It is the policy of Form Building Certifiers Pty Ltd that an Occupation Ce of TWELVE (12) MONTHS from the date of this Final Inspection Report.</li> </ul>	ertificate will NC		e expiration
ACCR	EDITED CERTIFIER_ Common	BPB No	0124 <sub>DAT</sub>	e 28/08/17



# FINAL INSPECTION REPORT

• •

• •

Submission of a compliance certificate from an appropriately qualified proximation of a lower areas were carried out in accordance with the requirements of ASI374 - Waterproceding of Wet Areas in Residential Buildings.         Image: Structural Engineers Certification for Inspections conducted         Image: Structural Engineers Certification Submission of a certificate from a licensed Plex Controller confirming termite protections have been provided in accordance with 45360.1         Image: Structural Engineer Structural Enginers Structural Enginers Structural Engineer Structural Engineer S	LA	ND TO WHICH THIS FIN	AL INSPECTION REPOR	T RESULT SHEET APPLIES
DA No.       N0525/16       CC No. 2017-048       CDC No.         CERTIFICATES REQUIRED       (To be provided all in one set of documents - NO drip feeding please)         Wet Area Certification for Wet areas       Submission of a compliance certificate from an appropriately qualified person verying the waterproofing of all wet areas were carried out in accordance with the requirements of A3:74.01 - Waterproofing of Wet Areas in Residuate Building.         Image: Structural Engineers Certification for Inspections conducted       Submission of a certification submission of a certificate from a licensed Electrician confirming all required smoke aliarms have been installed in accordance with the requirements of Part 3.7.2 of the Building Code of Australia (Vol.2).         Image: Structural Engineers Certification Submission of a certificate from a licensed Pleat Confirming termite protections have been provided in accordance with A3:560.1.         Image: Structural Engineer Statement Confirming all requirements have been satisfied.         Image: Structural Engineer Statement Confirming all requirements have been satisfied.         Image: Structural Engineer Statement Confirming all requirements have been satisfied.         Image: Structural Engineer Statement Confirming all requirements have been satisfied.         Image: Structural Engineer Statement Confirming all requirements have been satisfied.         Image: Structural Engineer Statement Confirming all requirements have been satisfied.         Image: Structural Engineer Statement Confirming all requirements have been satisfied.         Image: Structural Engineer State	Con	<sup>tact</sup> MultiDwell		Phone
CERTIFICATES REQUIRED       (To be provided all in one set of documents - NO drip feeding please)         Wet Area Certification for Wet areas       Submission of a compliance certificate from an appropriately qualified person verying the waterproofing of all wet areas were carried out in accordance with the requirements of AB3740 - Vaterproofing of Vaterasis in Resented Bluddings.         Image: Structural Engineers Certification for Inspections conducted       Since Alarm Certification submission of a certificate from a licensed Electrician confirming all required smoke alarms have been installed in accordance with the requirements of Parl 3.7.2 of the Bludding Code of Australia (Vol.2).         Image: Control Certification submission of a certificate from a licensed Electrician confirming all requirements of Parl 3.7.2 of the Bludding Code of Australia (Vol.2).         Image: Control Certification submission of a certificate from a licensed Plest Controller confirming termite protections have been provided in accordance with AS3660.1.         Image: Control Certification Submission of a certificate from a licensed Plest Controller confirming termite protections have been provided in accordance with AS3660.1.         Image: Control Certification Submission of a certificate from a appropriately qualified O NPER Civil Engineer O Licensed Plumber verying the adequacy of the somewater drainage system as installed.         Stormwater Certification Submission of a certificate from Applicator in accordance with AS458.         OS ONS Childsafe Locks on bedrooms       0 S 0 NS Continuous Handrail to stars         INSPECTION RESULT       PASS       FAIL       S = Satisfactory NS = Not Satisfactor	Add	<sup>ress</sup> 2 Old Barrenjoey F	d, Avalon	
Wet Area Certification for Wet areas         Submission of a compliance coefficient from an appropriately qualified person vertiying the waterproofing of all wet areas were carried out in accordance with the requirements of ASI370 - Waterproofing of Wet Areas in Redential Buildings.         Structural Engineers Certification for Inspections conducted         Simoke Alarm Certification Submission of a certificate from a licensed Electrician confirming all required smoke alarms have been installed in accordance with the requirements of Pari 3.7.2 of the Building Code of Australia (Vol.2).         Clazing Certification for Submission of a certificate from a licensed Pest Controller confirming termite protections have been provided in accordance with AS3660.1.         Termite Control Certification Submission of a certificate from a licensed Pest Controller confirming termite protections have been provided in accordance with AS3660.1.         BASIX Compliance Statement Confirming all requirements have been satisfied.         Submission of a certification Submission of a certificate from an appropriately qualified O NPER Civil Engineer O Licensed Plumber verying the adequacy of the stormwater diricate from Registered Surveyor confirming the set-out of building & finished ridge height.         Non-slip Stair Tread/Nose Finish Certification Submission of certificate from Applicator in accordance with AS4586.         OS ONS Childsafe Locks an bedroom       0 S 0 NS Continuous Handrail to stairs       Insched Ketter         Non-slip Stair Tread/Nose Finish Certification Submission of certificate from Applicator in accordance with AS4586.       S ONS Childsafe Locks an bedroom       0 S 0 NS Continuo	DAI	No. N0525/16	CC No. 2017-048	CDC No.
Submission of a compliance certificate from an appropriately qualified person verying the waterproofing of all wet areas were carried out in accordance with the requirements of AS3740 - Waterproofing of Wet Areas in Residential Building.         Image: Structural Engineers Certification for Inspections conducted         Image: Structural Engineers Certification for Inspections conducted         Image: Structural Engineers Certification for Inspections conducted         Image: Structural Engineers Certification for Storms and properties of Part 3.7.2 of the Building Code of Australia (Vol.2).         Image: Structural Engineers Certification for Storms and part of the Building Code of Australia (Vol.2).         Image: Structural Engineers Certification for Storms and part of the Building Code of Australia (Vol.2).         Image: Structural Engineers Certification for Submission of a certificate from a licensed Pest Controller confirming termite protections have been provided in accordance with AS3600.1.         Image: Structural Engineer Certification Submission of a certificate from an appropriately qualified O NPER Civil Engineer O Licensed Plumber verying the adequacy of the stormwater drainage system as installed.         Image: Structural Engineers Certification Submission of a certificate from Registered Surveyor confirming the set-out of building & finished ridge height.         Image: Structural Engineers Certification Submission of a certificate from Registered Surveyor confirming the set-out of building & finished ridge height.         Image: Structural Engineers       Structural Engineers         Image: Structural Engineers       Structural Engin	CE	RTIFICATES REQUIRED	) 🗹 (To be provid	ded all in one set of documents - NO drip feeding please)
Smoke Alarm Certification Submission of a certificate from a licensed Electrician confirming all required smoke alarms have been installed in accordance with the requirements of Part 3.7 2 of the Building Code of Australia (Vol.2).         Clazing Certification for		Submission of a compliance certificate	e from an appropriately qualified person ve	
Installed in accordance with the requirements of Part 3.7.2 of the Building Code of Australia (Vol.2).         Image: Control Certification for Submission of a glazing has been supplied and installed to satisfy the requirements of AS1288-2006 or A33959 BAL level         Image: Control Certification Submission of a certificate from a licensed Pest Controller confirming termite protections have been provided in accordance with A53680.1.         Image: BASIX Compliance Statement Confirming all requirements have been satisfied.         Image: Stormwater Certification Submission of a certificate from an appropriately qualified O NPER Civil Engineer O Licensed Plumber verifying the adequacy of the stormwater drainage system as installed.         Image: Stair Tread/Nose Finish Certification Submission of a certificate from Registered Surveyor confirming the set-out of building & finished ridge height.         Image: Non-slip Stair Tread/Nose Finish Certification Submission of certificate from Applicator in accordance with A54586.         OS ONS Childsafe Locks on bedrooms       0 S 0 NS Continuous Handrail to stars         INSPECTION RESULT       PASS IFAIL         S = Satisfactory NS = Not Satisfactory         1) Provide Geotechnical Form 3 as per Cond. E2         2) Certification required for Stormwater Drainage System as per Cond.E3 & E4         3) Provide Councils written approval that all restorations to public infrastructure have been completed satisfactorily as per Cond.E5         4) Install Laundry tub to wet area         5) Ensure sub floor area is clear of loose earth & achieves compliance with NCC/BCA	4	Structural Engineers Certific	ation for Inspections conducted	
Submission of a glazing certificate confirming all glazing has been supplied and installed to satisfy the requirements of AS1282-006 or AS1398 AL level         Image: Termite Control Certification Submission of a certificate from a licensed Pest Controller confirming termite protections have been provided in accordance with AS3680.1.         Image: BASIX Compliance Statement Confirming all requirements have been satisfied.         Image: BaSix Compliance Statement Confirming all requirements have been satisfied.         Image: BaSix Compliance Statement Confirming all requirements have been satisfied.         Image: BaSix Compliance Statement Confirming all requirements have been satisfied.         Image: BaSix Compliance Statement Confirming all requirements have been satisfied.         Image: BaSix Compliance Statement Confirming all requirements have been satisfied.         Image: BaSix Compliance Statement Confirming all requirements have been satisfied.         Image: BaSix Compliance Statement Confirming all requirements have been satisfied.         Image: BaSix Compliance Statement Confirming all requirements have been satisfied.         Image: Basix Compliance Statement Confirming all requirements have been satisfied.         Image: Basix Compliance Statement Confirming all requirements have been satisfied.         Image: Basix Compliance Statement Confirming all requirements for Statement Statement Confirming all requirements for Statement Statement Confirming all requirements for Statement S	2			
<ul> <li>provided in accordance with AS3660.1.</li> <li>BASIX Compliance Statement Confirming all requirements have been satisfied.</li> <li>Stormwater Certification Submission of a certificate from an appropriately qualified O NPER Civil Engineer O Licensed Plumber verifying the adequacy of the stormwater drainage system as installed.</li> <li>Survey Certification Submission of a certificate from Registered Surveyor confirming the set-out of building &amp; finished ridge height.</li> <li>Non-slip Stair Tread/Nose Finish Certification Submission of certificate from Applicator in accordance with AS4586.</li> <li>OS ONS Childsafe Locks on bedrooms 0 S O NS Continuous Handrail to stars OS ONS Non-slip Finish applied to stars INSPECTION RESULT PASS FAIL S = Satisfactory NS = Not Satisfactory 1) Provide Geotechnical Form 3 as per Cond. E2</li> <li>Certification required for Stormwater Drainage System as per Cond.E3 &amp; E4</li> <li>Provide Councils written approval that all restorations to public infrastructure have been completed satisfactorily as per Cond.E5</li> <li>Install Laundry tub to wet area</li> <li>Ensure sub floor area is clear of loose earth &amp; achieves compliance with NCC/BCA requirements</li> <li>Provide adequate tension to balustrade wires to comply with BCA table 3.9.2.1namely at post spaces around 1.8m centres or install additional wires.</li> </ul>		Submission of a glazing certificate cor	firming all glazing has been supplied and i	installed to satisfy the requirements of
Stormwater Certification Submission of a certificate from an appropriately qualified ○ NPER Civil Engineer ○ Licensed Plumber verifying the adequacy of the stormwater drainage system as installed.         Survey Certification Submission of a certificate from Registered Surveyor confirming the set-out of building & finished ridge height.         Non-slip Stair Tread/Nose Finish Certification Submission of certificate from Applicator in accordance with AS4586.         OS ONS Childsafe Locks on bedrooms       © S ○ NS Continuous Handrail to stairs         INSPECTION RESULT       PASS         Y FAIL       S = Satisfactory         NS = Not Satisfactory       NS = Not Satisfactory         1) Provide Geotechnical Form 3 as per Cond. E2         2) Certification required for Stormwater Drainage System as per Cond.E3 & E4         3) Provide Councils written approval that all restorations to public infrastructure have         been completed satisfactorily as per Cond.E5         4) Install Laundry tub to wet area         5) Ensure sub floor area is clear of loose earth & achieves compliance with NCC/BCA requirements         6) Provide adequate tension to balustrade wires to comply with BCA table 3.9.2.1namely         at post spaces around 1.8m centres or install additional wires.				d Pest Controller confirming termite protections have been
vertying the adequacy of the stormwater drainage system as installed.         Image: Survey Certification Submission of a certificate from Registered Surveyor confirming the set-out of building & finished ridge height.         Image: Survey Certification Submission of a certificate from Registered Surveyor confirming the set-out of building & finished ridge height.         Image: Survey Certification Submission of a certificate from Registered Surveyor confirming the set-out of building & finished ridge height.         Image: Survey Certification Submission of a certificate from Registered Surveyor confirming the set-out of building & finished ridge height.         Image: Survey Certification Submission of a certificate from Registered Surveyor confirming the set-out of building & finished ridge height.         Image: Survey Certification Submission of a certificate from Registered Surveyor confirming the set-out of building & finished ridge height.         Image: Survey Certification Submission of a certificate from Registered Surveyor confirming the set-out of building & finished ridge height.         Image: Survey Certification Result Image: Super Cond. E2         2) Certification required for Stormwater Drainage System as per Cond.E3 & E4         3) Provide Councils written approval that all restorations to public infrastructure have         beeen completed satisfactorily as per Cond.E5         4) Install Laundry tub to wet area         5) Ensure sub floor area is clear of loose earth & achieves compliance with NCC/BCA requirements         6) Provide adequate tension to balustrade wires to comply with BCA table 3.9.2.1	2	BASIX Compliance Statement	nt Confirming all requirements have been	satisfied.
Non-slip Stair Tread/Nose Finish Certification Submission of certificate from Applicator in accordance with AS4586.         ©S ONS Childsafe Locks on bedrooms       ©S ○ NS Continuous Handrail to stairs       ⊙S ○ NS Non-slip Finish applied to stairs         INSPECTION RESULT       PASS       ✓ FAIL       S = Satisfactory       NS = Not Satisfactory         1) Provide Geotechnical Form 3 as per Cond. E2       2) Certification required for Stormwater Drainage System as per Cond.E3 & E4         3) Provide Councils written approval that all restorations to public infrastructure have         been completed satisfactorily as per Cond.E5         4) Install Laundry tub to wet area         5) Ensure sub floor area is clear of loose earth & achieves compliance with NCC/BCA requirements         6) Provide adequate tension to balustrade wires to comply with BCA table 3.9.2.1namely         at post spaces around 1.8m centres or install additional wires.         ACCREDITED CERTIFIER       Jamman         BPB#       0124       DATE       26/7/17         IMPORTANT NOTE: It is the Policy of Form Building Certifiers Pty Ltd that an Occupation Certificate will not be issued after the	Z			ly qualified ONPER Civil Engineer O Licensed Plumber
OS ONS Childsafe Locks on bedrooms       Image: Signature Signatur		Survey Certification Submissio	n of a certificate from Registered Surveyor	confirming the set-out of building & finished ridge height.
INSPECTION RESULT       PASS       ✓ FAIL       S = Satisfactory       NS = Not Satisfactory         1) Provide Geotechnical Form 3 as per Cond. E2         2) Certification required for Stormwater Drainage System as per Cond.E3 & E4         3) Provide Councils written approval that all restorations to public infrastructure have         been completed satisfactorily as per Cond.E5         4) Install Laundry tub to wet area         5) Ensure sub floor area is clear of loose earth & achieves compliance with NCC/BCA requirements         6) Provide adequate tension to balustrade wires to comply with BCA table 3.9.2.1namely         at post spaces around 1.8m centres or install additional wires.		Non-slip Stair Tread/Nose Fi	nish Certification Submission of cert	ificate from Applicator in accordance with AS4586.
1) Provide Geotechnical Form 3 as per Cond. E2 2) Certification required for Stormwater Drainage System as per Cond.E3 & E4 3) Provide Councils written approval that all restorations to public infrastructure have been completed satisfactorily as per Cond.E5 4) Install Laundry tub to wet area 5) Ensure sub floor area is clear of loose earth & achieves compliance with NCC/BCA requirements 6) Provide adequate tension to balustrade wires to comply with BCA table 3.9.2.1namely at post spaces around 1.8m centres or install additional wires. ACCREDITED CERTIFIER Mamments BPB# 0124 DATE 26/7/17 IMPORTANT NOTE: It is the Policy of Form Building Certifiers Pty Ltd that an Occupation Certificate will not be issued after the	⊙s	ONS Childsafe Locks on bedroom	S OS ONS Continuous Handra	il to stairs OS ONS Non-slip Finish applied to stairs
<ul> <li>2) Certification required for Stormwater Drainage System as per Cond.E3 &amp; E4</li> <li>3) Provide Councils written approval that all restorations to public infrastructure have been completed satisfactorily as per Cond.E5</li> <li>4) Install Laundry tub to wet area</li> <li>5) Ensure sub floor area is clear of loose earth &amp; achieves compliance with NCC/BCA requirements</li> <li>6) Provide adequate tension to balustrade wires to comply with BCA table 3.9.2.1namely at post spaces around 1.8m centres or install additional wires.</li> </ul>	INS	PECTION RESULT	PASS 🗹 FAIL	<b>S</b> = Satisfactory <b>NS</b> = Not Satisfactory
<ul> <li>3) Provide Councils written approval that all restorations to public infrastructure have been completed satisfactorily as per Cond.E5</li> <li>4) Install Laundry tub to wet area</li> <li>5) Ensure sub floor area is clear of loose earth &amp; achieves compliance with NCC/BCA requirements</li> <li>6) Provide adequate tension to balustrade wires to comply with BCA table 3.9.2.1namely at post spaces around 1.8m centres or install additional wires.</li> </ul>	1) F	Provide Geotechnical Fo	orm 3 as per Cond. E2	
been completed satisfactorily as per Cond.E5 4) Install Laundry tub to wet area 5) Ensure sub floor area is clear of loose earth & achieves compliance with NCC/BCA requirements 6) Provide adequate tension to balustrade wires to comply with BCA table 3.9.2.1namely at post spaces around 1.8m centres or install additional wires. ACCREDITED CERTIFIER Amount <u>BPB# 0124</u> DATE <u>26/7/17</u> IMPORTANT NOTE: It is the Policy of Form Building Certifiers Pty Ltd that an Occupation Certificate will not be issued after the	2) (	Certification required for	Stormwater Drainage Sy	vstem as per Cond.E3 & E4
<ul> <li>4) Install Laundry tub to wet area</li> <li>5) Ensure sub floor area is clear of loose earth &amp; achieves compliance with NCC/BCA requirements</li> <li>6) Provide adequate tension to balustrade wires to comply with BCA table 3.9.2.1namely at post spaces around 1.8m centres or install additional wires.</li> <li>ACCREDITED CERTIFIER Amount</li> <li>BPB# 0124 DATE 26/7/17</li> <li>IMPORTANT NOTE: It is the Policy of Form Building Certifiers Pty Ltd that an Occupation Certificate will not be issued after the</li> </ul>	3) F	Provide Councils written	approval that all restorat	ions to public infrastructure have
5) Ensure sub floor area is clear of loose earth & achieves compliance with NCC/BCA requirements 6) Provide adequate tension to balustrade wires to comply with BCA table 3.9.2.1namely at post spaces around 1.8m centres or install additional wires. ACCREDITED CERTIFIER Advance <u>BPB# 0124</u> <u>DATE 26/7/17</u> IMPORTANT NOTE: It is the Policy of Form Building Certifiers Pty Ltd that an Occupation Certificate will not be issued after the	bee	n completed satisfactor	ily as per Cond.E5	
6) Provide adequate tension to balustrade wires to comply with BCA table 3.9.2.1namely at post spaces around 1.8m centres or install additional wires.          ACCREDITED CERTIFIER       Accredited Certifiers         MPORTANT NOTE: It is the Policy of Form Building Certifiers       Pty Ltd that an Occupation Certificate will not be issued after the	4) I	nstall Laundry tub to we	et area	
at post spaces around 1.8m centres or install additional wires. ACCREDITED CERTIFIER Additional wires BPB# 0124 DATE 26/7/17 IMPORTANT NOTE: It is the Policy of Form Building Certifiers Pty Ltd that an Occupation Certificate will not be issued after the	5) E	nsure sub floor area is clea	ar of loose earth & achieves o	compliance with NCC/BCA requirements
ACCREDITED CERTIFIER	6) F	Provide adequate tensio	n to balustrade wires to co	omply with BCA table 3.9.2.1namely
ACCREDITED CERTIFIER	atp	ost spaces around 1.8r	n centres or install additio	onal wires.
IMPORTANT NOTE: It is the Policy of Form Building Certifiers Pty Ltd that an Occupation Certificate will not be issued after the				
IMPORTANT NOTE: It is the Policy of Form Building Certifiers Pty Ltd that an Occupation Certificate will not be issued after the				
IMPORTANT NOTE: It is the Policy of Form Building Certifiers Pty Ltd that an Occupation Certificate will not be issued after the		Plan	mun	26/7/17
			rm Building Certifiers Pty Ltd that an (	
expiration of TWELVE (12) MONTHS from the date of this Final Inspection Report. ORM Building Certifiers Pty Ltd ABN 76 134 030 710   57 Carawa Road, Cromer NSW 2099   +61 2 9982 4882   admin@formbc.com   formbc.com	expir	ration of TWELVE (12) MONTHS from	n the date of this Final Inspection Rep	ort.



Number of	N	S	P	E	С	T		0	N	V	R	E	Ρ	0	R	T
-----------	---	---	---	---	---	---	--	---	---	---	---	---	---	---	---	---

۰.

🗋 Owner 🔲 Applicant 🗹 Builder	Other
Name MultiDwell	Tel/Email
PROPERTY ADDRESS	CC:CDC# CC2017-048
2 Old Barrenjoey Rd, Avalon	
INSPECTION TYPE	
Wet Area	
INSPECTION OUTCOME	
Certifier Opinion	Action Required (read with NOTES below)
Inspection stage is Satisfactory	✓ NO re-inspection required
Inspection stage is Satisfactory subject to Action Required	Re-inspection required
Inspection stage is Not Satisfactory	Tick if result has also been given verbally
NOTES	
Waterproofing of wet areas done satisfactorily	
Pipework penetrations in wall lining to be waterproofed	
Contractor to issue certification	
Works to be completed in accordance with NCC/BCA &	& AS3740
Builder made aware of water penetration issues assoc	iated with roof panel system due
to flashings not being installed as yet.	
ACCREDITED CERTIFIER	врв# <u>1714</u> дате <mark>8/6/17</mark>



IN	ISF	PE	С	T		O	Ν	R		P	Ο	R	T
----	-----	----	---	---	--	---	---	---	--	---	---	---	---

۰.

.

🗋 Owner 🔲 Applicant 🗹 Builder	Other
Name MultiDwell	Tel/Email
PROPERTY ADDRESS	CC:CDC# CC2017-048
2 Old Barrenjoey Rd, Avalon	L
INSPECTION TYPE	
Framing	
INSPECTION OUTCOME	
Certifier Opinion	Action Required (read with NOTES below)
Inspection stage is Satisfactory	MO re-inspection required
Inspection stage is Satisfactory subject to Action Required	Re-inspection required
Inspection stage is Not Satisfactory	Tick if result has also been given verbally
NOTES	
Framing all generally erected satisfactory & as per eng	ineering specifications and approval
Engineer to provide report if inspection conducted	
Builder to ensure adequate tie downs, connector brack	ets and bracing are installed in
accordance with AS1684	
Childsafe locks screens or restrictors required to all be	droom windows with sill
heights <1.7m where FGL is >2.0m below	
ACCREDITED CERTIFIER	врв# 1714 дате 26/5/17



# **INSPECTION REPORT**

Owner Applicant 🗹 Builder	Other
Name MultiDwell	Tel/Email
PROPERTY ADDRESS	CC:CDC# CDC2017-048
2 Old Barrenjoey Rd, Avalon	J
INSPECTION TYPE	
Piers/ Footings	
INSPECTION OUTCOME	
Certifier Opinion	Action Required (read with NOTES below)
Inspection stage is Satisfactory	NO re-inspection required
Inspection stage is Satisfactory subject to Action Required	Re-inspection required
Inspection stage is Not Satisfactory	Tick if result has also been given verbally
NOTES	
Piers/ footings all generally excavated satisfactorily and	d as per engineering specifications
Geotechnical and structural engineer to inspect and pro-	ovide reports
All excess soil and water to be removed from the base	of piers and trenches prior to the
placement of concrete	
ACCREDITED CERTIFIER	ВРВ#_1714 22/3/17



# PRE CC BUILDING INSPECTION RESULT SHEET

SITE ADDRESS

SITE ADDRESS	A	1
2	Old Banenjoe,	Read
APPLICATION DETAILS		
Name //	Puttiquell Group	Phone
Address		CC No.
Development Type		Date App. Received
OBSERVATIONS FROM SITI	E VISIT	
Site Access	Existing driveway Crossover	Battle-axe
Stormwater Drainage	Slope away fee hydraulu	To street
Easements/Sewer/SW	Manhole cover	Open drain/channel
Bushfire Hazard	No 🔲 Yes	
Flooding	Likely Not likely	
Slope of Block	Geotechnical hazard, likely	Not likely
Retaining Walls	Levels match plans	
Set Backs	Wall height is same as plan at l	nighest point (measure)
Neighbours Property	Works potentially affect neighbor	ours (excavation/zone of influence)
Plans & Specifications	Accurately depict existing site of	conditions/buildings 🔲 No
Site/Building Features	Comply with BCA No	
Building Work Commenced	No Yes	
COMMENTS	L	
Moyo	sol schofacty seflect diavately	& site Conditions He plans & deta

non врв# 0124 DATE ACCREDITED CERTIFIER

## PHIL MURPHYS PROPERTY MAINTENANCE PO BOX 435 TERREY HILLS 2084 LICENCE NO 114492C ABN 62 609 565 274

## **PROUDUCT:** DURABIT.

### **MANUFACTURER: DURAM INDUSTRIES**

### PERIOD OF GUARANTEE: SIX YEARS

## <u>PROJECT:</u> 2 OLD BARRENJOEY RD AVALON – BATHROOM

## **CLIENT: MULTIDWELL**

In the event of any defect in proofing against water penetration arising out of the material and workmanship, such a defect will be rectified at no cost to the client providing that the company is given notice in writing within fourteen days of any alleged failure to this application.

There shall be no liability for any failure or deterioration of the waterproofing system resulting from interference or damage because of structural cracking, mechanical causes, and point loads moisture entrapment, chemical damage or any other cause beyond the control of this company.

All membranes comply with AS4654 Parts 1 & 2-2012 for wet area waterproofing or AS CA55 for bituminous membrane systems. All membranes are applied in accordance with BCA 3.8.1.

This warranty does not extend to consequential damage to other property caused by water escaping through the failure of the above system.

DATED 8 6 2017 PHIL MURPHY

# Final Structural Certificate

Address: Multidwell PO Box 1245 Dee Why NSW 2099

Project: Proposed granny flat 2 Old Barrenjoey Road, Avalon NSW

Certificate ref: 16116- final

Re: No 2 Old Barrenjoey Road, Avalon NSW

During the construction work on site for the additions and alterations at No 2 Old Barrenjoey Road, Avalon NSW inspections of the following structural items were made:

- Footing piers

The structural elements inspected satisfy the design requirements for stability, strength and serviceability in accordance with the relevant clauses of the Australian Standards including AS 1684 (Residential timber-framed construction), AS 1720 (Timber structures), AS 3600 (Concrete Code), AS 2870 (Residential slabs and footings) and AS 4100 (Steel Code).

Geotechnical engineers inspection report confirming required allowable bearing capacity is requested to accompany this certificate.

Yours sincerely

Michal Korecky how . Sydney 31/08/2017

Michal Korecky MEngSc, MIE Aust Mob: 0438148944, Ph/fax: 99813332 koreckym@gmail.com ABN: 79 393 130 294 21 Nalya Road Narraweena NSW 2099 www.plansdesign.com.au

# SMOKE ALARM CERTIFICATION

Date: 25/08/17

I <u>Bilal Abbas</u> being the licenced electrician and responsible installer, hereby certify that the smoke alarm/s located as follows:

1x living area

, .

.

2 Old Barrenjoey (property address)

Number of Alarms: 1

Date of test: 21/08/17

Company name: Urban Sparks Electrical Pty Ltd

Signature :

Bulabbe

Licence No: 261975c

ABN: 99 083 030 853



Unit 1, 9 Accolade Avenue, Morisset, 2264 Phone: 4973 6529 Fax: 4973 6542 Email:clint@crystalcleargaa.com.au

ABN: 99 083 030 853

Monday, 21 August 2017

Project: 2 Old Barrenjoey Road, Avalon

The aluminium windows and doors supplied to the above project have been glazed in accordance with Australian Standards AS 2047 – 1999 and the recommended practice of the Federal Glass Merchants Association of Australia and in accordance with Australian Standards AS 1288 – 2006.

Yours faithfully,

Hunz

Clint Jones Lic. No. 132755C Crystal Clear GAA



Multidwell Group Pty Ltd t 1300 80 10 70 e info@multidwell.com.au www multidwell.com.au P.O.Box 1245 , Dee Why, NSW 2099

29 August 2017

• ,

Craig Formosa Form Building Certifiers Pty Ltd 57 Carawa Road Cromer NSW 2099

Dear Craig

#### BASIX @ 2 Old Barrenjoey Road, Avalon

Multidwell certifies that it has constructed the secondary dwelling at the above address as per BASIX Certificate No 771679S dated 27/10/16 and confirm that Lighting, Fixtures, Insulation Requirements, Windows and Glazed Door requirements are in accordance with certificate.

Yours sincerely Multidwell Group Pty Ltd

Paul Mathias Operations Manager



# **BASIX** Completion Receipt

Receipt no.: CR-IC2CC6JJ-771679S

This receipt is confirmation that the certifying authority identified below has satisfied the requirements of clause 154C of the Environmental Planning and Assessment Regulation 2000 for the development described in the 'BASIX Certificate details' section below.

Secretary Date of issue: Wednesday, 20/09/2017



### Principal certifying authority

Name:	Craig
Accreditation scheme:	BPB
Accreditation number:	0124

#### **Final Inspection**

Date of final inspection:

Wednescay, 26/07/2017

### **BASIX Certificate details**

BASIX Certificate no.	771679S
Project name	Greeves Residence (copy of)
Street address	2 Old Barrenjoey Road
Suburb	Avalon Beach
Postcode	2107
Local Government Area	Pittwater Council



Multidwell Group Pty Ltd t 1300 80 10 70 e info@multidwell.com.au www multidwell.com.au P.O.Box 1245, Dee Why, NSW 2099

01/08/2017

. .

Craig Formosa Form Building Certifiers Pty Ltd 57 Carawa Road Cromer NSW 2099

**Dear Craig** 

#### Walls and Roof @ 2 Old Barrenjoey rd, Avalon Beach

Multidwell certifies that materials used and method of installation meet the Performance Requirements or Deemed –To-Satisfy Provisions of Clause 1.2.2 and part 3.5.3 of the Building Code of Australia 2012 Vol 2

Yours sincerely Multidwell Group Pty Ltd

Paul Mathias Operations Manager





Multidwell Group Pty Ltd t 1300 80 10 70 e info@multidwell.com.au www multidwell.com.au P.O.Box 1245 , Dee Why, NSW 2099

19 September 2017

Craig Formosa Form Building Certifiers Pty Ltd 57 Carawa Road Cromer NSW 2099

Dear Craig

• •

.

#### Balustrade @ 2 Old Barrenjoey Road, Avalon

Multidwell certifies that it has provided adequate tension to balustrade wires to comply with BCA table 3.9.2.1 namely at post spaces around 1.8m centres.

Yours sincerely Multidwell Group Pty Ltd

Paul Mathias Operations Manager





# **GEEVES PLUMBING SERVICES**

ACN 057 939 401 ABN 71 057 939 401 PO Box 412 Newport Beach NSW 2106 Telephone 0407470877 Email john@geevesplumbing.com.au Plumb. Lic No. Ll0989 Con. Lic No. 189455C

30/08/17

Multidwell P.O. Box 1245 Dee Why NSW 2099

### Secondary Dwelling at 2 Old Barrenjoey Rd, Avalon Hydraulic Services Completion Certification

ATTENTION: Ms M MacLennan

Dear Margaret,

I, John Geeves of Geeves Plumbing hereby certify that the Hydraulic Services Installation for the secondary dwelling at 2 Old Barrenoey Rd, Avalon has been installed in accordance with the design documents and following conditions. The stormwater works have been installed as per Drawing No. 16116 dated 26/10/16.

#### Other Measures:

Item Description	Standard of Performance
Stormwater Drainage	AS/NZS 3500.3
Sanitary Plumbing	AS/NZS 3500
Cold Water Services	AS/NZS 3500 - 2003
Hot Water Services	AS/NZS 3500.4. Section 8
General Plumbing	AS/NZS 3500 - 2003 and Part J of the BCA
na da na mangana na man Na na	

The information contained in this statement is true and accurate to the best of my knowlege

John Geeves

0407470877

Regards,

Name of Contractor:

Company:

Address:

Phone Number:

Email:

john@geevesplumbing.com.au

Geeves Plumbing Services Pty Ltd

P.O.Box 412 Newport Beach NSW 2106

Signature

Date

#### SEDIMENT CONTROL FENCE DETAILS

SITE PLAN

SCALE 1:200

 $(N) \rightarrow$ 

SEDIMENT CONTROL

1:200

012345

 INSTALL SEDIMENT CONTROL STRUCTURES IN LOCATIONS INDICATED ON DRAWINGS AND AS OTHERWISE REQUIRED TO CONTROL SEDIMENT DURING ALL EXCAVATIONS AND WHILST AREAS OF THE SITE ARE EXPOSED TO EROSION.

10 M

- II. CONTROL STRUCTURES TO BE AS DETAILED OR OTHERWISE REQUIRED.
- III. REVIEW CONTROL MEASURES AND MAINTAIN STRUCTURES DURING CONSTRUCTION.
- IV. IF ADDITIONAL MEASURES ARE REQUIRED FOR EROSION CONTROL OR BY COUNCIL REQUIREMENTS REFER TO 'UNBAN EROSION AND SEDIMENT CONTROL' GUIDELINES PREPARED BY THE DEPARTMENT OF CONSERVATION AND LAND MANAGEMENT.

#### NOTES:

01

- 1. ALL GLAZING TO WINDOWS AND DOORS SHALL BE IN ACCORDANCE WITH THE BASIX REPORT.
- 2. EXTERNAL WALL FABRIC SHALL BE PAINTED WITH A SELECTED COLOUR.
- AN APPROVAL RATED INSULATION TO ALL EXTERNAL STEEL FRAMED WALLS, AND INSULATION MATERIAL TO BE PLACED IN CEILING SPACE WITHIN THE PERIMETER TO ALL EXTERNAL WALLS TO BE IN COMPLIANCE WITH THE BASIX REPORT.
- 4. ROOF FINISHES TO BE IN ACCORDANCE WITH THE BASIX REPORT.
- 5. ALL WORK CARRIED OUT TO BE IN ACCORDANCE WITH THE BCA.

6. ALL TIMBER FRAMING TO CODE AS1684.

7. ALL WINDOWS & DOORS AS NOTED ON PLAN WITH SELECTED COLOUR FINISH.

8. ALL GLAZING TO CODE AS1288.

9. ALL WATERPROOFING TO WET AREAS TO CODE AS3740.

- 10. ALL POWER OUTLETS & SWITCHES TO OWNERS REQUIREMENTS.
- 11. ALL PEST TREATMENT TO CODE AS3660.1-2000.
- 12. SMOKE DETECTOR DENOTED SD ON PLAN TO BCA/39.

ROOF - BASALT WALLS, GUTTERS - DULUX DOE P14.A3 WINDOWS - WHITE RAINWATER TANK - GREY

COLOURS:

NOTES-REV D	D	ISSUED FOR APPROVAL	06.04.17	CLIENT'S NAME:	PROJECT NUMBER 95		PO Box 1245
- COLOURS UPDATED	С	ISSUED FOR APPROVAL	14.10.16	MR & MRS GEEVES	DATE: 29.08.16	Multidwell	Dee Why NSW 2099
	В	ISSUED FOR APPROVAL	21.09.16	ADDRESS:	DRAWN BY: AS	Multicowell Group Pty Lto	info@multidwell.com.au T 1300 80 10 70
	A	ISSUED FOR APPROVAL	29.08.16	2 OLD BARRENJOEY ROAD	CHECKED BY: PM		www.multidwell.com.au
Copyright @ 2010 Multidwell Group Pty Ltd - The design and detail shawn in the drawing remains the sole property of Multidwell Group Pty Ltd and are not to be copied, revised or distributed without the express permission of Multidwell Group Pty Ltd with whom copyright resides.	No:	AMENDMENT	DATE	AVALON	SCALE (A3): 1:200	SITE PLAN	001



#### GEOTECHNICAL RISK MANAGEMENT POLICY FOR PITTWATER FORM NO. 3 – Post Construction Geotechnical Certificate to be submitted with Occupation **Certificate or Subdivision Certificate**

Development Application for		
	Name of Applicant	
Address of site	2 Old Barrenjoey Road, Avalon	

Declaration made by geotechnical engineer on completion of the Development

Ι,	Ben White	on behalf of	White Geotechnical Group Pty Ltd
	(Insert Name)		(Trading or Company Name)

on this the 28/7/2017

certify that I am a Geotechnical Engineer, Engineering Geologist and/or Coastal Engineer as defined by the Geotechnical Risk Management Policy for Pittwater - 2009. I am authorised by the above organisation/company to issue this document and to certify the organisation/company a current professional indemnity policy of at least \$2million. ; I prepared and/or verified the Geotechnical Report as per Form 1 dated referred to below.

#### Geotechnical Report Details:

Report Title: Geotechnical Report 2 Old Barrenjoey Road, Avalon	
Report Date: 02/11/16	
Author : BEN WHITE	
Author's Company/Organisation: WHITE GEOTECHNICAL GROUP PTY LTD	

I reviewed the original structural design, and where applicable the subsequently amended structural details (below listed) which  $\boxtimes$ have been incorporated into the completed project.

I have inspected and/or am satisfied that the foundation materials, upon which the structural elements (as detailed in the original X and amended structural documents) of the development have been erected, comply with the requirements specified in the Geotechnical Report and the Construction Certificate approved Structural Plans.

I have inspected the site during construction and to the best of my knowledge, I am satisfied that the development referred to in the development consent D.A. dated 15/11/2016.

D.A. No. N0525/16 Date consent given 24/01/2017

has been constructed in accordance with the intent of the Geotechnical Report, and the requirements of the conditions of Development  $\boxtimes$ Consent and the Construction Certificate approved Structural Plans relating to the geotechnical issues (including any treatment and/or maintenance plan that may be required to remove risk where reasonable and practical).

I am aware that Pittwater Council require this certificate prior to issuing an occupancy certificate for the development identified above and will rely on this certificate in regard to the development having achieved the "Acceptable Risk Management" criterion defined in the Policy and that reasonable and practical measures have been taken to remove foreseeable risk.

List of all work as executed drawings and Ongoing Maintenance plans relevant to geotechnical risk management.

No ongoing maintenance required.

Signature Ballut				
Name Ben Wh	ite			
Chartered Professi	onal Status	MSc Geol AusIMM CP GEOL		
Membership No.	222757			
Company	White Ge	eotechnical Group Pty Ltd		

Company

### northernbeaches.nsw.gov.au

# NORTHERN BEACHES COUNCIL

Sazzad Sarker, Asset Development Engineer 9am to 4:30pm Mon - Fri Phone 9970 1352

07 September 2017

Margaret MacLennan Multidwell Group Pty Ltd PO Box 1245, Dee Why, NSW 2099

Dear Sir/Madam,

Re: Final inspection of Works in Road Reserve at 2 Old Barrenjoey Road, Avalon Beach NSW 2107.

DA No. N0525/16- Compliance

A final inspection of the approved works in the road reserve at the above address was carried out on 06 September 2017.

The work has been completed in accordance with the approved application to Council's satisfaction.

Should you wish to discuss the matter further, please contact the abovementioned Officer.

Yours sincerely

Sazzad Sarker ASSET DEVELOPMENT ENGINEER

Civic Centre, 725 Pittwater Road Dee Why NSW 2099 ABN 57 284 295 198 t.02 9942 2111 f. 02 9971 4522 Village Park, 1 Park Street Mona Vale NSW 2103 ABN 57 284 295 198 t. 02 9970 1111 f. 02 9970 1200