

Schedule 11 - Suggested Checklist for Preliminary Assessment of Site Conditions in relation to the preparation of Site Stability Reports

1. Site Location (Street and Position in street - above or below; Site dimensions - block shape & size): [1/153 Balgowlah Road, balgowlah 2093 NSW](#)
2. Geotechnical Area in which the site is located): [G4](#)
3. Proposed development (general description, including maximum excavation depths, maximum fill depths, and proximity to existing structures): [Creation of a deck over existing balcony.](#)
4. Existing site: description eg. topography, slope angles (in degrees), exposures of rock and soil, existing site development, evidence of possible slope instability: [See 4\) below](#)
5. Recommendations: based on the above items, and the flowchart below that indicates the principal factor(s) considered in the assessment, it is recommended that:
 - ~~geotechnical assessment is required;~~ or
 - geotechnical assessment is not required.
 - ~~other comments:~~

DATE OF ASSESSMENT : [10.10.2024](#)

ASSESSMENT BY : [Charlotte Vergnolle](#)

4. EXISTING SITE ANALYSIS

[There is no history of site instability from adjacent sites](#)
[There will not be excavation >2m](#)
[There is no fill >1m present](#)
[The site is developed already](#)
[There is not excavation >2m present](#)

CHECKLIST FOR COUNCIL'S CONDITIONS AND NEED FOR GEOTECHNICAL CL



