



<u>LEGEND</u>

		Dulluling	DALC	Dalcony Height
		Walls	BOL	Bollard
		Kerb Bottom	BS	Bus Stop
		Concrete edge	BW	Bottom of Window
		Kerb top	CHIM.	Chimney Height
		Barrier	ER	Earth Rod
$ \mathfrak{M} $		Hedge	FH	Fire Hydrant
- 1 1		Fence	FL	Floor Level
-x-x-	-x-x-x->	Overhead Powerline	GU	Gully
	$\bigcirc \triangle$	Manholes	GFL	Ground Floor Level
△1		Survey Station & Name	GM	Gas Meter
			GV	Gas Valve
8		Bench Mark	HT	Height
			IC	Inspection Cover
S	AP.	Sapling	LGFL	Lower Floor Level
_	_		МН	Manhole
\	}	Tree, 12/0.5/10	PARA	Parapet Height
		(Spread/Trunk/Height)	PP	Power Pole
			SFL	Second Floor Level
		Area Of Undergrowth	SIL	Sill Height
			SP	Sign Post
		Gate	SV	Stop Valve
			SVP	Sewer Vent Pipe
IC		Inspection chamber	TD	Top of Door
CL		Cover level	TDW	Top of Door/Windo
IL		Invert level	TEL	Telstra
Inv	Ø0.25	Pipe invert (diameter)	TG	Top of Gutter
-GU		Gully	TL	Traffic Light
$-\kappa$ o		Back Gully	TW	Top of Window
МН		Manhole	TOF	Top of Fence
			TOW	Top of Wall
			UND	Underside Height
			WM	Water Meter
			W-B	Wall to Boundary

BALC Balcony Height

NOTES:

2. THE INFORMATION ON THIS SURVEY IS TO BE USED FOR DA PURPOSES ONLY. 3. IF THERE IS ANY POINT OR FEATURE i.e.(FLOOR LEVEL, WALL POSITION, ROOF OR RIDGE HEIGHT ETC) CRITICAL TO THE PREPARATION OF DESIGN PLANS OR CONSTRUCTION, THAT POINT OR FEATURE SHOULD BE MADE KNOWN TO US SO IT'S ACCURACY CAN BE CONFIRMED PRIOR TO THE COMPLETION OF DESIGN PLANS OF COMMENCEMENT OF CONSTRUCTION. 4. SOME STRUCTURES AND FEATURES ARE APPROXIMATE ONLY. IF USED FOR DESIGN CONFIRMATION OF ACCURACY SHOULD BE CONFIRMED. 5. FENCES ARE APPROXIMATE ONLY UNLESS SPECIFICALLY DIMENSIONED TO BOUNDARY. 6. SURVEY MARKS MUST BE PLACED PRIOR TO CONSTRUCTION OR ERECTION OF FENCES. 7. TREE INFORMATION HAS BEEN SURVEYED FROM GROUND LEVEL AND THEREFORE SHOULD BE TREATED AS APPROXIMATE ONLY, THE EXTENT OF THE CANOPY IS APPROXIMATE AND DIAGRAMMATIC ONLY. 8. STAIR RISES, STEPS AND LANDINGS HAVE NOT BEEN INDIVIDUALLY LOCATED AND ARE DIAGRAMMATIC ONLY. 9. THE RECORDS OF THE SERVICE PROVIDERS HAVE NOT BEEN INVESTIGATED, ONLY THOSE SERVICES THAT ARE VISIBLE AND ACCESSIBLE AT THE DATE OF SURVEY HAVE BEEN SHOWN. 10. SERVICES SHOWN ARE INDICATIVE ONLY, OTHER SERVICES MAY EXIST THAT ARE NOT SHOWN. THEREFORE FIELD CONFIRMATION SERVICE LOCATORS SHOULD BE OBTAINED TO CONFIRM EXACT POSITION AND DEPTH.

11. SITE AREA SHOWN HAS BEEN CALCULATED BY SURVEY.12. A SITE AND BOUNDARY SURVEY HAS BEEN CARRIED OUT.

13. ORIGIN OF LEVELS IS TAKEN BY GPS TO A.H.D

14. BEARINGS ARE ON MAGNETIC MERIDIAN.

1. ALL DIMENSIONS AND LEVELS SHOULD BE CHECKED ON SITE PRIOR TO DESIGN AND CONSTRUCTION.

COPYRIGHT:

THE INFORMATION SHOWN/CONTAINED IN THIS DRAWING/FILE IS COPYRIGHT. THE INFORMATION MAY ONLY BE USED FOR THE PURPOSE FOR WHICH IT WAAS PRODUCED. NO PART OF THIS DRAWING/FILE MAY BE USED OR REPRODUCED IN PART OR WHOLE, FOR ANY OTHER CLIENT, PERSON OR COMPANY WITHOUT THE PRIOR WRITTEN PERMISSION OF HILL & BLUME PTY. LTD.



CONSULTING SURVEYORS
ACN 000 721 004

102 Crown Street
Woolloomooloo
NSW 2011
Tel (02) 9332 4888
Fax (02) 9331 6422

Hill & Blume Pty Ltd

surveyors@hillandblume.com.au

60842001A

<u>PROJECT</u>

05/10/18

SHOWING SELECTED LEVELS

AND DETAIL OVER

LOT 1 IN DP 373531 BEING

1955 PITTWATER ROAD, BAYVIEW.

LGA
NORTHERN BEACHES

SCALE

1:100

DRAWN/PAPER SIZE
DGM/AO

SURVEY DATE

DRAWING No.

