GEOTECHNICAL RISK MANAGEMENT POLICY FOR PITTWATER FORM NO. 1(a) - Checklist of Requirements For Geotechnical Risk Management Report for **Development Application**

NIC **Development Application for** and Name of Applicant RON)) Beher (entra) Address of site

The following checklist covers the minimum requirements to be addressed in a Geotechnical Risk Management Geotechnical Report. This checklist is to accompany the Geotechnical Report and its certification (Form No. 1).

Geotechnical Report Details: Landrick Lish Astegment for Lot 19, De 8698, 77 Central la Report Title: Aralon Beuch 2107 (5620-1170) Report Date: 18th October 2020 Author: ma Ber soney heatech Pty Ltd. Author's Company/Organisation: Please mark appropriate box Comprehensive site mapping conducted _ (date) Mapping details presented on contoured site plan with geomorphic mapping to a minimum scale of 1:200 (as appropriate) Subsurface investigation required ∋ No Justification 2 Yes Date conducted 27 9 29 Geotechnical model developed and reported as an inferred subsurface type-section Geotechnical hazards identified Above the site on the site Below the site Beside the site Geotechnical hazards described and reported Risk assessment conducted in accordance with the Geotechnical Risk Management Policy for Pittwater - 2009 Consequence analysis Frequency analysis Risk calculation Risk assessment for property conducted in accordance with the Geotechnical Risk Management Policy for Pittwater - 2009 Risk assessment for loss of life conducted in accordance with the Geotechnical Risk Management Policy for Pittwater - 2009 Assessed risks have been compared to "Acceptable Risk Management" criteria as defined in the Geotechnical Risk Management Policy for Pittwater - 2009 Opinion has been provided that the design can achieve the "Acceptable Risk Management" criteria provided that the specified conditions are achieved. Design Life Adopted

Geotechnical Conditions to be applied to all four phases as described in the Geotechnical Risk Management Policy for

Pittwater - 2009 have been specified Additional action to remove risk where reasonable and practical have been identified and included in the report.

Risk assessment within Bushfire Asset Protection Zone.

I am aware that Pittwater Council will rely on the Geotechnical Report, to which this checklist applies, as the basis for ensuring that the geotechnical risk management aspects of the proposal have been adequately addressed to achieve an "Acceptable Risk Management" level for the life of the structure, taken as at least 100 years unless otherwise stated, and justified in the Report and that reasonable and practical measures have been identified to remove foreseeable risk

Signature ... Name NV Ban Hamilton Chartered Professional Status. AG.S. (EA) Membership No. 611.8464 Company Sydney Geotech (t) Ltd