

Environmental Compliance
Mon – Thurs 8am to 6pm, Fri 8am to 5pm
Phone: 9970 1300

20 October 2006

Rowena Louise McGilvray
7 Bilgola Avenue
BILGOLA NSW 2107

Record of Critical Stage Inspection

Issued under Clauses 162A & 162B of the Environmental
Planning and Assessment Regulation 2000 (as amended)

Development Consent:	N0183/05	
Construction Certificate:	CC0197/05	
Property:	Address: 7 Bilgola Avenue Bilgola Lot: 5 DP: 11978	
Critical Stage Inspection:	Stormwater System	
Description of works inspected:	All stormwater for dwelling	
Date of Inspection:	19 October 2006	
Inspected on behalf of Pittwater Council by:	Carl Georgeson	
Result of Inspection:	Satisfactory	
	Reinspection required	No

Carl Georgeson
Development Compliance Officer