

18 August 2021

Dear,

Naresh Mehrok Mehrok Homes

RESIDENTIAL DEVELOPMENT
RE: ONSITE DETENTION TANK
LOCATION: 83 PARKES RD COLLAROY PLATEAU

Reference is made to the site inspection carried out at the above address to determine the structural adequacy of the OSD tank walls.

ABN 41 154 140 002

Baulkham Hills NSW 2153 Suite 316, 5 Celebration Drive

Email: info@mearesconsulting.com.au

Bella Vista NSW 2153 Ph: (02) 8883 2891

P.O. Box 7063

Following a review of the approved plans for the tank and the inspection it is my opinion that the construction of the tank was in accordance with the approved plans.

Based on AS3600 Concrete Structures Code and the approved design plans it is my opinion that the tank is structurally adequate.

If you have any further questions please do not hesitate to give me a call.

I possess Indemnity insurance to the satisfaction of the building owner or my principle.

MEARES CONSULTING

Patrick Meares

BE, Grad Dip LGE MIEAust CPEng EngExec NER APEC Engineer IntPE(Aus)

STRUCTURAL DRAINAGE CIVII