

RECEIVED 20 APR 2017 PITTWATER COUNCIL

INTERIM OCCUPATION CERTIFICATE

Date Application Received	25.07.13					
Council	Northern Beaches Council - Pittwater DA Number		ber	N0071/13		
Occupation Certificate No.	IOC2013-181	Date App	roved	13.04.17		
CC No.	CC2013-181	Date App	roved	30.08.13		
Certifying Authority	Craig Formosa					
Accredited Certifier	Craig Formosa		Accredi	tation No.	BPB0124	
Accreditation Body	Building Professionals Board					
APPLICANT DETAILS						
Name	M & A Baylis		Ph No.	0431 496	996	
Address	c/- J. Willmore 11 Hudson Parade, AVALON	NSW 2107				
OWNER DETAILS						
Name	M & A Baylis					
Address	69 Marine Road, AVALON NSW 2107					
DEVELOPMENT DETAILS						
Subject Land	69 Marine Road, AVALON NSW 2107		Lot No.	112	DP	8394
Description of Development	Stage 1: Alterations and additions to an existi	ing dwelling or	nly (exclu	uding swimr	ning po	ol.)
Class of Building	1a Value of Work \$340,00		\$340,000.	0.00		
Outstanding Works Extending roof over rumpus room						
	THE BUILDING IS SUITABLE FOR (OCCUPATIO	N			
Certificates Attached RECORD OF INSPECTION	Mandatory Inspection Reports, Basix Co Smoke Detectors, Waterproofing, Glazin s		eipt, Sti	ructural Er	igineer	S, ,
Site Inspection prior to issue					2	2.07.13
Waterproofing					2	0.11.13
Final Inspection – issue of C	Occupation Certificate				0	2.04.14
Final Re-Inspection					0	6.04.17
CERTIFICATION						
, Craig Formosa, as the cer	tifying authority am satisfied that;					
(a) the building will no	ot constitute a hazard to the health or safety	of the occup	bants,			
(b) a current Develop	ment Application is in force for the building,					
	ng Development OR Construction Certificat	te has been i	ssued for	or the build	ling in	respect
	pecifications for the building,	A !!				
(a) the building is suit	able for its use under the Building Code of		3			
(a) all the properties of	conditions of development consent have be	een satisfied.				
(e) all the prescribed		Signed: Romore Date: 13.04.17				
(e) all the prescribed	re	D	ate: 13.	04.17		
Signed: epomo	re	D	ate: 13.	04.17		
Signed: epotence PCA Accreditation	No. BPB0124 y: Building Professionals Board	D	ate: 13.	04.17		

fet #409606



INSPECTION REPORT

Owner Applicant Suilder	Other
Name Silverfern Constructions	Tel/Email
PROPERTY ADDRESS	CC:CDC# CC2013-181
69 Marine Pde, Avalon	
NSPECTION TYPE	
R.I Final	
NSPECTION OUTCOME	
Certifier Opinion	Action Required (read with NOTES below)
Inspection stage is Satisfactory	MO re-inspection required
Inspection stage is Satisfactory subject to Action Required	Re-inspection required
Inspection stage is Not Satisfactory	Tick if result has also been given verbally
NOTES	
) Interim Occupation Certificate to be issued at this sta	age outstanding works include:
xtending roof over rumpus room	
) All previously identified issues of non-compliance re-	ctified to achieve compliance
 All certificates required issued 	
	·
	ВРВ# 1714 DATE 06/04/17
	UAIE

FORM Building Certifiers Pty Ltd ABN 76 134 030 710 | 57 Carawa Road, Cromer NSW 2099 | +61 2 9982 4882 | admin@formbc.com | formbc.com

BUILDING CERTIFIERS **INSPECTION REPORT** 5853 Builder □ Applicant Other Owner Name Silverfern Constructions Tel/Email **PROPERTY ADDRESS** Marine Pde, Avalors 69 **INSPECTION TYPE** Fingl **INSPECTION OUTCOME** Action Required (read with NOTES below) **Certifier Opinion** Inspection stage is Satisfactory NO re-inspection required Inspection stage is Satisfactory subject to Action Required Re-inspection required Tick if result has also been given verbally Inspection stage is Not Satisfactory NOTES remove vegetation / soil around hardwood beams at the lowest point at the deck. poin into bruch wall with k noil plate fixed 17 Bol bi-folding apenings certificates Proude - Sma ouing fel Bi fold window compliance la - Structural Prairie (Bush 02/04/2014 Accredited Certifier - BPB 0124 Date

FORM Building Certifiers Pty Ltd ABN 76 134 030 710 | PO Box 1824, Dee Why NSW 2099 | T/F +61 2 8021 9313 | info@formbc.com | www.formbc.com

INSPECTION REPORT 3726

Owner 🔾	Applicant	Builder	Other	
Name Silver	Fern Consh	uchans	Tel/Email	
PROPERTY A				
69 Mar	ine RO, AI	alon		
INSPECTION				
WATER P	and the second			
INSPECTION	OUTCOME	A Distance of the American	and the second	
Certifier Opinior	1		Action Required (read with NOTES below)	
Inspection star	ge is Satisfactory		□ NO re-inspection required	
Inspection stage	ge is Satisfactory sub	ject to Action Required	Re-inspection required	
□ Inspection stag	ge is Not Satisfactory	,	□ Tick if result has also been given verbally	
NOTES				
WATER PROC	FIRE TO BE	ATHROOM + LC	AUNDRY SATEFACTORY.	
WATERSTO!	5 PROVIDED) TO EDTRY	ROR RAYS.	
PROVIDE CERTIFICATE FROM LICONGED INSTALLER.				
-				
0/	1			
l lo	more		20/11/2013	
Accredited Certifie		OIRH		

BUILDING CERTIFIERS

FORM Building Certifiers Pty Ltd ABN 76 134 030 710 | PO Box 1824, Dee Why NSW 2099 | T/F +61 2 8021 9313 | info@formbc.com | www.formbc.com





INSPECTION REPORT

1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
_≥KDwner	□ Applicant	D Builder	Other
And the second s	AYLIS.		Tel/Email
PROPERTY A	ADDRESS	in the main and the second	and the second of the second
69	MARINE	POE, A	Acon
INSPECTION		anter-stand more as an inter-state of	and the second
An owner to supervise the supervised states and the supervised states	E CC.	Israk	
INSPECTION	in the state of the state of the state of the	The second states in the second second second	and the second
Certifier Opinio			Action Required (read with NOTES below)
Anspection sta	ige is Satisfactory		NO re-inspection required
Inspection sta	ige is Satisfactory s	ubject to Action Required	C Re-inspection required
Inspection sta	ge is Not Satisfacto	ory .	Tick if result has also been given verbally
NOTES			
Re CC	issue	- Mapo	sol rothif auto
site a	is sue	0/c -	Stage / orly
mim	in port.	not inc	luder at this stage.
		/	
	/		
	/		
/			
/			
/			
	0		
l	konnon	~	22 1 7 12013
Accredited Certifi	er - BPB 0/24	£	Date

FORM Building Certifiers Pty Ltd ABN 78 134 030 710 | PO Box 1824, Dee Why NSW 2099 | T/F +61 2 8021 9313 | info@formbc.com | www.formbc.com

A.C. WATERPROOFING SERVICES P/L

4.12.13.

A.C.N. 074 728 948 Postal Address: P.O. BOX 40 WATSONS BAY NSW 2030 Phone/Fax: 93401244Mobile: 041 1116061

Re: Waterproofing 69 Marine Parade, Avalon.

Dear Sir,

The Owner.

The Tremco TP90 as used in one bathroom and one laundry shall be guaranteed for a period of 7 years only. The Tremco N.E.M.used on balcony shall be guaranteed for a period of 5 years only, this area is to have a slip sheet between tile bed and membrane.

Both membrane systems have been applied to the recommendations and specifications of the manufacturer, this being Tremco P/L.

Tremco TP90 conforms to AS 3740 for wet areas.

Yours Faithfully, A. Cloete.

Davelo



A.B.N. 97 604 238 185 Licence # 147162C PO Box 1902, Dee Why NSW 2099 M: 0407 407 693

1st April 2014

Mark Baylis 69 Marine Pde Avalon NSW 2107

To whom it may concern,

Re: 69 Marine Pde, Avalon NSW 2107

This letter is to certify that the smoke alarm at the above address was fitted in accordance with Australian standard 3786-1993 and hardwired in accordance with BCA 3.7.2.

All electrical works comply with AS 3000.

Regards,

Peter Jordan

Barrenjoey Consulting Engineers pty ltd Stormwater Structural Civil abn 13124694917 acn 124694917

9th May 2014

M. Baylis 69 Marine Parade Avalon NSW 2107

STRUCTURAL WORKS CERTIFICATION 69 MARINE PARADE AVALON Job No 120712

Barrenjoey Consulting Engineers _{pty ltd} inspected the following structural components whilst under construction at the above site address.

- 1B7, 1B8 1B9 and 1J2
- 1B1 and IB3

It is our opinion that the above components / works have been carried out in accordance with the intention of the plans and instructions issued by this office and will be adequate to withstand the forces likely to be applied upon those elements. Noting it is our understanding that all other structural components were inspected by the Principal Certifying Authority during construction.

Should further information regarding this matter be required please contact our office as outlined below.

Regards BARRENJOEY CONSULTING ENGINEERS pty ltd

Per Lucas Molloy (Director) BE CPEng NPER

PO Box 672 Avalon NSW 2107 P:9918 6264 M: 0418 620 330 E: lucasbce@bigpond.com



Compliance Certificate

Including Bushfire Compliance

Airlite Windows & Doors Pty Ltd certifies that the windows and doors supplied to:

Address:

69 MARINE PARADE, AVALON

Order Number.

and the second second

J/N 5709

Date 18/11/2013

Delivery Date:

have been manufactured to comply with

Australian Standard AS2047 - 1999

Australian Standard AS1288 - 2006

Airlite products have been tested and passed by an N.A.T.A. accredited test laboratory.

Airlite certifies that the windows and doors supplied to the above address comply with the bushfire attack level (BAL) specified for each product on the next page as per the requirements of:

Australian Standard AS3959 - 2009

And any Cedar, or BAL-40 products as a result of tests conducted by CSIRO to meet.

Australian Standard AS1530.8.1 - 2007

Airlite provides a 7 Year Guarantee against faulty workmanship and materials.

Nick Marotta

Airlite representative ____

07/04/2014

The Builder/Installer certifies that the windows and doors supplied have been installed into the correct openings.

Builder/Installer

Date 8/4/14

ACCBF01-BW-V5 - Page 1/2

BASIX Completion Receipt

Receipt no.: CR-1491351080949-A130432

This receipt is confirmation that the certifying authority identified below has satisfied the requirements of clause 154C of the Environmental Planning and Assessment Regulation 2000 for the development described in the 'BASIX Certificate details' section below.

Director-General Date of issue: Wednesday, 05/04/2017



Planning & Infrastructure

Principal certifying authority

Name:	Craig
Accreditation scheme:	BPB
Accreditation number:	0124

Final Inspection

Date of final inspection: Wednesday, 02/04/2014

BASIX Certificate details

BASIX Certificate no.	A130432	
Project name	Baylis House	
Street address	69 Marine OTHER	
Suburb	Avalon	
Postcode	2107	
Local Government Area	Pittwater Council	

Silverfern Constructions

9 April 2014

Form Building Certifier Re: 69 Marine Pde Avalon

RE: REMOVE VEGETATION / SOIL

This letter is to certify that soil/vegetation was removed from around hardwood beam at the lowest point of the deck – as requested by Form Building Certifiers (Craig).

Yours sincerely,

9/4/14

DARRYL HUGGINS SILVERFERN CONSTRUCTIONS

> 819 Pittwater Road Dee Why NSW 2099 Telephone: 0407 215 093 Email: silver_fern@bigpond.com Licence No.124096C

Address:

69 MARIN PARADE, AVALON

Order Number:

Delivery Date:

J/N 5709	
18/11/2013	

ID	Description	Location	BAL
	3 LITE WIDOW WITH ANEETA INSERT RH	W1	12.9
	4 PANEL SLIDING DOOR	W2	12.9
	1LITE PANEL FIXED WINDOW	W9	12.9
	3 PANEL BIFOLD WINDOW	W12	12.9
	6 PANEL BIFOLD DOOR	W11	12.9
	3 PANEL STACKING DOOR	W13	12.9
	3 PANEL BIFOLD WINDOW	W18	12.9
	3 PANEL BIFOLD DOOR	W19	12.9
	I LITE SASHLESS WINDOW	W21	12.9
	5 PANEL BIFOLD DOOR	W23	12.9
	2 PANEL BIFOLD DOOR	W22	12.9
	2 PANEL BIFOLD DOOR	W24	12.9
	I LITE FIXED WINDOW	W20	12.9
- 10			-
1999 A 1999 A 1994			

ACCBF01-BW-V5 - Page 2/2

GEOTECHNICAL RISK MANAGEMENT POLICY FOR PITTWATER FORM NO. 3 – Post Construction Geotechnical Certificate to be submitted with Occupation Certificate or Subdivision Certificate

Development App	lication for	
	Name of Applicant	
Address of site	69 MARINE PARADE AVALON	

Declaration made by geotechnical engineer on completion of the Development

١,	PETER THOMPSON	on behalf of	Jack Hodgson Consultants Pty Ltd
	(Insert Name)		(Trading or Company Name)

on this the 23/03/2017

certify that I am a Geotechnical Engineer, Engineering Geologist and/or Coastal Engineer as defined by the Geotechnical Risk Management Policy for Pittwater - 2009. I am authorised by the above organisation/company to issue this document and to certify the organisation/company a current professional indemnity policy of at least \$2million.; I prepared and/or verified the Geotechnical Report as per Form 1 dated referred to below.

Geotechnical Report Details:

Report Title: RISK ANALYSIS AND MANAGEMENT FOR PROPOSED ALTERATIONS AND ADDITIONS PLUS POOL AT 69 MARINE PARADE AVALON
Report Date: 19/01/2012
Author : BEN WHITE

Author's Company/Organisation: JACK HODGSON CONSULTANTS PTY LTD

I reviewed the original structural design, and where applicable the subsequently amended structural details (below listed) which have been incorporated into the completed project.

I have inspected and/or an satisfied that the foundation materials, upon which the structural elements (as detailed in the original and amended structural documents) of the development have been erected, comply with the requirements specified in the Geotechnical Report and the Construction Certificate approved Structural Plans.

I have inspected the site during construction and to the best of my knowledge, I am satisfied that the development referred to in the development consent D.A. dated 20/08/2012

D.A. No_____ N0071/12 Date consent given 20/08/2012

has been constructed in accordance with the intent of the Geotechnical Report, and the requirements of the conditions of Development Consent and the Construction Certificate approved Structural Plans relating to the geotechnical issues (including any treatment and/or maintenance plan that may be required to remove risk where reasonable and practical).

I am aware that Pittwater Council require this certificate prior to issuing an occupancy certificate for the development identified above and will rely on this certificate in regard to the development having achieved the "Acceptable Risk Management" criterion defined in the Policy and that reasonable and practical measures have been taken to remove foreseeable risk.

List of all work as executed drawings and Ongoing Maintenance plans relevant to geotechnical risk management.

Signature	FJDL	ampoort
Name PETER	THOMPSO	N
Chartered Profess	ional Status	MIE Aust CPEng
Membership No.	146800	
Company Jack Hodgson Consultants Pty Ltd		son Consultants Pty Ltd

Report to Planning an Integrated Built Environment Committee for meeting to be held on 20 July 2009