



p: 02 9789 3837 | CLIENT: NTARCH

info@nswlandservices.com.au | CLIENT REF: 8806 www.nswlandservices.com.au 1/585 Canterbury Road

ADDRESS: 7 ROUNCE AVENUE Belmore NSW 2192
ABN: 72 634 829 575 SUBURB: FORESTVILLE

SCALE 1:100 OUR PROJECT REFERENCE & DETAILS: SCHEDULE OF SYMBOLS & ABBREVIATIONS SURVEY DETAILS: SURVEYED: X.X. E BB ELECTRICITY BOX G GV GAS VALVE

LP LIGHT POST KIP KERB INLET PIT STORMWATER MAINT. HOLE

BM BENCH MARK
STATE OR PERMINANT

PM SURVEY MARK

STORMWATER
MAINT. HOLE

TEL TEL TELECOM PIT

TGP TOP GRATED PIT

Ch CHAINAGE H HEIGHT SHEET SIZE: JOB NO: 7596 L.G.A.: NORTHERN BEACHES HYD HYDRANT DATE: XX-06-2021 X SV STOP VALVE LOT: 11 SECTION: -DP: 200198 PAGE COMPILED: RKLD WM WATER METER DATE: 26-06-2021 SOURCE: SCIMS DATUM: Australian Height Datum Communications TLP TOP LIDDED PIT T.R. TOP RETAINING S SPREAD Ø SMH SEWER MAINT. REVIEWED: C.C. DATE: 26-06-2021 DATUM ORIGIN: SSM 38518 REDUCED LEVEL: 120.83 DATE: 20-05-2021 G GM GAS METER KO KERB OUTLET FL FLOOR LEVEL D DIAMMETER Ø P SEWER INSPECTION 0F 1

DRAINAGE EASEMENT TO 6' WIDE

RIGHT OF WAY 12.0 WIDE

GENERAL & SITE SPECIFIC NOTES

Boundaries Identified

Contours are indicative of surface topography only. Surveyed spot levels are the only values at which reduced level can be relied upon. Contours are displayed at 0.2 metre major and 0.2 metre minor intervals.

Services shown have been derived from visual evidence apparent at the time of survey. It is strongly advised to visit 'dial before you dig' prior to any excavation or construction and verify critical locations with a suitably qualified service locator to AS 5488-2013 QL-A prior to any works or critical design.

It is strongly advised to review an up to date title search and give careful consideration to all items prior to any planning and/or